

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
A1-417		Cat 20T Excavator		
	195091	Off-hire Bellambi and disposal D1068.	11/09/2026	
	194123	July R&M 14//7/26 oil leak on hitch, blown o ring remove and replace o ring. 16/07/2026. Bucket tilt pin walked out. reinstall pin and new retaining bolt	13/07/2026	
	193847	Excavator - 2000hr service service completed @22/06/2026 @ 9963	22/06/2026	9963 Hours
	193652	June R&M Replace L/H idler.	22/06/2026	9963 Hours
	192883	May R&M * Hydraulic hose	29/05/2026	
	192770	GET CO - Bellambi Trazlbat Access ripper boots re-attach retainer and order new ones Deliver GET to site will fit when required Fit new teeth and bucket sides	29/04/2026	
	60956	Pre hire repairs as per inspection, BACKCHARGE - wash machine = 5hrs @ \$90 = \$450 BACKCHARGE - clean cab = 1hr @ \$90 = \$90 fBACKCHARGE - ill with fuel = 226L @ \$1.57 = \$354.82 wash and inspect leak at RH door Paint counterweight check track tension grease machine LH drive motor weep behind cover wash and inspect leak at filter housing in LH door re fit AM/FM radio fell out of mount. check it works also check why window wiper isn't latching check vibration at idle can feel it at revs as well remove client stickers tag fire extinguisher get tool box to open change o ring on engine oil fill cap adjust muffler so it doesn't hit engine cover engine cover cracked and latch not latching correctly fix sound proof sitting on engine tighten UHF aerial wash out cooler pack	23/04/2026	

Asset	W/O No	Description	Finished	Done Reading
		check tilt cyl barrel end pin movement in bucket to tilt pin crack around tilt hitch pin bucket repairs weld lhs door replace safety stickers as required 250hr service (separate work order)		
	192408	Excavator - 250hr service	8/04/2026	Hours
	60632	Off hire inspection - Wash - Clean cab - Oil / fuel leak Rh rear door - Paint counter weight - Check track tension - Grease - LH drive motor weep behind core - Leak at filter hosing Lh - radio fell into dish - Fill with fuel - Window washers/ wipers not working - Adjust muffler - Bonnet cracked - Tighten UHF - Client stickers	9/02/2026	
	59175	Damage - Forest Glen. Replace windscreen and subsequent blocked A/C filter	26/11/2025	
	57824	Excavator - 500hr service Pre hire repairs completed as per HME List 9526hrs	29/09/2025	Hours
	57817	Pre hire repairs as per HME inspection, w/o 57230 Hrs: 9562 Wash machine Fulcrum photos compelted Removal of wear plates and addition of new + crack repairs and choc blocks added Gut out gear strips, weld a wear stril Finishing off bucket works Remove RHS recoil assembly, remove and replace RHS sprocket, fit new first aid kit, fit new wiper blade, remove and remount AM/FM radio, clean cab out, remove rubbish, inspect, tag, bag fire extinguishers Chase up parts, order new seals for RHS track adjuster 500hr service, assemble track adjusters, fit track adjuster Fit chain, shim quick hitch, adjust chain tension, remove and replace LHS boom lift barrel end pin and bearing, fit new hyd oil cooler hoses Complete site and Maas paperwork, remove boom lift cylinder RHS, drain and fill RHS final drive oil, swap out UHF hand piece Reseal RHS boom lift, install fittings from tilt bucket and test tilt bucket, remove and replace engine oil filter hoses	29/09/2025	

Asset	W/O No	Description	Finished	Done Reading
		R+R engine oil filter hoses reseal, fit boom lift cylinder, fit quick connect fittings from bucket Assist with assembly, fit recoil, assist with service Fit chain and pin, remove broken bolts in drive motor covers, fit covers, remove broken grease fittings and fit new fitting to slur. R+R LHS barrel end bush/pin, inspect pin on bucket, clean work area Wash machine, Fulcrum photos, load machine, clean shed bay		
57230		HME Inspection - Excavator Remove muffler, modify after delete and re-install muffler DPF Delete Cut out 2 round plates to weld into the DPF and weld the hotdog exhaust and weld the end back on Quote #: 407	19/09/2025	
54656		Maryvale Site- Machine Immobiliser deactivate. DPF delete *Finish 9409hrs *Travelled to site hooked up laptop for Alex. *Hammer would not hook up. *Fixed wrong fittings. *Fitted hammer tested - all ok.	15/05/2025	Hours
54244		Replace e-stop and straighten damaged door (Happened after off hire inspection) - repair left engine door by panel beating , made bracing and welded up - replaced tool box E stop - Repair e-stop on toolbox of machine and trying to make a repair to the door on the left side of machine to limit door so it closes	17/04/2025	
54254		Carry out off hire/on -hire inspection - Weed & seed - Finish washing	16/04/2025	
53969		HME Inspection A1 Yard 9378.4 HRS	3/04/2025	9378 Hours
53578		Repair hyd leak on fitting Replace failed hyd hose -remove and clean hydraulic fittings from RH stick to bucket, refit fittings, test	25/03/2025	9335 Hours
53509		Carry out on-hire inspection 9335hrs	22/03/2025	9335 Hours
53231		Replace damaged quick coupler (Damaged by Site) 9336hr	10/03/2025	
52562		Off hire Hours: 9335	18/02/2025	9335 Hours
51514		A1-417. Wash. Pre hire repairs as per HME inspection, w/o 49459	14/01/2025	

Asset	W/O No	Description	Finished	Done Reading
	49123	Excavator - 250hr service Hours: 9,243hrs	14/01/2025	
	49459	HME Inspection - Excavator Repair coolant leak (bypass tube) Quote #:	27/11/2024	
	21144	Excavator - 1000hr service and repairs • Repair TFO tracker. Code list attached, displaying constant code 44. Tracker standards attached. Need this fixed for maintenance reporting. • Seat not going up and down. #This has been reported previously and identified as a non-issue - it's a spring seat. If you find an issue, please advise. * Repair engine coolant leak.	30/08/2024	8996 Hours
	20123	Hire on inspection	22/07/2024	8792 Hours
	18760	Failed R/H idler. 8787hrs.	12/07/2024	8790 Hours
	18641	Excavator - 250hr service	5/07/2024	8787 Hours
	18538	Jack up digger put on stands Split L & R tracks Line up finals and drain oils Remove both finals Strip clean and inspect both finals Rebuild both finals Fit RH & LH final Fill both finals to level Join both tracks / Adjust tracks Remove digger off stands Hours: 8,883	5/07/2024	
	49487	Supply 3 x lifting lugs Sunny Engine Lifting Lug GT2024, 4080Kg	4/07/2024	
	47730	PART C INSPECTION - ULAN WEST - MONTHLY	29/05/2024	Hours
	47991	PART C INSPECTION - 32960 - 28.5.2024 - ALEX	28/05/2024	Hours
	47723	500hr Service - Jack.L	17/05/2024	8582 Hours
	47791	PART C INSPECTION - ULAN WEST - 32932 - 3.5.2024 - ALEX	3/05/2024	Hours
	47644		3/05/2024	Hours
	47684	HOOKUP BUCKET WITH SIDE TILT - 34558 - BOWEN	16/04/2024	Hours
	47596	BUCKET BUILD - 33406 - WILLIAM	26/03/2024	Hours
	47688	INSTALL BLOCKS AND WEAR STRIPS - WELD AND FINISH - 32024 - WILLIAM	25/03/2024	Hours

Asset	W/O No	Description	Finished	Done	Reading
	47423	PART C INSPECTION - ULAN WEST - MONTHLY - PETER	22/03/2024		Hours
	47572	REPLACE BROKEN BOLTS - 34535 - 22.3.2024 - BOWEN	22/03/2024		Hours
	47484	REPAIR BUCKET, WELD IN NEW ADAPTORS & HARDFACE - 32010, 32011, 32013 - WILL	8/03/2024		Hours
	47220	250hr Service - JACK	29/02/2024	8320	Hours
	47334	REPAIR UHF WIRING, REPLACE FINAL DRIVE OIL, TIGHTEN LOOSE SEAT BOLTS - JACK	29/02/2024		Hours
	47188	PART C INSPECTION - ULAN WEST - MONTHLY	17/02/2024		Hours
	47310	POSITIONAL 728 AND JUMP STARTED, POSSIBLE BATTERY FAILURE - 31911 - DAVID LONSDALE	9/02/2024		Hours
	47315	FINISH TORQUE TRACKS - 28063 - BOWEN PRICE	2/02/2024		Hours
	47314	REPLACE CHAINS ON TRACKS AND TORQUE AND TORQUE TURN - 28062 - BOWN PRICE	1/02/2024		Hours
	47313	PUT PLATES ON REAR CHAINS, TORQUE TO SPEC - 30819 - RORY	1/02/2024		Hours
	47312	REPLACE CHAINS AND USE ALL OLD GROUSERS - 28061 - BOWEN PRICE	31/01/2024		Hours
	47311	REMOVE ALL PLATES OFF TRACKS, CLEAN PLATES OFF TRACKS - 30818 - RORY	31/01/2024		Hours
	47062	PART C INSPECTION - ULAN WEST - MONTHLY	18/01/2024		Hours
	47079	SAMPLE BOTH FINAL DRIVES AND CHANGE OIL IN BOTH - 25660 - DAVID	8/01/2024	8151	Hours
	46835	PART C INSPECTION - ULAN WEST - MONTHLY	19/12/2023		Hours
	46959	REPLACE BROKEN TRACK PIN & RE-CONNECT TRACK - 25623 - DAVID	12/12/2023	8016	Hours
	46573	2000hr Service - CHRIS, RORY	24/11/2023	8010	Hours
	46668	PART C INSPECTION - ULAN WEST - MONTHLY	17/11/2023		Hours
	46511	PART C INSPECTION - ULAN WEST - MONTHLY	19/10/2023		Hours
	46552	REPLACE ENGINE ECM AND FLASH WITH UPDATED SOFTWARE - WESTRAC (INV NO. SI 1725525)	12/10/2023		Hours
	46356	PART C INSPECTION - ULAN WEST - MONTHLY	14/09/2023		Hours
	46320	REMOVE ECM - 29803, 29702 - BOWEN, ALEX	1/09/2023	7827	Hours
	46276	RE-RUN TEST PROCEDURE FOR FUEL/WATER SENSOR - SENSOR FAILED, REPLACE SENSOR - 29015 - DAVID	22/08/2023	7824	Hours
	46238	INVESTIGATE FUEL/WATER SENSOR CAUSING ENGINE TO SHUT DOWN-SHORT IN HARNESS, FIT OVERLANDER FROM ECM TO THE FUEL/WATER SENSOR, NO ACTIVE CODES - 29010, 28476, 29011 - DAVID, ALEX	18/08/2023		Hours
	46145	PART C INSPECTION - ULAN WEST - MONTHLY	17/08/2023		Hours

Asset	W/O No	Description	Finished	Done Reading
	46180	ASSESS/TAKE PHOTO'S OF QUICK HITCH VALVE FOR REPLACEMENT - 28700 - DAVID	10/08/2023	Hours
	46179	DIAGNOSE REPORTS OF ENGINE SHUTTING DOWN - WATER SEPERATOR SENSOR VOLTAGE ABOVE NORMAL, CLEAN PLUG, TEST - 28696, 28845 - DAVID, PETER	9/08/2023	Hours
	45881	PART C INSPECTION - ULAN WEST - MONTHLY	17/07/2023	Hours
	45701	250hr Service - ALEX, BOWEN	4/07/2023	7639 Hours
	45658	PART C INSPECTION - ULAN WEST - MONTHLY	19/06/2023	Hours
	45774	REMOVE & REPLACE QUICK HITCH FITTING - 28304, 28402 - BROCK, ALEX	15/06/2023	Hours
	45413	PART C INSPECTION - ULAN WEST - MONTHLY	22/05/2023	Hours
	45336	500hr Service - ALEX	1/05/2023	7335 Hours
	45251	PART C INSPECTION - ULAN WEST - MONTHLY	19/04/2023	Hours
	45381	MEASURE & CUT NEW CUTTING EDGE, FIT TO BUCKET WITH NEW NUTS & BOLTS - 26527, 26350 - ALEX, BOWEN	17/04/2023	Hours
	45275	REPAIR LEAKING QUICK HITCH - 26421 - CHRIS	4/04/2023	7218 Hours
	45152	REPLACE CUTTING EDGE - 26212 - DAVID	17/03/2023	Hours
	45100	PART C INSPECTION - ULAN WEST - MONTHLY	16/03/2023	Hours
	45038	REBUILD UNDERCARRIAGE - 28774, 26888, 26889, 26890, 0013, 26891, 26893, 28777, 28779, 26895 - CHRIS, BEN, DANNY	2/03/2023	Hours
	44921	250hr Service - BEN, CHRIS	1/03/2023	7059 Hours
	44946	PART C INSPECTION - ULAN WEST - MONTHLY	21/02/2023	Hours
	45263	DIAGNOSE & REPAIR A/C - REPLACE CONDENSER, DRYER, TX VALVE, O-RINGS, CONTROL PANEL, UPDATE SOFTWARE - WESTRAC	27/01/2023	Hours
	44871	REPLACE MISSING BUCKET TILT PIN RETAINER BOLT - 27117 - DAVID	25/01/2023	Hours
	44716	PART C INSPECTION - ULAN WEST - MONTHLY	20/01/2023	Hours
	44835	INVESTIGATE A/C LEAK - 27107 - DAVID	18/01/2023	Hours
	44611	PART C INSPECTION - ULAN WEST - MONTHLY	22/12/2022	Hours
	44630	REPAIR TRACK ADJUSTER, TENSION TRACK - 27008, 26825 - ALEX, BEN	7/12/2022	Hours
	44413	1000hr Service - PETER, BOWEN	1/12/2022	6780 Hours
	44369	PART C INSPECTION - ULAN WEST - MONTHLY	21/11/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	44230	PART C INSPECTION - ULAN WEST - MONTHLY	22/10/2022	Hours
	44338	REPLACE BUCKET TEETH, REMOVE & REPLACE BOOM HOSE, REPLACE UHF & RE-SOLDER COAX CONNECTOR - 24389, 24399, 21856 - DAVID	17/10/2022	Hours
	44278	REMOVE WORN OUT BUCKET TEETH - 24374 - DAVID	29/09/2022	Hours
	44029	PART C INSPECTION - ULAN WEST - MONTHLY	20/09/2022	Hours
	44158	REPLACE RIPPER BOOT - 21643 - PETER	5/09/2022	Hours
	44178	DIAGNOSE SMOKE COMING FROM ENGINE BAY, RECOVER A/C GAS FROM SYSTEM, REMOVE FAILED A/C COMPRESSOR, REMOVE & REPLACE RECEIVER DRYER, INSTALL NEW A/C COMPRESSOR & FAN BELT, COMPLETE PRESSURE TEST, CARRY OUT VACUUM TEST, RE-GAS AS PER SPEC, START & CHECK MACHINE - WESTRAC	2/09/2022	Hours
	44128	DIAGNOSE ENGINE NOISE, RE-FIT BOOST ELBOW & TIGHTEN CLAMPS - 24346, 25705 - DAVID, BOWEN	30/08/2022	Hours
	43988	250hr Service - DAVE	24/08/2022	6404 Hours
	43909	PART C INSPECTION - ULAN WEST - MONTHLY	22/08/2022	Hours
	44062	DIAGNOSTIC TEST EGR ACTUATOR, FOUND EGR VALVE POSITION INCORRECT, TEST WIRES FROM ECM TO EGR-NO FAULTS FOUNS, ATTEMPT TO REMOVE EGR VALVE FROM MACHINE FOR FURTHER TESTING, VALVE POSITION BECAME UNSTUCK RETURNING TO COMMAND POSITION, REFIT & START MACHINE, FAULTS NOW INACTIVE, RECOMMEND REPLACING EGR VALVE - WESTRAC	4/08/2022	6333 Hours
	43761	PART C INSPECTION - ULAN WEST - MONTHLY	20/07/2022	Hours
	43891	REPLACE DAMAGED FITTING IN QUICK HITCH - 24301 - DAVID	18/07/2022	Hours
	43855	REMOVE & REPLACE STEREO, TEST - 21709 - BEN	13/07/2022	Hours
	43822	REPAIR QUICK HITCH FITTING, RELACE BUCKET TOOTH PIN - 22300, 24989 - BEN, DAVID	7/07/2022	Hours
	43793	RE-FIT MISSING TOOTH WITH NEW RETAINER, WELD ON OTHER LOOSE PIN, REMOVE REAINING PIECE OF BROKEN RETAINER PIN, CLEAN SURFACES, RE-FIT TOOTH WITH NEW PIN - 24977, 24985 - DAVID	29/06/2022	Hours
	43556	500hr Service - DAVID	28/06/2022	6136 Hours
	43740	FIT NEW BUCKET TOOTH & WELD IN RETAINER PI, REPLACE BROKEN QUICK HITCH FITTING - 24972, 24975 - DAVID	24/06/2022	Hours
	43616	PART C INSPECTION - ULAN WEST - MONTHLY	16/06/2022	Hours
	43668	REMOVE BROKEN TRACK PIN, CLEAN MUD FROM TRACK FRAME, REMOVE TRACK ADJUSTER, CLEAN & INSPECT ADJUSTER, FIT NEW PIN & TENSION TRACK TO SPEC - 24841, 24669, 24952, 24670 - ALEX, PETER, DAVID	9/06/2022	6034 Hours
	43367	PART C INSPECTION - ULAN WEST - MONTHLY	8/06/2022	Hours
	43504	DIAGNOSE CHECK ENGINE LIGHT - EGR FLOW ISSUE, CONTINUE TO MONITOR - 24913 - DAVID	11/05/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	43432	REPLACE BENT FITTING IN QUICK HITCH, TESTED-NO LEAKS - 24588 - DAVID	28/04/2022	Hours
	43221	PART C INSPECTION - ULAN WEST - MONTHLY	22/04/2022	Hours
	43359	FIT NEW ALTERNATOR & TEST - WESTRAC	4/04/2022	5732 Hours
	43301	REPAIRS - INSPECT TRACKS AND CHAINS FOR WEAR, CUSTOME TRACK SERVICE DONE - CLYNT	1/04/2022	Hours
	43094	250hr Service - BEN	22/03/2022	5732 Hours
	43248	ROTATE CUTTING EDGES, REPLACE NUTS & BOLTS - 24545 - DAVID	22/03/2022	Hours
	43073	PART C INSPECTION - ULAN WEST - MONTHLY	21/03/2022	Hours
	43121	INSPECT TRACKS FOR ADJUSTMENT - 24506 - DAVID	24/02/2022	Hours
	42875	PART C INSPECTION - ULAN WEST - MONTHLY	22/02/2022	Hours
	42983	INSPECT DAMAGE TO L/H ENGINE BAY DOOR - 23578 - DAVID	7/02/2022	Hours
	42937	DIAGNOSE QUICK HITCH ISSUE - 23458 - BEN	4/02/2022	Hours
	42732	PART C INSPECTION - ULAN WEST - MONTHLY	22/01/2022	Hours
	42695	2000hr Service, RE-ALIGN TRACK ADJUSTERS TO ADJUST TENSION - 23538, 23539 - ALEX, DAVID, PETER	30/12/2021	5404 Hours
	42601	PART C INSPECTION - ULAN WEST - MONTHLY	21/12/2021	Hours
	42691	DIAGNOSE RUNNING FAULT, REMOVE DPF, CUT OPEN & ATTEMPT TO CLEAN, REMOVE PART OF CORE TO UNBLOCK, WELD BACK TOGETHER, RE-FIT DPF, INSTALL EXHAUST PIPING & SENSORS, TEST RUN & BERN OFF DPF - 23601, 23429, 23523, 24090, 23432, 20777 - PETER, BEN, TIM, DAVID, ALEX	17/12/2021	5378 Hours
	42661	REPLACE BROKEN QUICK HITCH FITTING - 23513 - DAVID	10/12/2021	Hours
	42350	PART C INSPECTION - ULAN WEST - MONTHLY	22/11/2021	Hours
	42297	250hr Service - 23754, 20859 - PETER, DAVID	4/11/2021	5189 Hours
	42174	PART C INSPECTION - ULAN WEST - MONTHLY	21/10/2021	Hours
	42311	REPLACE HAMMER COUPLINGS - 20709 - ALEX	12/10/2021	Hours
	41998	PART C INSPECTION - ULAN WEST - MONTHLY	21/09/2021	Hours
	42107	REPAIR TOOTH ADAPTER ON GP BUCKET - 0446, 0476 - BCB ENGINEERING	9/09/2021	Hours
	41884	500hr Service - BEN	27/08/2021	4839 Hours
	41808	PART C INSPECTION - ULAN WEST - MONTHLY	21/08/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	41634	PART C INSPECTION - ULAN WEST - MONTHLY	22/07/2021	Hours
	41842	REPAIR GPS AERIAL WIRING, REPLACE GPS AERIAL, REPAIR AERIAL BRACKET - 20504 - PETER	20/07/2021	Hours
	41333	250hr Service, REPAIR HOUR METER - BLAKE	25/06/2021	4516 Hours
	41491	PART C INSPECTION - ULAN WEST - MONTHLY	21/06/2021	Hours
	41515	REPAIR HYD LEAK FROM QUICK HITCH, RE-RUN HYD HOSE, REPLACE FITTINGS, DIAGNOSE & REPAIR QUICK HITCH VALVE BLOCK - 19766, 19767, 10368 - BLAKE, BEN	28/05/2021	Hours
	41304	PART C INSPECTION - ULAN WEST - MONTHLY	18/05/2021	Hours
	41373	INSPECT GP BUCKET, REPLACE MISSING BUCKET TOOTH WITH NEW PIN - 10347, 10349, 10352 - BEN	13/05/2021	Hours
	41150	PART C INSPECTION - ULAN WEST - MONTHLY	25/04/2021	Hours
	40970	1000hr Service, TAKE OIL SAMPLES - 18524, 18525 - GABI	25/03/2021	4051 Hours
	41134	TOP UP HYD OIL, REPAIR BEACON - GABI	24/03/2021	Hours
	41122	CLEAN UP & WELD SENSOR BRACKET BACK ON - 0362 - BCB	16/03/2021	Hours
	41029	REPLACE WINDSCREEN, CLEAN AXLE PARTS - 10203, 18502, 18503 - JOHN, GABI	6/03/2021	3954 Hours
	40953	PART C INSPECTION - ULAN WEST - MONTHLY	4/03/2021	Hours
	40986	JUMP START, DIAGNOSE CHARGING ISSUE, REPLACE MUD BUCKET CUTTING EDGE, RE-FIT BUCKET PIN RETAINING BOLT - 10179, 20346 - BLAKE, BEN	24/02/2021	Hours
	41013	DIAGNOSE & REPAIR LOW POWER, DIAGNOSE & REPAIR BATTERIES LOSING CHARGE - WESTRAC	22/02/2021	Hours
	41011	DIAGNOSE & REPAIR A/C FAULT - WESTRAC	22/02/2021	Hours
	40931	JUMP START, CHECK ALTERNATOR - 10177 - BLAKE	19/02/2021	Hours
	40720	PART C INSPECTION - ULAN WEST - MONTHLY	27/01/2021	Hours
	40580	PART C INSPECTION - ULAN WEST - MONTHLY	4/01/2021	Hours
	40389	PART C INSPECTION - ULAN WEST - MONTHLY	21/12/2020	Hours
	40457	ASSIST WESTRAC WITH DIAGNOSING PRESSURE SWITCH, TOP UP A/C GAS - GB AUTO	1/12/2020	Hours
	40022	250hr Service, FITTED NEW PIN TO GP BUCKET, A/C REPAIRED BY GB AUTO, NEW UHF FITTED BY ANDREW BUT DIDN'T FIX THE PROBLEM - BEN	19/11/2020	3630 Hours
	40200	PART C INSPECTION - MOOLARBEN - MONTHLY	11/11/2020	Hours
	40179	PART C INSPECTION - ULAN WEST - MONTHLY	11/11/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	39997	PART C INSPECTION - MOOLARBEN - MONTHLY	21/10/2020	Hours
	39973	PART C INSPECTION - ULAN WEST - MONTHLY	21/10/2020	Hours
	39950	REMOVE & REPLACE BROKEN TRACK PIN, FABRICATE & INSTALL NEW CUTTING EDGE, INSPECT MACHINE - 23034, 22764 - BLAKE, BEN	22/09/2020	3519 Hours
	39717	PART C INSPECTION - ULAN WEST - MONTHLY	21/09/2020	Hours
	39924	REPAIR HOSES - BB'S HYDRAULICS	18/09/2020	Hours
	39739	PART C INSPECTION - MOOLARBEN - MONTHLY	15/09/2020	Hours
	39818	REPAIRS - CHECK A/C - STEVE	4/09/2020	Hours
	39867	CHECK FIRE EXTINGUISHERS - TOTAL FIRE SOLUTIONS	25/08/2020	Hours
	39612	500hr Service, DIAGNOSE & REPAIR EGR FAULT - BEN, WEBSTER	12/08/2020	3312 Hours
	39519	PART C INSPECTION - ULAN WEST - MONTHLY	10/08/2020	Hours
	39625	REMOVE & REPLACE BROKEN TRACK PIN, REPLACE BOLTS ON CUTTING EDGE, CHECK ENGINE FAULT ALARM - 22627, 22556 - TIM, JOHN	7/08/2020	3308 Hours
	39542	PART C INSPECTION - MOOLARBEN - MONTHLY	6/08/2020	Hours
	39478	TOP UP R/H FINAL DRIVE OIL, CHECK ALL FLUID LEVELS, CHECK WORK LIGHTS, GREASE, TROUBLESHOOT & REPAIR FAULTY EGR SYSTEM - 16928, 16930 - WEBSTER	21/07/2020	Hours
	39325	PART C INSPECTION - ULAN WEST - MONTHLY	13/07/2020	Hours
	39302	PART C INSPECTION - MOOLARBEN - MONTHLY	13/07/2020	Hours
	39129	PART C INSPECTION - ULAN WEST - MONTHLY	11/06/2020	Hours
	39111	PART C INSPECTION - MOOLARBEN - MONTHLY	11/06/2020	Hours
	38902	250hr service, REPAIR ISOLATION DOOR LATCH, REPAIR WEEPING RELEASE FITTING ON TILT - TIM	13/05/2020	3102 Hours
	38949	PART C INSPECTION - MOOLARBEN - MONTHLY	5/05/2020	Hours
	38972	PART C INSPECTION - ULAN WEST - MONTHLY	5/05/2020	Hours
	38994	REPAIRS - INSPECT FIRE EXTINGUISHERS - FIRESTORM	24/04/2020	Hours
	38800	PART C INSPECTION - MOOLARBEN - MONTHLY	8/04/2020	Hours
	38777	PART C INSPECTION - ULAN WEST - MONTHLY	7/04/2020	Hours
	38594	PART C INSPECTION - ULAN WEST - MONTHLY	23/03/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	38576	PART C INSPECTION - MOOLARBEN - MONTHLY	11/03/2020	Hours
	38694	REPLACE GREASE NIPPLE, TURN CUTTING EDGE, TIGHTEN BOLTS, DIAGNOSE HYD LINE WEEPING IN HITCH, REPAIR SEIZED RADIO SEAR BUTTON - 17414 - JOHN	4/03/2020	2840 Hours
	38379	PART C INSPECTION - MOOLARBEN - MONTHLY	5/02/2020	Hours
	38358	PART C INSPECTION - ULAN WEST - MONTHLY	4/02/2020	Hours
	38481	SWAP BOOM , REFILL HYD OIL, SWAP/REPLACE & GREASE FITTINGS, CHECK OVER FOR SITE - 19123, 19126, 19127 - BEN	30/01/2020	2694 Hours
	38293	PART C INSPECTION - ULAN WEST - MONTHLY	18/01/2020	Hours
	38176	PART C INSPECTION - MOOLARBEN - MONTHLY	13/01/2020	Hours
	37733	2000hr service, REPAIR L/H REAR DOOR & REPLACE LOCK ASSEMBLY	13/01/2020	2679 Hours
	38052	PART C INSPECTION - MOOLARBEN - MONTHLY	6/12/2019	Hours
	38119	REPAIR DOOR LATCH - STEVE	29/11/2019	Hours
	37851	PART C INSPECTION - MOOLARBEN - MONTHLY	18/11/2019	Hours
	37705	PART C INSPECTION - MOOLARBEN - MONTHLY	21/10/2019	Hours
	37804	CHANGE BOOM, REPAIR PANEL INSIDE DOOR, REPLACE WIPER MOTOR, NEW BOLTS IN LONG REACH - 17999, 18000, 17998 - TIM	18/10/2019	2518 Hours
	37508	PART C INSPECTION - MOOLARBEN - MONTHLY	17/09/2019	Hours
	37605	REPAIRS - LEAKING HITCH - STEVE	11/09/2019	Hours
	37476	REPAIRS - HITCH LEAKING OIL - STEVE	16/08/2019	Hours
	37348	PART C INSPECTION - MOOLARBEN - MONTHLY	13/08/2019	Hours
	37419	REMOVE & REPLACE BOOM, ATTACH HYD LINES & BOOM PINS, DIAGNOSE & REPAIR HYD LEAK - 18418, 18419, 17387, 17701 - JOHN, RYAN	5/08/2019	Hours
	37275	250hr service	30/07/2019	2268 Hours
	37381	CHANGE OUT BOOM - 17375, 18407, 17376, 18408, 17377 - RYAN, JOHN	26/07/2019	2268 Hours
	37304	REPAIRS - DAMAGED L/H INSPECTION DOOR, OIL LEAK ON TILT HOSE - STEVE	15/07/2019	Hours
	37187	PART C INSPECTION - MOOLARBEN - MONTHLY	9/07/2019	Hours
	37265	REPAIR TILT BUCKET - 17260 - BEN	2/07/2019	Hours
	37222	REPAIR TRACK - 21379 - JOHN	27/06/2019	Hours

Asset	W/O No	Description	Finished	Done Reading
	37066	PART C INSPECTION - MOOLARBEN - MONTHLY	20/06/2019	Hours
	37118	SWAP BOOM FROM LONG REACH TO STANDARD, CHECK OVER, REPAIR FAULTS, REPAIR LEAKING FUEL FILTER - 17216, 17218 - BEN	4/06/2019	2162 Hours
	36966	REPAIRS - MINOR OIL WEEP ON HYD LINE AT BASE OF BOOM - STEVE	20/05/2019	Hours
	36890	PART C INSPECTION - MOOLARBEN - MONTHLY	10/05/2019	Hours
	36787	ROTATE BUSH TO ALLOW GREASE FLOW, PRE MOBILISATION CHECK, REPLACE FIRE EXTINGUISHER - 17069 - RYAN	26/04/2019	Hours
	36757	REPAIRS - HOUR METER, BENT NIPPLE PROTECTOR, SHORT HOSE ON BOOM, GREASE PIN BUCKET END - STEVE	12/04/2019	Hours
	36739	NEW PINS & BUSHES IN LONG REACH - 11798, 21242, 21239, 21241, 21237 - TIM	11/04/2019	Hours
	36726	GREASE, NEW WINDOW - 21214 - TIM	2/04/2019	Hours
	36738	GLUE NEW GLASS TO FRAMES, FIT REAR ROLLER, ADJUST TRACK, WELD PIN ON BUCKET, CHECK OVER - 17039, 17040, 17041, 17038 - RYAN	1/04/2019	1984 Hours
	36635	RE-BUSH LONG REACH - 11795, 11797 - TIM	29/03/2019	1984 Hours
	36379	500hr service	15/03/2019	1979 Hours
	36553	REPLACE BUSHES ON LONG REACH - 21221 - TIM	6/03/2019	Hours
	35790	USO, BUCKET/LINKAGE, HYD LINES, GREASE BOOMS 11530/525/524/523 BEN.S	9/11/2018	Hours
	35370	250hr service	9/11/2018	1665 Hours
	35658	GREASE NIPPLES-11011 S.PEAKE	5/10/2018	Hours
	35213	DIAGNOSE SHUTTERING FAULT, REPLACE MIRROR, REMOVE AND INSTALL NEW STICKERS - 12452	19/07/2018	Hours
	35198	MINE SPEC AND SERVICE - 12092, 12605 - 13/7/18	13/07/2018	Hours
	34612	REPLACE HYDRALIC HOSE- CHECK FOR LEAKS- 16876- B SWARBRICK	15/03/2018	Hours
	34591	MINE SPEC- 14333-329	8/03/2018	Hours