

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1594		Cat 336E Excavator #3 (3363)		
	194997	clean and repair belly gaurds	26/08/2026	Hours
	194687	AC not working	6/08/2026	Hours
	193888	GPS problem	18/06/2026	Hours
	193835	order fittings Ryan Hilton	16/06/2026	Hours
	193718	250 Hour Earthmoving service Done @ 13624Hrs	11/06/2026	13624 Hours
	193540	Quick hitch hose replace	5/06/2026	Hours
	193007	336#3 repair bucket	1/05/2026	Hours
	191425	2000 Hour earthmoving service	19/02/2026	13422 Hours
	60838	336#3 Bucket Repairs Jason C	16/02/2026	Hours
	60724	Repair tilt bucket Gus A, Jason C	11/02/2026	Hours
	190381	2000 Hour earthmoving service	16/01/2026	
	189692	- Install fire extinguisher - R&R 2x primary fuel filter - R&R 1x secondary fuel filter	5/12/2025	
	188907	Refit bucket tooth - Pin coming out of bucket tooth - R&R new pin and lock.	12/11/2025	
	188953	Lost bucket tooth - Fit new tooth and lock bucket #096	11/11/2025	
	188670	Refit tooth to bucket - Refitted tooth - Test Hammer that is not working correctly.	22/10/2025	
	183192	Limp mode and Timing needs doing Ordered crankcase sensor - R&R crankcase timing sensor test ok	16/10/2025	
	175978	Bucket uncurls/creeps when loaded - Adjusted bucket reliefs ok	16/10/2025	

Asset	W/O No	Description	Finished	Done Reading
	186446	250 Hour Earthmoving service	15/08/2025	
	182925	500 Hour Earthmoving Service	15/03/2025	
	183185	Timing calibration	7/03/2025	
	182898	Fuel filter replaced	28/02/2025	
	182707	Replaced slack adjuster and tensioned track	7/02/2025	
	181767	Replaced RH track idler and tensioned tracks	15/01/2025	
	181886	Cut and blocked both heater hoses and filled with water	15/01/2025	
	181262	Re-fit bucket tooth Tensioned tracks	2/12/2024	
	175479	Bucket ram replaced	15/11/2024	
	180178	250 Hour Earthmoving service	14/11/2024	
	179549	Replaced tooth	10/09/2024	
	179257	Hitch un-jammed	30/08/2024	
	178372	Fire extinguisher out of date Fire extinguisher checked by Glen Windle	17/08/2024	
	178713	500 Hour Earthmoving Service	17/08/2024	
	178682	Grouser re-attached	24/07/2024	
	178028	Replaced water pump cover plate	23/07/2024	
	177662	250 Hour Earthmoving service	5/07/2024	
	175344	Top track roller = Inspected/OK	17/06/2024	
	176759	Replaced starter motor	30/05/2024	
	176037	500 Hour Earthmoving Service	20/05/2024	
	176412	Replaced quick hitch and hose	15/05/2024	
	176025	Replaced quick hitch Re-mounted hammer pipe clips	9/05/2024	
	175655	Replaced hose on stick	23/04/2024	
	174604	250 Hour Earthmoving service	23/03/2024	

Asset	W/O No	Description	Finished	Done Reading
	174214	A/C = Inspected/OK Greased tilt bucket	29/02/2024	
	171224	2000 Hour earthmoving service	19/12/2023	
	172151	Blow out air and A/C filters	9/12/2023	
	172135	Put quick hitch back on	6/12/2023	
	172143	Quick hitch eye repaired	4/12/2023	
	171923	Quick hitch cylinder eye replaced Replaced quick hitch	28/11/2023	
	171473	Replaced tilt bucket pin and cylinder	10/11/2023	
	167281	250 Hour Earthmoving service	28/08/2023	
	166386	Replaced hydraulic cooler Re-sealed bucket cylinder and replaced position sensor Repaired boom harness wiring and replaced stickers	21/06/2023	
	166030	Leaking oil from hydraulic oil cooler = Cleaned, bloanked off and parts ordered	8/06/2023	
	165493	Bucket cylinder replaced (2nd hand from PKWS) Repaired spool in main control valve	20/05/2023	
	164870	Slew motor hose replaced	2/05/2023	
	162794	track motor hose leaking Pirtek replaced	27/02/2023	
	162946	Fit belly guard	20/02/2023	
	162516	500 Hour Earthmoving Service	15/02/2023	
	158037	Toggle switch under seat repaired R&R engine air filters and A/C filters	27/01/2023	
	158896	250 Hour Earthmoving service	17/10/2022	
	159059	Hitch Inspection = OK	29/09/2022	
	158277	Need to inspect sensor and cable on top of boom	31/08/2022	
	156633	Fire extinguisher replaced	29/08/2022	
	157473	500 Hour Earthmoving Service	24/08/2022	
	158270	Replaced keeper bolt as needed	18/08/2022	
	155542	250 Hour Earthmoving service	25/06/2022	

Asset	W/O No	Description	Finished	Done Reading
	155660	Replaced both top strut hoses	15/06/2022	
	155394	Wont start = Inspected/OK	14/06/2022	
	155405	Hammer PSI pressure increased = OK	2/06/2022	
	155407	Fit hammer Replaced fitting on hammer	1/06/2022	
	154598	Quick hitch hose replaced	3/05/2022	
	153769	500 Hour Earthmoving Service	2/05/2022	
	154596	Hose fitting tightened	2/05/2022	
	154323	Bucket tooth replaced as needed	22/04/2022	
	153729	Bucket = Inspected/To be taken to PKWS for repair	13/04/2022	
	153732	Bucket tooth replaced	12/04/2022	
	153741	Low power/Limp mode = Inspected/OK	6/04/2022	
	153423	Bolt replaced from bucket	24/03/2022	
	153014	Hose under boom replaced by Pirtek	15/03/2022	
	148792	Front windscreen replaced Replaced grease unit hose on hammer	10/03/2022	
	153377	Oil fittings tightened as needed	9/03/2022	
	152221	Installed windscreen rock guard	9/03/2022	
	141721	Railing broken #railing welded up by Reeve	23/02/2022	
	152472	Plug on hammer replaced	22/02/2022	
	152609	Hammer fittings tightened as needed Replaced starter motor	21/02/2022	
	152274	Moil not greasing = Inspected/OK Hammer/hitch stuck = Inspected/OK	18/02/2022	
	151908	250 Hour Earthmoving service	18/02/2022	
	152273	DPF manual burn Replaced ARD head assembly	16/02/2022	
	151967	Hose to hammer auto greaser replaced by pirtek	14/02/2022	

Asset	W/O No	Description	Finished	Done Reading
	152194	Starter and batteries replaced	11/02/2022	
	152011	Hammer pin cover bolts tightened	11/02/2022	
	152000	Hammermoil replaced	7/02/2022	
	151773	Hammer hose fitting repaired as needed	3/02/2022	
	151772	Code on dash (After treatment fuel pressure high)= Reset = OK	2/02/2022	
	151481	Installed hammer	27/01/2022	
	151444	Replaced Moil	25/01/2022	
	151446	Inspected hammer and corrected machine settings	21/01/2022	
	151443	Fitting needs replacing by Pirtek	21/01/2022	
	151478	Relief valve on stick cylinder kitted	17/01/2022	
	150231	2000 Hour earthmoving service	21/12/2021	
	151461	Replaced hose on hammer and oil level switch	21/12/2021	
	150366	GPS not working Repair cable, replace fuse Ben P	3/12/2021	
	149981	Won't start Replaced batteries and replaced starter motor test-ok Reeve F	24/11/2021	
	148354	250 Hour Earthmoving service	19/10/2021	
	148741	Oil leak from bucket remove fitting clean out and replace Reeve F	19/10/2021	
	148749	Broken pin boss on tilt bucket Made up new one and welded on-OK Reeve F	18/10/2021	
	148785	Tooth missing on bucket replace tooth Reeve F	15/10/2021	
	148466	Outer tooth loose on bucket needs new pin and lock(ordered) Reeve F	13/10/2021	
	148504	Loose bolts on hitch pin keeper Tighten and check	11/10/2021	

Asset	W/O No	Description	Finished	Done Reading
		Reeve F		
	148407	Oil leak from hitch Replaced o-ring and tightened hose Reeve F	29/09/2021	
	147973	Blown quick hitch hose Replaced hose Pirtek test-ok reeve F	22/09/2021	
	148135	Bucket tooth fallen off bucket #CB081 Refitted tooth reeve F	17/09/2021	
	146450	500 Hour Earthmoving Service	30/08/2021	
	146751	Eng. oil leak Repl. remote eng. oil filter hoses. Fit all new P clamps. Top up oil. Checked Ok	24/08/2021	
	146324	Flashing light n/w. oil leak Turned flashing light sw. to on pos. & informed operator of it's location. Oil leak from worn hoses, weeping out through casing. Ordered hoses, topped up oil & instructed operator to vigilantly monitor & report if leak worsens	11/08/2021	
	146118	Bucket bolts broken Bolts broken from keeper plate ,top of centre pin. Actual bosses broken off. Contacted J. McGlynn. Bucket sent to PKWS for repairs	6/08/2021	
	146541	GPS cable to bucket broken Repl. cable. Check full range of motion & watched cable. Cable tied up making sure always clear to not pull cable on tilt. tested Ok	6/08/2021	
	145571	Fitting broken & oil leak. Replace broken fitting- Pirtek	8/07/2021	
	144324	250 Hour Earthmoving service	5/07/2021	
	144887	Bucket pin broken eye and bent out Remove broken bits of pin send to PKWS to repair Reeve F	23/06/2021	
	144890	Blown hose Remove belly guards, removed LH bottom track hose, replaced with Pirtek , topped up oil Reeve F	22/06/2021	
	144793	Fitted new cutting edges to tilt bucket Reeve F	11/06/2021	
	144292	Bucket GPS Replaced tilt bucket GPS harness-ok, bucket needs new cutting edges Reeve F	3/06/2021	

Asset	W/O No	Description	Finished	Done Reading
	143896	Hyd cap falling out Unjammed old cap and fitted new one Reeve F	26/05/2021	
	143890	Gps fault-tilt bucket sensor Replaced broken wire on plug, ran external wire Reeve F	24/05/2021	
	143236	Blown hose replaced blown tilt ram hose C Buck	5/05/2021	
	143114	Blown hose replaced blown quick hitch hose, topped up oil Reeve F	30/04/2021	
	141727	500 Hour Earthmoving Service	29/04/2021	
	142506	wont burn DPF, Remove DPF muffler, clean out with air R&R 2x main pump to valve xT6 hoses, R&R 2x coolant header tank hoses, refill radiator Complete manual DPF burn on CAT E.T B wise	17/04/2021	
	142479	Auto regen lockout over 120% Complete ash regeneration service on CAT E.T, R&R broken tilt bucket grease nipples, grease complete tilt bucket Dig out behind bottom boom pins, clean out bosses with bar B Wise	15/04/2021	
	142213	Blown hose under center of machine Changed 2 x track motor hoses C Buck	8/04/2021	
	142268	Auto DPF burn not working Code for high ARD fuel pressure, ran diagnostics procedure to replacement of head fitting filters(Grant W to order part) Replaced ARD filter fittings(ard ignition test failed reported to K North) Reeve F	24/03/2021	
	141881	Wont burn DPF No codes or events on computer seems to work correctly C Buck	18/03/2021	
	141602	Wont burn DPF Performed manual DPF regeneration through ET, operator to monitor-ok Reeve F	17/03/2021	
	140684	Hyd oil leak Track hose blown, replaced with Pirtek hose , tested-ok Reeve F	18/02/2021	
	138392	250 Hour Earthmoving service	8/02/2021	

Asset	W/O No	Description	Finished	Done Reading
	137447	Both track groups and segment ring need replacing, o-ring on engine filler cap need replacing Replaced tracks, sprockets, track adjusters NEW CAT GENERAL DUTY TRACKS AND SPROCKETS PKWS Scot A	28/10/2020	
	141414	Initial Plant Safety Audit	21/10/2020	
	136785	Check reverse alarm has been moved & check handrail Reverse alarm moved , handrail needs welding Reeve F	30/09/2020	
	136811	Track came off Released pressure in slack adjuster and push idler back in using machine Ran track back onto worn sprocket, pump slack adjuster back up to tension track(urgently needs new sprockets) Blake	29/09/2020	
	136449	500 Hour Earthmoving Service	29/09/2020	
	136659	blown tilt bucket hose Oil leak,tightened up hose on tilt bucket, checked other hoses,tested ok Cut off too long bolts on cutting edge flush Reeve F	26/09/2020	
	136263	Cutting edges Need cutting edge bolt and turn cutting edge C Buck	15/09/2020	
	136319	Track fallen off Refitted track to L/H of machine Note:track idler/adjuster very tight,tracks very worn Reeve F	10/09/2020	
	135426	move backup alarm Mounted alarm on back rail,make extension for wiring to new location,tested OK Reeve F	26/08/2020	
	135641	Track off Fit left track back on,pumped back up C Buck	25/08/2020	
	133874	250 Hour Earthmoving service	9/07/2020	
	132999	Wont start	16/06/2020	
	132937	wont start Jump started machine C Buck	15/06/2020	
	132316	2000 Hour earthmoving service	2/06/2020	
	131958	Tilt bucket broken pin Replaced pin in bucket	20/05/2020	

Asset	W/O No	Description	Finished	Done Reading
		C Buck		
	132071	Install lights on cab Install 2x led work lights on top of cab tracks/sprockets very poor condition,photo sent to K.N. bushes broken,sprocket missing teeth B Patrick	15/05/2020	
	131509	Light up on dash Changed fuel filters C Buck	29/04/2020	
	130561	250 Hour Earthmoving service	14/04/2020	
	129118	500 Hour Earthmoving Service	28/02/2020	
	129153	Oil leak on bucket Remove fitting out of ram Put thread tap on fitting Tested ok	27/02/2020	
	129421	Fuel leak Replaced both fuel lines from fuel pump to fuel filters	27/02/2020	
	129040	Fuel filters blocked Changed primary fuel filter Changed both fuel filters	25/02/2020	
	128772	Bucket won't Tilt New tilt bucket was hosed up incorrect changed hoses over tested ok.	12/02/2020	
	127553	250 Hour Earthmoving service	15/01/2020	
	127199	Oil leak Broken tilt bucket ram,R&R LHS tilt bucket ram B Wise	11/12/2019	
	123913	Needs music radio moved to to do list	21/11/2019	
	125525	500 Hour Earthmoving Service	10/10/2019	
	124734	Blown hose oil leaking from under machine Removed belly guard to access to blown hose,Replaced bu Pirtek Replaced RHF boom lift cyl. hoses-supplied by w/shop Hyd oil level ok but top up soon-informed G Withers,tested ok R Farquhar	13/09/2019	
	124099	250 Hour Earthmoving service	30/08/2019	
	124318	Oil leak on bucket Removed and replaced valve on tilt bucket Ryan Latham	28/08/2019	

Asset	W/O No	Description	Finished	Done Reading
	124058	Hydraulic leak on bucket Replace fitting in control valve on block on bucket #58 (block has hairline crack needs replacing) Ben Patrick	23/08/2019	
	123876	check hoses for oil leaks Parts ordered	16/08/2019	
	123430	Worn hoses Removed old hose on back of boom and replaced it with a cat hose. Replaced wire harness for grade control running over boom and stick Ryan Latham	27/07/2019	
	123054	500 Hour Earthmoving Service	25/07/2019	
	123008	blown hose.(boom to control valve) special remove hose assy & return to pkws ,9/7/19 fit repaired hose assy & test ok Glen Windle	8/07/2019	
	122266	Fit case drain hose fitted case drain hose over boom and stick Ryan Latham	14/06/2019	
	122176	Compaction Wheel collapsed on shaft. Needs boilermaker roller weld wheel back on roller attachment Scot Rodgers	12/06/2019	
	121321	250 Hour Earthmoving service	16/05/2019	
	120501	High soot level warning on dash Active code preventing dpf regeneration Replace faulty temp sensor carry out manual burn off OK	4/04/2019	
	119474	GPS not working	21/03/2019	
	119836	Gps playing up Ordered new boom harness for GPS	14/03/2019	
	119688	2000 Hour earthmoving service	13/03/2019	
	119612	KEEPER BOLT MISSING Put keeper bolt back in pin	4/03/2019	
	119407	Loose track RHS Pump RHS track up	7/02/2019	
	119078	250 Hour Earthmoving service	1/02/2019	

Asset	W/O No	Description	Finished	Done Reading
	118986	Tilt bucket pin fell out	16/01/2019	
		Bent both rams, swapped tilt bucket with spare one up the top of port yard and changed over GPS sensor on bucket		
	118745	install hammer tap fittings	8/01/2019	