

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
A1-421		Hitachi 21T Excavator		
	194513	Pre hire repairs as per HME inspection, W/O 194388 DISPOSAL BACKCHARGE - wash machine = 5hrs @ \$90 = \$450 BACKCHARGE - clean cab = 1hr @ \$90 = \$90 replace batteries replace seat cover complete 250hr service on separate WO repair weep at main suction check tracker no lights on tag and bag fire extinguishers repair travel alarm fill washer bottle first aid kit grease machine make sure everything is taking grease movement in bucket pin grease and check check track tension straighten belly guard inspect tilt grease or oil coming out put correct buckets with machine B403 and B404	3/09/2026	Hours
	194388	HME Inspection - Excavator Quote #: 569 6699.2 Flat batteries test, replace if required, Clean old ones and fit covers Seat covers Clean cab Wash 250 Hour service Check tracker Test tag fire extinguisher Fill washer bottle First aid kit Grease machine Slight movement in bucket pin Sprockets Straighten belly guard Grease on oil coming from tilt Weld up bucket pin Put correct buckets with machine B403 & B404	16/07/2026	6699 Hours
	192859	May R&M * Sort out parts	29/05/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
		Sort out parts * Fix tilt hitch * Replace H link to hitch pin (wrong pin)		
	192996	Excavator - 500hr service. 8061. Question: Check that grease points are receiving grease Answer: Minor Issues Comment: Tilt Hitch not taking grease * Clear out grease line for swivle hitch	7/05/2026	6535 Hours
	191259	Replace final drive cover plate - operator damage. Lake Cargelligo	6/05/2026	Hours
	192246	April R&M Replace engine belts. Belts purchased on 192194 (250hr service)	25/04/2026	6436 Hours
	192154	Excavator - 250hr service. 6283hrs Fix door up	8/04/2026	6283 Hours
	191578	March R&M. Lake Cargelligo. Replace broken A-Link (#Bent pin found on first attempt. Take spare pin from Dubbo - had to shorten pin).	31/03/2026	6227 Hours
	60972	Excavator - 2000hr service3 6026 hrs	25/02/2026	6023 Hours
	60677	February R&M Travelled out to location of digger. Carried out electrical test on 'exhaust temp sensor bank 1' - all tested ok. Checked over fluid levels and engine air cleaner, found broken air intake temp sensor. Ordered a new one to fit at later date. (Andersons Auto) Reported hydraulic leak. Tank found to be overfull. Drain to correct level. Fit new intake temp sensor.	10/02/2026	Hours
	59504	December / January R&M Electrical problem diagnosed Fuel starvation issue diagnosed need to inspect possible blockage in tank Clean out tank and inspect/repair	25/01/2026	Hours
	60114	Excavator - 250hr service Check Reverse camera working	16/01/2026	5771 Hours
	59289	Excavator - 500hr service 5565 hrs	27/11/2025	Hours
	58422	Excavator - 250hr service	14/11/2025	
	57866	Final drive oil leak reported by operator to site supervisor who requested inspection/diagnosis. Inspect and diagnose cause of final drive oil leak (Josh Bendall) Plant A1 421 Hitachi digger was reported to have an oil leak at the final drive, I removed the cover plates and followed the fluid lines back to the valve block and there was no evidence of an oil leak, no evidence of an oil leak was noticed anywhere on the under carriage, machine presents very clean. Remove final drive side covers. Inspect for oil leaks inside and outside, check hoses and piping. No evidence of leaks found. Unknown why the operator reported a fault that did not exist.	7/11/2025	
	58822	November R&M. Lake Cargelligo. Repair GPS tilt sensor cover. Mark Muller	1/11/2025	

Asset	W/O No	Description	Finished	Done Reading	
		Repair GPS tilt sensor cover - Mark Muller. Replace missing GET bolts (not client charge, not tightened correctly in Mudgee workshop).			
	57997	October R&M Will be adjusted next time Josh Bendall or his techs are on site. P.E. 29.09 Tighten A/C belts. check final drive oils, LH side took 500ml, rh side was over full 750ml. Drain oil to level mark and monitor	30/09/2025		
	55891	Pre hire repairs hrs 5118 - Made log grab bracket - Fulcrum - Fit tracks - Adjust tracks - Cut the hitch off the log grab and move it forward 150mm and make a new arm for the grab - Weld the hitch onto the grab - Cut off plate where the arm bolts to the hitch and cut out new plates and weld them on - Make a new bracket for the log grab arm to bolt to - Weld the brack onto the stick and paint it - Fit tilt lock out	20/08/2025	5118	Hours
	55816	Complete off hire Inspection 5114.3 GPS coming from Mudgee need to fir and get working Wash, clean cab Tag fire extinguisher R/H light not working Weld on bucket numbers Fill washer bottle B403 Mud bucket B404 GP Bucket RH track keeps going slack Clean out tool box First aid kit Fulcrum paperwork	26/06/2025		
	54642	Complete on hire inspection	2/05/2025		
	53696	Off Hire inspection	28/03/2025		
	52514	off hire and on hire inspections 5047hrs	14/02/2025	5047	Hours
	50037	Off hire inspections	11/11/2024	5018	Hours
	49569	Replace GET (Labour Only)	24/10/2024		
	49306	Fit new coolant bypass hose	16/10/2024		Hours
	49132	Re-mount broken GPS Sensor. Steel bracket cracked due to fatigue and vibration	10/10/2024		

Asset	W/O No	Description	Finished	Done Reading
	48081	HME. A1-421. Replace cracked window. Fulcrum On-Hire - Front glass cracked - Cab in rough state - undercarriage clean out	4/10/2024	
	21282	A1-421: Ulan West Monthly Part C Inspection	30/08/2024	4996 Hours
	20512	Excavator - 1000hr service.	22/08/2024	4976 Hours
	21050	Complete Off-Hire and Fulcrum Report	21/08/2024	4980 Hours
	20551	HME inspection 4911.8 HRS	31/07/2024	4912 Hours
	47956	DIP STICK REPAIR - FILL ENGINE, COOLANT, LUBES UP - 34466 - CHRIS	4/06/2024	Hours
	47922	FABRICATE MUD BUCKET - 33430,33429,33427,33428 - WILL BOYTON	28/05/2024	Hours
	47901	FABRICATE MUD BUCKET, INSTALL FINAL DRIVE, PUT TRACKS BACK ONTO MACHINE, PLUMB UP FINAL DRIVE, INSTALL RH FINAL, FIT RH TRACK, FILL RH FINAL OIL, RH TRACK, TEST MACHINE, PERFORM MUFFLER BURN - 31193,32832,33422,32833,31194,33423,32050,33424,33425	21/05/2024	Hours
	15433	Supply steel and fold for bucket A1-421	13/05/2024	
	47751	FAB MUD BUCKET, 32039,33416 - 26.4.2024 - WILLIAM	26/04/2024	Hours
	47573	FILL R/H DRIVE WITH 85W 140 OIL - 31985 - 19.3.2024 - DAVID	19/03/2024	Hours
	47221	250hr Service - WESTRAC	28/02/2024	4629 Hours
	46827	500hr Service - JESSE	12/12/2023	4360 Hours
	46895	REPAIR BENT TRACK PLATE - 101 - DANNY	20/11/2023	Hours
	46739	REPAIR QUICK HITCH ISSUE - 0095 - DANNY	15/11/2023	Hours
	46604	DIAGNOSE QUICK HITCH NOT LOCKING - FAILED RELAT VALVE - 0075 - DANNY	11/10/2023	4080 Hours
	46581	HOSE UP TILT HITCH & FIT H-LINK, PURGE PINS, INVESTIGATE QUICK HITCH NOT OPENING - 99 - JACK LEESON	10/10/2023	Hours
	46394	250hr Service - 99 - JACK LEESON	10/10/2023	4080 Hours
	46416	REPLACE BATTERY ISOLATOR - 94 - JACK	11/09/2023	3988 Hours
	45986	1000hr Service - 0042 - DANNY	31/07/2023	3802 Hours
	46083	FIT NEW CUTTING EDGE TO MUD BUCKET - 40 - DANNY MOERKERK	27/07/2023	3799 Hours
	46003	MEASURE UP CUTTING EDGE FOR REPLACEMENT - 0037 - DANNY	21/07/2023	Hours

Asset	W/O No	Description	Finished	Done Reading
	45967	RE-SHIM QUICK HITCH - 0031 - DANNY	10/07/2023	Hours
	45833	ASSESS MOVEMENT IN HITCH AREA - SHIMMING REQUIRED - 28617 - DAVID	29/06/2023	3654 Hours
	45564	250hr Service, REPLACE BROKEN GREASE NIPPLES ON BUCKET HITCH - BOWEN, ALEX	31/05/2023	3519 Hours
	45496	REPLACE A/C BELT & TENSION, REMOVE FRONT WINDSCREEN ROCK GUARD - 26478 - CHRIS	9/05/2023	3448 Hours
	45014	500hr Service - ALEX, DAVID	18/03/2023	3276 Hours
	44524	250hr Service - DAVE	5/01/2023	2925 Hours
	44119	2000hr Service - PETER	13/09/2022	2527 Hours
	43710	CHECK ALTERNATOR ISSUE/LIGHT STAYING ON - NO FAULT PRESENT - HITACHI	15/06/2022	Hours
	43638	INSPECT QUICK HITCH SOLENOID - SOLENOID FAILED - 24940 - DAVID	2/06/2022	Hours
	43446	250hr Service - CHRIS	17/05/2022	2282 Hours
	43190	BYPASS FAILED ISOLATOR ONSITE UNTIL NEW PARTS RECEIVED - 24527 - DAVID	9/03/2022	Hours
	43063	500hr Service - CHRIS, DAVE	3/03/2022	1998 Hours
	42652	250hr Service - 23536 - DAVE	29/12/2021	1707 Hours
	42330	1000hr Service, INSPECT CUTTING EDGE - 20856, 23755, 20860, 20870 - DAVID, PETER	10/11/2021	1446 Hours
	42126	REPLACE FITTING ON BOOM - 20588 - PETER	17/09/2021	Hours
	41956	250hr Service, REPAIR TILT LINKAGE SENSOR - BEN	9/09/2021	1112 Hours
	41706	REPLACE INTERCOOLER HOSE - 19790 - BLAKE	1/07/2021	Hours
	41278	500hr Service, REPLACE DAMAGED AIR HOSE - 19825, 18671, 19826 - GABI, PETER, NATHAN, ALEX	28/06/2021	814 Hours
	41450	REPAIRS - LOOSE FLASHING LIGHT BRACKET - JOHN	21/05/2021	Hours
	40476	250hr Service - 17380 - KELDAN	21/01/2021	387 Hours
	40214	PART C INSPECTION - MOOLARBEN - MONTHLY	11/11/2020	Hours
	40067	FIT EXHAUST, TURBO & DPF HEAT SHIELDING - 22787 - BEN	7/10/2020	Hours
	40084	FIT DIGITAL RADIO - GB AUTO	25/09/2020	Hours