

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1406		Cat 12M Grader #3 (12M3)		
	194905	Center shift seal kit replace broken scarifier tips and tines	26/08/2026	Hours
	194988	500 Hour Earthmoving Service Done @ 20626Hrs	25/08/2026	20626 Hours
	194469	Bush for mast missing retaining screws CN766 Yalwal Road Intersection	6/08/2026	Hours
	193515	12M#3 Cutting edge change	3/06/2026	Hours
	192538	250 Hour Earthmoving service Done @ 20364	6/05/2026	20364 Hours
	192616	12M#3 Remove and Replace Scarifier Tips - Matt S	16/04/2026	Hours
	189001	500 Hour Earthmoving Service	11/12/2025	
	189682	LHR wheel locked up - LHR wheel, chain adjusted broken - R&R new chain drive - Replace split pins - Adjust circle - Check engine fault	11/12/2025	
	189581	Oil Leak - Inspected - Coming from trans breather - Over filled	3/12/2025	
	188864	Replace Batteries - Replaced	3/11/2025	
	187805	250 Hour Earthmoving service	24/10/2025	
	188104	Replaced cutting edges, blade slides/plates Adjusted blade shims	8/10/2025	
	180886	Plant Risk Assessment Review	5/09/2025	

Asset	W/O No	Description	Finished	Done Reading
	187236	Repaired GPS	4/09/2025	
	187040	Inflated tyres	29/08/2025	
	185949	Steering wiring repaired	18/06/2025	
	183899	Replaced RH tandom sprocket and front axle bushes, pins and seals	9/04/2025	
	181441	2000 Hour earthmoving service	4/02/2025	
	181067	GPS cables = Inspected/OK	22/11/2024	
	181072	Engine won't start = Inspected/OK	19/11/2024	
	180566	Replaced LH axle bearings, planetary set Repaired LH axle housing, diff lock plate for piston GPS system replaced	29/10/2024	
	179367	250 Hour Earthmoving service	29/10/2024	
	178919	Circle slides loosened	23/08/2024	
	174157	Circle adjusted	21/08/2024	
	173918	Stereo wiring repaired Replaced blade slides	16/08/2024	
	176790	500 Hour Earthmoving Service	19/06/2024	
	174429	250 Hour Earthmoving service	22/03/2024	
	167292	Replaced full set blade slides and adjusted Replaced muffler	14/03/2024	
	170995	LH E-stop replaced	3/11/2023	
	170520	500 Hour Earthmoving Service	1/11/2023	
	170496	Tighten blade pins and replaced mirror	20/09/2023	
	167432	250 Hour Earthmoving service	10/08/2023	
	165932	SEAT BELT REPLACEMENT	27/06/2023	
	166642	Lower LH pivot blade tilt nut and washer replaced	27/06/2023	
	165906	500 Hour Earthmoving Service	15/06/2023	
	166384	Cutting edges replaced	14/06/2023	
	166178	Put A frame back together after bolts snapped	8/06/2023	

Asset	W/O No	Description	Finished	Done Reading
	165513	Circle adjustment adjusted	23/05/2023	
	164871	Replaced brake seals, friction disks, teeth on circle drive, drive gear Repaired swivel joint, ball to 'A' frame, lift, tilt cylinders, blade and slides	26/04/2023	
	158453	See work order 64871 for details.	24/04/2023	
	162730	250 Hour Earthmoving service	16/02/2023	
	161391	Blade slides replaced and adjusted	14/12/2022	
	160268	2000 Hour earthmoving service	24/11/2022	
	160658	Transmission calibrated	17/11/2022	
	158276	Replaced lift cylinder bottom ball caps	8/09/2022	
	158307	Fire extinguisher stolen = Replaced	1/09/2022	
	157821	250 Hour Earthmoving service	31/08/2022	
	157785	Brakes adjusted	31/08/2022	
	157136	Replaced lift cylinder back plate bolts Removed shims from turn circle as needed	25/07/2022	
	157111	Install circle wear strips	22/07/2022	
	155863	Replaced lift cylinder trunion bushes and lift cylinder cap bushes Replaced circle drive top wear strips	14/07/2022	
	155784	500 Hour Earthmoving Service	13/07/2022	
	154733	Replaced cutting edges	23/05/2022	
	153071	Reverse Camera replaced	14/05/2022	
	154227	250 Hour Earthmoving service	13/05/2022	
	148142	Won't change gears #Lever was jammed GWithers	9/05/2022	
	152518	Needs 2 tynes # Tynes fitted	9/05/2022	
	154456	Replace pinion shaft Adjust circle guides	7/05/2022	
	153372	Replaced fire extinguisher Replaced x2 ripper tyres Replaced bolt in GPS pole	3/03/2022	

Asset	W/O No	Description	Finished	Done Reading
	151599	500 Hour Earthmoving Service	22/02/2022	
	151765	Full set of cutting edges replaced	1/02/2022	
	152615	Replaced drive tyres	28/01/2022	
	149010	250 Hour Earthmoving service	19/11/2021	
	141722	Hydraulic pump o-ring/seal replaced Fuel gauge sensor wiring repaired Cylinder rams shims removed	24/09/2021	
	146767	500 Hour Earthmoving Service	8/09/2021	
	147880	Blade slides Replaced blade slides, shimmed up turn circle order sensor for code on dash C Buck	13/08/2021	
	144250	250 Hour Earthmoving service	17/06/2021	
	142924	steering fault light on Malfunction steering to the left by itself,excessive movement in cams Plug in ET 615-13, 616-14, 2252-14, follow workshop manual to trouble shoot ,clean and check sensors, lube rod ends, perform calibration, test drive no codes present Ben P	10/06/2021	
	142337	Broken lift ram balls Replaced 2x lift ram balls, all new bearings cups and shims for lift cylinder, replaced bottom o-ring on diff Blayden	25/03/2021	
	141244	Steering issues, scarefier teeth R&R full set of scarefier teeth, clear all logged codes on Cat ET Machine has intermittent steering sensor fault, clean connections on steering cylinder sensors-ok @ time of inspection B Wise	9/03/2021	
	142559	Flat tyre on pos 5 repaired by Premium tyre's(see attach)	9/03/2021	
	140899	2000 Hour earthmoving service	5/03/2021	
	140105	Steering light on Replaced sup steering pump C Buck	19/02/2021	
	147567	Plant Risk Assessment Review Assessment done by Stephen R.	18/02/2021	

Asset	W/O No	Description	Finished	Done Reading
	139741	Auto Blade not working Fault codes , checked fault codes on ET, checked hyd oil-ok, need to come back with diagnostic book for codes Lever setting needed reset Reeve F	21/01/2021	
	139591	HYD Fault light on,blade control not working ran through wiring diagnostics,found all to be working as expected, all power,earth and signal wire's ok to sensor, lever setting needed reset Reeve F	20/01/2021	
	139103	UHF not working Fixed plug on UHF C Buck	9/12/2020	
	136733		12/10/2020	
	136702	flat tyre pos 5 Repaired by Premium Tyres(see attach)	28/09/2020	
	136246	RHS tandem has no drive Removed covers and pipes to access tandem broken chain and sprocket get floated to PKWS Reeve f Remove both tandems and repair and reseal at PKWS (see all attachments)	24/09/2020	
	136618	Circle loose Took shim out of circle drive clutch Ryan L	24/09/2020	
	135819	T-block ordered,Shims slides	10/09/2020	
	135700	Cutting edges and blade slides Oil leaks,fit previously ordered parts Fit new blade slides to R/H top and bottom and left top,replaced leading valve block on goose neck and pipes and seals,test OK Reeve F	9/09/2020	
	135534	250 Hour Earthmoving service	4/09/2020	
	135673	Cutting edges and slide plates Replaced cutting edges and blade lift bushes C Buck	1/09/2020	
	133838	Air in transmission Checked transmission level-very over full,checked tandom oil levels L?H dirty,R/H overfull clean Suspect oil leaking/mixing between RH tandem and diff/trans,drained trans to correct level exact Operator to monitor,may need Tandem seals replaced Reeve F	29/06/2020	
	133427	Tyre repair pos 6 Check tyre and remove rio and fit plug on pos 6 Premium tyres	24/06/2020	

Asset	W/O No	Description	Finished	Done Reading
	132963	500 Hour Earthmoving Service	19/06/2020	
	132839	Lift ram yoke fallen out Hit LH lift ram yoke back into position,drilled out broken bolts,tapped holes out to M12x1.75. Refitted new bolts w/plate and shims,tested OK,checked other side Reeve F	11/06/2020	
	132505	A frame fallen off Bolted A frame back up C Buck	3/06/2020	
	131970	Flat middle right tyre Plug Pos4 Premium tyres	19/05/2020	
	131178	No hyd Found lock out switch to be faulty.replaced switch with a light switch to get machine going,parts ordered Fitted new implement lock out switch R Latham	30/04/2020	
	126618	250 Hour Earthmoving service	20/11/2019	
	126088	NO oil pressure Engine oil pressure light on Check with E.T engine oil pressure & park brake light on,pick parts up westrac,fit new switches,check E.T for clear codes B Patrick	29/10/2019	
	125376	500 Hour Earthmoving Service	11/10/2019	
	125656	Fit 6 new tyres Premium tyres	17/09/2019	
	124358	Circle drive motor u/s Pulled drive motor apart and changed all clutch plates and discs and shimed it all up Ryan Latham	6/09/2019	
	124036	250 Hour Earthmoving service	27/08/2019	
	123662	Pos. 1 tyre L/H front steer sidewall leak.	7/08/2019	
	123050	500 Hour Earthmoving Service	30/07/2019	
	123305	Loose muffler	26/07/2019	
	122630	Exhaust leak,blade lift cylinder inserts Replace exhaust coupling between turbo & exhaust neck,replace inserts on lift cylinders Ben Patrick	3/07/2019	
	121789	250 Hour Earthmoving service	3/06/2019	
	121744	Bad transmission oil leak and vibration in engine circle,oil leak ,RH wpier	28/05/2019	

Asset	W/O No	Description	Finished	Done Reading
		adjust circle,replace pinion & seal,circle teeth worn,replace trans to filter pipe replace rh wiper motor & arms,adjust Ben Patrick		
	121669	Turn circle locking up replaced turn circle slides Cameron Buck	23/05/2019	
	121579	circle tight readjust circle replace ripper tips x9 Ben Patrick	14/05/2019	
	121584	turn circle movement replace wear slides under turning circle flip cutting edges ,replace wiper blades,adjust turn circle Ben Patrick	9/05/2019	
	120575	2000 Hour earthmoving service	16/04/2019	
	120658	Needs cutting edges and dash gauges U/S Fit New edges and changed fuse	15/04/2019	
	120416	Need circle slides,blade slides and cutting edges (Monday 8-4-19) RnR worn blade slides	8/04/2019	
	119231	Front left Called premiums	28/03/2019	
	120054	Installed GPS	19/03/2019	
	119948	Flat battery Jump start machine	18/03/2019	
	119793	Remove discs from turn circle Removed one shim out of turn circle drive (inspected clutch plates) Replaced top turn circle wear plates Replaced bottom lift ram bushes on turn circle Rotated blade cutting edges	13/03/2019	
	119788	Exhaust U/S Fit new exhaust	8/03/2019	
	119501	250 Hour Earthmoving service	1/03/2019	
	119473	Turn cutting edges	22/02/2019	

Asset	W/O No	Description	Finished	Done Reading
	119440	White smoke out of engine Oil consumption RnR CAT REMAN turbo RnR turbo manifold studs nuts and gaskets and seals check oil levels test OK	7/02/2019	
	119273	Worn cutting edges Changed cutting edges	6/02/2019	
	119091	Air con cuts out, test electrical system found power to compressor but not pumping (clutch problem) replace compressor, dryer Evac system, replace compressor and dryer new seals used, pressure test system vac down install 20 ml oil , charge system and replace filters	18/01/2019	
	118905	500 Hour Earthmoving Service	15/01/2019	
	118564	A/C freezing Freezing at orifice tube Evac gas in system ,replace dryer/orifice ,pressure test , vac down system charge to CAT spec	14/12/2018	
	118122	Blade slides missing and front lights bracket rusted. Changed blade slides adjusted turn circle rotated cutting edges	27/11/2018	
	117916	250 Hour Earthmoving service	23/11/2018	
	117845	needs cutting edges Removed and replaced cutting edges	14/11/2018	
	117339	A/C not working Test system adjust gas pressure run for 1 1/2 hours no problems	20/10/2018	
	117211	Has fuel leak on fuel line Removed and clean injector Link seat refitted	18/10/2018	
	117123	Cutting edges worn Fit new cutting edges and bolts	11/10/2018	
	117058	Cutting edges Fit new cutting edges	10/10/2018	
	117057		8/10/2018	

Asset	W/O No	Description	Finished	Done Reading
	116466	500 Hour Earthmoving Service	19/09/2018	
	116618	Broken Fuel pipe RnR broken common rail fuel manifold on head RnR steel fuel line from pump to filter test OK Turn cutting edges and adjust door stricker	17/09/2018	
	116288	Install new blade slide and adjust install 2x bearings in LHS lift ram section replace inserts on lift cylinder	4/09/2018	
	115913	needs cutting edges Add shims to turn circle Adjust blade slide New floor mat	31/08/2018	
	114651	250 Hour Earthmoving service	31/07/2018	
	114870	Turn edges swapped LHS with RHS Fit new led light to RHS	17/07/2018	
	114321	needs cutting edges Fit new cutting edges	7/07/2018	
	114249	Needs cutting edges Fit new cutting edges and bolts	3/07/2018	
	116156	Install reverse camera kit	25/06/2018	
	116147	Check ET for codes, check sensors for damage found rod bent, clean out around sensors straightened rod, performed a calibration, replaced circle pinion drive gear new duo seal, adjust circle shims	12/06/2018	
	113570	LHS lift ram very loose / replace blade lift cylinder yoke bearings / remove shims front a frame ball	30/05/2018	
	113027	500 Hour Earthmoving Service	16/05/2018	
	113042	Engine water leak and needs cutting edges / r&r plastic elbow out of head for water jacket / r&r cutting edges	1/05/2018	
	112219	Blown front steer tyre. Requires 2 tyres to be fitted. Premiums sent to job	12/04/2018	
	112003	Blown Hose Pirtek sent to job	12/04/2018	
	111971	Needs cutting edges edges fitted	23/03/2018	
	112040	250 Hour Earthmoving service	14/03/2018	
	112704	oil leak turn circle/ edges Replace top turn circle slides, replace blade slide	3/03/2018	

Asset	W/O No	Description	Finished	Done Reading
		adjust circle, replace hydraulic shuttle valve rear steer valve body was cracked, replace cutting edge new bolts washers nuts used tightened GPS pole, replace fuel pressure sensor		
	110832	2000 Hour earthmoving service	1/02/2018	
	110700	Cutting edges. Replace cutting edges/ bolts, install new UHF arial lead kit.	15/12/2017	
	110299	A/C not working replace switch all tested fine	17/11/2017	
	110307	A/C tripping out Checked out all tested fine	15/11/2017	
	109690	250 Hour Earthmoving service	8/11/2017	
	110380	Worn out front end remove and replace end pins, bearings and seals. Remove and replace lift ram left hand side bearings and seals remove and replace blade side, rod end pin remove and replace blade tilt keeper pin and bolt	8/11/2017	
	109630	needs cutting edges and two scarifyers Remove and replace cutting edges and bolts	25/10/2017	
	109168	Exhaust bolts loose Remove and replace tips remove and replace 3 x broken bolts on muffler bracket	21/09/2017	
	108436	UHF cable end u/s and front steering bracket u/s Replaced aerial and wiring still needs new hand piece	12/09/2017	
	107534	500 Hour Earthmoving Service	31/08/2017	
	108333	Adjust circle shims, turn edges and replace right hand LED	8/08/2017	
	106622	Needs cutting edges and shimms for circle and scarifier shank Install new cutting edges, repair wire on speaker, put 2 x new circle slides in rear	2/08/2017	
	106396	250 Hour Earthmoving service	17/07/2017	
	106357	Blade nut coming loose Tighten 4 x nuts and replace split pins with bolts	11/07/2017	
	105894	Needs cutting edges and ripper scarifies and cups Remove and replace cutting edges and bolts Remove seized plug for circle drive Drain oil and refilled circle drive box	16/06/2017	

Asset	W/O No	Description	Finished	Done Reading
		Remove and replace lift ram cup inserts		
	105368	500 Hour Earthmoving Service	29/05/2017	
	107746	Install GPS pole Installed GPS blade post, turn circle needs attention with movement, refill drive with oil.	11/05/2017	
	108778	Worn circle leaking tandems Removed blade and resealed blade side cylinder, replaced pins and put back together removed circle replaced 4 worn sections and replaced circle drive and circle drive gear as were worn removed and resealed swivel new o-rings on all hoses removed new magnetic plugs in tandem drain replaced wear strips in circle and reshimmed	10/05/2017	
	107876	Circle guides work blade slides worn circle drive gear worn. replace circle guides Replace blade slides (upper and lower) Fit new circle drive gear.	7/04/2017	
	104953	250 Hour Earthmoving service	31/03/2017	
	104238	500 Hour Earthmoving Service	24/02/2017	
	107806	Remove and replace full set of cutting edges with nuts and bolts Inspect wear on ring gear for turntable and blade slides	30/01/2017	
	103576	250 Hour Earthmoving service	21/12/2016	
	103930	Cutting edges U/S. R&R cutting edges .	2/12/2016	
	102360	2000 Hour earthmoving service	18/11/2016	
	101837	250 Hour Earthmoving service	15/09/2016	
	101061	500 Hour Earthmoving Service	29/07/2016	
	100655	broken tandem chain# Replaced LHR tandem chain	25/07/2016	
	100032	250 Hour Earthmoving service	20/05/2016	