

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1138		Cat 745 ADT		
	194882	off hire inspection	17/08/2026	Hours
	193594	June R&M Fire system service	29/06/2026	Hours
	192844	May R&M * Welding repairs on step Replace reverse alarm	22/05/2026	Hours
	192707	Cat 745 ADT - 500hr Service Serviced carried out @ 10546	1/05/2026	10546 Hours
	192235	April R&M Replace P1 and P2 tyres. Sidewall splits - not from inpacks. Not a backcharge. P.E. Lagging supplied from Dubbo w/shop Window visor, remove Need to replace assembly Add new drop down visor	23/04/2026	Hours
	191767	March Monthly R&M WO: * Coolant leak, missing guard clips, blow out coolers. * Replace hose off the water pump * Replace speed nuts	31/03/2026	10404 Hours
	192208	RIM CRACK TESTING	27/03/2026	Hours
	60783	Cat 745 ADT - 250hr Service Dipstick oil is damaged 02/02/2026 LHS ramp leak oil RHS tyre crack Lights coming up on the dash all the time	28/02/2026	10324 Hours
	60503	February R&M Monthly WO: Fire suppression inspection low pressure alarm - 23/02/2026	23/02/2026	Hours
	60261	Pos 2 Tyre replacement Blown Double coin serial no D321403195 NEW ON MAXIM 251020j32301 50MM TREAD	22/01/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
	59935	January R&M Monthly WO -Jump start truck, return to workshop -Load nitrogen charging kit travel to Moolarben adjust pos 2 strut 700mm pin to pin. Retorque pos 2 wheel nuts -Faulty key barrel, temp repair until parts arrive 10108hrs -Repair defects, diagnose/repair fuel gauge fault, inspect artic for movement, replace 3rd axle brake cooler lines -Repair defects on list -Replace arm rests, repair wipers, replace ignition barrel 10143hrs	22/01/2026	Hours
	59535	Cat 745 ADT - 2000hr Service 10023 hrs -Prestart empty and replenish service trailer, and service 10023hrs -Service, defect repairs-oil leak under cab- trans cal- pick up hose from pirtek.	16/12/2025	Hours
	59550	December R&M Monthly WO: Grease tank follower not coming down, lip seal folder over, remove tank cover. Refit seal and test	1/12/2025	Hours
	58908	November Monthly R & M WO: -Bad connection in pressure switch on fire system bottle, repin plug and test 10/11	10/11/2025	Hours
	56726	August R&M Monthly work order: Fire alarm on panel system pressure low, united safety to charge up bottle	3/11/2025	Hours
	58336	Cat 745 ADT - 250hr Service and to do list 9765hrs - defects will be repaired when off hired	21/10/2025	Hours
	57336	Cat 745 ADT - 500hr Service and to do list repairs 9667 hrs - repair wiring to ECM	30/09/2025	Hours
	56337	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	24/09/2025	Hours
	57590	September R & M Monthly WO : - POS 4 loose nuts, re torque nuts and check 9552hrs - Light out due to damaged wiring, repair wiring and test	22/09/2025	Hours
	55632	R&M - June - Remove and replace worn steer cylinder bushes and pins 9217hrs - inspect movement in steer cylinders, found both L&R cylinders had movement in rod end, barrel end was fine. - remove L&R rod ends from machine, remove bearings from cylinders , clean surfaces and install new bearings. - fit pins and torque to 180ftbb while striking with mallet until torque was reached. - purge new bearings with grease cleanup work area, tracker not responding, check power to red 24v, white 14v, rang fleet support power not an issue, replaced tracker with new unit rang and had unit assigned to truck.	16/09/2025	Hours
	57597	HME 9547.3HRS MCO	5/09/2025	9547 Hours

Asset	W/O No	Description	Finished	Done Reading
	55952	JULY R & M- Moolarben -Park brake fault 9223hrs 02/07 - Check solenoid resistance reading tested within spec, test wiring and found no power or A958 wire, follow harness check plug connections. Remove panel behind seat check power at connector 16 and found broken wire refit panels and guiding. - Hyd temp alarm going off, fail sensor. Order new sensor	7/07/2025	Hours
	55142	250hr service and repairs 9201hrs - Set up A frame to be dropped by putting come alongs around each wheel group to tow points on the front of machine and rear of machine to hold it square. - remove bolts out of cap and remove cap. Clean up cap. - remove bearing retainer and clean it up as well as bolts. - Flip cap over and use rod to press bearing out. - Press bearing out and clean up area to install new bearing. - Install new bearing and new dust cover. - Jack A Frame back up and put bearing retainer back in and torque bolts to 120fp. - Put cap back on and tighten bolts - replace park light bulb - remove all slings and come alongs and clean up - Remove pos 3 tyre to go on P1126 - Replace RH side mirror mounts due to old mounts broken - install new dipstick - brake cooling hose replaced - bearings and pins now replaced	10/06/2025	Hours
	55346	Shift P1 to P3 as it is repaired tyre XXX (tyre was supplied from A1 stock) Fit P3 to P1 9211hrs	4/06/2025	9211 Hours
	55112	Accumulated gas pressure fault, diagnose and repair Accumulator gas pressure fault light on, test and charge to spec. Repair test port thread on bottom of accumulator, Replace grease fitting on tank 9208hrs	26/05/2025	9208 Hours
	54693	Service and repair Fire suppression system	16/05/2025	Hours
	54892	Tyre damage - Pos 2 - remove, replace and re fit pos 2 tyre, tyre was stuck on front and rear bead #Tyre replaced with one from P1140. No tyre charge labour only JH	15/05/2025	Hours
	54577	Remove and Replace RHS 1st axle tire due to damage (MCO)	1/05/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		-replace tyre with tyre from yard. May		
	54178	Fit grease coupling to grease quick fill 9054hrs	30/04/2025	Hours
	53893	Replace leaking hoist hose 8972hrs - replace leaking hoist leak RHS, hose made by pirtek - Oil leak in artic hyd hose, travel home	10/04/2025	Hours
	53636	Cat 745 ADT - 1000hr Service -Gas POS 1 strut 9027hrs	8/04/2025	9027 Hours
	53946	HME Inspection MCO 9013.3	4/04/2025	9013 Hours
	53748	Adjust strut pressures 8971km Prestart travel to mco. P1138 adjust strut heights to spec.	31/03/2025	8971 Hours
	53393	Remove and replace failed tyre. MCO. March Diagnose and repair grease system fault - remove POS 2 tyre for repair , refit pos 2 and torque wheel nuts. - diagnose and repair grease fault. - run test found that lines needed to be purge. - grease system has been run empty and not been filled for some time. Site cost	19/03/2025	Hours
	51266	Engine valve adjustment. Fuel pressure check Charge air system testing. #Leakage of air at wastegate. 5/01: Travel to site - fill out swims & work authorisation permit	13/02/2025	Hours
	51708	R&R front diff drive shaft unis 8634hrs	21/01/2025	Hours
	49908	Install UHF 8360hrs	21/01/2025	Hours
	51225	Cat 745 ADT - 500hr Service. 8500hrs -Purge 3rd axle A frame bearing, was not taking grease - POS 2 tyre under pressure, pump up resect valve - Start 500hr service - Purge grease system - Repair grease lose	15/01/2025	Hours
	49166	3rd axle a frame bearing excessive movement. Remove and replace bearing. Grease system not working. Empty. Fill and purge grease system.	11/11/2024	8370 Hours

Asset	W/O No	Description	Finished	Done Reading
	21045	Machine low power 8,106hrs - Low boost Check intake and exhaust systems. No faults found. Engage Westrac. Westrac found transmission faults that may be de-rating the engine Replace transmission speed sensors - intermediate sensor fault. LOW POWER NOT RESOLVED. Travel to MCO , wait for access to truck. hrs 8362, Investigate low power fault. Check turbo wheels, manually test waste gate, check injector valves, fuel pressure, fuel delivery volume found vibration in truck when revving around 1200 RPM, further investigation needed.	30/10/2024	Hours
	21213	Pos 1 a frame bearing failed. Remove replace A frame bearing Hours: 8106 est \$2000	3/10/2024	Hours
	48101	Repair horn wiring and replace horn Remove and replace water pump	11/09/2024	8175 Hours
	48592	Inspect and repaired wiring for plant tracker	9/09/2024	8151 Hours
	19972	ITS + Defect repairs as per task list. Assist with compliance inspection on site Repair broken grease fitting on rear A-frame bearing pin. Found grease fitting broken in pin, drilled and extracted fitting, replaced with new fitting, plumbed up hose and primed grease. Job completed. Dropbox output uni joint to front differential has play indicating trunnion wear, requiring replacement. Left side arm rest is falling down. Seat suspension feels excessively soft, recommend investigating. "Fault codes need troubleshooting to resolve. Some require factory access to clear. Fuel level indicator issues, not reading correctly. Passenger seat belt is expired, requiring replacement. Operator seat arm rest is falling down. Seat suspension feels excessively soft. Operator's are reporting poor engine power output and transmission sticking, carried out transmission fill calibration. Rear a frame front mount has no grease line and is dry. Looks worn. Recommend investigating. Dropbox output uni joint to front differential has play, requires replacement. Rear brake cooling hose perished. Lift cylinder hose perished." Action sample for transmission. Need to inspect that the trans breather and dipstick are not allowing dirt entry. Filler area to be clean prior to any top ups. Check front left final drive mag plug - Oil sample indicating higher iron.	25/07/2024	8040 Hours
	20291	HME- Inspection	24/07/2024	8039 Hours
	18592	Diagnose and repair beacon Fuel gauge faulty Coolant issues and leak Load counter fault	17/07/2024	8025 Hours
	19244	2000 Hour Topped up oil level, added hydraulic oil additive to tank. Replaced drive belt Rear a frame mount hasno grease line, looksvery dry. Recommend investigating Put additive in tankand topped up oil level	8/07/2024	8018 Hours

Asset	W/O No	Description	Finished	Done Reading
	49848	4000hr service @8000hrs. Carried out under Westrac CVA - 1st week of July. Late invoice. # Should have been receipted on WO19244 before it was closed.	5/07/2024	Hours
	16217	Blown head gasket, Loosing coolant into cylinder, leaking water pump. Check over machine for other defects. Replace head gasket Reseal water pump Reseal starter motor Pump up struts Cut open oil filter, check for metal Replace 3x Plant stickers Replace damaged hi vis tape Fit cab jack procedure decal Check and tag fire extinguishers/ fire suppression Fill and test auto greaser Fit a frame wire rope Replace hoist pump mount oring Replace steer pump mount oring Reseal rear structure cover plates Seg tie rubbing hoses under cab Replace centre driveshaft uni Check centre axle/ rear axle driveshaft yoke movement/ inspect splines & bolt tension Adjust front wiper arm Repair LHS wiper Adjust rear RHS wiper arm, replace window washer Test reverse alarm/ lights Check all fluid levels (split costs between A1 Earthworx and Maas Civil Assets)	7/06/2024	7740 Hours
	51903	Late CVA invoice for 7750hr service, completed pre-July 2024.	8/04/2024	7723 Hours
	11267	500 Hour service	31/01/2024	7520 Hours
	7636	Articulated Dump Truck - 250hr service	16/11/2023	7247 Hours
	6442	Articulated Dump Truck - 1000hr Service	6/09/2023	6988 Hours
	4930	Replace wiper blades Window seal kit Diagnose start issues	31/08/2023	Hours
	4807	Repairs to Estop circuits on Cat 740 moxy P1138 Ostendo Job: WS817804	29/08/2023	Hours
	1918	250hr service and off hire repairs	21/06/2023	6729 Hours
	2990	Finish off service Repair grease lines On hire inspection	7/06/2023	
	2134	Fill auto greaser and check over	23/05/2023	6692 Hours

Asset	W/O No	Description	Finished	Done Reading	
	1597	Carry out services and repairs	19/04/2023	6549	Hours
	1480	Fill auto grease and check over	28/03/2023	6376	Hours
	1424	Inspect noise coming from brakes	22/03/2023		
	1692	Service and fill auto greaser	14/03/2023	6265	Hours