

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1023		Cat 279C Posi Track		
	192636	Pre Hire Repairs as Per WO192632 Wash And Cab Clean (cab Filthy) Replace Cab Filters (full of Dust) Repair Damaged Door seal Clean Radiator Full of dust from site (only done before hire) Replace broken muffler Diagnose and repair Engine Fault light diagnose and possibly replace weeping line on 4in1 Bucket	22/04/2026	Hours
	192632	Off Hire Shearmans	17/04/2026	Hours
	192364	April R&M Monthly WO: - Identify / test battery, jumpstart machine, test charge rate, battery ordered - Changed out battery and check what the charge rate is	8/04/2026	Hours
	60994	Pre Hire Repairs 1. Wash machine ready for site 2. Clean cab and remove rubbish 3. R&R Bucket Lock Broken/Seized - remove lock pins/handles - clean pins and bores - install lock pins and replace broken handle - grease and test 4. Unblock Grease track from pivots - remove grease nipples from pins - use porta power to flush out pins - install nipples and grease 5. Front door seal u/s - remove and replace door seal 6. Exhaust Rusted through -remove exhaust muffler - clean surfaces - install new muffler with new gasket/ bolts 7. wiper arm u/s - remove and replace wiper arm 8. Ipas screen in cab loose/Not working - remove camera screen/ harness - found damaged spot in harness - repair damaged section of harness - remove useless screen mount - remounted screen to better location and mount	19/03/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
		9. Tracker wiring damaged - repair tracker wiring - re-route tracker wiring		
		10. Rear door pivots badly worn - remove and replace pivot bolts		
		11. Fan shroud broken and fan mounts pulled through - remove and replace fan shroud		
		12. Hydraulic quick couplers leaking - remove and replace quick coupler		
	191545	No A/C	17/03/2026	Hours
	58054	October R & M Monthly WO REZ: - inspect machine 4718hrs - Grease and fill hyd oil - Replace broken radiator latch	17/02/2026	Hours
	60852	Offhire Merotherie 4764hrs Quote 495	17/02/2026	Hours
	60611	February R&M Monthly WO: Hyd couplings won't couple up, release pressure and fit couplings and repair oil leak 4764hrs	5/02/2026	4764 Hours
	60063	January R&M Monthly WO: REZ OIL CHARGE OUT	31/01/2026	Hours
	59615	Positrack - 250hr Service 4750.9 - had to change final oils - Replace final oil	8/12/2025	4750 Hours
	59624	Pre hire repairs as per WO 59598 4751hrs	5/12/2025	Hours
	59598	Offhire Barrigan Hours 4750.9	5/12/2025	Hours
	58944	November R & M Monthly WO: - replace A/C compressor - De-gas A/C system as compressor bearing had failed. - Remove compressor and found new parts to be in correct. - Seal and secure A/C hoses so machine can be moved still. - Remove and replace A/C accumulator located under the cab. (Note: fittings were badly seized). - Return to site and fit new A/C compressor - Vac and leak test - All ok - Re-gas with dye and oil	25/11/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		- Test system - All ok		
57933		Positrack - 250hr Service and to do list from Mex 4716hrs	30/09/2025	4716 Hours
57510		September R&M DPF Delete - replace track 05/09 - investigate engine noise 19/9 2684hrs - Remove dpf, press out insides, pump up tracks, order new ac belt and idler - Repair door not closing properly	30/09/2025	Hours
57728		September R & M - Lift cab to find hose leak, RR hose and get new hose made, reassemble cab. Refill hyd oil tank as all the oil dried out	15/09/2025	Hours
53229		Diagnose and repair derating fault Replace bucket floor. 4660hr - Check for derating found broken wire on throttle - POS sensor & wear in - Linkage temp repair parts on order	16/07/2025	4660 Hours
56174		IPAS installation Please charge to MCA	9/07/2025	Hours
56009		Off hire repairs. 4653hr - install new rear service guard - access rail bent/ heat up and straighten rail - replace first aid kit - bucket step bent/ heat up and straighten - emergency exit latch missing/ replace missing latch - RHS bucket clam cylinder leaking/ remove, re-seal and install cylinder	7/07/2025	4653 Hours
55933		Pre hire inspection Spec for REZ 4632hr - carry out fulcrum inspection - carry out pre hire inspection - carry out 3D safety inspection	7/07/2025	4632 Hours
55995		Missing throttle cable 4624hrs	3/07/2025	4624 Hours

Asset	W/O No	Description	Finished	Done Reading
		Air con box filling with dirt and throttle cable broken for hand throttle - Replace throttle cable, - replace all seals, reseal air con box, wash and blow out evap and test		
	55935	Off Hire inspection Stubbo Replaced hand throttle cable Resealed air con box & blow out evap test	3/07/2025	Hours
	55616	Hand throttle missing.	2/07/2025	Hours
	54791	Replace track adjuster grease nipples - travel to Hollinsworth and replace both LH and RH track adjuster grease nipples, pump up tracks, travel back to workshop	7/05/2025	Hours
	53499	Positrack - 500hr Service 4564hrs	5/05/2025	Hours
	53945	Repair derating engine. Replace engine harness. Machine going into limp mode. Replace faulty e-stop	11/04/2025	Hours
	53414	A/C repairs 4503hrs	19/03/2025	Hours
	52913	Replace blown hose RH drive 4449hrs - Remove blown drive motor hose - Get new hose and oil replace and test	25/02/2025	Hours
	52266	Poor aircon performance, blocked evaporator remove clean and test 4387hrs	6/02/2025	Hours
	51900	Remove and Replace cutting edge (Bombira to be charged) 4373hrs	29/01/2025	4373 Hours
	51804	Pre mobilisation and weed and seed for Stubbo	20/01/2025	Hours
	50306	Remove and Replace blown Bucket Hose 4243hrs Replaced left hand side four in one bucket hose COMPLETE	19/01/2025	Hours
	51471	Positrack - 250hr Service 4348hrs -Replaced rear E-stop -Replaced LHR light bulb	9/01/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		-Replaced missing a/c compressor mount bolt -LH bucket tilt cylinder pin coil wasn't taking grease, removed pin and cleaned grease journal refit with grease nipple		
	51373	Refit left hand track 4344hours - Refit LH track	6/01/2025	Hours
	49080	REPAIRS; NO A/C, GREASE NIPPLES NOT TAKING GREASE, BUCKET QUICK HITCH ISSUES	24/10/2024	Hours
	49211	Hours: 4222 RHS front truck idler leaking Remove and repair/replace	15/10/2024	Hours
	49004	Replace engine air cleaners and ac filters PARTS SUPPLY ONLY requested by Ben Swarbick	4/10/2024	Hours
	49010	Hours: N/A Fulcrum On hire	3/10/2024	Hours
	20889	P1023. Pre hire repairs as per HME inspection. w/o 20862 Fit first aid kit Clean cab Replace missing cab safety pins Check and tag fire extinguisher Repair front lights Fill washer bottle Grease machine Replace 2x plant ID stickers Fit hi vis tape Remove old client stickers Change final drive oils Replace tracks Repair leaking fuel tank	16/08/2024	4190 Hours
	20862	HME Inspection - Positrack Quote #: 164	13/08/2024	4189 Hours
	17896	Travel to Stubbo Replace uhf and repair oil leak Travel to workshop	1/07/2024	4179 Hours
	16407	Tighten belts, Repair cover, replace missing bolts	15/05/2024	Hours
	15362	12 mile pre hire paperwork Fit fire extinguisher Fit QR stickers Repair flashing light wiring. Wash Fulcrum on-hire photos.	2/05/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
	8630	Diagnose and repair fuel leak Check and repair a/c Fit mount plate for track frame back onto machine Weld up bracket for hyd filter Take photos of damage Replace A/C compressor, flush system, replace filter, replace reciever drier Replace belts Repair bucket fit skin to bottom Grease machine get grease into tilt cylinders	14/03/2024	Hours
	7316	Minor R&M Adjust both tracks Refit LH track	20/11/2023	3985 Hours
	3623	July parts - AMCOR	27/07/2023	
	2927	4000hr service and grease. Replace missing alternator belt guard - including fabrication of brackets - also missing. Replace broken UHF mounting bracket First aid kit - place new one in cab. Replace wiper blades Replace blown rear light globe Fuel machine Replace V-belt. Re-install LH rear boom pin - walked out Replace A/C vent	8/07/2023	3985 Hours