

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1543		CAT 980K Wheel Loader #5		
	194769	Callout - Aircon not cold	3/08/2026	Hours
	194288	Remove load rite	14/07/2026	Hours
	193608	Pumped tyres up	26/06/2026	Hours
	60983	Wont start BArmour	23/02/2026	Hours
	190448	Bucket Change	19/01/2026	
	190361	Oil leak - Blown O-ring under the cab - R&R	15/01/2026	
	189917	Flat battery - Jump started	12/12/2025	
	189093	Hole in bucket floor - Template made	13/11/2025	
	188963	Flat batteries - Jump started and checked charging 27.5V	12/11/2025	
	188463	Oil leak lifting hose - See notes in documents	11/11/2025	
	188951	Install grease line - R&R	11/11/2025	
	188116	A/C = Inspected/OK	3/10/2025	
	180888	Plant Risk Assessment Review	5/09/2025	
	186866	250 Hour Earthmoving Service	2/09/2025	
	186529	Replaced bucket edge fasteners	5/08/2025	
	186094	2000 Hour Earthmoving Service	26/07/2025	
	184316	Replaced all bushes, seals and pins in Z-link, boom loushes at bucket	16/06/2025	
	177739	Lift ram and front timing cover re-sealed	16/06/2025	

Asset	W/O No	Description	Finished	Done Reading
	185032	250 Hour Earthmoving Service	14/06/2025	
	184188	Bucket pins = Inspected/OK	3/05/2025	
	184055	Replaced transmission filter hoses and seals	3/05/2025	
	183928	500 Hour Earthmoving Service	26/04/2025	
	183195	Re-seal oil filter housing	5/04/2025	
	183198	Replaced dipstick tube	17/03/2025	
	182379	250 Hour Earthmoving Service	15/03/2025	
	182025	A/C condenser core replaced	1/02/2025	
	181858	Replaced receiver dryer - 10.01.2025 Topped up gas - 23.01.2025	23/01/2025	
	181440	500 Hour Earthmoving Service	17/12/2024	
	181770	A/C re-gassed	17/12/2024	
	180141	6 bolts missing from bucket cutting edge # Replaced bolts and tightened	21/11/2024	
	180176	250 Hour Earthmoving Service	11/11/2024	
	179273	500 Hour Earthmoving Service	29/09/2024	
	178877	Park Brake shoes replaced/cleaned out drums = Tested/OK Replaced grease lines	23/08/2024	
	174519	A/C fan wiring repaired	21/08/2024	
	178852	Replaced engine oil dipstick tube	15/08/2024	
	177966	250 Hour Earthmoving Service	8/08/2024	
	177382	Repaired clamp on tilt pipe	24/06/2024	
	175706	2000 Hour Earthmoving Service	18/06/2024	
	176772	Replaced transmission filter housing o-rings	28/05/2024	
	176102	Coolant heater core blanked off Re-fit pin, bolt and keeper	20/05/2024	
	176028	Repaired front light brackets Replaced lift cylinder bolt	3/05/2024	
	175683	Replaced starter relay assembly	26/04/2024	

Asset	W/O No	Description	Finished	Done Reading
	175656	Blocked heater hoses	23/04/2024	
	174601	250 Hour Earthmoving Service	25/03/2024	
	173855	Replaced transmission filter housing assembly and filter	1/03/2024	
	173704	500 Hour Earthmoving Service	24/02/2024	
	173973	Replaced trans direction switch and arm rest position switch Adjusted park brake	23/02/2024	
	173963	Replaced latch on engine door	14/02/2024	
	172175	250 Hour Earthmoving Service	27/01/2024	
	173046	Re-attached cutting edges	24/01/2024	
	172344	Park brake solenoid repaired	16/12/2023	
	172338	Machine not moving = Re-connected park brake solenoid	9/12/2023	
	171467	Wash machine	14/11/2023	
	170990	Bucket wont rack back = Disconnect and re-connect solenoid coil - 07.11.2023, 14.11.2023	14/11/2023	
	170835	500 Hour Earthmoving Service	11/11/2023	
	170980	Replaced ARD ignition head assembly and spark plug	1/11/2023	
	170780	Replaced injectors x6	28/10/2023	
	169633	250 Hour Earthmoving Service	30/09/2023	
	169822	Replaced loadrite rotary switch and repaired wiring	22/09/2023	
	169800	Closed heater valve Re-run UHF wiring	21/09/2023	
	169843	Deisel entering cooling system = Replaced cylinder head/gasket kit, header tank, cooler pipe to transmission hose, implement valve o-ring	19/09/2023	
	168556	Replaced coolant lines	22/08/2023	
	164122	Replaced front tyres, steering pump/suction hose, A/C accumulator, receiver dryer, seat cushion, hoses to tilt cylinders and grease lines on frame Repaired steering pressure switch wiring. bonnet actuator pipe work	12/08/2023	
	167873	A/C receiver dryer, hoses, accumalator replaced	10/08/2023	
	167433	500 Hour Earthmoving Service	9/08/2023	

Asset	W/O No	Description	Finished	Done Reading
	168059	Reverse camera and bucket teeth replaced	25/07/2023	
	167117	Repaired steering malfunction Replaced ignition switch and intake hose	12/07/2023	
	167087	Replaced 3x hydraulic hoses	10/07/2023	
	167088	Replaced door latch	5/07/2023	
	166229	250 Hour Earthmoving Service	25/06/2023	
	166626	Replaced transmission solenoids Re-sealed lift cylinders and sump	22/06/2023	
	164356	2000 Hour Earthmoving Service	21/05/2023	
	165527	LH lift ram o-rings replaced	21/05/2023	
	164465	Replaced park brake shoes, tensioner & springs, rear steps & rubbers, tilt ram grease line Repaired bonnet, latch & handle, cooler latch, arm rest latch, coolant leaks Cleaned radiator and coolers Changed bucket	11/04/2023	
	163321	250 Hour Earthmoving Service	17/03/2023	
	163708	Replaced keeper pin bolt	16/03/2023	
	163668	Fuel cap replaced	16/03/2023	
	162498	ECM replaced (2nd hand ECM)	8/02/2023	
	162287	R&R all pulleys, tensioner on engine drive for A/C and alternator R&R belts	1/02/2023	
	162509	POS#3 tyre replaced	30/01/2023	
	161821	500 Hour Earthmoving Service	28/01/2023	
	154572	Hydraulic oil lines purged Auto greaser valve cleaned	15/01/2023	
	161053	250 Hour Earthmoving Service	16/12/2022	
	159922	500 Hour Earthmoving Service	9/11/2022	
	159930	SEAT BELT REPLACEMENT	1/11/2022	
	158776	250 Hour Earthmoving Service	1/10/2022	
	158929	Boom tilt hoses x2 replaced	20/09/2022	

Asset	W/O No	Description	Finished	Done Reading
	157271	500 Hour Earthmoving Service	22/08/2022	
	153768	250 Hour Earthmoving Service	1/07/2022	
	155911	Using water	29/06/2022	
	155383	Loader frame bolt grease nipples installed as needed RH steering cylinder harness repaired Replaced 2x O-rings on transmission filter housing	10/06/2022	
	153755	A/C wire from cab to compressor replaced (Pink)	19/04/2022	
	153417	A/C re-gassed Replaced low step rubbers RHR	31/03/2022	
	153021	Alternator replaced	18/03/2022	
	153020	A/C compressor repaired as needed	17/03/2022	
	148223	Re-located to WO's	14/02/2022	
	151527	2000 Hour Earthmoving Service	7/02/2022	
	151496	Steering = Inspected/OK	22/12/2021	
	149211	Grease lines, fittings u/s R&R o-ring seal on hyd pipe under cab Refit all grease lines fittings in hitch area test operation of grease canister-ok B Wise	3/11/2021	
	149116	Broken grease lines, broken step R&R RHR step assembly R&R several loader frame grease lines, fittings etc. Remove dog bone pins and unblock grease parts B Wise	1/11/2021	
	147378	250 Hour Earthmoving Service	30/09/2021	
	147963	Oil leak R&R o-ring seal on top of transmission, R&R hose assembly & clamps from trans oil cooler pipe, add CAT ELC, grease loader frame B Wise	8/09/2021	
	141608	Top pins wont grease Manually grease complete loader frame. R&R auto-greaser	27/08/2021	
	146640	Pins squealing/ steps bent Refit repaired R/H/S step assembly. Remove dog bone pins. grease complete loader frame manually. R&R auto-grease unit.	27/08/2021	
	145805	500 Hour Earthmoving Service	16/08/2021	

Asset	W/O No	Description	Finished	Done Reading
	146059	replace water pump, cutting edges worn R&R full set of cutting edges, bolts, nuts etc. R&R CAT reman w/pump. Fill with CAT ELC coolant	9/08/2021	
	146060	Getting hot Fill up coolant. Heater hose split. Cut back & reconnect. Check for other leaks. W/pump small leak from telltale	3/08/2021	
	144579	250 Hour Earthmoving Service	12/07/2021	
	143692	Wont start Checked crank-slow, battery flat isolator on, jump started replaced all batteries, tested-good Reeve F	19/05/2021	
	143351	Wont burn Remove muffler assembly, take to PKWS wash out, re4install (still no burn due to damaged core) Remove and clean head, purge fuel lines, still no burn, replace head-ok perform manual burn Ben P	5/05/2021	
	142448	Wont start Machine been idle for a while only 17v @ starter, jump started check charge-ok, fill coolant, trans oil to level, B Wise	13/04/2021	
	136892	500 Hour Earthmoving Service	19/03/2021	
	147575	Plant Risk Assessment Review Assessment done by Stephen R.	9/02/2021	
	140338	Wont start Checked batteries-ok, change fuel filters, found engine kill switch turned off Blake R(wrong machine cancel)	8/02/2021	
	139723	Tyre repair Premium tyre's	11/12/2020	
	138665	Won't burn 113% soot Try manual burn with ET won't burn ignition fault, remove ARD head & clean, install new plug, test spark/coil ok, remove muffler take to PKWS strip wash, very damaged core inside, put back on tractor, perform manual burn ok, complete burn Ben P	30/11/2020	
	138263	Won't start Checked key-barley cranking/starter clicking, jump started engine-running, checked charge rate-good Checked batteries may need replacing in future Reeve F	16/11/2020	
	136809	Bucket pin Removed loose keeper bolt dog bone pin, fitted spacer and tightened, fitted grease nipple to top RH and greased Reeve F	30/09/2020	
	136617	Soot problem High soot load, Plug on ET perform manual burn, completed burn still high soot,flush fuel system, clean spark plug Drive tractor for a while perform another burn on DPF perform burn for ash regen all levels at 0% Ben P	24/09/2020	

Asset	W/O No	Description	Finished	Done Reading
	135362	250 Hour Earthmoving Service	3/09/2020	
	134588	No A/C A/C condenser has a hole Replaced A/C condenser,receiver drier & pressure tested system,re-gased and tested-good(see A/C sheet #2008) Replaced bonnet latches,replaced cooler swing latch assy.replaced broken rear stair ladder,replaced drivers bottom step Reeve F	13/08/2020	
	134297	check over machine Fitter noticed machine had poor drive Remove trans suction pipe,weld hole re-fit OK B Wise	21/07/2020	
	133274	500 Hour Earthmoving Service	26/06/2020	
	132648	Measure bucket pins and relay info(was supposed to be #15 W/O 32649)	3/06/2020	
	131810	Wiper motor Rear wiper arm worn,oil leak under cab-needs wash to check,informed G Withers R Farquhar Fitted new rear wiper arm assembly C Buck	28/05/2020	
	129124	RH steer ram leaking	28/04/2020	
	131082	Oil leak R&R engine crankcase breather element,refill engine oil Repair UHF aerial antenna plug B Wise	21/04/2020	
	130892	High voltage Wont do DPF burn Repair wiring at ECU plug DPF sensor 5v+ ,perform manual burn off,Ash regen oilo leaking out of breather, drain oil level to full mark,order new oil seperator B Patrick	17/04/2020	
	130963	Starter u/s R&R CAT reman starter motor ass.R&R 3x broken grease fittings on loader frame ,grease bucket B Wise	16/04/2020	
	130559	250 Hour Earthmoving Service	9/04/2020	
	129357	Trans oil leak Remove trans steel pipe from under cab and replaced it with new one Replaced clamps	2/03/2020	
	128690	Check if muffler is abnormally loud Looked at machine and found nothing wrong R Latham	14/02/2020	
	129708	Hyd oil leak Looking at lift arm base Replaced leaking lift arm base (safety)	3/02/2020	

Asset	W/O No	Description	Finished	Done Reading
		Leaking R/H lift ram hose, Replaced leaking lift ram hose (pirtek) G Windle		
	127856	2000 Hour Earthmoving Service	24/01/2020	
	124630	No reverse camera Repaired by Brad Wise	10/12/2019	
	125973	Park brake not working properly, cracked windscreen, bent steps RHS front steps bent slightly, still serviceable, windscreen has been replaced, back screen still serviceable Park brake working well @ time of inspection B Wise	26/11/2019	
	126477	Bucket repairs as requested. Side wear plates, tap out pin locator bolt holes, Side walls extended then lined with chocky bars, Increase stoppers 1" high. Reskin floor, Tidy head board PKWS J Caruana	20/11/2019	
	126681	Bucket repairs see W/O # 26477	20/11/2019	
	125975	Bucket change Ryan H	19/10/2019	
	125380	250 Hour Earthmoving Service	15/10/2019	
	125707	Missing LHS adaptor Put new adaptor on LHS of bucket with new bolts and new tooth R Latham	14/10/2019	
	123681	Needs bucket change	11/10/2019	
	124383	Park brake slips, no reverse camera, bent steps, missing tooth Adjust park brake & test-full stall 2nd gear no movement ok Reconnected reverse camera & test ok, steps are bent but all intact & functional Bolt on adaptor & tooth missing on LHS of bucket-refer PKWS G Windle	10/10/2019	
	125065	Broken grease line R&R CAT grease line ass. & fittings to LHS tilt cylinder B Wise	4/09/2019	
	124629	Seat Not Pumping Up Broken Grease Line Repaired line and check seat change switch Brad Wise	30/08/2019	
	124098	500 Hour Earthmoving Service	30/08/2019	
	123599	Blown hose Remove hose for pirtek to make, reinstall hose test, fill auto grease unit with grease due to being empty and disabled Ben Patrick	1/08/2019	
	123500	R&R edge protector bolts R&R edge protector bolt on bucket No.89	25/07/2019	

Asset	W/O No	Description	Finished	Done Reading
		Brad Wise		
	123660	Ride control not working No gas in ride control accumulator,REpair leak at accumalator charge valve, charge accumalator to 550psi & test ok Glen Windle	20/07/2019	
	125964	Repair bonnet Fit bolts & panel cushion to bonnet sides & mud guards B Wise	16/07/2019	
	122956	250 Hour Earthmoving Service	15/07/2019	
	122768	Check ride control	8/07/2019	
	124466	socket pins dry grease bucket pins	1/07/2019	
	122455	no front windscreen wipers fit new front windscreen wiper motor & test ok Glen Windle	19/06/2019	
	122320	no flashing light change faulty light to new LED type	17/06/2019	
	122437	worn bucket teeth replaced all 8 bucket teeth Cameron Buck	11/06/2019	
	121792	500 Hour Earthmoving Service	5/06/2019	
	122079	install westrac gps install and test westrac gps Glen Windle	4/06/2019	
	121883	wipers not working remove wiper motor to identify correct part [refer to pkws] Glen Windle	30/05/2019	
	121844	seat goes down fit new inflate deflate switch Glen Windle	28/05/2019	
	121869	operator seat goes down on its own air leak at inflate /deflate switch,Refer PKWS Glen Windle	23/05/2019	
	121519	corner tips need to be fitted to bucket fit corner tips Glen Windle	11/05/2019	

Asset	W/O No	Description	Finished	Done Reading
	121275	bucket remove bucket teeth for transport Scot Rodgers	6/05/2019	
	120119	250 Hour Earthmoving Service	4/04/2019	
	119950	Bucket repairs and mudflap Weld edge protection on worn bottom of bucket Remove and replace front mudflap	14/03/2019	
	119301	500 Hour Earthmoving Service	12/02/2019	
	119348	Wont do burn Complete after burn procedure on cat ET test machine & burn off percentage ok B Wise	12/02/2019	
	118829	No flashing light, missing grease lines ,left step Check flashing light works good 2x grease lines broken @RHS Z link Both rear step assemblies needed Refer PKWS	16/01/2019	
	118154	250HR Earthmoving service	17/12/2018	
	118293	down on power possible fuel filter Turbo U/S INstall new cat turbo with gaskets ,nuts, studs, exhaust clamps do burn off and topped up coolant	4/12/2018	
	118188	Wont start Disabled ecu idel shutdown	27/11/2018	
	113618	Pins squeeling Broken grease lines Fit CAT grease lines and pipes to both dog bones @each end prime grease lines	6/11/2018	
	117611	Bucket teeth/ bottom plates U/S RnR 2x bottom wear plates and bolts RnR CAT bucket teeth and locks	25/10/2018	
	117261	2000 Hour earthmoving service	22/10/2018	
	115788	250HR Earthmoving service	10/09/2018	
	115135	A/C not working	30/07/2018	

Asset	W/O No	Description	Finished	Done Reading
		Hole in hose Re hosed system new seal new dryer pressure test vac down added 20ml oil charged system		
	116174	Flashing light not working	20/07/2018	
		Test wiring replace light		
	123511	Repair bonnet Fit bolts & panel washers to bonnet sides & mud guards Brad Wise	16/07/2018	
	113607	Bucket kick out not working and grease system fault on.	1/07/2018	
	114055	500 Hour Earthmoving Service	30/06/2018	
	114167	Air con Not cold	26/06/2018	
		tested A/C system Cleaned filters		
	114044	wiper lose	18/06/2018	
		Tightened up wiper		
	116221	Fit new grease canister	6/06/2018	
		Run test cycles for greaser to ensure line a and b are both greasing and reconnect lines		
	115895	Change bucket over for clinker shed new cutting edges fitted Repair broken grease lines Check over machine	24/05/2018	
	112260	250HR Earthmoving service	22/03/2018	
	112499	Fit full set of bucket teeth & locks	22/03/2018	
	110983	500 Hour Earthmoving Service	7/02/2018	
	111550	change bucket. remove gummy edge bucket, press bottom pins out, install rock bucket.	2/01/2018	
	110474	250HR Earthmoving service	5/12/2017	
	110378	Bucket teeth worn oil leak Remove and replace full set CAT bucket teeth and locks remove and replace 4 x grease lines on loader frame	21/11/2017	
	110090	Bucket teeth worn Fit 8 x new bucket teeth and locks	26/10/2017	
	109857	500 Hour Earthmoving Service	20/10/2017	

Asset	W/O No	Description	Finished	Done Reading
	109459	Air con not cold wiper needs new motor A/C tested fine	11/10/2017	
	109316	Replace ARD head remove and replace complete ARD head (433-3677) fit new spark plug and lead complete ARD burnoff, check soot level	27/09/2017	
	109311	Grease lines Remove and replace grease line repair holes for bottom bucket pins fit new fittings and clamps	19/09/2017	
	109169	Won't burn off plug in ET, check codes, test wiring from controller to coil test spark lead, remove spark plug and clean, still won't burn, remove ADR head, strip , clean, re-install, bleed fuel lines/flush, run through burn	15/09/2017	
	108489	Won't purge DPF engine fault on dash Clear faults with ET allow machine to auto purge no further faults	30/08/2017	
	107524	250 Hour Earthmoving service	27/08/2017	
	108400	ARD spark current low machine in limp mode Remove and replace ignition spark coil for ARD system Completed manual burn off process using ET completed ARD system check using CAT ET	21/08/2017	
	108579	Fit printer Made up bracket and fitted printer all tested fine	4/08/2017	
	108359	wipers and door strut Replace front wiper are/blade adjust and clean out window washer bottle, change gas strut on door, rear window wiper arm broken.	15/07/2017	
	108399	Oil leak remove and replace transmission cooler hose, fill transmission fitted E-stop in cab Fitted reverse quacker alarm	3/07/2017	
	108900	Prepare 980K for work	16/05/2017	