

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1393		Cat CS56 Smooth Drum Roller #7		
	192678	CS56#7 blown hose	22/04/2026	Hours
	188513	2000 Hour earthmoving service (12 Months Interval)	7/11/2025	
	187917	Replaced horn switch	1/10/2025	
	187441	UHF aerial replaced	30/09/2025	
	187900	Re-gassed A/C	26/09/2025	
	182716	Replaced batteries and isolator	20/02/2025	
	179933	Fire Extinguisher out of date # fitted new extinguisher	16/12/2024	
	180175	2000 Hour earthmoving service (12 Months Interval)	6/12/2024	
	174230	Roller 6 Months Service	2/05/2024	
	173037	Replaced batterys and cables	19/01/2024	
	172799	Jump started	15/01/2024	
	167971	Roller 6 Months Service	16/09/2023	
	164869	Lights wiring repaired	2/06/2023	
	162725	Roller 6 Months Service	20/02/2023	
	162048	Jump started	23/01/2023	
	161277	Wont start = Isolator left in = OK	6/12/2022	
	157559	Revolving light fuse replaced	31/08/2022	
	157268	Roller 6 Months Service	19/08/2022	
	157116	Bonnet latch and striker replaced	22/07/2022	
	155930	-Steering column lock adjuster strut and lever replaced -De-seized holding pin	7/07/2022	
	155929	Seat and base replaced	23/06/2022	

Asset	W/O No	Description	Finished	Done Reading
	155658	Wiring to ignition switch repaired	15/06/2022	
	155656	E-stop button replaced	15/06/2022	
	153427	Struts for bonnet replaced	31/03/2022	
	152008	Isolator replaced	11/02/2022	
	151602	Roller 6 Months Service	9/02/2022	
	151460	Wipers replaced/repared as needed	16/12/2021	
	147669	External Tyre Inspection	10/11/2021	
	149712	Initial Plant Safety Audit	20/09/2021	
	145809	Roller 6 Months Service	10/08/2021	
	146254	Window broken R&R Cat R/H/S upper window & lock assy. Tightened bolts on scraper bar	4/08/2021	
	140908	500 Hour Earthmoving Service	15/03/2021	
	141716	UHF not working Replaced power wire C Buck	9/03/2021	
	141420	Initial Plant Safety Audit	23/10/2020	
	136523	A/C switch broken Disassemble switch, removed broken end and temporarily refitted(parts ordered) Fit new blower fan control switch Reeve F	21/10/2020	
	132513	Cabin Repairs Machine sent to Bombo workshop to have Cabin repaired, rust and damage(see attachment) Run new heater hoses & repairs to A/C Job sheet 1891 B Patrick Plant inspection list Replaced broken l/h mirror Reeve F Replaced reverse alarm had voltage but not working,checked L/H mirror,cracked ordered,arm rest needs replacing rerouted UHF wiring to be accessible Reeve F	17/06/2020	
	132313	250 Hour Earthmoving service	29/05/2020	
	124289	Flat battery,wont start Removed and replaced batteries with cat batteries.Checked charge Ryan Latham	5/09/2019	
	123038	brake lights & blinkers required fit brake lights &blinkers & test ok	12/07/2019	

Asset	W/O No	Description	Finished	Done Reading
		Glen Windle		
	122122	500 Hour Earthmoving Service	27/06/2019	
	115439	250 Hour Earthmoving service	13/08/2018	
	116247	Fit new horn button	13/07/2018	
	108643	Water leak blanked off heater hoses as they had rubbed through under the engine	22/08/2017	
	107504	over heating knocking noise Remove engine filter, cut open inspect OK run engine sounds OK, water pump leaking bad. Remove and replace water pump assembly Fit new radiator cap, fill with CAT ELC Fit new forward/reverse lever Install injector trim codes with CAT ET	16/08/2017	
	106426	Replaced 6 injectors	11/07/2017	
	106063	500 Hour Earthmoving Service	11/07/2017	
	107774	Install new 'Lockout" master switch.	21/01/2017	
	102999	250 Hour Earthmoving service	18/11/2016	
	102926	air con not working#Replaced A/C switch	7/11/2016	
	100167	revolving light not working # Bad earth Cslade	20/05/2016	