

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1025		Cat CS56 Padfoot Roller		
	193503	Disposal D0967	28/05/2026	Hours
	193385	Off Hire Hollingsworth	22/05/2026	Hours
	192050	March R&M Monthly WO/Hollingsworth: - Machine lost all power find broken wiring on circuit	19/03/2026	Hours
	60218	January R&M Monthly WO/Hollingsworth: -No start, loose battery terminal caused short and damaged post, relug cable and replace terminal and test. 7302hrs	19/01/2026	Hours
	58016	Roller - 250hr Service 7300 hrs	5/11/2025	7300 Hours
	56545	Pre hire repairs - 7300 hrs Drum repairs Replaced ac thermostat cable	5/11/2025	Hours
	56279	off hire	22/07/2025	Hours
	54653	Roller - 250hr Service. Maryvale. *Finish 7249.6hrs *Removed battery box cover. (Which has bonnet mounted to it). *Found tabs broken off & other bolts seized. *Freed up other bolts & replaced 1 missing to try & fix bonnet coming open. *Need to weld tabs back on. *Tested power to flashing light - All ok.	6/05/2025	Hours
	51556	Pre hire repairs as per HME inspection. w/o 51080 7176hrs -Check fault codes - see oil pressure sensor had levels 3 severity, check and test, ordered new sensor, fitted and tested. - Remove cooling pack, cleaned radiators, fitted back, test add coolant. - Removed wider motor unit, repaired , fit back and tested.	3/04/2025	Hours
	52452	Reports of machine rough to drive Replace vibe motor pressure test park brake. *Pressure test park brake. *Fit new radiator cap.	13/03/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		*Completely strip seat c/o worn bushes, worn springs, defective strut, modify adjuster, free up seized levers, tension all fasteners. *C/O 6x defective drum rubbers. *Inspect drum plate flex & tension all drum mounting bolts. *Order parts required. *C/O vibe to under cab hose. *Pull mag plugs & top up drum oils. *Inspect movement in artic & front frame with jacks & crane. *Remove cab mounts & re-fit mounts & tension correctly - (Removed as 2 out of 4 were installed wrong - metal on metal). *Thoroughly washed machine for inspection. *Drum shell kit out of alignment due to only 1 half being secured to drum. *Remove all bolts, remove all dirt realign oxy & mag drill required anchor bolts through drum, mount bolt half shells to drum & tension bolt shells together & tension, vibe & operate retention bolts (repeat till bolts hold tension). *Remove steer cylinders, inspect bores (5+mm movement) told to reinstall. *Reasearch if able to adjust ride height to suit shell kit ("4+") to aid strain on rudders pins brushes & artic. *Fix & attach cloth back to interior panels in cab both pillars. *Drain 300L water from R/H tire & * 100L from L/H tire. (over filled & mismatched weight balance) *Pump to low end of scale to benefit ride comfort (14psi) tension nuts. *Remove belly guards tighten loose diff U-bolts x4 refit belly guards. *Cab hinge pins completely missing install bolts to stop cab bounce & so no one accidentally jacks cab & injures or damages equipment. *Cab jack cylinder not secure in mount, top side also missing rubber mount washers (Making the banging noise while operating) measure & make rubber washers to suit, re-fit cylinder in place. Very secure now. *Top up fluids. *Grease all points. *Test drive multiple times. *Fix bonnet latch (opening while operating).		
	51080	HME Inspection - Roller Quote #: 272	18/12/2024	7175 Hours
	49612	Diagnose no start. Battery terminal clamps - source of voltage drop. Replace battery terminal clamps	28/10/2024	Hours
	49433	NO A/C - DIAGNOSE & REPAIR Hours: 7,167hrs Found compressor bad connection, repin and test.	22/10/2024	Hours
	48433	Check over, level checks	16/09/2024	Hours
	18331	Repair drum oil leak. Drum drive retaining nut loosened during operation. Remove drive unit. Replace seals and bearings. Assemble and test. Repair TFO tracker.	8/07/2024	7076 Hours
	15271	diagnose steer fault	12/06/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
	13385	Repairs to hydraulic pump/parts - (Parts only)	25/03/2024	Hours
	8776	Complete pre-hire paperwork Diagnose faulty rear window washer Diagnose faulty air con	16/01/2024	Hours
	3450	HME inspection and repairs as per task list - Engine rebuild Replace batteries Fit Maas stickers, thinksafe, QR, reflective tape & 1 x A4 plant number Remove client stickers off windows, remove tint off back window Diagnose/repair engine oil leaks after wash, tappet cover, starter motor, steer pump mount, possible front crank seal, sump, front cover Coolant level low, possible radiator leak at L/H front bottom corner, pressure test Replace engine breather hose Engine is noisy at idle, perform a valve set. # valve adjustment OK. Cut engine filter, found alloy. #5 piston picked up. Remove engine, bore to oversize x 6. Rebuild engine. Replace 9KG extinguisher bracket, remove small extinguisher off bonnet Repair movement in the seat Replace steer pins/bearings on rod end of both cylinders Replace front & rear wiper blades, repair front washers not working Test A/C is working correctly Replace park brake globe in park brake button Replace vibe adjust knob. Repair oil leak on vibe side of drum Replace bonnet struts & striker Replace hood lining, light in cab re fitted & L & R pillars spray glued back on Replace 2 x big hoses to drum drive motor, replace 2 part clamp under cab that they run through Replace hose from steer pump to HMU & HMU to filter on L/H side of cab Replace top hose going to vibe pump Replace top bolt & washer for side guards under bonnet Inspect engine oil pressure sensor & wiring as had active code & alarming when started (oil pressure has been checked manually & is good) Change tyres to tractor pattern to suit padfoot Check artic & oscillation Re-seal pump leaking into rear structure Tidy up E stop wiring under cab Replace door seal Re-seal cab lift cylinder	11/12/2023	7045 Hours
	4664	Roller - 1000hr Service.	22/08/2023	7043 Hours
	2660	ANM Auto - Assist with fitment of replacement rocker cover. Assist with further diagnosis of water pump/ over heating issues Travel Cooma to Lobs Hole and return	19/06/2023	
	4245	Investigate oil leak	22/05/2023	
	2097	Oil leak	22/05/2023	
	4235	Fit water pump	19/05/2023	

Asset	W/O No	Description	Finished	Done Reading	
	2240	Finishing off water pump fit up	19/05/2023		
	2237	Started putting water pump on	18/05/2023		
	2080	Check water leak. Remove and order water pump	10/05/2023		
	1787	Investigate oil leak	19/04/2023		
	2611	Hitachi - 250 HR service Traveled to site. Carried out 6750 hour service as per maintenance planner	14/04/2023	6750	Hours
	1510	Top up engine oil	8/03/2023		
	500	Remove hose from drain to hydraulic pump. Make new one and fit to machine.	17/02/2023	1	Hours
	492	Check why machine cut out. Change estop in lab	14/02/2023	1	Hours
	1631	Jump start pad foot roller. Weld bolt to pin on rock hammer. Remove and replace broken clamp	6/02/2023		