

Equipment	Completed At	Task	Notes	Primary Meter
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/13/2026 11:16	250HR Service	10/05/2026 RH 10HRS 1000HR SERVICE SCRAPER BOX MISSING BOLTS FIT TWO WRONG SIZE BOLTS TO GET GOING ADJUSTED ALL SCRAPER TEETH	7000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/05/2026 9:08	refitted and tensioned scraper bar bolts	refitted and tensioned scraper bar bolts; 13/04/2026 - RYAN - 2HRS SCRAPER BAR FALLING OFF - RE-FITTED TIGHTENED ALL HARDWARE ASSESSED DEFECTS 17/04/2026 - AIDEN - 3HRS REMOVED & REPLACED 4 X DRUM RUBBERS ON LH SIDE THAT WAS ALL THE CRACKED ONES	7009 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/02/2026 10:38	fit cutter bar shims	fit cutter bar shims; 19/02/2026 - HASTINGS/BRAD - 2HRS DRIVE TO CHINCHILLA YARD RESEARCH REQUIRED - PARTS FOR ORDER 23/02/2026 - HASTINGS/BRAD - 1HR DRIVE TO MACHINE - T/S COOLANT LEAK ADJUST HOSE & CLAMPS PACK UP 24/02/2026 - DYLAN - 2HRS FIT CUTTER BAR SHIMS	6800 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/05/2026 6:01	250HR Service	31/01/2026 RH 2HR SERVICE 31/01/2026 BF 2.5HRS 250HR SERVICE - SCRAPER BAR REPAIR	6750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/06/2025 8:40	replace faulty compressor dryer and belt	replace faulty compressor dryer and belt 21/10/2025 DS 2HRS INVESTIGATE A/C NOT WORKING AC COMPRESSOR FAILED 23/10/2025 BF 1HRS A/C COMPRESSOR SEIZED; 31/10/2025 - HASTINGS/BRAD - 7.5HRS DRIVE TO TOWN - LOAD A/C EQUIP - DRIVE TO MACHINE FIT NEW CONDENSOR, ACCUMULATOR, HOSE & COMPRESSOR VAC DOWN & CHARGE 0.8KG R134A - TEST -8.2 DEGREES @ VENT FIT NEW DRIVE HOSE THROUGH ARTIC PACK UP 01/11/2025 - HASTINGS/BRAD - 2HRS DRIVE TO MACHINE FIT BELLY GUARD & PANELS TEST BATTERIES PACK UP	6517 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	10/21/2025 16:26	250HR Service	01/10/2025 - JACK - 3HRS SERVICE COMPLETED FUEL DRAIN ON SMALLER FILTER BROKE THREAD OFF GOT IT TOO SEAL CORRECTLY THROUGHT SENT PHOTOS & PART NO WORKSHOP MANAGER TIDY WORK AREA 07/10/2025 AW 1HR INSPECT AIR CON PUT GAUGES ON AND PRESSURE TESTED - OK 15/10/2025 - AIDEN - 3.5HRS PRESTART & TRAVEL OUT TO SITE INSPECT AIR CON WAS FREEZING UP TESTED & COULDN'T FAULT EVAPORATOR FOUND COMPRESSOR STARTING TO FAIL 17/10/2025 - AIDEN - 4HRS REMOVE & REPLACE BROKEN DOWN RUBBER & BANGING AROUND FIT NEW ONE - CHECK OTHERS STILL OK HAD TO REMOVE OUTSIDE ONES TO GET MIDDLE ONE OUT THREADS WERE DAMAGED - HAD TO CLEAN AS BOLTS WERE LOOSE	6499 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	10/02/2025 7:14	Defect list repairs	23/09/2025 BG 5.5HRS DRIVE TO MACHINE INSPECT FOR LISTED DEFECTS, T/S A/C. CANNOT FAULT A/C 9.2 DEGREES VENT, CHECK OVER MACHINE. PACK UP DRIVE TO YARD. UNLOAD AND HANDOVER DRIVE TO BASE TOOWOOMBA 29/09/2025 HM 3HRS A/C ISSUES - FOUND CUTCH SLIPS WHEN EWG HOT 29/09/2025 - JACK - 2HRS INSPECTED A/C FOR OBVIOUS LEAKS UNABLE TO FIND ANY 30/09/2025 - BRANDAN - 1HR NO A/C	6404 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	08/27/2025 14:29	Defect list repairs	26/08/2025 BG 1HR DRIVE TO MACHINE - CHECK OVER FOR DEFECTS	6385 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	08/25/2025 9:20	Defect list repairs	24/08/2025 - DUNCAN - 3HRS PERFORM GENERAL CHECKOVER FOUND DIESEL LEAK ON ENGINE REPLACED SEALS ON BANJO BOLT - RUN UP & CHECK	6385 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	08/19/2025 14:04	check over for defects	check over for defects 31/07/2025 HM 2HRS 250HR SERVICE 31/07/2025 BF 4.5HRS 250HR SERVICE, ADJUST SCRAPERS ELECTRICAL FAULT 29/07/2025 MC 1HR DROPPED BELLY PLATE AND REFITTED 01/08/2025 LM 1HR ASSIST WITH SOURCING PARTS AND HOSES 01/08/2025 BF 3HRS ELECTRICAL FAULT REPLACE SCRAPER FRAME BOLT	6250 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	08/19/2025 14:04	250HR Service	check over for defects 31/07/2025 HM 2HRS 250HR SERVICE 31/07/2025 BF 4.5HRS 250HR SERVICE, ADJUST SCRAPERS ELECTRICAL FAULT 29/07/2025 MC 1HR DROPPED BELLY PLATE AND REFITTED 01/08/2025 LM 1HR ASSIST WITH SOURCING PARTS AND HOSES 01/08/2025 BF 3HRS ELECTRICAL FAULT REPLACE SCRAPER FRAME BOLT	6250 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	07/24/2025 17:33	Replace 2x drum rubbers	Replace 2x drum rubbers	6180 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	07/15/2025 8:37	Defect list repairs	14/07/2025 - DUNCAN - 2HRS ADJUST SCRAPER	6180 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	07/12/2025 9:05	Defect list repairs	09/07/2025 - LUKE - 2.5HRS CHECK & ADJUST DRUM SCRAPERS TENSION SCRAPER BAR MOUNTS TIDY AREA & RETURN TRAVEL	6166 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/26/2025 15:28	replace water/ fuel sensor	replace water/ fuel sensor 19/06/2025 BF 1HR DEFECT INSPECTIONS 20/06/2025 BF 1HR REPLACE FUEL SENSOR	6069 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/18/2025 10:28	250HR Service	5000hr service and report; 02/06/2025 - AIDEN - 6HRS INSPECTED & CARRIED OUT 5,000HRS SERVICE AS PER SCHEDULE REPLACE ENGINE OIL, FILTER, FUEL, AIR, AIR CON & HYDRAULIC FILTERS CHANGE DIFF OIL & FOUND DRIVE OILS REAR CHANGE VIBE MOTOR & COOLING PUMP OILS REFILL TO LEVELS CHECK EC OIL LEVELS - TEST RUN - OK 02/06/2025 - MITCHELL - 4HRS COMPLETED FULL 1,000 HR SERVICE & CHECK OVER REPLACED ALL DRUM OILS TRAVEL BACK TO CAMP 27/05/2025 LM 1HR 1000HR, PARTS AND W/O 03/06/2025 AW 2.HRS FINISH OFF ROLLER SERVICE, CHECK OIL LEVELS. ADJUST SCRAPERS TO WHAT I COUL. CENTRE ONES WORN. CLEAN WORK AREA	6000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/18/2025 9:40	Replace drum scrapers	Replace drum scrapers; 10/06/2025 - MITCHELL - 2HRS TRAVELLED TO MACHINE DROPPED PARTS RETURN TRAVEL 10/06/2025 - BRANDAN - 5HRS REPLACE SCRAPERS - CLEAN ROCK FROM DRUM CHECK ENGINE FAULT	5983 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/14/2025 16:33	Replace hood support struts and 2x tyres	Replace hood support struts and 2x tyres; 13/05/2025 - HARRY - 1HR CHANGE OUT BONNET STRUTS	5875 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	05/12/2025 16:18	Defect list repairs	09/05/2025 BF 1HR ELECTRICAL FAULT. REVERSE LIGHTS 10/05/2025 BF 1HR INFLATE TYRE	5875 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/10/2025 6:13	Defect list repairs	09/05/2025 HM 0.5HR DIAGNOSE LEAK IN TYRE. NEEDS NEW TYRE	5875 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/10/2025 6:07	Defect list repairs	08/05/2025 BF 1HR INSPECT AIR LEAK IN RH TYRE	5875 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/25/2025 15:31	250HR Service	250hr service; 14/04/2025 - LUKE - 1HR 250HR SERVICE - PARTS & W/O	5750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/25/2025 9:33	Replace drum rubbers and rubbed AC line	Replace drum rubbers and rubbed AC line; 01/04/2025 HM 6HRS REPLACE ALL DRUM RUBBERS 01/04/2025 LM 1HR LOAD DRUM RUBBERS, TRAILER TO 159 INSPECTION, ORGANISE REPAIRS 07/04/2025 BG 2HRS DRIVE TO WASHDOWN. DRIVE TO MACHINE. START REMOVING A/C HOSE. REMOVE BELLY GUARD. FITTING SNAPPED. PACK UP DRIVE TO WOLEEBEE CAMP. 08/04/2025 BG 5.5HRS DRIVE TO WASH PAD, DRIVE TO MACHINE. CONTINUE WITH A/C HOSE. REMOVE BULKHEAD AND EVAP HOSES. RESEAL AND REFIT. ACCUMULATOR SEIZED. CHANGE OUT ACCUMULATOR. VAC AND CHANGE. FIT BELLY GUARD AND PANELS. TEST OK. PACK UP. 09/04/2025 BF 2.5HRS A/C DIAGNOSIS 13/04/2025 BF 2HRS A/C REPAIRS, INSTALL NEW HOSE 14/04/2025 - BRANDAN - 3HRS A/C REPAIRS 14/04/2025 - HARRY - 2HRS CHECK OUT DEFECTS REPAIR UHF MOUNT CHECKED DRUM RUBBER CHECKED RADIO	5755 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/27/2025 13:58	250HR Service	500hr service; 20.02.2025 - AIDEN - 4HRS INSPECTED& CARRIED OUT SERVICE ON ROLLER - 500HR SERVICE REMOVED & REPLACE ENGINE OIL & FILTERS HYDRAULIC FILER MONITOR ALTERNATOR - SLIGHT BEARING NOISE CHECK OVER MACHINE & DEFECTS 20.02.2025 - JACK - 4HRS 500HR SERVICE CHANGED DRUM RUBBERS TIDY WORK AREA ADJUST DOOR 21.02.2025 - AIDEN - 1HR CHECK & ADJUST DRUM SCRAPPERS 14.03.2025 HM 2HR VIBE INTERMITTING, CHECK PLUG AND SENSOR AND SENT BACK TO WORK 23.03.2025 - HASTINGS/BRAD - 2.5HRS DRIVE TO MACHINE. PLUG RHS TYRE. T/S A/C POOR WORKING - PRESSURE SLIGHTLY LOW	5500 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/27/2025 13:57	Replace alternator and belt	Replace alternator and belt; 26.02.2025 HW 3 HOURS CHANGE OUT ALTERNATOR AND BELT	5544 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/24/2025 13:04	Defect list repairs	22.01.2025 - HASTINGS/BRAD - 0.5HR DRIVE TO MACHINE CHANGE OUT SENSOR - TEST - OK	5430 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/24/2025 12:51	Replace restriction sensor	Replace restriction sensor; 23.01.2025 - HASTINGS/BRAD - 2HRS DRIVE TO MACHINE & ADJUST SCRAPPERS CHECKOVER - NEEDS DRUM RUBBERS	5429 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/15/2025 11:26	Defect list repairs	14.01.2025 - BG - 5.5HRS DRIVE TO MACHINE T/S DIFF, PRES INTAKE CODE REMOVE & TEST SENSOR SENSOR INTERMITTENTLY FAILING ORDER PARTS PACK UP TOOLING DRIVE TO BASE AT TOOWOOMBA	5375 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/08/2025 12:03	JACKSON PARTS		5341 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/30/2024 11:14	Defect list repairs	29/11/2024 - HARRY - 1HR CHECK OVER & ORDER PARTS - DRUM RUBBERS & FIRE EXTINGUISHER BRACKET	5253 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/27/2024 15:27	Replace drum pedistal caps	Replace drum pedistal caps	5247 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	11/21/2024 17:03	250HR Service	250hr service; 02.11.2024 - JOSIAH - 2.5HRS TRAVEL TO MACHINE CARRY OUT SVC	5226 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/19/2024 16:11	AC service and regas	AC service and regas; 28.10.2024 - JM - 3.5HRS REPLACED ACCUMULATOR RE-GASSED 30.10.2024 - RILEY - 1.5HRS CHECK DEFECTS - RUN UP - CHECK AIR CON FAULT	5247 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	10/23/2024 16:07	Replace 4x drum rubbers	Replace 4x drum rubbers; 17.10.2024 - LUKE - INSPECT DRUM RUBBERS & STEERING PIN LOCK OUT CHECK DRUM PIRH CUIRING & PLUGS 17.10.2024 - JACK - 0.5HR CHECKOVER DEFECT LIST & TO CREATE WORK 21.10.2024 - HM - 9HRS TRAVEL TO YARD COLLECT PARTS & LOAD UP TRAILER TRAVEL OUT TO SITE CHANGED OUT DRUM RUBBERS WELDED 7 FITTED STEERING LOCK PIN LOADED AIR - RESTRICTION CODES NEEDS AIR FLOW SENSORS 22.10.2024 - JM - 2.5HRS ADJUSTED SCRAPERS & INSPECTED REPLACED DRUM RUBBERS	5176 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	10/10/2024 16:39	Replace and adjust scrapers as required	Replace and adjust scrapers as required; 30.09.2024 - BW.HD - 3HRS REPLACED & ADJUSTED DRUM SCRAPERS 30.09.2024 - BF - 1HR SCRAPERS 30.09.2024 - LUKE - 1.5HRS ORGANISE PARTS & W/O FOR DRUM SCRAPER ADJUSTMENT	5117 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	09/21/2024 15:56	Defect list repairs	20.09.2024 - JOSIAH - 3.5HRS TRAVEL TO SITE TO INSPECT DRUM PADS WITH RUSTY RETURN TRAVEL TO KENYA; 20.09.2024 - LUKE - 1HR ORGANISE INSPECTION FOR PADFOOT DAMAGE	5093 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	09/16/2024 14:21	Replace alternator and fanbelt	Replace alternator and fanbelt; 03.09.2024 - BEN/HASTINGS - 2.5HRS REPLACED ALTERNATOR & BELT 04.09.2024 - JACK - 1HR TRAVEL TO MACHINE & FIT CABIN FILTER	5082 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	08/28/2024 13:32	250HR Service	5000hr service; 23.08.2024 LUKE 1HR ORGANISE PARTS & W/O 24.08.2024 JACK 7.5HRS COLLECT PARTS, OILS & ORGANISE WITH SERVICE TRUCK - 5000 HR SERVICE TRAVEL TO MACHINE - TAKE OIL SAMPLES DROP ENGINE OILS & DIFF OILS PULLED BELT & INPSECTED PULLEYS DROPPED & FITTED THE REST OF OILS REFITTED REST OF GUARDS TIDY WORK AREA 25.08.2024 JOSIAH 1.5HRS REPLACE DRUM FINAL OIL DIAGNOSE A/C FAULT 4982HRS 25.08.2024 JACK 1.5HRS CHANGED VIBE SUPPORT & DRIVE MOTOR OIL ASSISTED IN CHECKING A/C ISSUES	5000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	07/24/2024 6:11	Replace bonnet catch and latch. Adjust scrapers	Replace bonnet catch and latch. Adjust scrapers 15/07/2024 - BG - 1HR DRIVE TO MACHINE REPLACE HOOD LATCH ADJUST SCRAPERS PACK UP TOOLING 16/07/2024 - BG - 1HR DROVE TO MACHINE TYS BEACON NOT WORKING REPAIR HARNESS TEST -OK- PACK UP	4919 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	06/30/2024 16:20	Replace broken filter base	Replace broken filter base; 06.05.2024 JM 0.5 HOURS HYD HOUSING SWAPPED ZIP TIED UP 13.05.2024 JACK 2.5 HOURS REMOVED OLD FILTER HOUSING AND FIT NEW ONE AND FILTER 28.06.2024 BRAD 0.5 HOURS - 4836 HOURS DRIVE TO MACHINE T/S BEACON - LOOK UP PART NUMBERS	4826 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/24/2024 14:50	250HR Service	250hr service; 18.06.2024 MC 3 HOURS COMPLETED FULL 250 HOUR SERVICE AND CHECK OVER 18.06.2024 MACKA 4 HOURS COMPLETED FULL 250 HOUR SERVICE AND ADJUST SCRAPERS	4750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/24/2024 5:38	Rectify pitch sensor issues	Rectify pitch sensor issues; 06.05.2024 LUKE 1 HOUR ORGANISE TEMPORARY REPAIRS FOR BROKEN FILTER HOUSING . 07.05.2024 JM 3.5 HOURS THROUGH TESTING UNABLE TO GET IT TO FAULT 07.05.2024 LM 1 HOUR RESEARCH BROKEN PARTS AND ORDER	4602 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/20/2024 10:18	hyd hoses	hyd hoses; 14.05.2024 BRANDON 4 HOURS BREAKDOWN - DRIVE TO SITE AND REMOVE 2 X DRUMS HYDRAULIC HOSES AND RETURN TO TOWN 14.05.2024 JOSIAH 4 HOURS TRAVELLED TO SITE STARTED REPLACING 2 X DRIVE MOTOR HOSES RETURN TRAVEL 14.05.2024 LUKE 1.5 HOURS ORGANISE REPAIRS FOR BLOWN HOSE PICK UP HOSES AND SEND FITTER FOR FITMENT 15.05.2024 LUKE 5 HOURS TRAVEL TO SITE REPLACE 2 X VIBE MOTOR HOSES FILL HYDRAULIC OIL	4589 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/27/2024 8:50	Defect list repairs	26.04.2024 BF 2 HOURS PITCH ANGLE SENSOR FAULT LOGGED DTC; 25.04.2024 LF 1 HOUR ORGANISE REPAIRS FOR PITCH SENSOR MALFUNCTION	4500 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/23/2024 10:57	250HR Service	250hr service, diagnose drum/vibe noise; 22.03.2024 JACK 3 HOURS ROLLED AROUND TO GET IT TO MAKE A NOISE PULLED VIBE METER AND TOPPED UP OIL IN CARTRIDGE 22.03.2024 AIDEN 1.5 HOURS ASSIST JACK ON ROLLER AND INSPECTED VIBRATOR DRUM 24.03.2024 BRAD 8.5 HOURS DISASSEMBLE AND REMOVE DRUM REMOVE MOUNTS AND ESSEUTRIC WEIGHT. STRIP AND INSPECT FOR DAMAGE PACK UP TOOLING RETURN TRAVEL TO RUBY JO CAMP 25.03.2024 JACK MAYES 11 HOURS DRAIN ELECTRIC WEIGHT HOUSING GIL ASSIST HYD FITTER MAKE BRACKET LIFTING TOOL TO LIFT OUT HOUSING TOOK MEASUREMENTS CUT OUT AND WELD TOGETHER SPLIT LID OFF MADE PARTS LIST 25.03.2024 BG 12.5 HOURS ASSIST WITH DRIVE PLATE DRIVE MOTOR AND FINAL DRIVE REMOVED FABRICATE C BRACKET TOOLING REMOVE ECCENTRIC WEIGHT DISSASSEMBLE WEIGHT RESEBACH PARTS	4500 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/11/2024 5:49	Defect list repairs	07.03.2024 BRAD 2.5 HOURS PRESTART. DRIVE TO MACHINE INSPECT FOR NOISE IN VIBE CHECK OIL AND LEVEL MONITOR. PACK UP	4437 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/09/2024 11:31	Defect list repairs	08.03.2024 RILEY 0.5 HOURS STARTING FAULT TIGHTEN BATTERY TERMINALS	4429 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/03/2024 11:58	Defect list repairs	ENGINE LIGHT DIAGNOSIS AND DEFECT	4390 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/01/2024 14:41	Defect list repairs	CAN BUS FAULT DIAGNOSIS	4390 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	02/27/2024 17:26	REPLACE DAMAGED/BROKEN PARTS	Replace leaking drum hose; 22.02.2024 BRAD 4.5 HOURS DRIVE TO MACHINE CHANGE OUT DRUM DRIVE HOSE ADJUST ALL SCRAPERS PACK UP TOOLING DRIVE TO CAMP	4377 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/15/2024 8:17	Defect list repairs	HOSE LEAKING TOOK PHOTOS	4346 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/09/2024 13:25	250HR Service	250hr service and repairs; 02.02.2024 BF 3 HOURS 250 HOUR SERVICE AND INSPECTIONS R AND R DRUM RUBBERS 03.02.2024 BF 4.5 HOURS AC INSPECT AND DIAGNOSE DRUM RUBBERS	4250 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/05/2024 8:39	Defect list repairs	REPLACE 1 X BATTERY	4123 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	12/12/2023 10:11	250HR Service	500hr service; 5/12/2023 BENN 5 HOURS LOAD PARTS TRAVL FROM CHINCHILLA TO SURAT 500 HOUR SERVICE REPAIR FUEL CAP 07.12.2023 - BENN - 4HRS TRAVEL TO SITE DRAIN AND REFILL DIFF, FINALS, DRUM ECCENTRIC AND HUB OILS 08.12.2023 - BENN - 2.5HRS TRAVEL TO SITE CLEAN DRUM ADJUST AND REPLACE SCRAPERS AS REQUIRED	4000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/28/2023 12:37	Defect list repairs	DEFECT REGISTER 27.11.2023 BENN MCFARLANE 1 HR CHECK POOR AIRCON CLEAN CABIN FILTER (3989)	3978 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/21/2023 6:26	REPLACE DAMAGED/BROKEN PARTS	G.ET & Replace drum rubbers; 7.11.2023 JACK 4 HOURS REMOVE DRUM RUBBERS REPLACE WITH NEW BUSH REPEAT X 3 ADJUST SCRAPERS REPLACE 2 3925 HOURS	3925 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	11/16/2023 19:29	REPLACE DAMAGED/BROKEN PARTS	AC repairs; 7.11.2023 CG 2 HOURS TRAVEL TEST AC ALL GOOD ADD 50 GRAMS OF HYCHILL 10.11.2023 CG 1.5 HOURS TEST AC SYSTEM CYCLES 13-14 DEGREES INSPECT AND ADJUST SCRAPERS AS NECESSARY.	3925 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	10/28/2023 7:32	Defect list repairs	CLEAN DRUM AND REPLACE ALL SCRAPERS AS REQUIRED	3884 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	09/19/2023 5:06	250HR Service	250hr service; 14/09/2023 CARL 4 HOURS REPLACE ENGINE OIL AND FILTERS 4 X FUEL FILTERS 2 X AIR FILTERS CABIN FILTER ECCENTRIC HOUSING OILS X 2 VIBE SUPPORT OIL FINAL DRIVE OIL SAMPLES FROM ENGINE AND ECCENTRIC HOUSINGS 3745 HOURS 15.09.2023 CARL 1 HOUR 3745 HOURS REMOVE VIBE PAD WITH BROKEN BOLTS ATTEMPT TO REMOVE BROKEN BOLT REQUIRE WELDER 17.09.2023 CARL 3.5 HOURS WELD OUT BROKEN BOLT FROM DRUM MOUNT TAP THREADS FIT NEW PD AND NEW BOLTS	3750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/23/2023 9:24	REPLACE DAMAGED/BROKEN PARTS	Replace hood latch and striker; 20.06.2023 BM 1.5 HOURS REPLACE HOOD LATCH AND STRIKER	3520 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	06/13/2023 18:15	250HR Service	500hr service 12.06.2023 BENN 2.5 HOURS 500 HR SERVICE, ALL FILTERS, CHECK DRUM RUBBERS, CLEAN DRUM, REPLACE AND ADJUST NECESSARY SCRAPERS, CHECK REVERDSE LIGHT FAULT. 12.06.2023 CARL 2 HOURS ASSIST 500 HR SERVICE AND ADJUST ALL SCRAPERS ON DRUM, REPLACE 5 X SCRAPERS.	3500 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/09/2023 8:38	Defect list	RUB PROOF HOSES	3322 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/08/2023 16:59	REPLACE DAMAGED/BROKEN PARTS	Replace drum mount rubbers; 06.04.2023 AA 3.5 HOURS REMOVE AND REFIT NEW RUBBER DRUM MOUNTS 19.04.2023 LUKE MCFARLANE 2.5 HOURS TRAVEL TO SITE, REPLACE 5 X DRUM MOUNT RUBBERS ON LHS 22.04.2023 JACK MAYES 8 HOURS HOSES BLOWN, PULLED HOSE OT, TRAVEL TO ROMA ENZED TO GET HOSES MADE. RETURN STARTED FITTINGS AND ROUTING HOSES. 23.04.2023 JACK MAYES 8 HOURS FINISH CONNECTIG AND ROCOATING HOSES. ZIPTIE LINES SO DONT RUB. ACTIVATE AND OPERATE MACHINE TO TEST FOR LEAKES. 02/05/2023 BS 1 HOUR DIAGNOSE AND LOCATE AND REPAIR BROKEN WIRE IN BEACON CIRCUIT LOCATE AND REFIT CLIP FOR UHF MIC REFIT BATTERY ISOLATOR COVER	3187 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	05/08/2023 15:42	REPLACE WEARING PARTS	Replace scrapers; 04.05.2023 BS 1 HOURS ADJUST SCRAPERS 06.05.2023 1 hour BS 2 WORN OUT DRUM SCRAPERS	3368 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/19/2023 17:32	250HR Service	250hr service 13.04.2023 Luke McFarlane 5 hours remove seat, remove all rights from rear spport, remove both seat cushions and scavol base, refit all components to now seat shell and refit seat and counter console. Position drum correctly, repair damaged thread and secure loose drum mounts, tension all drum rubber bolts. 15.04.2023 BENN MCFARLANE 0.5 HOURS REFIT FIRE EXTINGUISHER AND BRACKET.	3257 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/03/2023 12:47	Heater Hose	Heater Hose	3002 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/26/2023 10:12	250HR Service	1000hr service; 20/02/2023 BENN 3 HOURS 1000 HOUR SERVICE ALL FILTERS DIFF OIL FINAL OIL CHECK AND ADJUST SCRAPERS CHECK DRUM RUBBERS 25/02/2023 AA 2.5 HOURS REPLACE HEATER HOSE	3000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/25/2023 5:49	Defect list repairs	Remove hose from drive motor to control valve, install new hose and 2 new Orings from BJ Hydraulics Dalby (2939hr). - 4.5hrs	2909 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	02/08/2023 9:06	250HR Service	250hr service 31/01/2023 - Jack Mayes - 2.5 HOURS 250 hr service 31/01/2023 - Benn McFarlane 2.5 HOURS Travel to 207, 250hr service, check drum rubbers, travel to pit. (2792) 02/02/2023 - Benn McFarlane Replace primax fuel filter (2800hrs) - 0.5hrs	2750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/31/2023 7:37	REPLACE DAMAGED/BROKEN PARTS	Drum rubbers; 27/01/2023 BS 4 HOURS DRILL OUT BROKEN DRUM RUBBER BOLT AND REMOVE BROKEN SECTION 28/01/2023 BS 3 FINALISE DAMAGED THREAD REPAIR AND REPLACE 3 SPLIT DRUM RUBBERS	2774 Hours

P1175 CAT Padfoot Roller 2021 CAT CP76B	01/09/2023 12:01	250HR Service	Service Drum rubbers; 3/11/2022 BRANDON 5 HOURS PERFORM 250 HOUR SERVICE 4/11/2022 BRANDON 7 HOURS REPLACE 6 DRUM RUBBERS AND LEFT HAND SIDE OF DRUM REPAIR WX THREADS IN MOUNTING PLATES	2250 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	09/21/2022 12:58	Replace damaged/broken parts	Scrapers Drum rubbers 15/09/2022 Benn McFarlane 4hrs Inspect scrapers, replace 4 x LH drum mounts. (2,066hrs) 17/09/2022 Benn McFarlane 3hrs Clean drum, replace 18 scrapers, check door catch and hydraulic hose. (2,070hrs) 3hrs	2070 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	09/03/2022 17:17	250HR Service	1000hr service; 29/08/2022 BS 5 HOURS CARRY OUT 2000 HOUR SERVICE, SAPLE AND REPLACE OILS, CHANGE ALL FILTERS. eEMPTY ALL RUBBISH AT IOR PAD	2000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	07/27/2022 17:53	250HR Service	Service 250hr 20/07/2022 - Benn McFarlane - 2.5hrs 250hr service. (1,750hrs)	1750 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/30/2022 16:38	250HR Service	Service 18/06/2022 - Anthony Andrews - 2.5hrs Service 500hr.	1500 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	06/30/2022 15:06	Adjust scrapers	Adjust scraper bars	1605 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/29/2022 12:30	REPLACE DAMAGED/BROKEN PARTS	oil leak under cab 28/04/2022 - Luke McFarlane - 1hr Inspect for hyd leak under cab. Hose replaced from vibe motor to hydraulic bank under cab. (1,329hrs)	1329 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/27/2022 9:01	Locate and repair hydraulic leak	25/04/2022 - Brad Smith - 2hrs Locate hydraulic seal under cab. Tag out machine and remove hose. (1,318hrs) 26/04/2022 - Brad Smith - 3hrs Fit new hose, route through existing clamps. Check for leaks - ok. (1,318hrs)	1318 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	04/13/2022 7:11	250HR Service	250hr service 12/04/2022 - Brad G 4hrs Carry out 250hr service. Pack up (1250hrs) 12/04/2022 - Jack Mayes 2hrs Carry out 250hr service. (1252hrs)	1250 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/10/2022 14:16	RECTIFY FAULTS	DRUM RUBBERS BROKEN (POSSIBLE WARRANTY)	1114 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/07/2022 16:47	250HR Service	07/03/2022 - Josiah MacPherson - 4hrs Carry out 1000hr Service	1000 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	03/06/2022 10:17	Oil Leak	05/03/2022 - Luke McFarlane - 4.5hours Travel to Avon Downs. Diagnose oil leak and remove hydraulic hose. Take to Miles for replacement. Return to site and refit. Check. (987)	987 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B	01/25/2022 15:27	Replace UHF ariel	Replaced UHF ariel	874 Hours
P1175 CAT Padfoot Roller 2021 CAT CP76B		250HR Service	500hr service; 12.01.2023 BS 4 HOURS REMOVE BLOWN HOSE CARRY OUT 500 HOUR SERVICE FIT NEW HOSES AND TEST	2500 Hours