

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1099		Cat CP563C Padfoot Roller #5 (5635)		
	194984	2000 Hour earthmoving service (12 Months Interval)	19/08/2026	11465 Hours
	189431	Vibe switch Faulty - Parts ordered - R&R joystick handle and vibe button - 3/12	3/12/2025	
	186733	2000 Hour earthmoving service (12 Months Interval)	23/09/2025	
	185945	Repaired radiator	3/09/2025	
	183188	Replaced thermostat	5/03/2025	
	182227	A/C hose - Compressor to condenser	7/02/2025	
	182214	Replaced batteries	30/01/2025	
	181639	Jump started	11/12/2024	
	180902	Replaced front window	30/10/2024	
	178871	2000 Hour earthmoving service (12 Months Interval)	18/10/2024	
	179249	A/C re-gassed	29/08/2024	
	175673	Flat batteries = Isolator left on. Replaced battery light globe on dash	23/04/2024	
	175680	Replaced alternator	17/04/2024	
	173277	Roller 6 Months Service	27/02/2024	

Asset	W/O No	Description	Finished	Done Reading
	169876	Replaced batteries	4/09/2023	
	166768	Roller 6 Months Service	20/07/2023	
	162057	Replaced alternator, batteries and terminals	19/01/2023	
	161310	Roller 6 Months Service	11/01/2023	
	161255	Replaced hydraulic pump and seals	24/11/2022	
	156402	A/C condensor hose replaced and re-gassed	7/07/2022	
	154611	Radiator Repaired/Re-fitted	28/06/2022	
	155260	Roller 6 Months Service	25/06/2022	
	154606	Reverse camera wiring replaced	5/05/2022	
	151476	Radiator sent for repair and re-fitted Replaced wiper motor	18/01/2022	
	150314	Roller 6 Months Service	13/12/2021	
	149985	Radiator leaking top pipe Pipe cracked remove radiator and cooler as a unit, split and send for repairs Reeve F	17/11/2021	
	149683	Initial Plant Safety Audit	16/11/2021	
	149331	LH headlight fallen off Bracket rusted off cab re-weld in different position and repaired wiring Reeve f	4/11/2021	
	149058	A/C not cold A/C belts slipping modify bracket to adjust belt A/C cold-ok Reeve F	29/10/2021	
	148016	Rear grate fallen off Refitted Reeve F	22/09/2021	
	148102	Scraper tooth adaptor worn, loose tooth Re-weld adaptor order new tooth and pin Fit new teeth and pin & locks Reeve F	16/09/2021	
	148114	Muffler leak Replaced muffler and clamps Reeve F	31/08/2021	
	148119	Belt squeal Adjusted belts, fitted missing bolts to condenser ,topped up oils	26/08/2021	

Asset	W/O No	Description	Finished	Done Reading
		Reeve F		
	146354	Window loose/ rattling Bent window channels back into place. Siliconed around bottom window to stop dust & hold	11/08/2021	
	144891	Isolator switch u/s Replaced isolator switch Reeve F	22/06/2021	
	144110	Roller 6 Months Service	8/06/2021	
	144222	Checks Replaced fire extinguisher everything else ok Reeve F	1/06/2021	
	135841	Sluggish ,overheating light on Oil cooler very blocked-cleaned out,minor coolant leaks,stop leak for now,will need look at Will not run in rabbit mode(shift solenoid ordered Changed shift solenoid-problem persists,checked and adjusted main pump retested valves ok,main pump pressures good 600psi stalled,Replaced rear hydraulic propulsion motor due to excessive case drain,fast travel speed problem still occuring Roller been taken to PKWS Reeve F(see attachments) Checked case drains front ok,rear excessive when driving new rear drive motor ordered Reeve F	9/12/2020	
	138663	A/c not working Reclaimed gas .replaced listed components, regassed ,tested good (see A./C sheet #2012) Reeve F	1/10/2020	
	127973	Over heating A/C not working Repair wiring to air cond compressor B Patrick	28/04/2020	
	129488	2000 Hour earthmoving service	16/03/2020	
	129577	Air con not cold Found belt loose and slipping Hand made bracket for A/C has no adjustment Slotted out holes in bracket, correct to be operated Tested A/C with belt tight and gauges Getting cold but high side high, may be moisture present Reeve	12/03/2020	
	129121	a/c NOT COLD Re pair wiring to air cond compressor (broken between pressure switch and compressor)	28/02/2020	
	124426	wont start Replaced both batteries and check charging Cameron Buck	11/09/2019	

Asset	W/O No	Description	Finished	Done Reading
	123467	250 Hour Earthmoving service	5/08/2019	
	123490	Wont start Jump started (charging at 27.6v) Cameron Buck	1/08/2019	
	122963	Seat belt stuck	11/07/2019	
	122647	Oil leaking under cab Call pirtek and replaced 2 hoses C Buck	3/07/2019	
	123170	Blown hose Replaced blown hose Cameron Buck	3/07/2019	
	121318	500 Hour Earthmoving Service	20/05/2019	
	121300	A/C starts off cold but then gets hot window latch tighten air conditioning compressor belt adjuster missing,test system make bracket to hold compressor Ben Patrick	15/05/2019	
	121273	Window wont stay up window latches missing reverse camera not working window latches on order replace missing fuse for reverse camera Glen Windle	13/05/2019	
	120013	Check over machine to go to apbp	19/03/2019	
	116238	Fit new drive motor hose and wrap other hoses test OK	27/06/2018	
	116233	Fuel draining back into tank Remove debris from flapper valve in fuel primer pump and test OK	26/06/2018	
	114155	needs fuel and air filters Clean debris from fuel system primer and test OK	22/06/2018	
	110117	250 Hour Earthmoving service	14/11/2017	
	109655	Bad miss in engine Replaced #5 injector	19/10/2017	
	107519	500 Hour Earthmoving Service	25/08/2017	
	105348	Engine dying when vibration on	9/05/2017	
	107779	Replaced window latch	18/01/2017	

Asset	W/O No	Description	Finished	Done Reading
	107784	Replaced air conditioning belt. Compressor adjuster missing. Installed new hydraulic motor for ventilation and shaft is new.	11/01/2017	
	102637	250 Hour Earthmoving service	27/10/2016	
	102439	Seat U/S#Rebuild seat ass fit new armrests cushions suspension ass	14/10/2016	