

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1207		Dynapac CA6500PD Padfoot Roller		
	194870	Roller - 250hr Service Uhf only works from time to time	11/08/2026	Hours
	194131	July R&M No start R&R battery 7/7/26 hours 4781 fuel leak at bottom of fuel tank, remove damaged section of hose and re-join 17/7/26 hours 4795 remove and replace alternator, test and confirm repair Fault 14/07/2026 Machine shut down low power issues Access machine find that alternated charge rate is only 23Volts Need to remove and replace alternator Jump start and try move of pad (lower power won't move) Alternater ordered 12/07/2026 Battery replacement 14/07/2026	23/07/2026	Hours
	194466	Rework - Incorrect parts supplied and fitted - Check charging fault on machine - Found to have power at alternator - Check all connections at batteries as they had previously been changed * All ok - Get machine started and out of the trench it had broken down in - Check charge rates at alternator - Noticed the sticker on the alternator stated it was 12v, the machine is 24v. - A correctly rate alternator needs to be ordered and fitted to the machine	22/07/2026	Hours
	193949	June Monthly R&M WO: Speed sensor fault, clean speed sensor clear codes and test	23/06/2026	4713 Hours
	60954	Pre hire repairs as per inspection, 4706 HRS * Topped up hydraulic oil wash machine Backcharge \$315 clean cab \$95 hose for tappet cover drain leaking check clamp replace missing zip tie on heater hoses a/c compressor rubbing on cover clean leaves and sticks out of cooler pack fuel drain hose hanging down check a/c pressure cold but could be better	24/02/2026	Hours
	59510	off hire inspection	19/12/2025	Hours

Asset	W/O No Description	Finished	Done Reading
	58854 November R&M Replace Hood/ bonnet struts - RH & LH Fixed oil leaking on drum Pad fans changed Operations manual added RH bonnet strut leak fixed	29/11/2025	Hours
	57869 October R&M. Repair coolant leak. Leaking from drain hose. Josh Bendall. 20.09 o Reverse camera not fitted. Install supplied kit. Replace UHF aerial as required o Missing A/C knob. Need pics to place an order. Any underlying issue that may have caused the knob to break? o First aid kit reported to be missing. Check and advise. Inspect if in machine, ensure not depleted.	20/09/2025	Hours
	53164 Pre hire repairs as per HME inspection. w/o 523743 4646 hrs Assist with cylinder removal Assist with removal of pin steer arm Clean cab remove old stickers put out floor mat Clean cylinder up, reseal cylinder, find parts, remove bearing, seized, clean up, fix bore Clean up bay. Paper work/fulcrum. Check over. Stickers. Ripper cylinder strip down reseal. Rod damaged Clean/wash out dynapac roller. Start removing steer cylinder out of roller Complete paper work reinstall new rear main seal lip on crank had to push seal further in on fresher area install fly wheel and pump back clean out dusted air intake. Run up machine and test. Finish welding them off and check over it so they were all done and clean up the shed after it Gouge off old pad feet, grind that half up, started to weld new ones on Help gouge pin out Install pump, clean out intake pipes, check over machine, paperwork Pin seized in bush Put the rest of the feet on and continue to weld them on Removal of right steering pin Remove LH Rear steer pin Remove pump out off, Strip down flywheel remove rear main steel. Remove stalk on steering wheel strip down re soldier. Fix light issues adjust fingers price up new parts Stickers Testing electrical Wash off oil around pump. Remove LH cylinders Wash underneath machine, try to remove rear LH steer cylinder pin. Locator jammed try to remove. cut off locator, try hammer pin. Try slide hammer pin, thread on slide hammer scrapped off in pin. Remove snapped bolt. Heavy duty weld on M20 thread rod allow to cool before enerpack. Remove and fit new bearings, seized, install steer cylinder, fit guards, check paperwork and FULCRUM Remove LH rear steer pin Clean cylinder up, reseal cylinder, find parts, remove bearing, seized, clean up, fix bore	19/09/2025	Hours
	52677 Check over - Fill fuel - Adjust scrapers - Fit UHF	19/02/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	52374	HME Inspection - Roller Quote #: 312	10/02/2025	4644 Hours
	49680	Roller - 500hr Service Hrs: 4532 Replace Belts - Heath Crocket to advise belt numbers to purchasing 30.10.P.E. Adjust scrapers Need to update filter kit Adjust all scrapers x 18 chisel / hammer off heaps of rock/ mud build up on drum& scraper blades Air compressor blow gun all cooler packs/ radiator, big amount of blocked fins, used fin comb to remove blockages.	18/11/2024	Hours
	48668	Roller - 250hr Service	30/09/2024	Hours
	15377	Pre hire inspection, Fulcrum pics. Travel to site, repair steer oil leak (O'ring) Replace fuel cap. Return to Dubbo.	9/05/2024	Hours
	8939	HME Inspection - Roller Quote #: Hours: 4136 23/01/2024 diagnose oil leak at drum replace drum gear detail cab tag and bag fire extinguishers first aid kit replace wiper blades diagnose washers not working grease machine remove client stickers wheel nut indicators complete 12 mile paperwork take photos repair access step and door top up engine oil put R clip in steer lock replace missing bolts in dash repair blinker stalk	7/03/2024	4136 Hours
	6394	Roller - 4000hr Service Tighten sump drain	17/10/2023	3933 Hours
	4940	HME inspection & defect repairs	31/08/2023	Hours
	2899	Dynapac - Rebuild drum cartridges EMS - Attend site and diagnose fault with no A/C. 0.100g of gas was reclaimed. Roller will need new A/C comp & high side hose to condenser. Machine now not in a running state to complete repairs. Install rebuilt vibe rotors into drum, measure shaft clearance all ok. Install drum back into roller, fit side supports and front counter weigh, fill and check all oils including, drum drive reduction and 2 x vibes, run test all ok.	18/08/2023	3874 Hours