

## Work Order History Report

| Asset        | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                        | Finished   | Done Reading |
|--------------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
| <b>T0325</b> |        | <b>Kenworth T608 Water Truck</b>                                                                                                                                                                                                                                                                                                                                                                                   |            |              |
|              | 193914 | Water Truck - 250hr Service                                                                                                                                                                                                                                                                                                                                                                                        | 4/07/2026  | 1750 Hours   |
|              | 192893 | May R&M<br>* Strip spray head. Remove debris, reassemble                                                                                                                                                                                                                                                                                                                                                           | 23/05/2026 | Hours        |
|              | 191644 | - inspect for Tooraweenah Rd job<br>- wash truck of mud<br>- clean out cab<br>- fit hearing protection sticker<br>- carry out on hire inspection                                                                                                                                                                                                                                                                   | 20/03/2026 | Hours        |
|              | 191360 | Off hire Barigan<br>1465 hrs                                                                                                                                                                                                                                                                                                                                                                                       | 26/02/2026 | Hours        |
|              | 60448  | Prehire repairs as per 60418<br>1424hrs/ 20897km<br>Cab Clean as Filthy \$210.00 Backcharge<br>Outside wash filthy \$420.00 Backcharge<br>Replace missing cab air vents \$150.00<br>Diagnose erratic Tacho and Pyro Gauge Faults \$525.00<br>Straighten rear Lightbar \$105.00<br>Straighten rear ladder \$105.00<br>repair Faulty UHF \$55.00<br>Replace missing Hose nozzle \$105.00<br>Brake Adjustment \$55.00 | 13/02/2026 | Hours        |
|              | 60418  | offhire Inspection NACAP<br>1421hrs                                                                                                                                                                                                                                                                                                                                                                                | 2/02/2026  | 1421 Hours   |
|              | 60049  | Check over as per CP<br>- brake adjustment<br>- tighten 1st diff carrier<br>- tighten 1 diff torque rods<br>- clutch adjustment and changed linkage set up<br>- bolted up roof console                                                                                                                                                                                                                             | 12/01/2026 | Hours        |
|              | 59897  | Sprays not working                                                                                                                                                                                                                                                                                                                                                                                                 | 18/12/2025 | Hours        |
|              | 57904  | A SERVICE and TRUCK REPAIRS. 19213 odo.                                                                                                                                                                                                                                                                                                                                                                            | 1/12/2025  | 19213 Hours  |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Finished   | Done | Reading |
|-------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------|---------|
|       |        | ENGINE OIL 15W40 40L<br>OIL FILTER GENUINE<br>SUMP WASHER GENUINE<br>WINDOW CLEANER<br>ALL BRAKE ADJUST AND INSPECTION<br>ALL BALL JOINT-REGREASE<br>M/T OR AUTO AND DIFF FLUID LEVEL AND CONDITION<br>CHECK<br>ALL BUSH AND SPRING CHECK<br>ALL BRAKE OPERATION CHECK AND TEST<br>ALL LIGHT CONDITION CHECK<br>ALL TYRE PRESSURE AND CONDITION CHECK<br>FAN BELTS CONDITION AND TENSION, BEARINGS CHECK<br>COOLING SYSTEM (RADIATOR AND HOSEA, INTER COOLER)<br>POWER STEERING SYSTEM<br>TURBO CHARGER AND EXHAUST MANIFOLDER AND STUDS<br>PARKING BRAKE AND REAR BRAKE ADJUST<br>MANUAL AND AUTO TRANSMISSION AND REAR DIFF OIL<br>LEVEL AND CONDITION CHECK<br>CLUTCH ADJUST<br><br>Brake adjustments<br>Wiper replacement<br>Seat belt replacement |            |      |         |
| 57288 |        | HVIS Inspection - Yearly. Booked in Silverwater 12/09 @ 9:40am                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 19/09/2025 |      | Hours   |
| 56037 |        | Off-Hire repairs<br><br>- carry out list of repairs<br>- remove rear diff<br>- rebuild diff<br>- replaced wheel bearings on rear drive axle<br>- replaced steer wheel bearings<br>- find coolant leak, tightened clamps<br>- replaced heater tap, test heater<br>- replaced draglink, replaced RH tie rod end<br>- replaced fuel tank straps<br>- replaced kinked hydraulic hoses, mount loose valve<br>- replaced exhaust elbow on RH slack<br>- repair plug on horn<br>- find & repair air leaks<br>- repair & adjust clutch linkage, replaced rose joints<br>- adjust clutch<br>- test drive<br>- replaced slack adjuster on LHS rear drive axle<br>- weed & seed                                                                                   | 30/07/2025 | 1269 | Hours   |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Finished   | Done Reading |
|-------|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | <ul style="list-style-type: none"> <li>- Fulcrum photos</li> <li>- on-hire paperwork</li> <li>- fit wheel nut indicators</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                     |            |              |
|       | 55707  | Water Truck - 2000hr Service/Annual 1269hrs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 25/06/2025 | 1269 Hours   |
|       |        | <ul style="list-style-type: none"> <li>- carried out service</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |            |              |
|       | 55650  | rotate tanks and adjust clutch<br>1256 hrs <ul style="list-style-type: none"> <li>- Tanks spun due to worn straps</li> <li>- Loosen straps spin tank &amp; tighten straps</li> <li>- Adjust clutch</li> <li>- Travel to &amp; from site to workshop</li> </ul>                                                                                                                                                                                                                                                                          | 17/06/2025 | 1256 Hours   |
|       | 55382  | fuel tanks turned, spin tanks tank around. <ul style="list-style-type: none"> <li>- Turned tanks to correct position</li> <li>- RH tap broken, near rubbers may fix the issue</li> </ul>                                                                                                                                                                                                                                                                                                                                                | 13/06/2025 | Hours        |
|       | 54858  | "Site inspection<br>Pre-hire inspection<br>On hire inspection"<br>1163hrs <ul style="list-style-type: none"> <li>- complete off hire</li> <li>- complete weed and seed wash</li> <li>- change out starter motor</li> <li>- change out 2 mudflaps</li> <li>- rotate both fuel tanks</li> <li>- complete on hire inspection</li> </ul>                                                                                                                                                                                                    | 15/05/2025 | 1163 Hours   |
|       | 52221  | *Replace Broken hubcap and inspect wheel bearings. <ul style="list-style-type: none"> <li>- Travel to site</li> <li>- Investigate issue with leaking hub, found LH front cap missing the bung</li> <li>- Jacked up wheel and removed cap</li> <li>- Removed outer wheel bearing and checked, all OK</li> <li>- Refitted wheel bearing and adjusted</li> <li>- Fitted new cap and filled with fresh oil</li> <li>- Adjusted both front brakes, cleaned down wheel</li> <li>- Found axle 2 LH outer tyre flat, pumped up tyre.</li> </ul> | 18/03/2025 | Hours        |
|       | 51816  | Vehicle Overheating and Seatbelt inoperative (Tamworth) <ul style="list-style-type: none"> <li>- Attended truck on back Kootingal Road</li> <li>- Removed drivers seat</li> <li>- Removed &amp; replaced seatbelt</li> <li>- Tested all OK</li> </ul>                                                                                                                                                                                                                                                                                   | 7/02/2025  | Hours        |
|       | 51564  | On hire inspection<br>*Finish 1019.6hrs<br>-Replace steering shaft universal joints                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 14/01/2025 | Hours        |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Finished   | Done Reading   |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|----------------|
|       |        | -tighten bonnet hinge<br>-replace clearance light                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |            |                |
|       | 51419  | Replace water valve handle and replace squished section of hose on hose reel<br>15757<br>-Replace butter fly valve handle<br>-Cut off and re fit fitting on hose reel                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 7/01/2025  | Hours          |
|       | 49286  | Carry out Pre-Hire<br>-Replace worn Uni Joint<br>-Replace Diff temp sensor                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 15/10/2024 | Hours          |
|       | 49018  | Hours: 14947<br>HME Inspection/Fulcrum off hire                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 4/10/2024  | Hours          |
|       | 18572  | HVIS Inspection - Yearly. Booked Mudgee 13/08 @ 2:40pm<br>Inspected at Mudgee Repairs<br>Replaced 4x Batteries                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 16/07/2024 | 14450<br>Hours |
|       | 12321  | Check over, complete Maas pre-hire paper work;<br><br>Fault: front bonnet sitting low, parts ordered<br>Correction:<br>- fit bushes in front bonnet, pivot points at radiator<br>- adjust top bonnet rest blocks, fitted new bolts<br>- pull bonnet forward on RHS at pivot mount<br><br>Fault: cannon not working<br>Cause: no air to wall tap valve<br>Correction: replace control tap<br><br>Fault: rear spray not working<br>Correction: replaced complete spray head<br><br>Fault: wiper blades U/S<br>Cause: worn out<br>Correction: replaced blades<br><br>- repair air leaks in spray control box in cab<br>- replace all quick connect fittings<br>- every time you stop one leak another would start<br>- unit had 1/4" supply hoses & 6mm in control box | 11/04/2024 | 14401<br>Hours |
|       | 6618   | Off-hire/Pre-hire repairs<br><br>Fault: air leak in control box<br>Cause: fitting leaking<br>Correction: R+R fitting<br><br>Fault: fuel lines misting fuel                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 7/12/2023  | 13823<br>KM    |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                | Finished   | Done Reading |
|-------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | Cause: wear & tear<br>Correction: R+R all fuel lines                                                                                                                                                                                                                                                                                                                                       |            |              |
|       |        | Fault: tanks spinning<br>Cause: loose tank straps<br>Correction: R+R tank strap rubber, tightened tank straps                                                                                                                                                                                                                                                                              |            |              |
|       |        | Fault: front LHS guard needs bolts<br>Cause: missing bolt<br>Correction: replaced bolt                                                                                                                                                                                                                                                                                                     |            |              |
|       |        | Fault: all brakes brakes adjusting<br>Cause: wear & tear<br>Correction: adjusted brakes                                                                                                                                                                                                                                                                                                    |            |              |
|       |        | Fault: ride height valve / rod loose<br>Cause: wear & tear<br>Correction: R+R valve, tightened rods, adjusted height                                                                                                                                                                                                                                                                       |            |              |
| 7580  |        | Water Truck - 250hr Service                                                                                                                                                                                                                                                                                                                                                                | 6/12/2023  | 992 Hours    |
| 5609  |        | Replace A/C belt<br>- remove A/C tensioner, bolt snapped when undoing<br>- had to remove alternator / A/C bracket<br>- x2 bolts broke in it also like while undoing them<br>- had to put in drill press and drill out<br>- put thread inserts in it<br>- put back on with new bolts<br>- put alternator & A/C compressor back on<br>- put tensioners and belts back on<br>- test operation | 1/11/2023  | 866 Hours    |
| 4925  |        | Remove and clean radiator.<br><br>Charge to Maas Civil - refer to Travis Colby.<br><br>- drain coolant<br>- disconnect hoses, remove A/C condenser & lift out of way<br>- remove radiator<br>- wash radiator out & aftercooler<br>- blow core out with air after washing<br>- refit radiator<br>- refill with coolant<br>- move truck to washbay                                           | 1/09/2023  | 13952 Hours  |
| 3643  |        | HVIS Inspection - Yearly. Booked in @ Dubbo 01/08 @ 8:30am: wash engine for inspection, remove dribble bar for inspection, take vehicle over pits for inspection, refit dribble bar.                                                                                                                                                                                                       | 7/08/2023  | 11850 KM     |
| 924   |        | Check over & rectify faults.<br>Fitted PTO pressure switch.                                                                                                                                                                                                                                                                                                                                | 22/06/2023 | 11828 KM     |

| Asset | W/O No | Description                                                                                                                                                                                 | Finished   | Done Reading |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | Repair headlight surrounds on RHS.<br>Replaced flashing lights.<br>Repaired dash blinker indicators.<br>Filled out Maas Plant Hire paperwork.                                               |            |              |
|       | 289    | Water Truck - 250hr Service: Carry out service. Re-connect air tank drain cond. Johnny pump up L/H 2nd axle outer tyre.<br>Trav service: Change ignition switch. Turn R/H fuel tank.        | 28/04/2023 | 1073 Hours   |
|       | 17561  | Batteries over charging - batteries had boiled/exploded. Replaced all batteries and one terminal. Checked alternator - found it was overcharging. Removed and replaced with new alternator. | 18/04/2023 | Hours        |
|       | 17563  | High/Low noise transmission - remove AUX, strip down, replaced worn components, reassembled and refitted.                                                                                   | 8/03/2023  | Hours        |
|       | 17564  | Fitted new isolator, replaced four batteries.<br>Diagnose check engine light - oil pressure sensor, found broken wires, repaired harness.<br>Repaired roof console.                         | 1/07/2022  | Hours        |