

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0363		Hino FM1J Water Truck		
	193648	June/July R&M	10/07/2026	Hours
	192869	May R&M Diagnose and test noisy pump (HYD) Assess coolant leak Replace breather	29/05/2026	Hours
	60842	February - March R&M Replace hydraulic internal tank cooling hoses. Supply O/N T363 A/C Thermostat - Josh Bendall.	30/04/2026	19893 Hours
	192166	April R&M - Lake Cargelligo Defect repairs after HVAIS inspection. BAM to complete the repairs: Replace Alternator. Replace Water pump. 250hr service. Replace fan hub. Adjust brakes. Plate rear suspension hangers. Replace dimmer switch. Replace wiper blades. Repair demister - not working. Re-seal leaking intermediate plate/rocker box. Replace engine belts. Replace drag link boots.	7/04/2026	Hours
	60897	HVIS Inspection - Yearly. Booked in Dubbo 27/03 @ 1:55pm	7/04/2026	Hours
	192167	Water Truck - 250hr Service BAM completing service	2/04/2026	19738 Hours
	60182	January R&M Blown hose replace Sticky sprayers Blown hydraulic hose, check air leaks. top up hydraulic oil Replace stereo head unit	27/01/2026	Hours
	60161	Low air flow. Cabin filter missing - dust entry has blocked the evaporator. Replace evaporator. Replace condenser due to high head pressure. Replace thermistor due to freezing over. Re-gas. (NOTE - PARTS ETA TBA)	22/01/2026	Hours

Asset	W/O No	Description	Finished	Done Reading	
	59640	Water Truck - 1000hr Service 19305 hrs	21/01/2026	19305	Hours
	59648	December R&M Diagnose cause of park brake intermittently applying. Repair broken mount for park brake lever. Replace damaged fan belt	8/12/2025		Hours
	59372	A/C progressively getting hot. Diagnose and repair. Lake Cargelligo Repair AC in water truck, Top up with gas and found AC is not cycling on thermostat causing AC to freeze. Ordered parts and notified operators,	28/11/2025		Hours
	59188	Inspected radio not working Clear defects	12/11/2025		Hours
	56964	Repair Sprayers and multiple air leaks - disassemble sprayers and clean rocks out of them. - re-seal sprayers that were leaking air.	1/10/2025		Hours
	57037	Water Truck - 250hr Service Odo: 18,669hrs - carry out service - fix air leak in seat - fix dribble bar hose - replace clearance light LHS - bolt up number plate bracket - replace reverse buzzer	13/08/2025	18669	Hours
	55150	repair oil leak 18517 hrs - Go to site to diagnose leak - Wash leak - Reseal fittings - Drive back to site	13/06/2025		Hours
	53629	check over for pits, drive truck to mudgee for pit inspection. *Inspected truck for pit inspection. *Fault - Marker light inop. *Cause - Broken wire. *Correction - Repaired wires. *Washed under truck. *Greased truck.	27/03/2025		Hours
	54908	HVIS Inspection - Yearly 238780 km	20/03/2025	238780	KM
	53413	Replace 2 tyres, match up drive tyres	18/03/2025		Hours

Asset	W/O No	Description	Finished	Done Reading
	52690	CAPITAL off-hire repairs On hire. *Oil leak at hydraulic motor on water pump. *Front seal in HYD motor missing. *Remove HYD motor + mounting from water pump, remove coupling. *Strip HYD motor, source seals over town, reassemble + fit. *Bumper bar damaged, removed bar, panel beat as best as possible & refit bumper bar. *Reverse camera not working. *Broken cable + missing rear camera. *Replaced complete unit, Run cable + secure, mount. *New motor & wire up. *Wipers + washers not working. *Blown fuse + blocked hosing. *Locate + replace fuse, Clear hosing & jets till washer's work. *Cab filthy, remove mats & clean dirt + rocks from under mat + remove drivers seat to clean dirt. *Vacuum floor + wash mats. *Inspect clamps under air tank, Clamp bolt broken. *Replaced broken bolt with new one, cut OCD bolt out with angle grinder. *Drivers side window not winding up sometimes. *Door switch controller faulty. *Remove switch + panel & replace window now operates but jams at bottom, window regulator needs replacing. * Removed skin etc + replace window regulator. *R&R axle torque rod lower brushes worn + axle ___ out. *Remove torque rods + press brushes out + press new brushes in, refit torque rods. *R&R radiator. *Replaced RHS outer door handle. *Replaced LHS rear marker. *Fit new tag to fire extinguisher. *Fit hose back to hose reel. *Carried out service as per checklist. *Secured dribble bar with new hammer locks. *Cleaned inside of truck & outside/underneath. *Repaired rust holes on the back of the cab & repainted. *3rd axle LHS tires replaced. *Replaced RHS tire rod end. *Repaired air leaks on all sprayers & around the truck. *Replaced center sprayer. *Fit new fire extinguisher bag. *Adjusted fire extinguisher mounting bracket. *Removed old Maas stickers. *Replaced asset number stickers. *Replaced yellow reflector tape. *Replaced batteries & battery terminals. *Replaced rear bar & refitted lights to new bar. *Rewired rear tail light wiring & marker light wiring. *Replaced brake light switch. Finish 18,251hrs	18/03/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	52773	Water Truck - 250hr Service	24/02/2025	Hours
	52110	off hire inspection and quote up any repairs.	31/01/2025	Hours
	48584	PTO not engaging Hours 17 794	2/12/2024	Hours
	49531	WATER PUMP FOR SPRAYERS NOT WORKING - DIAGNOSE & REPAIR Hours: 18,027hrs	24/10/2024	Hours
	49136	Water Truck - 1000hr Service Hours 17938	18/10/2024	Hours
	48641	Cannon not working. Right inside door handle broken. PARTS ONLY NO LABOUR CHARGED	24/09/2024	Hours
	8484	HVIS Inspection - Yearly. Booked in Mudgee 06/02 @ 2:40pm	6/02/2024	22971 Hours
	7508	Water Truck - 250hr Service completed by A1 Earthworx - driver seat needs replacing - dribble bar hose broken (3 inch suction) - fuel bowl on water operator needs replacing - hand primer for fuel needs replacing (leaking)	30/11/2023	17264 Hours
	7745	Minor R&M - REPLACE BLOWN PTO PUMP & TOP UP HYD OIL (157L)	28/11/2023	17264 Hours
	5164	Pre-Hire inspection. - complete pre-hire inspection - clean vehicle - repair PTO leak, fitting snapped in PTO, had to remove engine mount to get in there to remove snapped fitting - put bung in place of fitting as it was not needed, put engine mount back in and check oil level	13/09/2023	18666 Hours
	4472	Check over Vehicle, replace batteries: - repair middle rear spray - helicoil stripped bolt holes & broken bolts in spray head clamps - had to jump start truck; charged batteries all day, unable to start next day - replaced batteries - sent to electrical bay for A/C & demister faults - replace blower fan fuse - test A/C, pressure test - find leak - replace compressor - pressure test, vac and charge - test A/C (300g R1349) - repair coolant temp sensor wiring - clear engine controller fault codes - clear ABS codes - repair estop wiring - replace rear tank level gauge - put water in tank & test sprays etc	24/08/2023	

Asset	W/O No	Description	Finished	Done Reading
		- free up water cannon, no sideways movement - rectify broken bolt in LHS rear spray - repair wiring light on dash, clear trans codes - send to washbay		
	739	Water Truck - 250hr Service: had trouble priming fuel filters, low beam not working, replaced blown fuse, door latch LHS sticking, lubed up door.	17/05/2023	16840 Hours
	17587	Bonnet cable not working - ordered new cable.	13/04/2023	Hours
	17580	Repaired and cleared defects.	13/04/2023	Hours
	17594	Flashing light not working - found bad crimp terminal on switch, fitted new crimp terminal.	3/04/2023	Hours
	17593	Carried out pre-rego check - found truck needs shackle pin bushes, rear torque rod bushes - ordered parts.	3/04/2023	Hours
	17592	Window washer not working - reconnected split line and filled with water.	3/04/2023	Hours
	17591	Replaced shackle pins and bushes.	3/04/2023	Hours
	17590	replaced LH park light globe.	3/04/2023	Hours
	17589	Hydraulic hose leaking - organised for new hydraulic hose to be made.	3/04/2023	Hours
	17588	Cleaned truck - ready for inspection.	3/04/2023	Hours
	17586	Loose bolt on leading arm mount - LHS back drive. Tightened, all okay.	3/04/2023	Hours
	17585	Fitted two white reflectors to the front of the water tank.	3/04/2023	Hours
	17584	Replaced wiper blades.	3/04/2023	Hours
	17583	Brake lights coming on with tail lights - have constant power, booked in with electrician - fitted resistors.	3/04/2023	Hours
	17582	Check truck won't turn off - swapped relay around and truck turned off.	3/04/2023	Hours
	17581	Replaced faulty start stop relay.	3/04/2023	Hours
	17595	Carried out 250hr service.	28/11/2022	Hours
	17596	Carried out rego repairs: - replaced front shocks - replaced worn spring eye bushes - repaired air leaks at back of gear box - replaced steer tyres, replaced third axle RHS tyres - adjusted brakes - replaced rear axle torque rod bushes - repaired reverse light - replaced rear marker signs - fitted and tested universal tracker	18/03/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
-------	--------	-------------	----------	--------------