

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0363		Hino FM1J Water Truck		
	56090	Repair Sprayers and multiple air leaks WO OUT OF OLD MEX 56964 WON56090	19/05/2026	
	56342	OFFHIRE AND REPAIRS - replace front cab mounts. - remove and re-kit swivel joints on water cannon. - replace all sprayer switches in cab. - diagnose and repair electrical issues. - replace tail lights. - re-fit timber under water cart body. - jack up rear of truck and support chassis. - remove wheels, remove springs, remove trunnions. - inspect bushes, bushes and trunnions were worn badly. - cut trunnions and press out of hangers. - remove old bushes. fit new bushes. - install new trunnions and seals. - mount hangers back to chassis. - paint hangers. - install spring packs and tension u-bolts. - replace all torque rod bushes and bolts as they were very rusty. - replace rear cab lock. - repair rear sprayer heads. - fit cap to fill coupling. - fix hydraulic leaks at front of tank. - replace water pump, had to remove harmonic balancer. 2 bolts broke in the balancer when removing. - extract broken bolts, fit water pump, fit balancer, fill with coolant and check for leaks. - replace solenoid valves for water cannon. -replace stripped drive axle wheel stud and nut - fit missing radiator overflow cap. - weed and seed vehicle, detail inside of cab, fulcrum on hire photos.	30/10/2025	