

## Work Order History Report

| Asset  | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Finished   | Done Reading |
|--------|--------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
| A1-750 |        | <b>Sterling LT7500 Water Truck</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |            |              |
|        | 194668 | August R&M<br>- Battery/ steering issues<br>- No pressure from sprays. Inspection of pump and pto carried out. Test ok, Inspection of system to find that there is an electric over hyd diverter valve for water pump. Inspected fuses, found blown fuse, replaced and tested ok                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 30/07/2026 |              |
|        | 194165 | Defect repairs as per NF<br>Rear ds guard pole loose<br>Grill broken rubbing on condenser, inserted new rivet<br>Ac belt remove and replace<br>Steering shaft unimexcessive movement<br>2x uni in Pto shaft excessive movement<br>Multiple air leaks on primary tank, x2 air fittings and loose check valve<br>Drive shocks leaking remove and replace<br>Tanks full of water<br>Reverse alarm inoperative<br>Outlet of turbo leaking tighten clamp<br>Low coolant took 5l, pressure tested system no visible leaks found<br>Multiple hose clamps loose tighten<br>Flashing light causing pump to fluctuate found bad earth re wired lights at control box<br>Hose real drive pump seals leaking<br>Centre spray butterfly valve leaking remove and replace<br>Rear bar cracked welded and plated<br>Tranny oil not on dipstick<br>Temp gauge globe blown<br>Kinked air line cut and inserted air joiner<br>Load test batteries ok<br>Removed fill point flap due to broken<br>8468 - No dash lights | 7/07/2026  | 9623 Hours   |
|        | 193905 | Water Truck - 250hr Service<br>7654 - Center spray leaking<br>7943 - Check operation of Horn - not working<br>7942 - Leak at drive motor on hose reel, front seal.<br>8209 - Reverse Alarms - stopped working.<br>8081 - Flashing lights power supply needs to be wired directly to battery, pulsing of lights plays up with pump controller makes it pulse up and down. not good on pump.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 1/07/2026  | 9620 Hours   |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Finished   | Done Reading |
|-------|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | 13231 Flashing light needs to have direct power from battery, it is causing pump fluctuations while on. 16.05.2025                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |            |              |
|       |        | 13229 Blaffels need inspection as a little noisy. 16.05.2025                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |            |              |
|       |        | 13675 Check service sticker - report if missing or service due Failed - 8031 09.07.2025                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |            |              |
|       | 192902 | May R&M<br>- Brake adjustment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 29/04/2026 |              |
|       | 60315  | Failed 24/30 booster<br>Replace 1st drive axle RHS booster, travel back to workshop.<br>Brake were dragging, found that pos 6 brake was bypassing and pos 5 has wrong booster on it<br>Replace rear axle RHS booster only to find misdiagnoses and the service brake relay valve had broke, get drier to go to<br>Dubbo pick up new one and fitting pull old one out and all post lock fitting broke so airier got move, fit up new one but<br>needed adapters, one air fitting was wrong so couldn't finish<br>Get fitting from town travel to Gulgong put fitting in hook up air line, test valve                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 2/02/2026  |              |
|       | 59148  | Brakes locked on<br>400000km/9175hrs<br>- adjust brakes and test                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 22/01/2026 |              |
|       | 57908  | HVIS Inspection - Yearly. Booked in Dubbo 31/10 @ 10:25am.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 31/10/2025 |              |
|       | 56646  | Capital -Repairs<br>-Remove remaining shackle bushes<br>- install rear bushes<br>- Install hangers<br>- remove front springs pin and bushes<br>- install new bushes and pins<br>- Install PTO shaft with new belts<br>- install all LHS panels that were removed<br>- grease the truck<br>- install both LHS and RHS front wheels<br>- loosen tank straps and attempt to rotate tank<br>- install backing plate on 2nd drive<br>- install new bolts for shackle pins<br>- fill hyd tank and filter<br>- segregate fuel hoses and route different doe to rubbing on frame<br>- order parts<br>- start diagnosing issue with primer pump/ no start fault<br>- install new bolt for engine mount RHS<br>- adjust 2nd drive brakes<br>- remove power steering resevoir and clean dirty and leaking seal<br>- R & R E stop due to intermittent<br>- repair LHS mirror light<br>- tighten loose mudguard<br>- install RHS spray nozzle<br>- remove blower control switch and order<br>- organise cummins insite to connect to truck<br>- diagnose oil pressure issue to be unplugged and sensor leaking oil | 11/09/2025 | 8849 Hours   |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Finished   | Done Reading |
|-------|--------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | <ul style="list-style-type: none"> <li>- remove truck rods and press out</li> <li>- found issue and notified Travis</li> <li>- complete work sheet</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |            |              |
|       | 54292  | Water Truck - 250hr Service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | 14/08/2025 | 8845 Hours   |
|       | 56543  | Off hire Inspection EX Stubbos<br>8842hrs<br><ul style="list-style-type: none"> <li>- carry out and complete off hire inspection</li> <li>- fulcrum pics</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 28/07/2025 | 8842 Hours   |
|       | 54276  | Replacing oil pump pressure line<br>8723hrs<br><ul style="list-style-type: none"> <li>- replaced hydraulic pressure hose to pump from flow meter to pump</li> <li>- removed blown hose</li> <li>- sealed up windscreen pump in washer bottle</li> </ul> tested ok                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | 16/04/2025 |              |
|       | 52983  | Remove and replace cab fan<br>Hours: 8506                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 3/04/2025  |              |
|       | 53668  | Repair rego defects 272814km<br>Inspect excessive oil leak on rear of engine sump.<br>Inspect oil leak On first diff at seal to drive shaft.<br>Remove inner and outer 2nd axle Tyers on L/H side to inspect drum, brake shoes and slack adjuster.<br><ul style="list-style-type: none"> <li>-1st drive axle brakes replaced</li> <li>-1st axle brake shoes and drums</li> <li>- remove output seal, clean and replace new output seal</li> <li>- install drive shaft, torque bolts to 130</li> <li>- remove sump on engine and replace gasket, torque bolts to 20</li> <li>- diagnose brake issue, found check vale from primary air tank to secondary air tank partially blocked not allowing it to seat correctly.</li> <li>- clean check valve and install, brake issue solved.</li> </ul> | 2/04/2025  |              |
|       | 53209  | Diagnose starting fault<br>8551hrs<br><ul style="list-style-type: none"> <li>- change start switch</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 11/03/2025 |              |
|       | 52710  | Oil pressure switch ECU single wire (nominal open)<br>8505hrs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 10/03/2025 | 8526 Hours   |
|       | 52854  | Possible brake dragging, diagnose and repairs<br>8526hrs<br><ul style="list-style-type: none"> <li>- Locate water truck</li> <li>- Jack up wheel, inspect brake, read just and grease s cam</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 6/03/2025  | 8526 Hours   |

| Asset | W/O No | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Finished   | Done Reading |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | - Test brake<br>- Functions tested ok - complete                                                                                                                                                                                                                                                                                                                                                                                                                                                  |            |              |
|       | 52982  | Park break slow to apply diagnose and repair<br>Hours: 8505                                                                                                                                                                                                                                                                                                                                                                                                                                       | 28/02/2025 | 8505 Hours   |
|       | 53050  | Water funnel (fill point) requires refitting/bolt.                                                                                                                                                                                                                                                                                                                                                                                                                                                | 28/02/2025 |              |
|       | 52066  | Water sprays not working, diagnose and repair<br>8375hrs                                                                                                                                                                                                                                                                                                                                                                                                                                          | 29/01/2025 | 8375 Hours   |
|       | 52017  | Diagnose starting fault , rewire ignition<br>8373hrs<br>-repair bad connection on start signal circuit                                                                                                                                                                                                                                                                                                                                                                                            | 29/01/2025 | 8373 Hours   |
|       | 51612  | Diagnose Starting Fault<br>Remove and Replace Failed Starter motor.<br>*Fit new starter motor.<br>*Starter motor was wrong, starter was not messing with ring gear - corrected.<br>*Voltage tests - removed starter motor.<br>*Fitted another new starter motor - had to bolt all earth lead together.<br>*New starter - Works fine.<br>*All earth lead will have to be cleaned up and bolted up to better earthing points.                                                                       | 22/01/2025 |              |
|       | 51418  | Replace failed transmission relay control<br>8343 hours<br>-change out relay control board<br>-put cab back together and test                                                                                                                                                                                                                                                                                                                                                                     | 14/01/2025 | 8343 Hours   |
|       | 50140  | NO A/C - DIAGNOSE & REPAIR<br>No air con, pressure test & found leaking high side hose<br>Hours: 8,089hrs                                                                                                                                                                                                                                                                                                                                                                                         | 13/11/2024 |              |
|       | 48961  | HVIS Inspection - Yearly. Booked in Mudgee 6/11 @ 2:10pm                                                                                                                                                                                                                                                                                                                                                                                                                                          | 6/11/2024  |              |
|       |        | REGO REPAIR DEFECTS<br>- REPLACE X2 STEER TYRES by gregs tyres. Tighten up uni caps. Repair tail light wiring<br>- REPAIR NUMBER PLATE<br>- REPLACE UNI JOINT                                                                                                                                                                                                                                                                                                                                     |            |              |
|       | 48719  | Water Truck - 2000hr Service/Annual<br>Completed 2000 hr service, replaced drive uni joints                                                                                                                                                                                                                                                                                                                                                                                                       | 29/10/2024 | 8032 Hours   |
|       | 49347  | R&M AS PER BELOW:<br>-R/H bumper bent while vehicle was parked by anther vehicle at wast cell<br>-This issue was check last summer, once engine oil gets warm as the day gets hotel and the oil pressure co<br>-Heater fan was to be replaced when dash was done, still stopping and having to tap it to restart it<br>-Spare tyre hold needs to be removed as it is broken<br>-Wiper sprays not working<br>-Cross tubes need reweld<br>-Loud whistle coming from under dash, between 80 to 100km | 17/10/2024 | 8022 Hours   |

| Asset | W/O No                                                                                                                                                                                                   | Description                                                                                                                                                                                                                                                                                                                                                                             | Finished   | Done | Reading |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------|---------|
|       |                                                                                                                                                                                                          | -Electrical wiring security and condition Failed - Intermittent engagement of starter.<br>-R/H middle clearance light still missing<br>-PTO light missing on new dash installation<br>-Engine oil over full<br>-Lights including Head, Stop, Tail, Indicators, work. L/H rear light not working<br>-Cross tubes need reweld<br>-HARD TO START<br>-HEATER N/W<br>-POWER STEERING LEAKING |            |      |         |
| 49294 | HME Inspection                                                                                                                                                                                           | 8020.4                                                                                                                                                                                                                                                                                                                                                                                  | 14/10/2024 | 8020 | Hours   |
| 21294 | A1-750: Ulan West Monthly Part C Inspection                                                                                                                                                              |                                                                                                                                                                                                                                                                                                                                                                                         | 30/09/2024 |      |         |
| 21352 | REPLACE AIR OPERATED BUTTERFLY VALVE                                                                                                                                                                     |                                                                                                                                                                                                                                                                                                                                                                                         | 31/08/2024 | 7897 | Hours   |
| 18715 | R+R TYRES INNER & OUTER ON POS 5<br>POS 5 TYRE FLAT NOT ROUNDS<br>REMOVE AND INSPECT TYRES                                                                                                               |                                                                                                                                                                                                                                                                                                                                                                                         | 8/07/2024  |      |         |
| 48050 | REPAIR DEFECTS, CHARGE OUT DRAG LINK, HEATER CONTROL VALVE NOT WORKING - 32993,37435,32854 - ALEX, ABBY, FRANK                                                                                           |                                                                                                                                                                                                                                                                                                                                                                                         | 28/06/2024 |      | Hours   |
| 47820 | 500hr Service - JACK.L                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                                                                         | 26/06/2024 | 7781 | Hours   |
| 47741 | PART C INSPECTION - ULAN WEST - MONTHLY                                                                                                                                                                  |                                                                                                                                                                                                                                                                                                                                                                                         | 29/05/2024 |      | Hours   |
| 47997 | PART C INSPECTIONS - 32960 - 28.5.2024 - ALEX                                                                                                                                                            |                                                                                                                                                                                                                                                                                                                                                                                         | 28/05/2024 |      | Hours   |
| 47933 | MANUALLY GREASE ARTICULATION PINS, RNR AUTO GREASER, CYCLE AUTO GREASER, RNR MUFFLER - 24725, 34108 - RORY, JOHN H                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                         | 27/05/2024 |      | Hours   |
| 47881 | REPLACE 100a BREAKER WITH 120a - 32148 - 2.5.2024 - DAVID                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                         | 2/05/2024  |      | Hours   |
| 47755 | CHANGE ENGINE BELT, INSPECTED 3 COOLANT LEAKS, REPAIRED 2 LEAKS, NEEDS TO BE RECHECKED - 33328, 32921 - 22.4.2024                                                                                        |                                                                                                                                                                                                                                                                                                                                                                                         | 29/04/2024 |      | Hours   |
| 47698 | DEFECTS, COOLANT, AIRLINE, BENT/BROKEN TAIL LIGHT, CHANGE TYRE, TIGHTENED WATER FILTER, REPAIRED EARTH WIRING, TIGHTEN WATER FILTER, REPAIR STARTER EARTH WIRING - 30957,30851,32474,30842 - RORY, PETER |                                                                                                                                                                                                                                                                                                                                                                                         | 16/04/2024 |      | Hours   |
| 47545 | REMOVE LADDER, INSTALL CONDUITE ON CLEARANCE LIGHT WIRING, P CLAMP UP - 32369,32743,32468 - ALEX,JAYSON,PETER                                                                                            |                                                                                                                                                                                                                                                                                                                                                                                         | 20/03/2024 |      | Hours   |
| 47544 | REMOVE HAYDRAULIC LINES REAR OF BODY, RECONNECT SLEEVE LINES, FLAG FITTED, FRONT HUB OIL CHANGE, REMOVE REAR LADDER FRAME, FILL CAP ON TOP OF BODY, MODIFY MUFFLER TIP - 32297,32355,32298 - CHRIS, ALEX |                                                                                                                                                                                                                                                                                                                                                                                         | 12/03/2024 |      | Hours   |
| 47214 | 250hr Service, REPLACE TRANSMISSION OILS & FILTERS, REPLACE FRONT & REAR DIFF OILS & FILTER, REPLACE HYD FILTER - 32354, 32294 - ALEX, DARCY                                                             |                                                                                                                                                                                                                                                                                                                                                                                         | 8/03/2024  | 7334 | Hours   |
| 47496 | ITS INSPECTION/CHECK OVER/REPAIRS FOR UWO, FIT ID STICKERS, REPAIR WIRING, FIT E-STOP & WIRING, FIT                                                                                                      |                                                                                                                                                                                                                                                                                                                                                                                         | 7/03/2024  | 7334 | Hours   |

| Asset | W/O No | Description                                                                                                                                                         | Finished   | Done Reading |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       |        | FRONT ISOLATOR LOCK, REPLACE BATTERIES                                                                                                                              |            |              |
|       | 47495  | DIAGNOSE START ISSUES - REMOVE & REPLACE STARTER MOTOR - 32335 - ALEX                                                                                               | 28/02/2024 | Hours        |
|       | 47228  | UNBLOCK MUFFLER, REMOVE TURBO PIPE AND TEST, FIND BOOST LEAK, TAKE TRUCK TO HHR FOR A/C CHECK - JOHN HODGES - 24724                                                 | 20/02/2024 | 7270 Hours   |
|       | 47150  | REGISTRATION RENEWAL - QUARTERLY                                                                                                                                    | 29/01/2024 | Hours        |
|       | 47133  | REPAIR FLAT TYRE, MAKE UP SEAT ADAPTER PLATE - 28978, 28048 - ALEX, BOWEN                                                                                           | 18/01/2024 | Hours        |
|       | 47035  | REPLACE SEAT - 28015 - BOWEN                                                                                                                                        | 22/12/2023 | Hours        |
|       | 46571  | 2000hr Service - PETER, FRANK, RORY                                                                                                                                 | 27/11/2023 | 7000 Hours   |
|       | 46579  | REGISTRATION RENEWAL - QUARTERLY                                                                                                                                    | 1/11/2023  | Hours        |
|       | 45195  | HVIS INSPECTION - ANNUAL                                                                                                                                            | 28/09/2023 | Hours        |
|       | 46491  | CHECK OVER FOR REGO, REPLACE DUMP PIPE, REPLACE 1ST DRIVE TORQUE ROD BUSHES, GREASE CHECK LIGHTS, ADJUST BRAKES - 25222, 28889 - RORY, PETER                        | 27/09/2023 | Hours        |
|       | 46492  | REMOVE & REPAIR MUFFLER - MUDGE MUFFLER MAN                                                                                                                         | 26/09/2023 | Hours        |
|       | 46380  | REPLACE PUMP IMPELLOR - 24720 - JOHN                                                                                                                                | 8/09/2023  | 6644 Hours   |
|       | 46225  | 250hr Service, REPLACE BOLTS IN REAR GUARD POST, REPAIR MUFFLER BRACKET - CHRIS, PETER                                                                              | 1/09/2023  | 6613 Hours   |
|       | 46241  | REMOVE & REBUILD PUMP - 24718 - JOHN                                                                                                                                | 7/08/2023  | 6520 Hours   |
|       | 46046  | REGISTRATION RENEWAL - QUARTERLY                                                                                                                                    | 31/07/2023 | Hours        |
|       | 45978  | REPAIR TRACKER - 238534 - RORY                                                                                                                                      | 14/07/2023 | Hours        |
|       | 45530  | 500hr Service - 29291 - ALEX, PETER                                                                                                                                 | 22/06/2023 | 6354 Hours   |
|       | 45507  | REPAIR SPRAY CONTROLS - 24721 - JOHN HODGES                                                                                                                         | 15/05/2023 | 6170 Hours   |
|       | 45348  | REGISTRATION RENEWAL - QUARTERLY                                                                                                                                    | 1/05/2023  | Hours        |
|       | 44823  | 250hr Service, REPLACE TANK STRAPS, REPLACE COOLANT HOSE, REPLACE FRONT DRIVE TYRES, REPAIR TANK BRACKET, REPAIR LADDER SUPPORTS, REPAIR EXHAUST BRAKE - TIM, BROCK | 16/03/2023 | 5940 Hours   |
|       | 44860  | REGISTRATION RENEWAL - QUARTERLY                                                                                                                                    | 30/01/2023 | Hours        |
|       | 44845  | REPLACE BRAKE SWITCHES, REPAIR EXHAUST FLANGE, REWIRE FLASHING LIGHTS, REPAIR DASH - 24717 - JOHN                                                                   | 19/01/2023 | 5628 Hours   |
|       | 44639  | REPAIR BRAKE LIGHTS, DIAGNOSE NO START/NO DRIVE, REPAIR TRANSMISSION WIRING, TEST DRIVE - 24716, 26163 - JOHN, ALEX                                                 | 5/12/2022  | 5417 Hours   |
|       | 44419  | 1000hr Service, TIGHTEN PUMP FRAME & PUMP BOLTS - ALEX, BOWEN                                                                                                       | 3/12/2022  | 5410 Hours   |

| Asset | W/O No | Description                                                                                                                                                                                                                                                         | Finished   | Done | Reading |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------|---------|
|       | 44378  | REGISTRATION RENEWAL - ANNUAL                                                                                                                                                                                                                                       | 31/10/2022 |      | Hours   |
|       | 44352  | REMOVE & REPLACE PUMP SEAL, CLEAN OUT DRIBBLE BAR, ADJUST FAN JETS - 24715 - JOHN                                                                                                                                                                                   | 19/10/2022 |      | Hours   |
|       | 44240  | REPAIR DEFECTS - 89602 - JOHN                                                                                                                                                                                                                                       | 29/09/2022 |      | Hours   |
|       | 44288  | REPAIR TYRE, RE-WIRE REVERSE CAMERA, REPAIR MUDFLAPS, REPAIR CONTROL SWITCHES, SPEED TEST PUMP, ADJUST SPEED, REMOVE PUMP CONTROLLER & CLEAN OUT, RE-ADJUST PUMP SPEED - 25809, 25731, 24713, 24714 - JOHN, BOWEN                                                   | 29/09/2022 | 5129 | Hours   |
|       | 43351  | HVIS INSPECTION - ANNUAL                                                                                                                                                                                                                                            | 30/08/2022 |      | Hours   |
|       | 44137  | REMOVE & REPAIR 2ND DRIVE R/H INNER TYRE, REPLACE LIGHTS, TIGHTEN FUEL TANK BRACKET, TIGHTEN EXHAUST BRACKET, REPAIR OI LEAK, REPAIR AIR LEAK - 21764, 22342 - BEN, TIM                                                                                             | 30/08/2022 |      | Hours   |
|       | 44102  | REBUILD WATER PUMP - 24702, 22340 - JOHN, TIM                                                                                                                                                                                                                       | 25/08/2022 |      | Hours   |
|       | 44054  | DIAGNOSE NO PRESSURE & LEAKING PUMP, REMOVE PUMP, INSPECT SEAL-FAILED AGAIN - 24712 - JOHN                                                                                                                                                                          | 17/08/2022 | 5065 | Hours   |
|       | 43997  | CHECKOVER & REPAIRS FOR REGO, REPLACE UNI IN STEERING, REPAIR EXHAUST LEAK, REPAIR AIR LEAK FROM PARK SWITCH, TIGHTEN U-BOLT ON UNI, REPAIR MARKER LIGHT, ADJUST & GREASE BRAKES, REMOVE WATER PUMP & REPLACE SEALS, RE-FIT PUMP - 22330, 22332, 21621 - TIM, PETER | 11/08/2022 |      | Hours   |
|       | 43959  | CHECK A/C - HRR                                                                                                                                                                                                                                                     | 8/08/2022  |      | Hours   |
|       | 43945  | CHECK HORTON FAN & A/C, RE-ASSEMBLE WATER PUMP, TIGHTEN MUDGUARD BRACKET, CHANGE COOLANT FILTER - 21541, 21544 - CHRIS                                                                                                                                              | 28/07/2022 | 5057 | Hours   |
|       | 43896  | REPLACE STARTER MOTOR, CHANGE DIFF & TRANS OILS, REPAIR BULK WATER PUMP LEAK - 21537 - CHRIS                                                                                                                                                                        | 22/07/2022 | 5057 | Hours   |
|       | 43864  | FIT NEW EXHAUST MANIFOLDS, CHECK A/C, DIAGNOSE START ISSUE, CLEAN EARTH POINTS TO CHASSIS, REPLACE ISOLATOR, DIAGNOSE FAN ISSUE, FIT SHORTER MUDFLAPS, GREASE FRONT END - 21528, 21529, 21534 - CHRIS                                                               | 15/07/2022 | 5015 | Hours   |
|       | 43554  | 250hr Service - CHRIS                                                                                                                                                                                                                                               | 8/07/2022  | 5010 | Hours   |
|       | 43837  | REPAIRS - REPLACE EXHAUST MANIFOLD - DAVID                                                                                                                                                                                                                          | 8/07/2022  |      | Hours   |
|       | 43828  | REMOVE & REPLACE GUARDS, DIAGNOSE EXHAUST LEAKS, REMOVE MANIFOLD - 21520 - CHRIS                                                                                                                                                                                    | 7/07/2022  |      | Hours   |
|       | 43473  | REPLACE CLEARANCE LIGHT, REPAIR WASHERS, ADJUST HEADLIGHTS, MAKE WHEEL CHOCK BRACKET, FIT NEW STEER TYRES, REMOVE RADIO SPEAKER, REPLACE PIPE REFLECTORS, REMOVE & REBUILD DASH - 24704, 24707, 24708 - JOHN                                                        | 6/05/2022  |      | Hours   |
|       | 43064  | 500hr Service, FIT ID STICKERS - PETER, ALEX                                                                                                                                                                                                                        | 8/03/2022  | 4602 | Hours   |
|       | 43096  | REPAIR SPRAY - FURNEY'S BUILDING & PLUMBING                                                                                                                                                                                                                         | 15/02/2022 |      | Hours   |
|       | 43007  | CHANGE STEER TYRE ONSITE - 20932 - TIM                                                                                                                                                                                                                              | 10/02/2022 |      | Hours   |

| Asset | W/O No | Description                                                                                                                                                                     | Finished   | Done Reading |
|-------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|--------------|
|       | 43005  | SERVICE, FIT FIRE EXTINGUISHER BRACKET TO REAR, MOUNT WHEEL CHOCKS, MOUNT WHEEL NUT INDICATORS, REPLACE GLOBE IN REAR BEACON, TOP UP HYD OIL - 23814, 23362, 23370 - ALEX, GABI | 20/01/2022 | Hours        |
|       | 43006  | REMOVE & REPLACE DRAG LINK - 23787 - PETER                                                                                                                                      | 7/12/2021  | Hours        |