

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0748		Komatsu HM300-2 ADT		
	194400	Replace front left tyre	13/07/2026	Hours
	192965	ADT HM300-2 - Hepa - 500hr Service Done @ 13653hrs	5/05/2026	13653 Hours
	191944	ADT HM300-2 - Hepa - 500hr Service Done @ 12155	26/03/2026	Hours
	191438	no A/C and seat no good Bwise	2/03/2026	Hours
	191240	Kom 748 Body lever not working Bwise	23/02/2026	Hours
	60980	Kom 300 Seat wont adjust Gwindle	18/02/2026	Hours
	55787	ADT HM300-2 - Hepa - 1000hr Service at Orchard Hills 33169 Hrs - Fuel primer on fuel pump leaking diesel - RH Side light out on roof - Slack adjuster has damaged dust boot - Fuel breather perished - Fuel sender loom has damage to conduct - LHF tyre has gashes - Middle LH tyre has gash on inside - RHF tyre has deep gouge & cracks - Eng really sooty down low without to much load - Rub pin carrier bent	7/07/2025	12595 Hours
	55277	Machine stuck in second gear. (Garde - Orchard Hills) - Machine felt as if brakes were grabbing - Found transmission oil to be low - Cleaned around brake pedal assembly for dirt - Tim delivered trans 30 oil to site - Topped up transmission with 20L if trans 30 oil - Brake lights were constantly on - Believe brakes to be stuck on - Continually operated the brake pedal - Had to manually force brake pedal upwards until pedal popped into correct position - Cleaned down spool and lubricated well, it is now moving freely - Machine now shifting gears - Test & operate - Machine all okay	3/06/2025	Hours
	55763	Capital Repairs - #Refurbish Tub	30/04/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	52396	Replace batteries. Inspect and repair hydraulic oil leak at Orchard Hills. Replace tub cylinder bearings	26/03/2025	Hours
		(LHS cyldinder barrel end bore worn, bearing pushes in. Missing spacer. Pin worn. RHS cylinder barrel end missing both spacers)		
	53388	ADT HM300-2 - Hepa - 500hr Service 12588hrs - Repair hydraulic oil leak - Diagnose issue with oil leak - Take off pannels under wheel arche and find issue - Grease tail shafts - Tub cylinder bearings in top are worn and hanging out - Remove & replace & reseal leaking hydraulic pipe - Inspect grease pump fault - Found and cleaned dirty connector	20/03/2025	12588 Hours
	51688	Wash. Guarde pre-hire. Re-seal brake accumulator - LHS.	22/01/2025	Hours
	48147	Pre hire repairs as per HME inspection. w/o 48076 BACKCHARGE Replace LH bottom mirror \$190.23 BACKCHARGE Clean cab \$70 Check fire extinguishers Check fire suppression Replace radio Fit safety stickers as required Check and top up levels, finals and diffs need top up Paperwork, fulcrum photos	28/10/2024	12350 Hours
	48076	HME Inspection - Articulated Dump Truck Quote #: 190	6/09/2024	12343 Hours
	18733	Diagnose repair electrical fault Slow to power machine up, park brake applied while driving unable to start after isolating machine Dismantle cab & test all powers. Further testing 11/7/24. Remove turbo timer & repair cab earth. Reassemble & test.	11/07/2024	12230 Hours
	17982	Pre hire repairs as per HME inspection, W/O 17917. Clean cab Check and tag fire suppression Fit seat covers Repair LHS middle blinker Replace radio & antenna Grease machine	1/07/2024	12213 Hours

Asset	W/O No	Description	Finished	Done Reading
		Auto greaser fault, fill and test Fit QR stickers Remove old client stickers Check all levels Replace trans filter hose Replace leaking breather hose RHS Top up diff/ final drive oils Replace missing drive shaft covers Repair oil leak on bung under cab Repair leaking couplers RHF, tighten Replace brake hose on LHS Replace hose in artic Fit spring to artic hoses Repair drivers door handle Replace 2x a/c vents in cab		
	15222	Replace drive shaft bolts / Supply sun gear circlip @A1 PARTS ONLY	30/06/2024	Hours
	17917	HME Inspection - Articulated Dump Truck Quote #: 128	12/06/2024	12213 Hours
	14884	Supply front axle shaft from P0770 Remove and replace driveshaft seal, fit repaired shaft	14/05/2024	Hours
	9456	SUPPLY PARTS ONLY Supply 2000hr service kit Inside door latch handle	22/03/2024	Hours
	7903	Pre hire repairs as per HME inspection. Fit tracker Clean cab Check and tag fire extinguishers move reverse alarm to outside Fit operators manual Fit seat cover Repair front park lights Repair LH headlight Fit new wiper blades Replace washer bottle, test washers Fit new brake pedal cover or grip tape Grease machine manually Connect grease lines, repair auto greaser Fit stickers as required Hi vis tape as required Check cooling system for leaks, top up bottle Blow out radiator Replace pos 1 axle seal Replace front drive shaft uni joints Replace 3x couplings on RHS front	29/01/2024	11881 Hours

Asset	W/O No	Description	Finished	Done Reading
		Reseal relief valve on EPC valve Replace rear track rod, bent badly Replace bush and seals in left and right steer cylinder, live end Replace barrel end bushes in left and right tub cylinders Repair/replace headboard, patch hole in front of tub Replace faded e stops Paint tow points/ tub locks red Remove and blank off window switch Wash machine Fit wheel nut indicators		
	7828	HME Inspection - Articulated Dump Truck Quote #: 37	6/12/2023	11881 Hours
	7455	Check over / 250hr service	25/11/2023	Hours
	7613	Weld Hydraulic Pressure Pipe	20/11/2023	11732 Hours
	6898	Install New Headlights	7/11/2023	11604 Hours
	6847	Replace Pos 5&6 Tyres	6/11/2023	11604 Hours
	6364	Articulated Dump Truck - 500hr Service	22/10/2023	11530 Hours
	5617	Repair operator seat.	4/10/2023	Hours
	3751	Auto Greaser Fault	24/09/2023	
	5287	Minor R&M 25.09.2023 - 01.09.2023 Quarterly inspection	15/09/2023	Hours
	4879	Supply canvas seat cover. Fix Handrail No hour reading available.	13/09/2023	Hours
	5185	Remove door & adjust linkages, straighten brackets	10/09/2023	11212 Hours
	4445	2x new tryes	13/08/2023	
	3075	July - Minor R&M HME inspection	8/07/2023	
	2455	1000hr service	4/06/2023	
	2431	1000hr service	4/06/2023	
	2468	Prep for service, pick filters	3/06/2023	
	2282	Straighten tub position sensor, refit.	17/05/2023	
	1805	Gear selector diff breather issue	23/04/2023	

Asset	W/O No	Description	Finished	Done Reading
	1568	Fixed steering column issue	9/04/2023	
	1843	Repair door and window fault	23/03/2023	
	1406	Air conditioning	22/03/2023	
	1400	Aircon problem	21/03/2023	
	1497	Top up air conditioning	12/03/2023	
	1518	Regas air con	10/03/2023	
	1609	Service and defects	6/03/2023	
	1649	Top up fluids	11/02/2023	
	11261	1000hr service.	15/09/2022	Hours
	11256	Change batteries, fit door latch, repair lights	10/09/2022	Hours
	11258	Check brakes - staying on, clean dirt and rocks away from foot pedal.	4/07/2022	Hours
	11253	Repair RHS headlight, refit seat slide handle.	26/06/2022	Hours
	11248	R+R left hand headlight globe, adjust door.	23/06/2022	Hours
	11247	1000hr service.	2/06/2022	Hours
	11244	Check all F/D, drive lines and unis - ok, grease all drive line units, torque all wheel nuts and complete pre-hire paperwork.	12/03/2022	Hours
	11241	500hr service, moving checks, inspect drive shafts, fitted mirror, tied up artic hoses, fit lower RHS mirror, check final and diff mags, unblock washer bottle.	25/01/2022	Hours
	11240	Diff and assist mechanic.	22/10/2021	Hours
	11238	Assemble wheel end with new bearings and seals.	17/09/2021	Hours
	11237	Re-fit greaser components to sales machine (P740).	13/09/2021	Hours
	11230	Repair auto greaser, remove pumping element from wrecker and fit - checked operation, ok. Found delivery hose holding 500 psi - remove, check and flush. Refit and checked operation - still going over relief. Remove delivery valve block - found all passages blocked. Unblocked all passages, refit and rechecked - still going over relief. Swap delivery block with wrecker, checked - ok. Re-assemble system.	10/09/2021	Hours
	11219	Complete all site paperwork and Maas paperwork. Fit safety stickers, fit wheel nut indicators, repair rear window washer and replace wipers.	9/09/2021	Hours
	11218	Fitted windscreen wipers, fitted tub tilt sensor, cleaned out cab and tub.	9/09/2021	Hours
	11217	bring machine to workshop and check over before hire. Found auto greaser not building pressure, pump element u/s, start on pre hire paperwork.	8/09/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	11216	Clean out dirt in tub.	8/09/2021	Hours
	11215	Pump up tyres, replace and adjust rod for tub alarm.	17/08/2021	Hours
	11214	Removed tub sensor, picked up coolant overflow bottle and travelled to site, fitted to machine.	14/07/2021	Hours
	11213	Fitted up new tilt angle sensor.	2/07/2021	Hours
	11212	Removed seat and fitted.	27/01/2021	Hours
	11239	Carry out check over and fill greaser.	21/01/2021	Hours
	11211	Replaced seat covers.	18/11/2020	Hours
	11210	Clean out evaporator.	14/11/2020	Hours
	11209	Fit DPF and swap guards.	9/11/2020	Hours
	11207	Start machine, organise parts, condition report, check service history.	18/10/2020	Hours
	11208	Straighten guards.	14/10/2020	Hours
	11206	Remove covers, remove muffler for diff installation, start repair of fuel tank step.	13/10/2020	Hours
	11205	Check repairs check, pre-hire paperwork. Check and tag fire suppression.	11/09/2020	Hours
	11204	Check for repairs/paperwork.	10/09/2020	Hours
	11203	Handrails - cut, paint, fan and install.	3/09/2020	Hours
	11202	Fit suspension block, fix front window washer set, fix operators reading light, finish pre-hire paperwork.	1/09/2020	Hours
	11201	Complete paperwork, clear rear window washer - order front set.	24/08/2020	Hours
	11196	Bolt belly guards, weld hinges on belly guard Change Am/FM radio antenna Fit stickers, test fire suppression Fit new lights Clear water lines, pump up U/S	22/08/2020	Hours
	11192	Fit UHF and seal Fix tail light problems Attempt to straighten RH step guard Refit seat Fit bonnet latch (from another machine) Fit tail light cushion Refit guards	21/08/2020	Hours
	11200	Check/top up wheel ends, adjust door latch.	20/08/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	11188	Drain hyd tank Repair/replace switch on seat Check change brake accumulator Replace flex coupling Straighten bonnet Straighten worklight guards Replace door strut bracket Fill hyd tank	20/08/2020	Hours
	11187	change LH bumper, replace coolant, fill auto greaser, weld extinguisher mounts and fit tag.	19/08/2020	Hours
	11185	Start to remove LH nose cone.	18/08/2020	Hours
	11184	Jump start, remove belly guards.	18/06/2019	Hours