

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0259		Mack Trident Tipper		
	51713	prep for sale	16/01/2025	KM
	20641	x1 TYRE REPAIR done by Gregs Tyres Odo: 771,018km	6/08/2024	KM
	19725	REPAIR AIR LEAK AT 1ST DRIVE AXLE	30/07/2024	KM
	18426	Tipper - Truck B2 Service (60,000kms) Replaced uni in front drive shaft 778107km	8/07/2024	KM
	48025	RNR CLUTCH - 34145,34146,34772 - PETER,RORY	20/06/2024	KM
	48012	R AND R CLUTCH - 34771 - PETER	19/06/2024	KM
	47931	REPAIR WATER LEAK - 32959, 32956 - ALEX	27/05/2024	KM
	47695	REMOVE TFO UNIT, COULD NOT FIND TRACKER, PULL ALL RUBISH, BOOMS, A1 DOCUMENTS, TAGS CARDS - 34425 - DARCEY	13/04/2024	KM
	47493	REPAIR STEERING COLUM LOCK - 30925 - RORY	21/02/2024	KM
	47444	CHANGE INTAKE HOSE ON TURBO - 32323 - ALEX MACKAY	21/02/2024	KM
	47149	REGISTRATION RENEWAL - QUARTERLY	29/01/2024	KM
	47083	REPLACE CAB AIR BAG HEIGHT VALVE, REPLACE CAB BLOWER FAN - 32224, 28036 - CHRIS, BOWEN	11/01/2024	766053 KM
	47032	REPLACE BLOWN AIR BAG - 25657 - DAVID	5/01/2024	KM
	47031	REMOVE & REPLACE WASHER BOTTLE, CLEAN WASHER PUMP, REPAIR CAB AIR BLOWER SPEED CONTROL, REMOVE & REPLACE BATTERIES - 32211 - CHRIS	2/01/2024	KM
	47030	JUMP START TRUCK, DIAGNOSE & REPAIR STARTING ISSUES - 25544, 25545 - FRANK	19/12/2023	KM
	46902	DIAGNOSE & REPAIR CAB BLOWER FAN FAULT - 29894, 29695 - BOWEN, CHRIS	6/12/2023	763262 KM
	9140	Repairs & Maintenance completed by A1 Earthworx 6/11/23 WO# 24224: remove & replace A/C hose, regas 21/11/23 WO# 24295: replace headlight globes, replace RH bonnet strap, re-torque all tyres 30/11/23 WO# 24365: repair air leak, re-tension tarp cables, replace shifter boot, check over 6/12/23 WO# 24391: diagnose & repair cab blower fan fault	6/12/2023	763262 KM

Asset	W/O No	Description	Finished	Done Reading	
	46876	REPAIR AIR LEAK, RE-TENSION TARP CABLES, REPLACE SHIFTER BOOT, CHECK OVER - 29884, 31759 - BOWEN, JAYSON	30/11/2023	763009	KM
	46806	REPLACE HEADLIGHT GLOBES, REPLACE R/H BONNET STRAP, RE-TORQUE ALL TYRES - 25311, 31840 - RORY, PETER	21/11/2023		KM
	46735	REMOVE & REPLACE A/C HOSE, RE-GAS - HRR	6/11/2023		KM
	46705	REPLACE STEER TYRES, CHECK OVER FOR AIR LEAKS, REPLACE TABLET BRACKET - 31815 - PETER	2/11/2023		KM
	9138	Repairs & Maintenance completed by A1 Earthworx 15/9/23 WO# 23911: adjust clutch, set cruise toggle switch 18/9/23 WO# 23945: diagnose & repair derating fault 28/9/23 WO# 23978: diagnose & repair fuel system fault 4/10/23 WO# 24019: prep and re-weld mudflap bracket 28/10/23 WO# 24107: drain LH fuel tank, fit new screw clips behind kick panel, diagnose & repair fuel system fault, re-assemble front end of truck 2/11/23 WO# 24194: replace steer tyres, check over for air leaks, replace tablet bracket	2/11/2023		KM
	46578	REGISTRATION RENEWAL - QUARTERLY	30/10/2023		KM
	46618	DRAIN L/H FUEL TANK, FIT NEW SCREW CLIPS BEHIND KICK PANEL, DIAGNOSE & REPAIR FUEL SYSTEM FAULT, RE-ASSEMBLE FRONT END OF TRUCK - 29761, 31801, 29848, 29850, 29852, 26698 - ALEX, PETER, BOWEN, CHRIS	28/10/2023		KM
	46391	15,000 km Service, TIGHTEN YOKE & U-BOLTS - PETER, BOWEN	18/10/2023	755397	KM
	9139	Tipper - Truck A Service (15,000kms) completed by A1 Earthworx WO# 23880 - tighten yoke & u-bolts	18/10/2023	755397	KM
	46530	PREP & RE-WELD MUDFLAP BRACKET - 29746 - ALEX	4/10/2023	753148	KM
	46489	DIAGNOSE & REPAIR FUEL SYSTEM FAULT - 28890 - PETER	28/09/2023	752245	KM
	46456	DIAGNOSE & REPAIR DERATING FAULT - 25206 - RORY	18/09/2023		KM
	6980	Repairs & Maintenance completed by A1 Earthworx 2/8 WO# 23613 reassemble engine to transport to WTG Dubbo 22/8 WO# 23750 diagnose electrical issues, remove & replace 1&2 injectors, remove & replace brake solenoid, carry out valve adjustment, clear all fault codes & reprogram injectors, remove & replace starter solenoid, test operation, replace radiator, fill cooling system with coolant & pressure test, repair exhaust leak (Western Truck Group) 23/8 WO# 23771 diagnose high beam coming on with blinker, repair headlight wiring, wash 31/8 WO# 23814 repair clutch air assist cylinder 15/9 WO# 23911 adjust clutch, set cruise toggle switch 18/9 WO# 23945 diagnose & repair derating fault	18/09/2023	750445	KM

Asset	W/O No	Description	Finished	Done Reading
	46422	ADJUST CLUTCH, SET CRUISE TOGGLE SWITCH - 29645 - CHRIS	15/09/2023	750445 KM
	46325	REPLACE CLUTCH AIR ASSIST CYLINDER - 26679 - CHRIS	31/08/2023	KM
	46282	DIAGNOSE HIGH BEAM COMING ON WITH BLINKER - REPAIR HEADLIGHT WIRING, WASH - 26667, 28288 - CHRIS, BOWEN	23/08/2023	KM
	46261	DIAGNOSE ELECTRICAL ISSUES, REMOVE & REPLACE 1 & 2 INJECTORS, REMOVE & REPLACE BRAKE SOLENOID, CARRY OUT VALVE ADJUSTMENT, CLEAR ALL FAULT CODES & REPROGRAM INJECTORS, REMOVE & REPLACE STARTER SOLENOID, TEST OPERATION, REPLACE RADIATOR, FILL COOLING SYTEM WITH COOLANT & PRESSURE TEST, REPAIR EXHAUST LEAK - WESTERN TRUCK GROUP	22/08/2023	746587 KM
	46124	RE-ASSEMBLE ENGINE TO TRANSPORT TO WTG DUBBO - 26649, 28269 - CHRIS, BOWEN	2/08/2023	746587 KM
	46063	INVESTIGATE INJECTOR FAULTS, TEST ENGINE HARNESS - NO FAULTS FOUND, SUSPECT FAILED ECM - 26647 - KEEVILS, CHRIS	31/07/2023	746587 KM
	46030	REGISTRATION RENEWAL - QUARTERLY	27/07/2023	KM
	46088	MAKE UP TESTING HARNESS FOR INJECTORS, TEST INJECTORS, REMOVE & REPLACE ENGINE & A/C BELTS, INSTALL NEW FAN SHROUD, REMOVE & INSPECT FAN HUB, BOLT UP TURBO WITH NEW GASKETS & BOLTS, HOOK UP ALL OIL & COOLANT LINES, RE-RUN INJECTOR HARNESS BACK INTO HEAD & CONNECT, CLEAN DIRT FROM AIR DRYER, INSPECT CLUTCH CABLE, REPAIR AIR LEAK WHEN CLUTCH ENGAGED, CHANGE OUT TORQUE RODS, PULL OUT AIR ASSIST CYLINDER & TEST FOR CLUTCH, REPLACE HEADLIGHTS, INSPECT CLUTCH WEAR - 26637, 28251, 26639, 28254, 28258, 26641 - CHRIS, BOWEN	26/07/2023	KM
	46009	REMOVE HOSES & BLOCK, REMOVE FAN & FAN SHROUD, DRAIN COOLANT, REPLACE WINDOW REGULATOR, REPLACE CLUTCH CABLE, REMOVE TURBO, EGR & MANIFOLD, CLEAN UP ALL MOUNTING SURFACES, RE-FIT NEW MANIFOLD WITH NEW GASKET, RE-FIT EGR WITH NEW GASKETS & BOLTS - 28249, 28250 - BOWEN	21/07/2023	746587 KM
	45975	REPAIR FLAT L/H FLAT TYRE, DIAGNOSE ENGINE MISS, TEST HARNESS, RE-CHECK INJECTORS & TEST - 0033, 26634, 26635 - DANNY, CHRIS	14/07/2023	746587 KM
	45908	REPAIR FAULTY WIRE AT SPEED SENSOR, TEST - 0028 - DANNY	5/07/2023	KM
	45842	REPAIR OIL LEAK AT COMPRESSOR, REPLACE 4 DRIVE TYRES REAR AXLE & RE-TENSION - 28613, 28325, 28227 - DAVID, BOWEN, BROCK	30/06/2023	743778 KM
	45786	REPLACE INTAKE HOSE, REPLACE HORTON FAN, REPLACE L/H 1ST DRIVE SHOCK - 29285 - PETER	20/06/2023	741405 KM
	45690	REPAIR ELECTRICAL PLUG WIRING - 26575 - ALEX	1/06/2023	KM
	45605	REPLACE FRONT STEER TYRES - 27567, 26491 - BROCK, CHRIS	17/05/2023	KM
	45604	FIT & ACTIVATE TFO TRACKER - 29245 - PETER	16/05/2023	KM
	45333	15,000 km Service, TIGHTEN 1ST DRIVE YOKE NUT, TIGHTEN L/H REAR U-BOLTS, REPAIR AIR LINE FOR CLUTCH - 27459 - PETER, RORY	16/05/2023	734734 KM
	45466	CHEANGE 2 TYRES, FIT NEW TFO TRACKER, REPLACE HUB SEAL & WHEEL BEARINGS - 29301 - TIM	4/05/2023	KM
	45330	REGISTRATION RENEWAL - QUARTERLY	24/04/2023	KM

Asset	W/O No	Description	Finished	Done Reading
	45392	TIGHTEN RADIATOR HOSE CLAMPS, REPLACE STRIPPED BOLT FOR COOLING PIPE, REPLACE DAMAGED SECTION OF SERVICE BRAKE HOSE - 26347, 26438, 26264 - BOWEN, CHRIS, DAVID	17/04/2023	KM
	45283	REPAIR BLOWER FAN WIRING - 26510 - ALEX	4/04/2023	KM
	45214	REPAIR AIR LEAK ON COMPRESSOR, REPLACE INTERCOOLER, REPAIR DEFECTS - 27673, 27094 - PETER, ALEX	24/03/2023	KM
	45078	REPLACE TARP SLIDES & CABLES - 27640 - PETER, DAVID	2/03/2023	KM
	44923	15,000 km Service, REPAIR INTERCOOLER LEAK, REPLACE HEIGHT VALVE, REPAIR AIR LEAK, INSPECT EXHAUST BRAKE, REPAIR FRONT GRILL, WELD/REPAIR L/H/R BODY MOUNT, REPAIR WINDSCREEN WASHERS - 25877, 26983 - BOWEN, TIM	17/02/2023	714541 KM
	44966	FIT AIR DRYER KIT - 27612 - PETER	10/02/2023	KM
	45028	REPAIR DRIVE LINE NOISE - FOUND RIDE HEIGHT VALVE ON REAR SUSPENSION TO BE OVER INFLATING AIRBAGS, THROWING DRIVELINE ANGLES OUT. REMOVE & REPLACE RIDE HEIGHT VALVE, SET RIDE HEIGHT & ANGLES. TEST DRIVE - HI-TORQUE	3/02/2023	714504 KM
	44885	CLEAN OUT AIR DRYER - 25859 - TIM	1/02/2023	KM
	44859	REGISTRATION RENEWAL - QUARTERLY	30/01/2023	KM
	44802	REPLACE BOTTOM RADIATOR HOSE & FILL WITH COOLANT, REPLACE L/H 1ST DRIVE BOOSTER, TEST STARTER MOTOR, REMOVE & REPLACE STARTER MOTOR, REMOVE & REPLACE BATTERY TERMINALS, ADJUST CLUTCH, REMOVE & REPLACE 1ST DRIVE SLACK ADJUSTERS, REMOVE & REPLACE REAR SLACK ADJUSTERS, ADJUST BRAKES, TENSION WHEELS, FIT NEW TFO TRACKER, ADJUST TARP, REPAIR AIR LEAK IN CAB - 26770, 26772, 26773, 26774 - PETER	13/01/2023	KM
	44680	DIAGNOSE/ADJUST BRAKES, TEST - 26837 - BEN	16/12/2022	KM
	44637	ADJUST BRAKES, REPAIR BRAKE SLACK ADJUSTERS, CLEAN BRAKE SHOES & DIFF AREA - 26074, 26076 - CHRIS	6/12/2022	KM
	44470	REMOVE OLD GPS SYSTEM & FIT NEW TRACKER - 26709 - PETER	10/11/2022	KM
	44388	60,000 km Service, REPLACE A/C BLOWER FAN, REPLACE R/H/F PARKER GLOBE - 26125 - PETER, DAVID	10/11/2022	699750 KM
	44381	REGISTRATION RENEWAL - QUARTERLY	31/10/2022	KM
	44405	REMOVE SEAT AND REPAIR AIR LEAK, RE-FIT NUMBER PLATE, REPAIR HYD SUCTION LINE & REFILL HYD OIL, REPLACE MUDFLAP, INSPECT BLOWER FAN IN CAB - 25834, 21791, 26022 - TIM, BEN, CHRIS	28/10/2022	KM
	44349	REPLACE TARP RELAY & WIRING, ADJUST TARP - 25818 - TIM	10/10/2022	KM
	44284	RELINCE CENTRE OF PITMAN ARM ON STEERING BOX, REPAIR WIRING TO BOTH DIFFS, INSPECT EXHAUST GAS TEMP SENSOR, WELD CRACK ON REAR OF BIN, MOVE UHF - 25816 - TIM	6/10/2022	KM
	44190	REPLACE POWER STEERING BOX, CHECK/ADJUST STEERING, ADJUST STEERING WHEEL, RE-FIT RADIATOR, TORQUE R/H/F WHEEL, REPAIR WHEEL BRUSH - 25721, 22355, 21658 - BOWEN, TIM, PETER	16/09/2022	KM
	43924	HVIS INSPECTION - ANNUAL	14/09/2022	KM

Asset	W/O No	Description	Finished	Done Reading
	44135	REPLACE 2 FRONT TYRES, REPLACE LIGHTS AND REPAIR WIRING, R/H/L AIRBAG REPLACED, TIGTEN U-BOLTS & AIRBAG BOLTS, ADJUST BRAKES, GREASE, REBUILD RINGFEEDER, REPLACE MUDFLAP, TIGHTEN BOOSTER, REPLACE TIE ROD END, REMOVE DRAG LINK & POWER STEERING, REPLACE BOLTS IN AIRBAG BEAM - 22343, 25707, 22344 - TIM, BOWEN	1/09/2022	KM
	44106	DIAGNOSE START ISSUES, REMOVE & REPLACE ECU & PROGRAM, REMOVE & REPLACE ALL BATTERIES & ONE NEGATIVE TERMINAL, REMOVE & REPLACE SAFETY RELIEF VALVE - WESTERN TRUCK GROUP	26/08/2022	691938 KM
	44098	DIAGNOSE NO START ONSITE-ECM FAILURE - 24337, 24338 - DAVID	23/08/2022	KM
	43976	REGISTRATION RENEWAL - QUARTERLY	10/08/2022	KM
	43995	CHECK OVER FOR REGO, REPLACE MISSING FRAME BOLTS, REPAIR TIE ROD CLAMP, DIAGNOSE ADR35 FAULT, REMOVE & REPLACE DRYER UNIT, TRACK/TRACE AIR SYSTEM, REMOVE & REPLACE PARK BRAKE RELEASE VALVE, TEST ADR35 SYSTEM, REASSEMBLE CAB, REPAIR DAMAGED AIR FITTINGS - 21735, 21736, 21738 - BEN	10/08/2022	KM
	43965	REPAIR DEFECTS, REMOVE & REPLACE CLUTCH CYLINDER ENDS, REPAIR BELLHOUSING BOLT, REMOVE & REPLACE FRONT & REAR ENGINE MOUNTS, REPLACE CAB SHOCK, REPLACE TAILSHAFT CENTRE BEARING, REPLACE DOOR LATCH, REMOVE L/H 1ST DRIVE WHEEL TO CLEAN ALL COMPONENTS, REPLACE BRAKE SHOES & HUB SEAL, RE-FIT WHEEL & RE-TENSION, RE-FIT FUEL TANKS & RE-PLUMB, HOOK UP HYD LINES, FILL HYD OIL, REPLACE CAB AIR BLOWER, REPAIR OIL LEAK FROM COMPRESSOR, ADJUST BRAKES, REPAIR AIR LEAKS ON FIREWALL, INSPECT FRONT STEERING/SUSPENSION, REPAIR AIR TANK DRAINS, TEST/ADJUST CLUTCH, CHANGE GEARBOX OIL, CHECK R/H/F BLINKER - 24879, 24880, 2173, 24316, 24882, 24883, 21733, 24884, 21734 - BEN, ALEX, DAVID	5/08/2022	691214 KM
	43944	CHECK OVER FOR REGO - 21605 - PETER	26/07/2022	KM
	43723	15,000 km Service, INSPECT FOR TRANSMISSION NOISE - 24687 - BEN, PETER	1/07/2022	684148 KM
	43787	REPAIR COOLANT LEAK - 24858 - ALEX	29/06/2022	KM
	43738	ADJUST BRAKES - 22294 - BEN	22/06/2022	KM
	43676	REPLACE 8 DRIVE TYRES - 21501 - CHRIS	7/06/2022	677895 KM
	43661	REPLACE DRIVE TYRES - 22271 - BEN	7/06/2022	KM
	43590	REPAIR L/H 2ND DRIVE OUTER TYRE - 24653 - PETER	23/05/2022	KM
	43516	DIAGNOSE ELECTRICAL WARNING LIGHT, REMOVE & CLEAN OUT EGR SENSORS, TEST DRIVE-TRUCK HAD FULL POWER, REPLACE STEREO ANTENNA & LEAD, INSPECT TRUCK FOR DEFECTS, REPAIR HEADLIGHT, REPLACE PARK LIGHT BULBS - 24914, 22242 - DAVID, BEN	12/05/2022	KM
	43472	FIT NEW TYRES TO RIMS, REPLACE HEATER FAN, REPAIR L/H REAR INNER TYRE - 24705, 20980, 24638, 24640 - JOHN, TIM, PETER	4/05/2022	KM
	43439	TIGHTEN FRONT GUARDS - 22229 - BEN	28/04/2022	KM
	43318	DIAGNOSE START ISSUE, TIGHTEN TERMINAL FROM START REALY TO STARTER MOTOR, REPLACE WIPER MOTOR, TEST TARP - 24554, 24621 - DAVID, PETER	7/04/2022	668154 KM

Asset	W/O No	Description	Finished	Done Reading
	43134	15,000 km Service, REPLACE STEERING SHAFT UNI'S, REPLACE AXLE TEMP GAUGE, REPLACE RADIO, REPLACE SEAT, REPLACE GEAR STICK BUSH, ADJUST BRAKES, STRAIGHTEN STEERING WHEEL, REPAIR AIR LEAK, REPLACE TARP CABLE, WASH & CHECK OVER, REPAIR DOOR SEAL - 23872 - ALEX, TIM	24/03/2022	666677 KM
	43262	TOP UP HYD OIL, REMOVE & REPLACE AIR TANK DRAIN BUNG - 23862 - ALEX	15/03/2022	KM
	43194	REPLACE R/H TAIL LIGHT - 23692 - PETER	9/03/2022	KM
	43046	DIAGNOSE ENGINE LIGHT AND LOW POWER, REMOVE & REPLACE FAULTY TURBO, CALIBRATE & CHECK OPERATION, TEST DRIVE, REMOVE & REPLACE FAULTY SENSOR, CHECK FOR LEAKS ON TURBO - WESTERN TRUCK GROUP	21/02/2022	658767 KM
	43051	REPAIR BROKEN AIR TANK BRACKETS, CLEAN OUT EGR SENSORS, READ & CLEAR FAULT CODES, INVESTIGATE TURBO AGT ACTUATOR FAULT - 23594, 23669, 24417, 23672 - DAVID, PETER, GABI	17/02/2022	KM
	42997	TIGHTEN TARP CABLES - 23844 - ALEX	11/02/2022	KM
	42975	SERVICE & RE-GAS A/C - HRR	10/02/2022	KM
	42957	REPLACE HETAER HOSE ON FIREWALL, CLEAN & CHECK EGR & INTAKE SENSORS, REPLACE 3RD AXLE R/H OUTER TYRE - 23654, 23393 - PETER, GABI	4/02/2022	KM
	42917	REPLACE STEER TYRES - 23647 - PETER	28/01/2022	KM
	42858	REPLACE HYD FITTING FOR TRAILER, REPLACE A/C CONDENSOR & DRIER, REPAIR FRONT GRILL, REPLACE BONNET HINGE BUSHES, ADJUST FRONT BUMPER, CHECK/TEST WIRING FOR DIFF SENSORS - 23363, 23821, 23551, 23639 - ALEX, PETER, DAVID, GABI	20/01/2022	KM
	42744	15,000 km Service, REPLACE INDICATORS, REPLACE CROOF CLEARANCE LIGHT, CONNECT HORS, REPLACE R/H E-STOP, TIGHTEN 1ST DRIVE DIFF YOKE NUTS, RESEAL REAR HYD FITTINGS, RELACE FROM JACK SHAFT UNI - 23811, 23360 - ALEX, GABI, PETER	14/01/2022	649176 KM
	42704	MAKE NEW MUDGUARD BRAKET, REPLACE 2 REAR MUDFLAPS - 20766, 20774 - ALEX	16/12/2021	KM
	42672	RE-SKIN TRUCK - 0617, 0618, 0619, 0658, 0659, 0660, 0647, 0662, 0620, 0661, 0662, 0616 - BCB ENGINEERING	10/12/2021	KM
	42580	REPLACE STEERING COLUMN STRUTS, REPLACE COOLANT LEVEL SENSORM REPLACE HEADLIGHT GLOBE - 23327, 23334 - GABI, ALEX	26/11/2021	KM
	42502	CHECK STEERING COLUMN LOCKING STRUTS - 23311 - GABI	11/11/2021	643345 KM
	42463	REPLACE FAILED BOOST HOSE ONSITE - 20851 - DAVID	1/11/2021	642427 KM
	42284	CLEAN ALL EGR SENSORS & PIPES, CLEAR FAULT CODES, REPAIR GRILL, RE-FIT BOOST HOSE, REPAIR FRONT BUG DEFLECTOR, REPLACE AIR MANIFOLD, CHANGE SWITCHES IN CAB, REPAIR FRONT BUMPER, FIT NEW EGR VALVE, RE-FIT & RE-SEAL EXHAUST PIPES & CLAMPS - 24034, 23718, 23720, 23721, 23723, 23725, 23727 - TIM, PETER	14/10/2021	KM
	42245	DIAGNOSE FAULT CODES, REPLACE AIR HOSE, CLEAN PRESSURE SENSOR - 23957, 23965 - GABI	30/09/2021	636492 KM
	42045	60,000 km Service, REPLACE 4 TYRES REAR AXLE & R/H 1ST AXLE, REPLACE L/H/R AIRBAG, WHEEL ALIGNMENT, REPAIR AIR LEAK IN ENGINE BAY, REPLACE BATTERY BOX - 23950 - GABI, ALEX	22/09/2021	634008 KM

Asset	W/O No	Description	Finished	Done Reading
	42137	REPAIR PTO HOSE ONSITE - 20589 - PETER	17/09/2021	KM
	42078	REPLACE 3 AXLE L/H SHOCK HOLDER - 23917 - GABI	1/09/2021	KM
	41980	RE-ALIGN STEERING WHEEL, ADJUST CLUTCH, REPLACE R/H STEER U-BOLTS, REPLACE WIPER BLADES, REPAIR WASHERS, FIT FIRE EXTINGUISHER, REPLACE REAR DIFF SENSOR WIRING, REPLACE TURBO GASKETS, INSPECT EXHAUST BRAKE, REPAIR WIRING, INSPECT FOR POWER STEERING LEAK - 18930, 20549 - CHRIS, PETER	20/08/2021	630449 KM
	41951	REPLACE HYD FITTING, REPLACE ELECTRICAL PLUG, INSTALL GPS, TENSION R/H STEER U-BOLTS, SWAP MUDGUARDS - 10220, 18839, 20538, 19915 - JOHN, BLAKE, PETER, BEN	13/08/2021	KM
	41906	REPLACE L/H 2ND DRIVE SHOCK, REPLACE HOSE CLAMP ON EGR PIPE, CHECK OVER/SHAKER, CHECK FOR CRACK IN BLOCK, TIGHTEN TURBO BOLTS, DIAGNOSE NO CABIN FAN, MAKE WIRING HARNESS FOR TRAILER TARP, REPLACE MANIFOLD GASKETS ON TURBO, REMOVE BROKEN BOLTS FROM MANIFOLD, REPLACE REFLECTORS, REPLACE L/H SHOCK HOLDER 3 AXLE, REPLACE TARP RELAY, REPLACE BOOST CLAMPS, TEST A/C, FIT HUB CAPS - 20510, 20527, 10217, 10476, 19887, 10219 - PETER, JOHN, TIM, GABI	7/08/2021	KM