

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0277		Kenworth T401 Prime Mover		
	194359	Fulcrum photos On hire Maas Paperwork	11/06/2026	
	191623	WORK OUT LOW POWER ISSUE	5/06/2026	
		*Carry out full inspection, write list *Replace hub seal and brakes on 2nd axle LHS *Replace air valve under cab *Replace leaking drive shocks *Replace missing bull bar bolts *Take to ASM to inspect low power *Found it was barometric air pressure sensor *Replace sensor, put trailer on track and take for big test drive to confirm fault was fixed *Replace diff breathers *Replace diff oil *Clean truck, take on-hire photos		
	193936	Pre pit inspection for rego	2/06/2026	
		- Carried out inspection - Found leaking shock front RHS - Removed & Replaced shade - Brake tested vehicle - all good/Passed - Everything else was all good - Take truck over pits + return - Job complete 21/04/26 - Tighten turntable bolts after pit inspection		
	59200	diagnose and repair truck shutting down *Pressure test intercooler and piping *Test waste gate actuation *Fit new turbo *Engine intake system extremely dusted	29/05/2026	
	56625	Breakdown large air leak, brakes won't release WON56625 *Fault - truck not mobile *Cause - air leak *Correction - drive to porto talls rd and fit air leak under seat and test truck operation *Remove and replace oil pressure sensor	13/10/2025	