

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0417		Kenworth K200		
		Full Cummins Rebuild at 500,000 klms by Cummins Tamworth in August 2022		
	193344	Prime Mover B Service (20,000kms) Replace tie rod ends and gearbox pinion nut. No horn Ps beacon out Reverse alarm not working Tighten exhaust clamp near egp CAC pipe loose Note rear door on gantry box has been hit Tie rod ends Nhvr unable to read Box output has movement Powerdivider input movement and pinion leak Wear plates welds torn for rear leafs Steer backing plates ps missing Bottom rad hose coolant leak	2/06/2026	KM
	193064	Replace Hand Rail As per PJ	6/05/2026	KM
	192740	Grease, inspection, defect repair, as Requested MV Checkover fix flashing light and air ram scoop, fixed LHS spotlight Carry out inspection, grease, and fix a couple little things	23/04/2026	KM
	192361	Puncture Repair	2/04/2026	KM
	191850	Hydraulic Hoses & Air Fittings for \$17 to work with Inco B double trailers Replace PTO switch and re-plumb/test, change and connect trailer control air lines, replace hydraulic hose between A & B trailer Change out air fittings and test and re connect air line, fir new hydraulic hose	11/03/2026	KM
	191177	Case Drain Fittings & Air fittings as per MV	20/02/2026	KM
	59845	k200 cab conversion parts spread across fleet	18/12/2025	KM
	58824	Replace tyres	1/12/2025	KM
	58640	Repair broken drivers outside door handle spring	27/10/2025	KM
	57875	Wiper Blades	23/09/2025	KM

Asset	W/O No	Description	Finished	Done Reading
	57269	Exchange Transmission Parts only, Fit later	25/08/2025	KM
	56828	Prime Mover B2 Service (40,000kms) Odo: 778,284km	5/08/2025	778284 KM
		- carried out service as per checklist - cab jack ordered & to be replaced - replaced radiator cap		
	56212	Diagnose and repair truck over heating Odo: 770,440km	16/07/2025	KM
		Fault: over heating Cause: stuck thermostat Correction: - drained coolant - removed A/C belt - removed A/C compressor - removed top radiator hose - removed thermostat housing - removed thermostat - bench tested thermostat, no good - R+R thermostat gasket - installed new thermostat - installed thermostat housing with new gasket - installed top radiator hose - installed A/C compressor - installed A/C belt - topped coolant - test drove & monitored, all OK - checked & topped coolant		
		Fault: install pipe split Cause: wear & tear Correction: R+R intake pipe		
	56256	STEERING ADJUSTMENT	15/07/2025	KM
	55789	Replace steer tyres, drive rotation	25/06/2025	KM
	55584	Prime Mover B Service (20,000kms) 761528km	16/06/2025	761528 KM

Asset	W/O No	Description	Finished	Done Reading
		761528km -Replaced fuel filter bowl due to filler cap broken - Replaced shift cables & adjusted to spec		
	54683	replace condensor and pipes REPLACE REAR CAB MOUNT 749493 km - Roof light inop, faulty light - tested Good - AC Inop leaking - Remove grill - Remove condenser & mounts - Drilled & tapped threads as bolts broke - Installed new condensor - Pressure tested system - R&R side line as leaking - R&R receiver drier - Pressure tested good - Filled Gas - Repaired plug on rear of compressor - Test operation good - Rear cab mounts own Test drove & got temp, performed injector test and passed Diagnose fault codes, replace condensor lines, recover a/c gas AC repairs, replace condensor Suspension repairs	13/05/2025	749491 KM
	53835	Prime Mover B2 Service (40,000kms). *Finish 742,691km *Completed service as per check list. *Parts ordered for further repairs.	7/04/2025	KM
	51980	Prime Mover B Service (20,000kms) 721178km -diagnose fuel gauge not working - repair all broken/cut wires - tidy up wires and put new conduit on	28/01/2025	721178 KM
	51879	Supply Fuel Gauge.	22/01/2025	KM
	49449	Carry out repairs on To-Do list. - tyre rubbing harness, previously fixed - wiring repaired by sparky charging now operational - replace both door seals - remove axle clean mating surfaces & reseal - R+R jaw kit in turntable, apply grease & test operation - R+R LH door control module	30/10/2024	717905 KM
	48829	check steering, truck wandering very bad Remove and replace Steering box Test drive and check over	8/10/2024	712834 KM

Asset	W/O No	Description	Finished	Done Reading
	20488	replace all front cab suspension and bushes. - Order all parts to replace front cab mounts. - parts pictures that were supplied didnt include all parts needed. had to go down to inland trucks and go through all the parts that were required. - jack cab up and down several times to get it in the correct position. - remove bullbar and FUPS bar. - strip cab mounts out of cab, remove old bushes. - clean all grease off mounts. - fit new bushes to cab mounts and install. - fit new cab shocks. - had to remove steering box and draglink from rhs to replace the cab mounts and suspension. - fit steering box and draglink back on. - on RHS the cab bump stop mount was damaged to had to get the boilies to cut it out and weld new plate in there for it. - replace bump stops for cab suspension. - connect auto greaser lines for cab mounts. - fit bullbar and FUPS bar back to truck. - adjust clutch.	7/08/2024	697318 KM
	20486	Prime Mover C Service (100,000kms) Carry out c-service as per checklist. - remove and replace transmission cooler lines as the hoses were sweating oil through them and leaking. - remove and replace power steering suction hose that was ordered at a previous service. - carry out service on icepack. - test drive and check over work carried out.	6/08/2024	KM
	20487	Prime Mover - Annual Roadworthy Compliance Inspection Carry out inspection as per checklist	5/08/2024	KM
	18774	Repair fan fault complaint of engine fan being stuck on, when truck arrived at workshop there was no fault with the fan, checked all wiring plugs, no fault found. replace blower motor.	11/07/2024	KM
	17836	Replace drive tyres	26/06/2024	KM
	17950	Repair Wiring to icepack. - icepack failure to start - melted harness - replace all damaged wires and relays - test, OK	13/06/2024	KM
	17643	Prime Mover B2 Service (40,000kms) - completed service as per checklist	3/06/2024	679962 KM

Asset	W/O No	Description	Finished	Done Reading
		- R+R wiper blades due to damage		
		Fault: splitter inoperative Cause: worn o-rings Correction: R+R splitter valve & all o-rings		
		Fault: safety signs inoperative Cause: wear & tear Correction: R+R signs		
15774		Replace fan motor - R+R fan motor	23/05/2024	KM
15702		LOCKABLE FUEL CAPS SUPPLIED @ INLAND TRUCK CENTRES INV# 1018201	13/05/2024	KM
15276		wheel alignment	29/04/2024	KM
15274		Repair lights and diff temp sensors	29/04/2024	KM
		- repairs to rear light harness - repairs to both diff temp sensor harnesses		
15104		Prime Mover B Service (20,000kms)	22/04/2024	665264 KM
		- completed service as per checklist - R+R x2 front steer bungs as leaking - R+R front compressor bung as leaking		
14306		Replace steer tyres	12/04/2024	KM
13538		Minor R & M - replaced leaking trans cooler lines - adjusted clutch - replaced batteries - checked battery cables - checked steering	2/04/2024	KM
13476		Fit dash cam - fit dash camera & test	26/03/2024	KM
16800		Boost dropping to 200 on gauge when hot - replaced boost hoses. Lost clutch brake at lobs, had to start truck in gear - checked over.	12/03/2024	KM
16799		New shocks fitted - Shocks R/S.	12/03/2024	KM
16806		Cracked LH windscreen - replaced. Excessive play in kingpin/turntable - no fault found.	12/03/2024	KM
16808		Jumping out of 3/8 gear, grinding noise when letting clutch out - no fault found.	12/03/2024	KM
10019		Fit New Shock Absorbers	1/03/2024	642730 KM

Asset	W/O No	Description	Finished	Done Reading
		Fault: truck rides roughly Cause:shocks Correction: - removed old shocks - fit new shocks - ran airlines from shocks to cab - fit x2 regulators - plumbed in airlines - tested shocks, all good		
	10174	Replace LHS cab ram	1/03/2024	642730 KM
		Fault: cab ram leaking Cause: slit in line on ram Correction: - R+R ram - top oil		
	16804	Running light out on LH fuel tank. LH front white clearance light out on T349 - repaired.	1/03/2024	KM
	16805	Cab suspension knocking - new shocks fitted.	1/03/2024	KM
	9599	R&R Clutch, remove and reseal front and rear Differential.	29/02/2024	642730 KM
		Fault: clearance light inoperative Correction: no fault found		
		Fault: diff temp gauge inoperative Cause: loose wires Correction: remove dash, checked gauge wires, push wires onto gauge, installed dash		
		Fault: leaking diffs x2 Cause: wear & tear Correction: removed drive & jack shafts, removed axles, removed diff centres, cleaned all surfaces, sealed diffs, installed diff centres, sealed axles, installed axles, topped oil, installed jackshaft		
		Fault: clutch worn Cause: wear & tear Correction: removed all necessary airlines & tanks, removed all necessary grease lines, breathers, clutch linkages, removed tower off top of box, removed gearbox, removed old clutch, removed flywheel, sent flywheel to be machined, cleaned all necessary surfaces, rekit front of gearbox, installed & tensioned flywheel, install & tensioned new clutch, installed & tensioned gearbox, installed tower, installed all necessary grease lines, airlines, breather & linkages, installed airtanks & airlines, installed drive shaft, checked oil, adjusted clutch, test drove, all good		
	9834	Fit Draw Fridge	29/02/2024	642730 KM
		Fault: under bunk fridge inoperative Cause: wear & tear Correction:		

Asset	W/O No	Description	Finished	Done Reading
		- removed bedding - removed fridge - moved motor location on new fridge - installed new fridge - wired in new fridge - installed all bedding		
10035		Prime Mover B2 Service (40,000kms) - completed service as per checklist	29/02/2024	642730 KM
16802		Brake light resettable fuse popping - repaired.	29/02/2024	KM
16801		Rear diff temp gauge not working - repaired.	29/02/2024	KM
52138		replace horton and repair to do list ice pack belts 723873km -replaced LHS steer hub cap due to it leaking	22/02/2024	KM
9484		Replace radiator stay rubbers and repair boost leak Complaint: radiator stay bushes worn Cause: wear and tear Correction: R+R radiator stay rubber Complaint: truck low power Cause: boost leaks Correction: - replace LHS and RHS bottom boost hoses - tighten all boost clamps	21/02/2024	636216 KM
9789		Adjust wastegate. Diagnose and repair low power complaint. Pressure test boost system, all ok. Dyno test vehicle to check wastegate pressures. Adjust wastegate to suit manufacture specifications dyno test vehicle to check results. all ok	19/02/2024	KM
11885		ENGINE VIBRATION / MISFIRE / FLUTTER REPAIRS COMPLETED BY INLAND TRUCK CENTRES INV# 872685 MOVED TUCK INTO WORKBAY CARRIED OUT ENGINE CYLINDER TESTS FOUND CYLINDER 3 MISFIRING INJECTOR TEST FOR CYL3 FAILED REMOVED PIPING, TIES ETC AS REQUIRED TO ACCESS ROCKER COVER REMOVED COVER AND WIRING AND INJECTOR 3 INSTALL NEW INJECTOR IN CYLINDER 3 AND REFIT HARNESS CARRYOUT VALVE ADJUSTMENT, AS PER OEM PROCEDURES & SPECIFICATIONS REFIT COVER AND ALL PARTS REMOVED FOR ACCESS RAN ENGINE AND ALL OK WASHED ENGINE, TEST DROVE AND ALL OK RELEASED TRUCK AND DID PAPERWORK	5/02/2024	KM
8875		Replace top torque rod. - drive to Oranade	22/01/2024	633125 KM

Asset	W/O No	Description	Finished	Done Reading
		- replaced torque rod - drive to workshop - replaced tail shaft straps & bolts that got damaged		
16803		Torque rod broken - replaced.	22/01/2024	KM
8693		Repair A/C Fault: A/C inoperative Cause: front seal blown out on compressor Correction: - remove and replace compressor - remove and replace receiver drier - replace o-ring on compressor and drier hoses - pressure test - vac down and charge with R134A - replace shrouder valves - test A/C	13/01/2024	628910 KM
8147		Minor R & M - ordered new blind spot mirror - windscreen replaced - welded crack in icepack mounts - adjusted jaws in turntable	12/01/2024	KM
16807		Blindspot mirror cracked - replaced.	12/01/2024	KM
8123		Supply & fit Kenworth K200 LH & RH Windscreen	14/12/2023	626669 KM
16809		Wiring rubbed through RH steer - repaired. Pyro gauge inoperable - repaired.	7/12/2023	KM
7672		ROTATE TYRES	1/12/2023	620458 KM
7428		Prime Mover B Service (20,000kms) Fault: service due Cause: km's travelled Correction: complete service as per checklist	27/11/2023	618727 KM
16810		Cracked drivers side windscreen - replaced. Ice pack mount cracked - repaired. DEF injection connection broken - repaired.	27/11/2023	KM
7199		Replace head unit and Fan Belt (Supply Parts Only)	17/11/2023	KM
7187		Replace boost hose - drove to Inland & picked up parts - drove to Truck on Dunedoo Rd - repaired truck, replaced hose	16/11/2023	KM

Asset	W/O No	Description	Finished	Done Reading
		- travelled to workshop		
	6508	Replace fan belts	30/10/2023	607521 KM
	6022	Replace cab shocks and steering shaft	17/10/2023	600077 KM
	5433	Prime Mover C Service (100,000kms or Annually) - refit air dryers - check steering, found pittman arm loose, tightened - remove backing plates to check brakes - insulators on taper cover - service ICR pack	26/09/2023	598295 KM
	3324	July - Minor R&M Supply Wedge globe	25/09/2023	KM
	5226	Horton fan staying locked in all the time. - remove dash panels behind accelerator pedal - replace coolant level module - put dash panels back on - replace coolant temp sensor - fault trace wiring harness - found pulled out pin in dutch plug, replace pin and reconnect	18/09/2023	595495 KM
	16812	Check steering wandering - repaired, all ok.	18/09/2023	KM
	16811	Repaired engine fan stuck on.	18/09/2023	KM
	4815	Diagnose and repair indicators on Kenworth T417 Ostendo Job WS817823	29/08/2023	KM
	4466	Rotate Steer Tyres	14/08/2023	585995 KM
	4372	09/08/23 Minor R&M Supplied Wheel Bearings at Cloncurry	9/08/2023	KM
	3693	Prime Mover B Service (20,000kms): put vehicle on shacker - all good, fix air leak - tighten bolts and replace missing bolt.	28/07/2023	581664 KM
	3313	PARTS SURPLIED weathershield clips	27/07/2023	KM
	3403	Replace Suzzie coils. (air and Electrical) Ripped off (Didn't disconnect from trailer): R+R suzie coils	14/07/2023	574000 KM
	2738	Fit cradle and bullbar blinkers.	28/06/2023	570536 KM
	2498	#7550 Front Diff Leaking. Snapped torque rod. Fixed by Shano (per Harley 16/06)	16/06/2023	KM
	16813	Check front diff leaking - added to to-do list.	16/06/2023	KM
	16820	Install cradle for tablet - added to to-do list.	16/06/2023	KM
	2201	Prime Mover B Service (20,000kms): Remove old windscreen washer bottle and replace with new - fill with water, replace RHS no. plate light solder joints	15/06/2023	559150 KM

Asset	W/O No	Description	Finished	Done Reading
		RHS no. plate tight, solder joints.		
	4186	Truck has huge vibration and noise under load. Bring back to workshop and put over pit. Check all driveline and diffs, ok. Found torque rod on front diff broken. Order new parts and get them picked up. Input shaft has some movement. Remove drive shaft and yolk. Tighten bearing. Refit yolk and drive shaft. Fit new torque rod. Test drive, ok.	14/06/2023	KM
	4184	Leaking front pinion seal and drive line vibration. Remove drive shaft and yolk. Front bearing had movement and metal found in front cover. Remove front cover and input shaft and inspect. Found power divider gear bushes and shaft u/s. Order and get parts picked up. Remove oil pump, oil galleries were blocked. Clean, lube and refit. Fit new gear shaft bearing and seal. Adjust bearing. Refit yolk and drive shaft and fill with oil.	13/06/2023	KM
	1881	Mount up and wire secondary battery system 12 to 24 for jumpstarting	15/05/2023	KM
	16814	Check brakes on T0595 - will re-check brakes on service, all okay.	10/05/2023	KM
	1811	Install secondary battery system with 24v jumpstart	24/04/2023	542921 KM
	16817	Bearing collapse on T0595, grease lines on T0596. Grease lines blocked, replaced grease lines.	20/04/2023	KM
	16815	Check front cab mounts - checked, unable to fault.	12/04/2023	KM
	16819	Carried out 40,000km service.	12/04/2023	KM
	16821	Replaced front and rear engine mounts.	12/04/2023	KM
	16823	Check front and rear springs worn out, rough. Removed front wheels and all spring pin bolts, support on safety stands, removed ad blue tank and brackets, remove shock absorbers and U-bolts, Remove old springs and fit new springs with new U-bolts and nuts, Torque U-bolts and refit shackles with new bushes and pins, Refit ad blue tank and brackets, Fit new front shocks, manually grease all spring pins and reconnect auto grease lines, refit wheels and remove stands, removed all rear wheels, cut U-bolts from springs and removed spring packs, removed trunnions and replaced bushes and trunnion bolt, torqued trunnion bolts, fit new rear springs and U-bolts, torque U-bolts, refit wheels, fit new shock absorbers.	12/04/2023	KM

Asset	W/O No	Description	Finished	Done Reading
	16822	Replaced front wipers. Replaced turbo, replaced manifold gaskets, replaced exhaust flex.	12/04/2023	KM
	16824	Down on power - sent to ASM for tune up/inspection - found turbo leaking on exhaust side.	12/04/2023	KM
	16818	Make new stif bar. Cut 100x100x5mm RHS to 2.5m, welded.	28/03/2023	KM
	16825	Carried out B Service - 20,000km service.	30/01/2023	KM
	16826	A/C not leaking - unblock drain, place sponge around hoses. Machine screw in missing bolt hole ice pack leak. Unblock drain grease lines. Joiner fitted springs - no damage front or rear.	30/01/2023	KM
	16827	Repaired start/stop switch for ice pack.	1/12/2022	KM
	16831	Replace driving lights.	17/11/2022	KM
	16833	Boost hose keeps coming off - cab rubbing on pipe. Checked pipe - Russell has re-positioned and replaced clamps - all okay.	17/11/2022	KM
	16829	Checked cab mounts - replaced cab mount shocks.	16/11/2022	KM
	16828	Carried out 100,000km service.	16/11/2022	KM
	16832	Suspension check over - replaced front axle shocks.	16/11/2022	KM
	16830	Repaired flashing lights - not working.	15/11/2022	KM
	16842	Check LHS blinker on bull bar not working - repaired wiring and fitted plug.	15/11/2022	KM
	16837	Guards breaking up - grind paint off, grind broken welds out, level pipe, make template for gusset, plasma cut gussets out, weld cracks up, weld gussets in, paint, tig weld aluminum mud guards. Engine fan constantly running - repaired harness.	2/11/2022	KM
	16838	Check steering pulling to the left - carried out wheel alignment.	27/10/2022	KM
	16835	Structure and bodywork - roof leaking water. Removed overhead storage and sprayed roof with hose to find leak - could not find leak with hose, resealed beacons.	25/10/2022	KM
	16834	Put legs on the front and put a block behind pin.	17/10/2022	KM
	16839	Carried out 20,000km service	8/09/2022	KM
	16841	Check power drain - monitor. Check for air leak - no air leak found.	8/09/2022	KM
	16840	Repaired front cab mounts, LH window, T0596 lights wiring.	8/09/2022	KM
	16844	T0417 not holding air - checked for leaks, no leaks found.	8/09/2022	KM

Asset	W/O No	Description	Finished	Done Reading
	16863	Check leak on top of gearbox - remove remote tower from gearbox, strip down, replace brass bushes, replace main shaft, reassemble, refit, replace detent springs.	23/08/2022	KM
	16845	Remove hubs and replace seals, inspect brakes and bearings when removed. Fit new wheel seal, new bearings, cleaned brakes.	17/08/2022	KM
	16843	Check - loosing acceleration. Marked as complete on VMMR #51302.	15/08/2022	KM
	16848	Loosing air, LH window not working. Replaced LHS window regulator and control module.	15/08/2022	KM
	16849	Diff lock not working - power divider, re-kitted o-rings and plunger	15/08/2022	KM
	16854	Under powering, smell - new program is latest Cummins program - all okay.	15/08/2022	KM
	16862	Check burning oil - rebuilt engine.	15/08/2022	KM
	16846	Replace windscreen - Replaced at Dubbo Windscreens.	12/08/2022	KM
	16836	Replaced tyres.	19/07/2022	KM
	16851	Replaced drive tyres.	19/07/2022	KM
	16852	Topped up oil, drive tyres replaced.	19/07/2022	KM
	16856	Inverter not working - repaired inverter.	13/07/2022	KM
	16855	Batteries low on cranking power, replaced all batteries.	13/07/2022	KM
	16857	Fix Ad blue - connected laptop and checked for codes - no codes active.	13/07/2022	KM
	16858	Carried out 20,000km service.	22/06/2022	KM
	16860	Check engine issue - Engine oil pressure dropped, oil filter collapsed causing low pressure, replaced oil filter. (Repairs carried out by Cummins Emerald).	22/06/2022	KM
	16859	Cab jacking system leaking oil. Replaced all hydraulic hoses coming from cab jack hydraulics.	22/06/2022	KM
	16873	Check starter motor - remove and replace failed starter motor.	17/05/2022	KM
	16887	Check speedometer malfunction - all fixed.	10/05/2022	KM
	16865	Carry out B Service - 20,000km service.	29/04/2022	KM
	16870	Engine oil filter to block gasket failed, replaced oil filter rubber hose and resealed adaptor to block.	29/04/2022	KM
	16869	Rear mudguards removed and cracks welded from the underside.	29/04/2022	KM
	16875	Check turn table not locking properly. Turntable rebuilt with overhaul kit, turntable jaws adjusted.	29/04/2022	KM

Asset	W/O No	Description	Finished	Done Reading
	16881	Ice pack won't stay on. Ice pack cabin mounted switch faulty - replaced. all ok.	29/04/2022	KM
	16885	After treatment light on - repaired.	2/04/2022	KM
	16882	Check brake issue - brakes checked and found to be within spec. AX164 brakes recalibrated and adjusted by ASM.	30/03/2022	KM
	16867	Carry out C Service - 100,000km Service	26/03/2022	KM
	16886	Check LH driving lights not working - repaired.	25/02/2022	KM
	16878	Replaced rear shocks. Check A/C not cold - unable to fault. Check oil leak at back of engine. Fit TFO tracker. Adjusted brakes. Grease line to turntable repaired, turntable removed, and lock repaired.	7/02/2022	KM
	16891	Carried out B Service - 20,000km service.	7/02/2022	KM
	16892	Batteries need testing - dropping volts when truck isn't running, fit new alternator. Replaced two slack adjusters. Fixed Adblue sender gauge. Welded cracks on mudguards. Inspected rear end (springs) - continue to monitor. Check fan constantly running - found too much gas in system, removed some gas. Check lack of power - unable to fault.	30/11/2021	KM
	16894	Check draw fridge not working - unable to fault. Remove and replaced radiator core.	24/11/2021	KM
	16895	Welded rear guards. Repaired battery/ignition switch. Replaced leaking windscreen. Re-welded cracked mudguard. Replaced broken headlight protector. Replaced front cab mount shocks. Stop engine coming on at idle - no codes, all cleared. Repaired icepack. Check compressor bypassing oil - inspected continue to monitor. Repaired drop in voltage on startup. Check aftertreatment light on - fault cleared and wiring repaired. Check autogreaser not working - replaced injectors on float. Radiator removed and cleaned. Engine light on startup - injector tubes replaced. Broken steps on RHS side - replaced steps. LHS side steps bent from blow out - re-adjusted steps.	10/11/2021	KM
	16904	Check smoking badly from underneath - replace exhaust gasket at DPF.	9/09/2021	KM