

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0417		Kenworth K200		
	199302	Prepare for disposal Diposal no D1027 Odometer: 841170 km. Date: 05/08/2026 Carried out underneath wash and outside Degreased chassis and rims soaped up the whole truck and sponged. K.A - Clean all rubbish from cab, inspect for sale & remove all MAAS equipment	31/08/2026	KM
	57647	REPLACE FLAT BATTERIES WON57647 *Replace batteries *Check coolant leak *Replace low radiator hoses	29/05/2026	KM
	61158	Fit PTO Fit 50mm Turntable *Remove LHS tank for mod *Fit PTO and pump *Run 5x 1/4 lines from cab to hookup and PTO *Fit side tipper switches to dash and PTO switch *Make tipper control mount *Refit tank and replumb *Fit cab switched *Refill tanks *Replace turntable top	17/02/2026	KM
	60111	Replace Ice Pack Motor *R+R icepack motor *Regas A/C circuit *Remove condenser to gain access to motor *Remove starter motor to gain access to engine mounts *Remove engine harness and A/C hoses *Remove engine and drain oils *R+R all filters *Refit new engine *Modify new engine harness to svit existing wiring *Refit condenser and pressure test A/C system *Regas A/C	17/02/2026	KM

Asset	W/O No	Description	Finished	Done Reading
		*Fit remote start in cabin *Test engine and A/C		
	60699	Prime Mover B Service (20,000kms) Odo: 822,489km - carried out B Service - replaced LH rear marker - check & clear washer nozzles, flush out washer bottle, refill with clean water - remove jack shaft drain, front diff - remove yoke & diff housing cover - reseal & refit cover - fit new through shaft bearings - get yoke seal installed - made up, fit new seal & fit yoke - fit jackshaft & new oil - adjust clutch - check air leaks - replace compressor, unloaded hoses - replace air fittings near foot valve - replace 2 roof clearance lights	8/01/2026	KM
	56523	Prime Mover C Service (100,000kms) WON56523 800,929km - complete service as per checklist - remove both differentials & clean both maxing surfaces & reseal / reassemble - R+R all exhaust brake detent pistons - adjust all drive wheel bearings - R+R all steer wheel bearings - replace x2 coolant hoses & clamps & change filter & replace coolant - R+R gearbox, swap harness & fittings, remove & swap lids from both gearboxes & setup clutch - remove & re-kit both cross locks - remove & re-kit power divider - replace strap kits for driveshaft & tension bolts - replace strap kits for jackshaft & tension bolts - repair bell housing & remove & replace fork shaft bushes & install new tork - swap bellhousing onto new gearbox	27/10/2025	KM
	56337	MARKER LIGHT - replace RHS marker light	22/09/2025	
	56066	ABS ISSUE Fault: ABS light Cause: sensor Correction: - tested sensor	8/09/2025	

Asset	W/O No	Description	Finished	Done Reading
		- checked wiring		
		- diagnosed as sensor		
		- R+R sensor		
		- R+R cab jack as old jack inoperative		