

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0375		Sterling Fuel Truck		
	194506	Repair field service pump for engine oil on the rear. Fit new drum and second hand oil pump Remove contaminated engine oil drum Test system	23/07/2026	Hours
	60896	HVIS Inspection - Yearly. Booked in Dubbo 27/03 @ 1:55pm	27/03/2026	Hours
	58632	Capital repairs - Prep for Lake Cowal - No self shutting gate on top of tank - Seal on top of access door - Passenger seat movement - Passenger window no operation - Passenger door lock knob missing - Reverse camera not working - Engine light intermittent on - Driver side seat won't slide - Front platform no gate or handrail - Exhaust pipe mount needs tightening - Oil & grease drums not in area - Axle 2 LHS no oil in hub - Axle 1 RHS bearing movement - Air line on gearbox needs repair - Loose radiator mounts - Dash cam front & rear facing - All wiring over tank in split - Radiator cap - Fire risk assessment for no fire suppression - In cab e-stop move it & abs light comes on - Switches in cab need labelling - Truck not starting. Replace starter - Battery isolator single pole? - Re-seal fuel reel retract motor - Exhaust leak in engine bay - Bonnet cracked & locators broken local contact - Fan belt missing rib - Turbo drain hose leak - Missing ply for fuel compartment - Battery & alternator cable in split conduct - Rear fire extinguisher not in bay - Oil delivery hose starting to perish - Protective boots missing on relay & alternator	25/02/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
		- Tidy wiring bonnet - Tidy drivers door trim - Mine UHF - check with Tony restock - Needs new beacon switch - Needs wheel chocks - Various stickers 3 point contact etc - First aid kit - Turbo lagging - Various air leaks - Coolant filter - No jump start or isolator - Brakes dont apply when engine off		
	60902	Pulled dash apart, AC issues. Lake Cowal.	11/02/2026	Hours
	59479	December R&M - 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION - INTRO TO SITE - INSPECTION - INSPECT ISSUE WITH AIR COMPRESSOR, TEST OPERATION - SWAP OVER GREASE DRUMS - RHR OUTER TYRE PUMP UP	7/01/2026	Hours
	55474	HVIS Inspection - Yearly	15/04/2025	Hours
	54227	Pink Slip	14/04/2025	156600 KM
	54226	Pink Slip. Cancelled - Duplicate work order 54227	14/04/2025	Hours
	51610	Capital - carry out full inspection. *Finish 1988.5hrs *Do inspection and quote parts for repairs. *Replaced 2nd axle LHS mud guard and mud flap. *Replaced rose joint on clutch, readjusted clutch. *Diagnosed compressor not starting, repaired damaged fuel lines, replaced and relocated electric inline fuel pump. *Replaced all scams, scam bushes, brake shoes. *Replaced drive wheel bearings on front drive RHS & rear drive LHS. *Replaced Hi Vis tape. *Rivet passenger handle on. *Fit passenger seat belt. *Diagnose exhaust brake not working, fix airline. *Replaced front drive slack adjusters. *Put on brake tester. *Repair linkages in passenger door.	16/01/2025	Hours
	49389	Service/Fuel Truck - 250hr Service & Replace 3rd axle cam bushes Hours: 9,165hr Compressor Annual Service	16/11/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
	20308	DIAGNOSE COMPRESSOR NOT STARTING - FUEL SHUT OFF SOLENOID FAULTY REPLACE IGNITION BARREL - COMPRESSOR Travel to site. Fit new fuel solenoid & test. Further testing found lift pump failed. Fit new lift pump after pick up from yard. Supply spare solenoid. Odo: 9,127hrs	26/08/2024	9153 Hours
	17390	REPAIRS FROM HVIS INSPECTION Going over pit inspection Engine brake not working Cabin fan not working, so cannot clear windscreen of a morning Interior light not working	26/06/2024	Hours
	15555	DIAGNOSE / REPAIR A/C BLOWER NOT WORKING	30/04/2024	Hours
	14305	DIAGNOSE / REPAIR FUEL SHUT OFF HANDLE	30/04/2024	Hours
	14623	SUPPLY NEW HANDPIECE - FUEL NOZZLE, FLOW METER	16/04/2024	Hours
	17612	Passenger buckle missing. Gears grind when selecting from a standing start. Door latches, hinges and locks failed. Driver's door latch out of adjustment. Refer to MEX WE 9367.	15/03/2024	Hours
	10985	DIAGNOSE COMPRESSOR NOT STARTING	11/03/2024	Hours
	9367	Door latches, hinges and locks failed / Drivers door latch out of adjustment _ Adjust/repairs to drivers door Clutch free play failed / gears grind when selecting from a standing start - Adjust clutch Seats/ Seatbelts failed - passenger buckle missing Electrical Repairs around dash Check over TFO WO 9022 work by Tim Somers	23/02/2024	Hours
	17613	Top left of dash display - engine defect light is illuminated, repaired.	8/01/2024	Hours
	6182	Fit Grip Tape to the Top Deck	24/11/2023	Hours
	8358	Pick up fuel solenoid & travel to truck. Test of wiring found short in harness which burnt solenoid. Repair & test.	16/11/2023	8935 Hours
	5943	Replace oil 2 oil nozzles. Lights/Terminals (04/07/2023) Missed invoices.	2/11/2023	Hours
		INLAND PETROLEUM LUBEMATE DIGITAL CONTROL GUN F EXTENSION (METERED) .x2		
		NAPA DUBBO 9-33V LED RED/AMB SIDE MARKER LED REVERSE MODULE HORIZONTAL 9-33V LED INDICATOR LIGHT AMBER		

Asset	W/O No	Description	Finished	Done Reading
		10-30V LED STOP/TAIL LIGHT RED 12V 27/7W 32/3CP W2.5X16 DT 6 WAY KIT WITH SOLID TERMINALS DT 8 WAY KIT W/ SOLID TERMINALS DT 12 WAY KIT W/ SOLID TERMINALS		
6030		Minor R&M Travel to truck. Remove burnt out solenoid & source parts. Pick up parts & travel to truck. Fit fuel solenoid & test.	25/10/2023	8920 Hours
442		HVIS Inspection - Yearly. To be completed on repairs are done. Booked in 28/07/23 @1:10pm Dubbo. Also needs to be pink slipped prior (must be done by 18/07) Transmission repairs - tow vehicle to w/shop - remove damaged transmission - replace rear engine seal, damaged flywheel, clutch, rear engine mounts, yoke & uni at transmission - refit transmission & all components - replace gear stick tower - carry out inspection for pits & list faults - replace damaged & faulty washer bottle - repair L/H headlight assembly - carry out B-Service - repair steer axle rocker & shackle pins - replace rear marker plates - replace brakes on 4th axle R/H/S, s-cam & bushes R/H/S, slack adjusters on L/H & R/H 4th axle, booster 4th axle R/H - adjust all brakes - cut out & replace loose chassis bolts LH & RH - replace RH mirror and rewire light - roof mount air compressor - repair exhaust leak (broken pipe) - repair various air leaks at control box - repair air leak at grease pump not pumping - fit new 205 engine oil & pump - test fuel system OK - repair hyflow hose reel not retracting - remove pump and clean out, refit, order new pump - bypass valve leaking air regulation; new one on order - take vehicle over pits for inspection - electricians carried out work on A/C & lights - carry out site pre-hire inspection - replace drag link & replace greenstick boot	21/08/2023	KM
2232		Drove to marica to load truck on float	17/05/2023	Hours
1797		Order door latch	27/04/2023	KM

Asset	W/O No	Description	Finished	Done Reading
	266	ANM Auto - Travel cooma to Marica Fit replacement fuel stop solenoid to compressor. Repair door handle linkage.	22/04/2023	KM
	1477	Check head lights not working change head light fuse	14/04/2023	KM
	1464	Wiring issue	12/04/2023	KM
	1767	Rectify fuel leaks and electrical issues	11/04/2023	KM
	1765	Investigate compressor and electrical issues	10/04/2023	KM
	1763	Replace fuel hose on fuel truck	9/04/2023	KM
	1544	Pump/hose problem	4/04/2023	KM
	17614	Fitted new fuel metre, induction at Marica.	1/04/2023	Hours
	1494	Adjust brakes, repair light bar wiring	11/03/2023	KM
	1620	Rectify additional faults	28/02/2023	KM
	1623	Rectify defect list	27/02/2023	KM
	17615	Serviced compressor.	12/01/2023	Hours
	17616	Replaced faulty isolator switch.	7/11/2022	Hours
	92	Service and repairs Repair reverse camera. Replace fire extinguisher. Repair gear knob. Replace flashing light. Replace front indicator on bulbar. Repair electric windows. Repair exhaust brake. Repair damaged seat and seat belt. Full service.	13/10/2022	148196 KM
	17617	Checked and drained air tanks to check dual brake circuit. Defect cleared.	6/06/2022	Hours