

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0375		Sterling Fuel Truck		
	62373	Carry out off hire Inspection (Complete) Fulcrum Photos (Complete) CARRY OUT REPAIRS FROM INSPECTION 9201hrs - 17/02/26 - Washed inside of the cab - Pressure cleaned outside of truck - Remove radiator - Removed bonnet - Removed tensioners and belt - Cleaned front of engine - Remove and replace front crank seal - Fit new water pump - Fit new tensioners and belt - Install fan and radiator - Fill with coolant and run truck - Put bonnet and grill back on - Replace 2nd axle LHS wheel seal, brakes and bearings - replace air drier filter - Replace oil/grease handles - Repair various air leaks behind LHS quarter guard - Replace LHS clearance light - Take to Hannafords for new steer tyres Clarkey - Replace centre dash piece, repair A/C controls, repair fan switch put dash back together. T0375 - Front main seal - 30 hrs - Belt - Water pump failed /Leaking - 4x steer tyres - L/R clearance lights between drive nop - 3hr - LHS 2nd axle wheel seal - 3hrs - needs new oil hand piece (Leaking everywhere) 2 hrs - need new grease hand piece (Leaking everywhere) 2hrs - Centre dash piece all broken and hanging off - 3hrs - A/C controls broken/Hanging out of dash 1hr - A/C fan control broken - Try and put dash back together all pulled apart and broken laying in the floor 5hr	1/06/2026	

Asset	W/O No	Description	Finished	Done Reading
		- needs good wash/detail - 8 hrs		
		Odometer: 158264KM 100hrs		
		-		
193815		Service/Fuel Truck - 250hr Service Odo: 9,384hrs	17/04/2026	
		- carry out service		
56969		labour only for repairing fibreglass *Repair holes, underside of bonnet *Prep and fibreglass bonnet guides ns and fs *Reinforce fibreglass with steel plate *Reinforce cracks on underside of bonnet with steel plate than glass over *Rub back fibreglass then paint. *Fabricate bonnet loactors backing plate	21/02/2026	