Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			LAB		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			LAB		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043451	28/10/2021	GEN	39			PART		ROC
PM169	XQ90ZR	00043566	9/11/2021	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00043566	9/11/2021	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5		SERVICE COMPLETED BY IAN				
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	16	1ST SERVICE AND CHECK OVER CON			YAT	
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	06			MK13584	YAT	
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	06			A3380W1687	YAT	
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	06			17237	YAT	
PM169	XQ90ZR	00043837	25/11/2021	CUMAE5	06			WF2127	YAT	
PM169	XQ90ZR	00043888	29/11/2021	GEN	39			LAB		ONTI
PM169	XQ90ZR	00043888	29/11/2021	GEN	39			LAB		ONTI
PM169	XQ90ZR	00044472	23/12/2021	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00044472	23/12/2021	CUMAE5		SERVICE COMPLETED BY BEN				
PM169	XQ90ZR	00044472	23/12/2021	CUMAE5	16	FITTED MASS STICKER TIGHTENED DASH CLUSTER CON			YAT	
PM169	XQ90ZR	00044472	23/12/2021	CUMAE5	06			MK13584	YAT	
PM169	XQ90ZR	00044472	23/12/2021	CUMAE5	40			3413005	YAT	
PM169	XQ90ZR	00044472	23/12/2021	ECO	00	LABOUR APPREN				
PM169	XQ90ZR	00044472	23/12/2021	ECO		SERVICE COMPLETED BY BEN				
PM169	XQ90ZR	00044472	23/12/2021	ECO	16			CON	YAT	
PM169	XQ90ZR	00044472	23/12/2021	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00044472	23/12/2021	ECO	40			10W50	YAT	
PM169	XQ90ZR	00044545	7/01/2022	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00044545	7/01/2022	TYRES	15			33000051		BRIA

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00044827	22/01/2022	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00044827	22/01/2022	CUMAE5		SERVICE COMPLETED BY IAN, KEIRAN AND BEN				
PM169	XQ90ZR	00044827	22/01/2022	CUMAE5	00	ADJUST CLUTCH REPLACED INDICATOR ON BULLBAR LH LABOUR APPREN				
PM169	XQ90ZR	00044827	22/01/2022	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00044827	22/01/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00044827	22/01/2022	ECO	00	LABOUR APPREN				
PM169	XQ90ZR	00044827	22/01/2022	ECO		SERVICE COMPLETED BY KEIRAN				
PM169	XQ90ZR	00044827	22/01/2022	ECO	16			CON	YAT	
PM169	XQ90ZR	00044827	22/01/2022	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00044827	22/01/2022	ECO	40			10W50	YAT	
PM169	XQ90ZR	00045069	3/02/2022	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00045069	3/02/2022	CUMAE5		SERVICE COMPLETED BY IAN				
PM169	XQ90ZR	00045069	3/02/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00045629	22/02/2022	CUMAE5	01	LABOUR				
PM169	XQ90ZR	00045629	22/02/2022	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	00	LABOUR APPRENK				
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5		SERVICE COMPLETED BY KEIRAN, IAN AND BRENDAN				

PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	00	TIGHTENED ALL VISOR BOLTS LABOUR MECH1					
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	00	LABOUR SUBMEC					
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	16			CON	YAT		
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	06			MK13584	YAT		
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	06			FS19764	YAT		
PM169	XQ90ZR	00045629	22/02/2022	CUMBE5	40			3413005	YAT		
PM169	XQ90ZR	00045953	8/03/2022	CUMAE5	00	LABOUR MECH1					
PM169	XQ90ZR	00045953	8/03/2022	CUMAE5		SERVICE COMPLETED BY IAN AND TYLER					
PM169	XQ90ZR	00045953	8/03/2022	CUMAE5	00	A SERVICE COMPLETED REAR MARKER SIGN REPLACED - L/H TYRES SORTED BY BRIDGESTONE TYRE FITTER LABOUR TI					
PM169	XQ90ZR	00045953	8/03/2022	CUMAE5	16			CON	YAT		
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			PART			BRIAUS
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			33000241			BRIAUS
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			33000125			BRIAUS
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			33000125			BRIAUS
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			33000241			BRIAUS
PM169	XQ90ZR	00045946	8/03/2022	TYRES	15			PART			BRIAUS
PM169	XQ90ZR	00046003	9/03/2022	TYRES	15			77000194			BRIAUS
PM169	XQ90ZR	00046803	9/03/2022	TYRES	15			77000194			BRIAUS
PM169	XQ90ZR	00046003	9/03/2022	TYRES	15			77000194			BRIAUS

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00046803	9/03/2022	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00046803	9/03/2022	TYRES	15			77000194		BRIA
PM169	XQ90ZR	00046803	9/03/2022	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			LAB		NOR
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			PART		NOR
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			PART		NOR
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			PART		NOR
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			PART		NOR
PM169	XQ90ZR	00046063	11/03/2022	GEN	39			LAB		NOR
PM169	XQ90ZR	00046261	21/03/2022	CUMAE5	00	LABOUR APPRENK				
PM169	XQ90ZR	00046261	21/03/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND BEN				
PM169	XQ90ZR	00046261	21/03/2022	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00046261	21/03/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00046261	21/03/2022	ECO	00	LABOUR APPRENK				
PM169	XQ90ZR	00046261	21/03/2022	ECO		SERVICE COMPLETED BY KEIRAN AND MICK				
PM169	XQ90ZR	00046261	21/03/2022	ECO	00	HAD ALOT OF OIL AROUND BOTTOM OF SLEEPER MOTOR C FAULT - CHECK NEXT SERVICE LABOUR MECH				
PM169	XQ90ZR	00046261	21/03/2022	ECO	16			CON	YAT	
PM169	XQ90ZR	00046261	21/03/2022	ECO	40			3413005	YAT	
PM169	XQ90ZR	00046261	21/03/2022	ECO	40			10W50	YAT	
PM169	XQ90ZR	00046754	9/04/2022	CUMAE5	00	LABOUR APPRENK				
PM169	XQ90ZR	00046754	9/04/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN, BEN AND IAN				
PM169	XQ90ZR	00046754	9/04/2022	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00046754	9/04/2022	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00046754	9/04/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00047052	19/04/2022	CUMAE5	01	LABOUR				
PM169	XQ90ZR	00047052	19/04/2022	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5		SERVICE COMPLETED BY BEN, MICK AND TYLER				
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	00	TOPPED UP ENGINE COOLANT REPLACED G/BOX FILTER DF HUB REPLACED OIL RHS STEER HUB REPLACED F/E FITTED F/E HOLDER RHS DOG BOX LABOUR MECH				
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	00					
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	00	LABOUR TRADEA				
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	40			3413005	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	06			17237	YAT	
PM169	XQ90ZR	00047052	19/04/2022	CUMBE5	11			330.3067G	YAT	
PM169	XQ90ZR	00047336	5/05/2022	TYRES	15			LAB		NABC
PM169	XQ90ZR	00047336	5/05/2022	TYRES	15			LAB		NABC
PM169	XQ90ZR	00047395	6/05/2022	CUMAE5	00	LABOUR SUBMEC				
PM169	XQ90ZR	00047395	6/05/2022	CUMAE5		SERVICE COMPLETED BY BRENDAN				
PM169	XQ90ZR	00047395	6/05/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00047395	6/05/2022	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00047395	6/05/2022	DEFECT						
PM169	XQ90ZR	00047395	6/05/2022	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00047395	6/05/2022	DEFECT		Reported Defect :-Defect Code : 00007402				
PM169	XQ90ZR	00047396	6/05/2022	ECO	00	Defect Reference : 40452 Date : 21/01/2022 Description of Defect : L/H BUNK SPEAKER NOT WORKING R/H DOOR CARD BROKEN LABOUR SUBMEC				
PM169	XQ90ZR	00047396	6/05/2022	ECO		SERVICE COMPLETED.				
PM169	XQ90ZR	00047396	6/05/2022	ECO	16			CON	YAT	
PM169	XQ90ZR	00047396	6/05/2022	ECO	40			10W50	YAT	
PM169	XQ90ZR	00047396	6/05/2022	ECO	06			2175254	YAT	
PM169	XQ90ZR	00047529	10/05/2022	GEN	39			LAB		CUM
PM169	XQ90ZR	00047529	10/05/2022	GEN	39			LF14000NN		CUM
PM169	XQ90ZR	00047529	10/05/2022	GEN	39			LF14000NN		CUM
PM169	XQ90ZR	00047529	10/05/2022	GEN	39			LAB		CUM
PM169	XQ90ZR	00047533	12/05/2022	GEN	00	LABOUR APPRENB				
PM169	XQ90ZR	00047533	12/05/2022	GEN		REPAIR COMPLETED BY BEN				
						CHANGED NUMBER PLATES FROM XQ48UH TO XQ90ZR AS REAR NU				
PM169	XQ90ZR	00047533	12/05/2022	GEN	16			CON	YAT	
PM169	XQ90ZR	00047766	21/05/2022	CUMAE5	00	LABOUR MECH				
PM169	XQ90ZR	00047766	21/05/2022	CUMAE5		SERVICE COMPLETED BY MICK AND BRENDAN				
PM169	XQ90ZR	00047766	21/05/2022	CUMAE5	00	FITTED MAINTENANCE LABEL LABOUR SUBMEC				
PM169	XQ90ZR	00047766	21/05/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00048069	3/06/2022	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00048069	3/06/2022	CUMAE5		SERVICE COMPLETED BY BEN AND BRENDAN				
PM169	XQ90ZR	00048069	3/06/2022	CUMAE5	00	REPLACED LHS FRONT MUDGAURD AND FRONT MUDFLAP LOWER GRILL BOLT LABOUR SUBMEC				
PM169	XQ90ZR	00048069	3/06/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00048069	3/06/2022	CUMAE5	11			K127-1116-09A	YAT	
PM169	XQ90ZR	00048069	3/06/2022	DEFECT		Reported Defect :-Defect Code : 00007648 Defect Reference : 40456 Date : 19/05/2022 Description of Defect : SERVICE DUE 22.5.22 GEARSTICK RUBS ON SEAT ALOT				
PM169	XQ90ZR	00048185	8/06/2022	GEN	39	SERVICE 03.06.2022 LAB				STEMC
PM169	XQ90ZR	00048185	8/06/2022	GEN	39			PART		STEMC
PM169	XQ90ZR	00048185	8/06/2022	GEN	39			CON		STEMC
PM169	XQ90ZR	00048185	8/06/2022	GEN	39			CON		STEMC
PM169	XQ90ZR	00048185	8/06/2022	GEN	39			PART		STEMC
PM169	XQ90ZR	00048185	8/06/2022	GEN	39			LAB		STEMC
PM169	XQ90ZR	00048433	20/06/2022	CUMAE5	01	LABOUR				
PM169	XQ90ZR	00048433	20/06/2022	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	00	LABOUR MECH				
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5		SERVICE COMPLETED BY MICK AND BRENDAN				

						ADBLUE FLUSH (AIRSIDE) COMPLETED RHS CAB RAM WEEPING (BEFORE 2 YEAR WARRANTY EXPII TRIM BROKEN (WARRANTY) LABOUR SUBMEC					
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	00						
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	16			CON	YAT		
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	06			LF14000NN	YAT		
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	06			FF5776	YAT		
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	06			AS2474	YAT		
PM169	XQ90ZR	00048433	20/06/2022	CUMBE5	40			3413005	YAT		
PM169	XQ90ZR	00048847	7/07/2022	CUMAE5	00	LABOUR APPRENK					
PM169	XQ90ZR	00048847	7/07/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND TYLER					
PM169	XQ90ZR	00048847	7/07/2022	CUMAE5	00	REPLACED EXPIRED EXTINGUISHER LABOUR APPREN					
PM169	XQ90ZR	00048847	7/07/2022	CUMAE5	16			CON	YAT		
PM169	XQ90ZR	00048848	7/07/2022	ECO	00	LABOUR APPRENB					
PM169	XQ90ZR	00048848	7/07/2022	ECO		SERVICE COMPLETED BY BEN					
PM169	XQ90ZR	00048848	7/07/2022	ECO	16			CON	YAT		
PM169	XQ90ZR	00048848	7/07/2022	ECO	06			ED2175254-S	YAT		
PM169	XQ90ZR	00048848	7/07/2022	ECO	40			10W50	YAT		
PM169	XQ90ZR	00049049	12/07/2022	GEN	39			LAB			FLEWF
PM169	XQ90ZR	00049049	12/07/2022	GEN		COMPLETED BY FLEET IMAGING INV-10127					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
						TOUCH UP PAINT ON PASSENGER SIDE ABOVE TYRE				
PM169	XQ90ZR	00049049	12/07/2022	GEN	39			LAB		FLEWF
PM169	XQ90ZR	00049391	27/07/2022	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00049391	27/07/2022	CUMAE5		SERVICE COMPLETED BY BEN, TYLER AND KEIRAN				
						AS PER DEFECT 7648, GEAR STICK IS ONLY JUST TOUCHING SEAT *REMINDER FOR DEFECT 7942 TO BE REPAIRED BY BROWN AND H				
PM169	XQ90ZR	00049391	27/07/2022	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00049391	27/07/2022	CUMAE5	00	LABOUR APPRENK				
PM169	XQ90ZR	00049391	27/07/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00049397	28/07/2022	TYRES	15			33000051		BRIAUS
PM169	XQ90ZR	00049397	28/07/2022	TYRES	15			33000051		BRIAUS
PM169	XQ90ZR	00049784	10/08/2022	CUMAE5	01	LABOUR				
PM169	XQ90ZR	00049784	10/08/2022	CUMAE5		SERVICE COMPLETED TYLER				
PM169	XQ90ZR	00049784	10/08/2022	CUMAE5	00	* CHECK WHEEL BEARINGS NEXT SERVICE FOR METAL LAB APPREN				
PM169	XQ90ZR	00049784	10/08/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00049786	10/08/2022	ECO	01	LABOUR				
PM169	XQ90ZR	00049786	10/08/2022	ECO		SERVICE COMPLETED BY TYLER				
PM169	XQ90ZR	00049786	10/08/2022	ECO	00	LABOUR APPREN				
PM169	XQ90ZR	00049786	10/08/2022	ECO	16			CON	YAT	
PM169	XQ90ZR	00049786	10/08/2022	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00049786	10/08/2022	ECO	40			10W50	YAT	
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN, MICK AND BEN				
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	00	ADJUSTED CLUTCH REPLACED WIPER BLADES LABOUR ME				
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	06			MK13584	YAT	
PM169	XQ90ZR	00050029	20/08/2022	CUMAE5	40			3413005	YAT	
PM169	XQ90ZR	00050029	20/08/2022	DEFECT		Reported Defect :-Defect Code : 00007891				
PM169	XQ90ZR	00050507	9/09/2022	CUMAE5		Defect Reference : WO 49784 Date : 10/08/2022 Description of Defect : * CHECK WHEEL BEARINGS NEXT SERVICE FOR METAL LAB MECH				
PM169	XQ90ZR	00050507	9/09/2022	CUMAE5	00	SERVICE COMPLETED BY MICK AND TYLER				

							NEEDS 2 NEW WINDSCREENS ASAP - AWAITING REPLY FROM OPE				
							NEED TO GO TO BROWN AND HURLEY FOR CAB RAM BEFORE WAF				
PM169	XQ90ZR	00050507	9/09/2022	CUMAE5	00		LABOUR APPREN				
PM169	XQ90ZR	00050507	9/09/2022	CUMAE5	16				CON	YAT	
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00050507	9/09/2022	DEFECT			Reported Defect :-Defect Code : 00007742				
PM169	XQ90ZR	00050569	9/09/2022	WARRAN	39		Defect Reference : WO48433 Date : 20/06/2022 Description of De				
							RHS CAB RAM WEEPING (BEFORE 2 YEAR WARRANTY EXPII				
							TRIM BROKEN (WARRANTY)				
							LABOUR				
PM169	XQ90ZR	00050569	9/09/2022	WARRAN			REPAIR COMPLETED BY ROCKLEA TRUCK ELECTRICAL INV#				
							CHECKED OVER FOUND ALTERNATOR TO BE FAUKLTY, REPLACED AND T				
							DXA4125RTE - 12V 80AMP DENSO STYLE ALTERNATOR (CURRENT S				
PM169	XQ90ZR	00050578	14/09/2022	GEN	39		LABOUR				
PM169	XQ90ZR	00050578	14/09/2022	GEN			REPAIR COMPLETED KEIRAN AND TYLER				
							- COMPLETED FULL AFTER TREAT FLUSH				
PM169	XQ90ZR	00050578	14/09/2022	GEN	00		- REPLACED INJECTOR AS IT WAS BLOCKED LABOUR MECH				
PM169	XQ90ZR	00050578	14/09/2022	GEN	00		LABOUR APPREN				
PM169	XQ90ZR	00050578	14/09/2022	GEN	16				CON	YAT	
PM169	XQ90ZR	00050820	23/09/2022	CUMAE5	00		LABOUR MECH1				
PM169	XQ90ZR	00050820	23/09/2022	CUMAE5			SERVICE COMPLETED BY KEIRAN				
PM169	XQ90ZR	00050820	23/09/2022	CUMAE5	16		PLEASE REMIND MICK OF DEFECT #7969		CON	YAT	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				77000180	BRIAUS01	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				77000194	BRIAUS01	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				33000051	BRIAUS01	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				33000051	BRIAUS01	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				77000194	BRIAUS01	
PM169	XQ90ZR	00050845	26/09/2022	TYRES	15				77000180	BRIAUS01	
PM169	XQ90ZR	00051061	1/10/2022	GEN	39				LAB	QUAWIND01	
PM169	XQ90ZR	00051061	1/10/2022	GEN	39				LAB	QUAWIND01	
PM169	XQ90ZR	00051407	17/10/2022	CUMAE5	00		LABOUR APPRENB				
PM169	XQ90ZR	00051407	17/10/2022	CUMAE5			SERVICE COMPLETED BY BEN AND TYLER				
PM169	XQ90ZR	00051407	17/10/2022	CUMAE5	00		REPAIRED TRAILER LIGHTS WIRING LABOUR APPREN				
PM169	XQ90ZR	00051407	17/10/2022	CUMAE5	16				CON	YAT	
PM169	XQ90ZR	00051442	17/10/2022	ECO	00		LABOUR APPRENB				
PM169	XQ90ZR	00051442	17/10/2022	ECO			SERVICE COMPLETED BY BEN				
PM169	XQ90ZR	00051442	17/10/2022	ECO	16				CON	YAT	
PM169	XQ90ZR	00051442	17/10/2022	ECO	06				ED2175254-S	YAT	
PM169	XQ90ZR	00051442	17/10/2022	ECO	40				10W50	YAT	
PM169	XQ90ZR	00051877	7/11/2022	CUMAE5	01		LABOUR MECH				
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00051877	7/11/2022	CUMAE5			SERVICE COMPLETED.				
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	00		LABOUR APPRENB				
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5			SERVICE COMPLETED BY BEN AND TYLER				
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	00		TOPPED UP ENG COOLANT LABOUR APPREN				
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	16				CON	YAT	
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	06				AF1969M	YAT	
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	06				MK13584	YAT	
PM169	XQ90ZR	00051877	7/11/2022	CUMBE5	40				15W40	YAT	

PM169	XQ90ZR	00051877	7/11/2022	DEFECT		Reported Defect :-Defect Code : 00008149 Defect Reference : 40458 Date : 17/10/2022 Description of Defect A SERVICES, SLEEPER AIR SERVICE NEW WIPER BLADES CHANGE AIR CON, CAB FILLER TRAILER ABS LIGHT KEEPS COMING ON AND OFF UNPLUG T PLEASE				
PM169	XQ90ZR	00051877	7/11/2022	DEFECT		COULDN'T FAULT ABD LIGHT, TOLD KEG TO MONITOR Reported Defect :- Defect Code : 00008127 Defect Reference : 40458 Date : 17/10/20 SERVICE DUE - DONE FRIDGE NOT WORKING, TURNS ON BUT WON'T GET COLD				
PM169	XQ90ZR	00051870	7/11/2022	GEN	39			LAB		KLADE
PM169	XQ90ZR	00051870	7/11/2022	GEN	39			LAB		KLADE
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			LAB		RURME
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			PART		RURME
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			ENVLEV		RURME
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			ENVLEV		RURME
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			PART		RURME
PM169	XQ90ZR	00052227	22/11/2022	GEN	39			LAB		RURME
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			LAB		YATTR
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			PART		YATTR
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			CON		YATTR
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			LAB		YATTR
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			PART		YATTR
PM169	XQ90ZR	00052979	1/12/2022	GEN	39			CON		YATTR
PM169	XQ90ZR	00052437	3/12/2022	CUMAE5	00	LABOUR MECH1				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00052437	3/12/2022	CUMAE5		REPLACED ELECTRICAL PLUG ADJUSTED RIDE HEIGHT TO 10.5" BITH SIDES SERVICE COMPLETED BY KEIRAN				
PM169	XQ90ZR	00052437	3/12/2022	CUMAE5	16	CON		YAT		
PM169	XQ90ZR	00052447	3/12/2022	DEFECT		DEFECT CLEARED BY KEIRAN				
PM169	XQ90ZR	00052447	3/12/2022	GEN	00	LABOUR MECH1				
PM169	XQ90ZR	00052447	3/12/2022	GEN		REPAIR COMPLETED BY KEIRAN				
PM169	XQ90ZR	00052447	3/12/2022	GEN	06			ED2175254-S	YAT	
PM169	XQ90ZR	00052447	3/12/2022	GEN	40			3413005	YAT	
PM169	XQ90ZR	00052447	3/12/2022	GEN	16			CON	YAT	
PM169	XQ90ZR	00052642	10/12/2022	CUMAE5	00	LABOUR MECH1				
PM169	XQ90ZR	00052642	10/12/2022	CUMAE5		TOPPED UP WITH 4 L OF OIL				
PM169	XQ90ZR	00052642	10/12/2022	CUMAE5		REPLACED PRESSS STUD ON LEFT HAND ROAD TRAIN SIGN BLADES FITTED SECOND HAND ANTISAIL BRACKET TO RIGHT HAND COMPLETED BY KEIRAN AND FLYNN				
					00	LABOUR APPRENF				
PM169	XQ90ZR	00052642	10/12/2022	CUMAE5	40			3413005	YAT	
PM169	XQ90ZR	00052642	10/12/2022	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00052642	10/12/2022	DEFECT		Reported Defect :-Defect Code : 00008389 Defect Reference : 40460 Date : 09/12/2022 Description of Defect LH ROAD TRAIN SIGN CLIPS BROKEN NEW WINDSCREEN W NOT GETTING WATER PRESSURE OUT OF WINDOW WASHE POSSIBLE DEFECT CLEARED BY KEIRAN				
						PART		VIEWTR01	EX00026367	
PM169	XQ90ZR	00052840	12/12/2022	GEN	39					

PM169	XQ90ZR	00052840	12/12/2022	GEN	39			LAB	VIEWTR01	E
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			PART	VIEWTR01	E
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			PART	VIEWTR01	E
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			PART	VIEWTR01	I
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			PART	VIEWTR01	I
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			LAB	VIEWTR01	I
PM169	XQ90ZR	00052840	12/12/2022	GEN	39			PART	VIEWTR01	I
PM169	XQ90ZR	00053111	3/01/2023	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00053111	3/01/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5	01	LABOUR MECH				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5		SERVICE COMPLETED BENNY - ADJUSTED TURNTABLE AND CLUTCH - TIGHTENED RHS HUB CAP - BLOWN WASHER JEST LABOUR APPRENB				
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5	00					
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00053111	3/01/2023	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00053111	3/01/2023	DEFECT		Reported Defect :-Defect Code : 00008463				
PM169	XQ90ZR	00053111	3/01/2023	ECO		Defect Reference : 40461 Date : 03/01/2023 Description of Defect B SERVICE DUE POSSIBLE RH STER HUB LEAK RH WIPER WASHER NOT SPRAYING ON WINDOW ADBLUE 3 CODE CLUTCH ADJUSTMENT LABOUR MECH				
PM169	XQ90ZR	00053111	3/01/2023	ECO	01	SERVICE COMPLETED BENNY				
PM169	XQ90ZR	00053111	3/01/2023	ECO	00	BLOWN AIR FILTER LABOUR APPRENB				
PM169	XQ90ZR	00053111	3/01/2023	ECO	40			10W50	YAT	
PM169	XQ90ZR	00053111	3/01/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5		SERVICE COMPLETED. REPLACED BATTERIES LABOUR APP				
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	00					
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	00	LABOUR APPREN				
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	00	LABOUR APPRENF				
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	16			PART	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	06			WF2126	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	06			17237	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	06			A-3380W1687	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	40			85W140	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	06			LF637	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	06			1409408	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	16			MF70ZZDT	YAT	
PM169	XQ90ZR	00053882	3/02/2023	CUMCE5	16			CON	YAT	
PM169	XQ90ZR	00053882	3/02/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00053891	3/02/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00053882	3/02/2023	DEFECT						
PM169	XQ90ZR	00053891	3/02/2023	DEFECT						
PM169	XQ90ZR	00053882	3/02/2023	DEFECT		DEFECT CLEARED.				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00053891	3/02/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00053882	3/02/2023	DEFECT		Reported Defect :-Defect Code : 00008232 Defect Reference : 40459 Date : 15/11/2022 Description of Defect RIGHT HAND SIDE SPRING PRESSURE IS FAULTY				

PM169	XQ90ZR	00053882	3/02/2023	DEFECT		WINDSCREEN WIPERS Reported Defect :- Defect Code : 00007969 Defect Reference : WO50507 Date : 09/0 NEEDS 2 NEW WINDSCREENS ASAP - AWAITING REPLY FR(NEED TO GO TO BROWN AND HURLEY FOR CAB RAM BEFOI LABOUR APPRENF				
PM169	XQ90ZR	00053891	3/02/2023	ECO	00					
PM169	XQ90ZR	00053891	3/02/2023	ECO		SERVICE COMPLETED.				
PM169	XQ90ZR	00053891	3/02/2023	ECO	06		ED2175254-S	YAT		
PM169	XQ90ZR	00053891	3/02/2023	ECO	06		PART	YAT		
PM169	XQ90ZR	00053891	3/02/2023	ECO	16		PART	YAT		
PM169	XQ90ZR	00053891	3/02/2023	ECO	16		CON	YAT		
PM169	XQ90ZR	00053890	3/02/2023	EXOINS	00	LABOUR APPRENB				
PM169	XQ90ZR	00053890	3/02/2023	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATT INSPECTION COMPLETED BY EXODAS WORKSHOP				
PM169	XQ90ZR	00053890	3/02/2023	EXOINS	16		CON	YAT		
PM169	XQ90ZR	00054197	17/02/2023	GEN	39		LABEXT			ROC
PM169	XQ90ZR	00054197	17/02/2023	GEN	39		PART			ROCTF
PM169	XQ90ZR	00054197	17/02/2023	GEN	39		PART			ROCTF
PM169	XQ90ZR	00054197	17/02/2023	GEN	39		LABEXT			ROC
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		PART			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		LABEXT			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		MISCON			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		ENVLEV			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		ENVLEV			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		MISCON			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		LABEXT			BROI
PM169	XQ90ZR	00054492	20/02/2023	GEN	39		PART			BROI
PM169	XQ90ZR	00054298	23/02/2023	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00054298	23/02/2023	CUMAE5		SERVICE COMPLETED. REPAIRED RADIATOR				
PM169	XQ90ZR	00054298	23/02/2023	CUMAE5	00	GRILL LABOUR APPRENF				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00054298	23/02/2023	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00054298	23/02/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00054298	23/02/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00054298	23/02/2023	DEFECT						
PM169	XQ90ZR	00054298	23/02/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00054289	23/02/2023	GEN	39			PART		KENAL
PM169	XQ90ZR	00054289	23/02/2023	GEN	39			CON		KENAL
PM169	XQ90ZR	00054289	23/02/2023	GEN	39			LABEXT		KENAL
PM169	XQ90ZR	00054610	2/03/2023	TYRES	15			33000051		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			11004493		BRIAU
PM169	XQ90ZR	00054610	2/03/2023	TYRES	15			33000085		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00054610	2/03/2023	TYRES	15			33000051		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			33000241		BRIAU
PM169	XQ90ZR	00054610	2/03/2023	TYRES	15			33000085		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			33000241		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00054640	2/03/2023	TYRES	15			11004493		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			11004493		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000085		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			11004496		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000084		BRIAU

PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000051		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000051		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			11004496		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000085		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00054620	3/03/2023	TYRES	15			11004493		BRIAU
PM169	XQ90ZR	00054515	6/03/2023	CUMAE5	01	LABOUR MECH				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00054515	6/03/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	00	LABOUR APPREN				
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	16			MK13584	YAT	
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	16			FS19764	YAT	
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00054515	6/03/2023	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00054515	6/03/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00054516	6/03/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00054515	6/03/2023	DEFECT						
PM169	XQ90ZR	00054516	6/03/2023	DEFECT						
PM169	XQ90ZR	00054515	6/03/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00054516	6/03/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00054516	6/03/2023	ECO	00	LABOUR APPREN				
PM169	XQ90ZR	00054516	6/03/2023	ECO		SERVICE COMPLETED.				
PM169	XQ90ZR	00054516	6/03/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00054516	6/03/2023	ECO	40			10W50	YAT	
PM169	XQ90ZR	00054516	6/03/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00055058	24/03/2023	CUMAE5	00	LABOUR MECH 1				
PM169	XQ90ZR	00055058	24/03/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00055058	24/03/2023	CUMAE5	00	LH SIDE DRIVERS BRAKES LISTTING LABOUR APPRENF			LOW	
PM169	XQ90ZR	00055058	24/03/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00055058	24/03/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00055058	24/03/2023	DEFECT						
PM169	XQ90ZR	00055058	24/03/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00055443	6/04/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00055443	6/04/2023	DEFECT						
PM169	XQ90ZR	00055443	6/04/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00055443	6/04/2023	ECO	00	LABOUR APPRENF				
PM169	XQ90ZR	00055443	6/04/2023	ECO		SERVICE COMPLETED.				
PM169	XQ90ZR	00055443	6/04/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00055443	6/04/2023	ECO	40			10W50	YAT	
PM169	XQ90ZR	00055443	6/04/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00055441	6/04/2023	GEN	39			WHEALI		DLLAS
PM169	XQ90ZR	00055441	6/04/2023	GEN	39			TYRREP		DLLAS
PM169	XQ90ZR	00055441	6/04/2023	GEN	39			TYRREP		DLLAS
PM169	XQ90ZR	00055441	6/04/2023	GEN	39			WHEALI		DLLAS
PM169	XQ90ZR	00055442	11/04/2023	CUMAE5	00	LABOUR MECH 3				
PM169	XQ90ZR	00055442	11/04/2023	CUMAE5		SERVICE COMPLETED. GEARBOX STILL STICKING IN GEAR WHEN UNDER LOAD RO. TRAIN SIGN REVETS REQUIRE REPAIRS				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00055442	11/04/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00055442	11/04/2023	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00055442	11/04/2023	DEFECT						
PM169	XQ90ZR	00055442	11/04/2023	DEFECT		DEFECT CLEARED.				

PM169	XQ90ZR	00055442	11/04/2023	DEFECT		Reported Defect :-				
						Defect Code : 00009045 Defect Reference : 40465 Date : 05/01/20				
						Description of Defect :				
						A SERVICE SLEEPER SERVICE				
						GEAR BOX STILL STICKING WHEN UNDER LOAD				
						GRILL LEFT BOTTOM LOOSE				
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			11004493		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			77000180		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000517		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000085		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000085		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000517		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			77000180		BRIAUS
PM169	XQ90ZR	00055531	12/04/2023	TYRES	15			11004493		BRIAUS
PM169	XQ90ZR	00055607	17/04/2023	CUMAE5	00	LABOUR MECH				
PM169	XQ90ZR	00055607	17/04/2023	CUMAE5		SERVICE COMPLETED. FIXED UP REAR				
PM169	XQ90ZR	00055607	17/04/2023	CUMAE5		GUARD LHS FIXED UP GRILL				
						LABOUR APPRENF				
					00					
PM169	XQ90ZR	00055607	17/04/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00055607	17/04/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00055607	17/04/2023	DEFECT						
PM169	XQ90ZR	00055607	17/04/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00055678	19/04/2023	TYRES	15			33000188		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			11004496		BRIAUS
PM169	XQ90ZR	00055678	19/04/2023	TYRES	15			33000188		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000370		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000536		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000051		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000085		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000085		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000051		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000536		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000370		BRIAUS
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			33000084		BRIAUS

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00055694	19/04/2023	TYRES	15			11004496		BRIAUS
PM169	XQ90ZR	00055835	24/04/2023	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00055835	24/04/2023	DEFECT						
PM169	XQ90ZR	00055835	24/04/2023	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00055835	24/04/2023	GEN	00	LABOUR APPRENF				
PM169	XQ90ZR	00055835	24/04/2023	GEN		REPAIR COMPLETED.			OU	
PM169	XQ90ZR	00055835	24/04/2023	GEN	00	ADBLUE FLUSH BLOW WATER JETS LABOUR MECH 1			T	
PM169	XQ90ZR	00055835	24/04/2023	GEN	06			AS2474	YA	
PM169	XQ90ZR	00055835	24/04/2023	GEN	16			CON	YA	
PM169	XQ90ZR	00055890	27/04/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00055890	27/04/2023	DEFECT						
PM169	XQ90ZR	00055890	27/04/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00055890	27/04/2023	DEFECT		Reported Defect :-Defect Code : 00009116				
PM169	XQ90ZR	00055890	27/04/2023	GEN		Defect Reference : 40466 Date : 26/04/2023				
						Description of Defect : TIGHTEN B/R GRILL				
						LOOSE TIGHTEN GEAR KNOB CHECK OIL				
						SLEEPER AIR CHECK DRIVE TYRES				
						LABOUR MECH 1				
					00					
PM169	XQ90ZR	00055890	27/04/2023	GEN		REPAIR COMPLETED.				

TOOK BOLTS OUT OF GRILL AND PUT LOCK TIGHT ON TO KEEP EM
CHECKED OIL IN SLEEPER AIR, WAS ALL GOOD BUT FOUND THE BE

PM169	XQ90ZR	00055890	27/04/2023	GEN	00	LABOUR APPREN			
PM169	XQ90ZR	00055890	27/04/2023	GEN	11		13A0990	YAT	
PM169	XQ90ZR	00055890	27/04/2023	GEN	16		CON	YAT	
PM169	XQ90ZR	00056182	11/05/2023	CUMAE5	01	LABOUR MECH			
PM169	XQ90ZR	00056182	11/05/2023	CUMAE5		SERVICE COMPLETED.			
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	00	LABOUR MECH 1			
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5		SERVICE COMPLETED. REPLACED BELTS & TENSIONER REI			
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	00	RERIVETED ROAD TRAIN SIGN BACK ON WILL NEED DRIVE E SLEEPER AIR SERVICE TO BE DONE NEXT TIME ITS BACK. LABOUR APPREN			
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	06		MK13584	YAT	
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	40		15W40	YAT	
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	11		6PK1590	YAT	
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	11		D84-1000-31223	YAT	
PM169	XQ90ZR	00056182	11/05/2023	CUMBE5	16		CON	YAT	
PM169	XQ90ZR	00056182	11/05/2023	DEFECT	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00056182	11/05/2023	DEFECT						
PM169	XQ90ZR	00056182	11/05/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00056182	11/05/2023	DEFECT		Reported Defect :- Defect Code : 00009185 Defect Reference : 40467 Date : 10/05/2023 Description of Defect : B SERVICE SLEEPER SERVICE TIGHTEN GEAR KNOB WIPER BLADES IF NEEDED LABEXT				
PM169	XQ90ZR	00056513	16/05/2023	GEN	39					ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			S30-200		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			LABEXT		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			LABEXT		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			LABEXT		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			S30-200		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			LABEXT		ROCTR
PM169	XQ90ZR	00056513	16/05/2023	GEN	39			LABEXT		ROCTR
PM169	XQ90ZR	00056669	27/05/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00056670	27/05/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00056669	27/05/2023	DEFECT						
PM169	XQ90ZR	00056670	27/05/2023	DEFECT						
PM169	XQ90ZR	00056669	27/05/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00056670	27/05/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00056669	27/05/2023	DEFECT		Reported Defect :-Defect Code : 00008957				
PM169	XQ90ZR	00056669	27/05/2023	DEFECT		Defect Reference : PM169 Date : 24/03/2023 Description of Defect LH SIDE DRIVERS BRAKES LISTTING LOW Reported Defect :-				
						Defect Code : 00009186 Defect Reference : PM169 Date : 11/05/2 : WILL NEED DRIVE BRAKE RELINE ASAP SLEEPER AIR SERVICE TO BE DONE NEXT TIME ITS BACK. L				
PM169	XQ90ZR	00056670	27/05/2023	ECO	00					
PM169	XQ90ZR	00056670	27/05/2023	ECO		SERVICE COMPLETED.				
PM169	XQ90ZR	00056670	27/05/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00056670	27/05/2023	ECO	40			10W50	YAT	
PM169	XQ90ZR	00056670	27/05/2023	ECO	16			CON	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00056669	27/05/2023	GEN		REPAIR COMPLETED.				
PM169	XQ90ZR	00056669	27/05/2023	GEN		REPLACED ALL BRAKE SHOES ON BOTH DRIVES REPLACED DRIVE DRUMS				
					00	LABOUR APPREN				
PM169	XQ90ZR	00056669	27/05/2023	GEN	02			KSMA2124707Q	YAT	
PM169	XQ90ZR	00056669	27/05/2023	GEN	02			PART	YAT	
PM169	XQ90ZR	00056669	27/05/2023	GEN	16			CON	YAT	
PM169	XQ90ZR	00056972	6/06/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00056972	6/06/2023	DEFECT						
PM169	XQ90ZR	00056972	6/06/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00056972	6/06/2023	GEN	00	LABOUR MECH 1				
PM169	XQ90ZR	00056972	6/06/2023	GEN		REPAIR COMPLETED.				
PM169	XQ90ZR	00056972	6/06/2023	GEN	16	REPLACE FRONT INDICATOR IN BULLBAR 2110-24V YAT				
PM169	XQ90ZR	00056972	6/06/2023	GEN	16			CON	YAT	
PM169	XQ90ZR	00057121	12/06/2023	CUMAE5	00	LABOUR APPRENF				
PM169	XQ90ZR	00057121	12/06/2023	CUMAE5		SERVICE COMPLETED. REPLACED 1KG FIRE EXTINGUISHER CAMERA BRACKET ON DASH NEEDS REPLACING, AS ITS BROKEN.				
PM169	XQ90ZR	00057121	12/06/2023	CUMAE5	00	LABOUR MECH 3				
PM169	XQ90ZR	00057121	12/06/2023	CUMAE5	19			FIREEXT1KG	YAT	
PM169	XQ90ZR	00057121	12/06/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00057121	12/06/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00057121	12/06/2023	DEFECT						
PM169	XQ90ZR	00057121	12/06/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00057671	3/07/2023	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00057671	3/07/2023	CUMAE5		SERVICE COMPLETED. NEXT 'A' SERVICE WILL BE DUE FOR SLEEPER				
PM169	XQ90ZR	00057671	3/07/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00057671	3/07/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00057671	3/07/2023	DEFECT						
PM169	XQ90ZR	00057671	3/07/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00057689	3/07/2023	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00057689	3/07/2023	TYRES	15			33000085		BRIA
PM169	XQ90ZR	00057689	3/07/2023	TYRES	15			33000051		BRIA
PM169	XQ90ZR	00057689	3/07/2023	TYRES	15			33000085		BRIA
PM169	XQ90ZR	00057799	5/07/2023	GEN	39			A-7318		BROHU
PM169	XQ90ZR	00057800	5/07/2023	GEN	39			A-7318		BROHU
PM169	XQ90ZR	00057799	5/07/2023	GEN	39			A-7318		BROH
PM169	XQ90ZR	00057800	5/07/2023	GEN	39			A-7318		BROH
PM169	XQ90ZR	00058099	13/07/2023	GEN	39			LABEXT		FLEV

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00058099	13/07/2023	GEN	39			LABEXT		FLEWF
PM169	XQ90ZR	00058032	17/07/2023	GEN	15			33000085		BRIAUS
PM169	XQ90ZR	00058032	17/07/2023	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00058032	17/07/2023	GEN	15			33000085		BRIAUS
PM169	XQ90ZR	00058032	17/07/2023	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00058300	25/07/2023	CUMAE5	00	LABOUR MECH 3				
PM169	XQ90ZR	00058300	25/07/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00058300	25/07/2023	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00058300	25/07/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00058300	25/07/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00058300	25/07/2023	DEFECT						
PM169	XQ90ZR	00058300	25/07/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00059227	23/08/2023	ECO	01	LABOUR APPRENF				
PM169	XQ90ZR	00059227	23/08/2023	ECO		SERVICE COMPLETED BY FLYNN ON			23/08/2023.	
PM169	XQ90ZR	00059227	23/08/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00059227	23/08/2023	ECO	40			3413005	YAT	
PM169	XQ90ZR	00059227	23/08/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00059306	23/08/2023	GEN	39			LBP2189GH		BROHU

PM169	XQ90ZR	00059306	23/08/2023	GEN	39			LBP2189GH		BROHL
PM169	XQ90ZR	00059226	25/08/2023	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00059226	25/08/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	01	LABOUR MECH 1				
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5		SERVICE COMPLETED BY NICK & FLYNN ON 23/08/2023.				
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	00	REPLACED 2 X FRONT DRIVE SHOCKERS LABOUR APPRENF				
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	06			FS19763	YAT	
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00059226	25/08/2023	CUMBE5	10			K374-38K1T	YAT	
PM169	XQ90ZR	00059226	25/08/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00059226	25/08/2023	DEFECT						
PM169	XQ90ZR	00059226	25/08/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00059226	25/08/2023	DEFECT		Reported Defect :- Defect Code : 00009411 Defect Reference : PM169 Date : 30/06/2 Description of Defect : NEXT 'A' SERVICE WILL BE DUE FOR SLEEPER AIR.				
PM169	XQ90ZR	00059339	25/08/2023	GEN	39	DEFECT CLEARED 23/08/2023 SLEEPER AIR SERVICE CARRI OUT. LABEXT		FLEWRI01		

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00059339	25/08/2023	GEN	39			LABEXT		FLEWF
PM169	XQ90ZR	00059547	5/09/2023	CUMAE5	00	LABOUR MECH 1				
PM169	XQ90ZR	00059547	5/09/2023	CUMAE5		SERVICE COMPLETED 05/09/2023				
PM169	XQ90ZR	00059547	5/09/2023	CUMAE5	00	REPLACED AUTO SLACK ADJUSTER RHS STEER. FITTED GE STICK KNOB. REPAIRED DRIVING LIGHTS. LABOUR APPRENF				
PM169	XQ90ZR	00059547	5/09/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00059547	5/09/2023	CUMAE5	16			R801079	YAT	
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			11004493		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			77000180		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000520		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			11004493		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			77000180		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000520		BRIAUS
PM169	XQ90ZR	00059559	5/09/2023	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			0A5801F1F1A0A		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-IVU-TRANS		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-BYPASS-12		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-AIR-KW		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AWIMM TRUCK		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AWIMM TRUCK		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-AIR-KW		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-BYPASS-12		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			AW-IVU-TRANS		EMAX0
PM169	XQ90ZR	00060052	19/09/2023	GEN	39			0A5801F1F1A0A		EMAX0
PM169	XQ90ZR	00060266	28/09/2023	CUMAE5	01	LABOUR APPREN				
PM169	XQ90ZR	00060266	28/09/2023	CUMAE5		SERVICE COMPLETED BY TYLER & BEN ON 26/09/2023.				
PM169	XQ90ZR	00060266	28/09/2023	CUMAE5	00	REWIRED LOWER SPOTLIGHTS TO WORK REPLACED PULL FOR TURNTABLE HANDLE LABOUR APPRENB				
PM169	XQ90ZR	00060266	28/09/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00060266	28/09/2023	CUMAE5	40			3413005	YAT	
PM169	XQ90ZR	00060605	5/10/2023	ECO	01	LABOUR MECH 1				
PM169	XQ90ZR	00060605	5/10/2023	ECO		SERVICE COMPLETED BY NICK ON 05/10/2023.				

PM169	XQ90ZR	00060605	5/10/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00060605	5/10/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00060605	5/10/2023	ECO	40			3413005	YAT	
PM169	XQ90ZR	00060544	6/10/2023	CUMAE5	01	LABOUR MECH 1				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00060544	6/10/2023	CUMAE5		SERVICE COMPLETED BY NICK, MATT & JOSEPH ON 05/10/2(				
						REPLACED CABLE IN STEERING COLUMN. SERVICED SLEEP				
						PBS TABLET HAS BEEN INSTALLED REPLACED WIPER BLAD				
						LABOUR MECH 3				
PM169	XQ90ZR	00060544	6/10/2023	CUMAE5	00					
PM169	XQ90ZR	00060544	6/10/2023	CUMAE5	00	LABOUR APPRENJ				
PM169	XQ90ZR	00060544	6/10/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00060544	6/10/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00060544	6/10/2023	DEFECT						
PM169	XQ90ZR	00060544	6/10/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00060544	6/10/2023	DEFECT		Reported Defect :-				
						Defect Code : 00010048				
						Defect Reference : 42420B Date : 05/10/2023 Description of Defect :				
						NEEDS PBS TABLET INSTALLED				
PM169	XQ90ZR	00060544	6/10/2023	DEFECT		DEFECT CLEARED 05/10/2023				
						PBS TRACKER INSTALLED				
						Reported Defect :-Defect Code : 00010047				
						Defect Reference : 42420A Date : 06/10/2023 Description of Defec				
						ICE PACK SERVICE				
PM169	XQ90ZR	00060544	6/10/2023	DEFECT		DEFECT CLEARED 05/10/2023 SERVICE CARRIED OUT				
						Reported Defect :-				
						Defect Code : 00010046 Defect Reference : 42420 Date : 05/10/20				
						A-SERVICE, STEERING TILT, WIPERS, SPOTLIGHTS AGAIN				
PM169	XQ90ZR	00060734	10/10/2023	GEN	39	DEFECT CLEARED 05/10/2023				
						REPLACED WIPER BLADES, CARRIED OUT 'A' SERVICE LABC				
PM169	XQ90ZR	00060734	10/10/2023	GEN		REPAIR COMPLETED.				
						DRIVING LIGHT ELECTRICAL WIRING FAULT - ISOLATE WIRING FAUI				
						CHECK OPERATION ONCE COMPLETE				
PM169	XQ90ZR	00060734	10/10/2023	GEN	00	LABOUR APPRENF				
PM169	XQ90ZR	00060734	10/10/2023	GEN	16			CON	YAT	
PM169	XQ90ZR	00061129	25/10/2023	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00061129	25/10/2023	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	01	LABOUR MECH 3				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5		SERVICE COMPLETED BY MATT, TYLER & JOSEPH ON 25/10/				
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	00	LABOUR APPREN				
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	00	LABOUR APPRENJ				
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00061129	25/10/2023	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			99015526		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000084		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000517		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			99015526		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000084		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000517		BRIAUS
PM169	XQ90ZR	00061291	27/10/2023	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00070489	9/11/2023	WEICAL		CALIBRATED BY NATHAN BENNETT 09/11/2023				

AIR GAUGE:
ADJUSTED:
WEIGHBRIDGE:

AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LABOU

PM169	XQ90ZR	00062917	17/11/2023	GEN	39	
PM169	XQ90ZR	00062917	17/11/2023	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 17/11/2023.

XQ90ZR

Reported complaint/ fault: Aftertreatment light on

Connect to truck and follow fault tree for fault code 3548. Resolved fault wit
system. Once aftertreatment system was flushed numerous times took truc

PM169	XQ90ZR	00062043	22/11/2023	CUMAE5	01	LABOUR APPRENF
PM169	XQ90ZR	00062043	22/11/2023	CUMAE5		SERVICE COMPLETED BY FLYNN & JOE ON 22/11/2023.

REPLACED NEW TRAILER PLUG ON BACK OF TRUCK. REPLACED T/
REPLACED TWO WIPER BLADES
TIGHTENED BOLTS ON GRILL AS THEY WERE LOOSE. SWAPPED AI

NOTED: CRACK IN WINDSCREEN DRIVER'S SIDE MIDDLE OF WINDS

PM169	XQ90ZR	00062043	22/11/2023	CUMAE5	00	LABOUR APPRENJ			
PM169	XQ90ZR	00062043	22/11/2023	CUMAE5	16		CON	YAT	
PM169	XQ90ZR	00062043	22/11/2023	CUMAE5	31		82161/25	YAT	
PM169	XQ90ZR	00062043	22/11/2023	CUMAE5	13		WIPRBLAD	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00062044	22/11/2023	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00062044	22/11/2023	DEFECT						
PM169	XQ90ZR	00062044	22/11/2023	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00062044	22/11/2023	ECO	01	LABOUR APPRENJ				
PM169	XQ90ZR	00062044	22/11/2023	ECO		SERVICE COMPLETED BY JOE ON 22/11/2023.				
PM169	XQ90ZR	00062044	22/11/2023	ECO	16			CON	YAT	
PM169	XQ90ZR	00062044	22/11/2023	ECO	40			10W50	YAT	
PM169	XQ90ZR	00062044	22/11/2023	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00062209	23/11/2023	GEN	39			LABEXT		QUAW
PM169	XQ90ZR	00062300	23/11/2023	GEN	39			LABEXT		QUAW
PM169	XQ90ZR	00062209	23/11/2023	GEN	39			LABEXT		QUAW
PM169	XQ90ZR	00062300	23/11/2023	GEN	39			LABEXT		QUAW
PM169	XQ90ZR	00065083	30/11/2023	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00065083	30/11/2023	DEFECT						
PM169	XQ90ZR	00065083	30/11/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00065083	30/11/2023	GEN	39	LABOUR				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00065083	30/11/2023	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 30/11/2023.				

K032 TANK STRAP RUBBERS WORN, LEFT HAND FRONT
Inspect tank straps found frontmost lh strap lining deformed. Got nev
and remove tank light panel. Unbolted lh front strap. Removed lining
Reconnected light panel

Part Number Part Description Quantity Total Cost K89-1004-1260 LI
Parts Totals: 1.00
K031 WINDOW TINTING SCRATCHED, BOTH SIDES
Remove lh door trim panels. Unbolt inner panel from door frame. Ins
come free and harness was rubbing on window. Use duct tape to tap
Refit inner panel. Check operation of window ? okay, could not see c
area.

O/N for tint repair has been removed, will need to raise another card
Part Number Part Description Quantity Total Cost 52703-1 MINI FU
Parts Totals: 4.00
K031-2 WIRING INSIDE THE PEEK WINDOW IS HANGING DOWI
Took photos of driver?s side window then stripped door down and se
K011 WHEN APPLYING BRAKES, AIR LEAK REPORTED.
-CUSTOMER DIAGNOSED AS TRACTOR PROTECTION VALVE I
Found air leaking from blue suzi when service brake applied. Got ne
Removed valve. transferred fittings to new valve. bolted new valve. r
? okay. Connected
trailer gauges and checked operation of trailer air supply ? okay. AIR

PM169	XQ90ZR	00062635	5/12/2023	WEICAL		ADJUSTED: 16.680 WEIGHBRIDGE: 16.980				
PM169	XQ90ZR	00062570	7/12/2023	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LABOUR APPRENB				
PM169	XQ90ZR	00062570	7/12/2023	CUMAE5		SERVICE COMPLETED BY BEN & NICK ON 07/12/2023. REPLA				
PM169	XQ90ZR	00062570	7/12/2023	CUMAE5	00	EXTINGUISHER WINDSCREEN HAS BEEN REPLACED LABOUR MECH 1				
PM169	XQ90ZR	00062570	7/12/2023	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00062570	7/12/2023	CUMAE5	19			FIREEXT1.5KG	YAT	
PM169	XQ90ZR	00062570	7/12/2023	DEFECT	01	LABOUR MECH				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00062570	7/12/2023	DEFECT						
PM169	XQ90ZR	00062570	7/12/2023	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00062570	7/12/2023	DEFECT		Reported Defect :-				

Defect Code : 00010325 Defect Reference : PM169 Date : 22/11/2023 Des
WINDSCREEN HAS CRACK ON DRIVER'S SIDE IN MIDDLE OF WINDS

						DEFECT CLEARED 07/12/2023 WINDSCREEN HAS BEEN REPLACED
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	LABOUR
PM169	XQ90ZR	00062741	11/12/2023	GEN		REPAIR COMPLETED BY BROWN & HURLEY 11/12/2023

K057 A/C BLOWS HOT AIR
Complaint- A/C blows hot air $495.00 Cause- compressor
CorrectionChecked for fan cutting in found its not cutting in Turn on fan a/c
Test pressure switch all ok
Test power to compressor found power at the plug but compressor not clut
Removed drive belt and A/C belt Removed compressor and receiver dryer
Replaced seals and replaced receiver dryer Replaced seals and replaced c
Carried out full system Vacuum Re-gas system and test pressures
Part Number Part Description Quantity Total Cost
K251-571 FILTER-FREON, RECEIVER/DRYER 1.00 131.71
0R9303 O-RING-A/C NO6 2.00 0.22
F69-1019 COMPRESSOR-REFRIGERANT 1.00 467.34
0R9304 O-RING-A/C NO8 1.00 0.20
0R9305 O-RING-A/C N010 1.00 0.60

PM169	XQ90ZR	00062741	11/12/2023	GEN	39	LAB	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	K251-571	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	CON	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	F69-1019	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	CON	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	CON	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	R134A	BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39	CON	BR

PM169	XQ90ZR	00062741	11/12/2023	GEN	39			ENVLEV		BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			ROUNDING		BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			LAB		BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			K251-571		BR
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			CON		BR

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			F69-1019		BROI
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			CON		BROI
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			CON		BROI
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			R134A		BROI
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			CON		BROHU
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			ENVLEV		BROHU
PM169	XQ90ZR	00062741	11/12/2023	GEN	39			ROUNDING		BROI
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			11004493		BRIA
PM169	XQ90ZR	00062797	14/12/2023	GEN	39	LABOUR	APPRENJ			
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			77000180		BRIA
PM169	XQ90ZR	00062797	14/12/2023	GE		REPAIR COMPLETED BY JOSEPH ON 14/12/2023. REPLACE REPLACED 2 CLUSTER LIGHTS				
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000084		BRIA
PM169	XQ90ZR	00062797	14/12/2023	GEN	16			CON	YAT	
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000370		BRIA
PM169	XQ90ZR	00062797	14/12/2023	GEN	06			TRPCAF0001	YAT	
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000517		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000518		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000118		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			11004493		BRIAUS
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			77000180		BRIAUS
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000084		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000370		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000517		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000518		BRIA
PM169	XQ90ZR	00062822	14/12/2023	GEN	15			33000118		BRIA
PM169	XQ90ZR	00063251	3/01/2024	CUMAE5	01	LABOUR	APPRENB			
PM169	XQ90ZR	00063251	3/01/2024	CUMAE5		SERVICE COMPLETED BY BEN ON 03/01/2023.				
PM169	XQ90ZR	00063251	3/01/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00063212	3/01/2024	ECO	01	LABOUR	APPRENJ			
PM169	XQ90ZR	00063252	3/01/2024	ECO	01	LABOUR	APPRENJ			
PM169	XQ90ZR	00063212	3/01/2024	ECO		SERVICE COMPLETED BY JOE & BEN ON 03/01/2024. REPLAC				
PM169	XQ90ZR	00063252	3/01/2024	ECO		COOLING FAN SERVICE COMPLETED BY JOE ON 03/01/2023.				
PM169	XQ90ZR	00063212	3/01/2024	ECO	00	LABOUR	APPRENB			
PM169	XQ90ZR	00063252	3/01/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00063212	3/01/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00063252	3/01/2024	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00063212	3/01/2024	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00063252	3/01/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00063212	3/01/2024	ECO	40			10W50	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00063212	3/01/2024	ECO	03			PART	YAT	
PM169	XQ90ZR	00063211	4/01/2024	GEN	07			K-4460-PAC		BROI
PM169	XQ90ZR	00063211	4/01/2024	GEN	07			308935-531-PAC		BROI
PM169	XQ90ZR	00063211	4/01/2024	GEN	07			K-4460-PAC		BROI
PM169	XQ90ZR	00063211	4/01/2024	GEN	07			308935-531-PAC		BROI
PM169	XQ90ZR	00063245	5/01/2024	GEN	39	LABOUR	APPRENB			
PM169	XQ90ZR	00063245	5/01/2024	GEN		REPAIR COMPLETED BY BEN, AARON & JOE ON 05/01/2023. F				
PM169	XQ90ZR	00063245	5/01/2024	GEN	00	AND INPUT SHAFT KIT LABOUR MECH 4				
PM169	XQ90ZR	00063245	5/01/2024	GEN	00	LABOUR	APPRENJ			
PM169	XQ90ZR	00063245	5/01/2024	GEN	16			CON	YAT	
PM169	XQ90ZR	00063245	5/01/2024	GEN	07			308935-531-PAC	YAT	
PM169	XQ90ZR	00063245	5/01/2024	GEN	07			K-4460-PAC	YAT	
PM169	XQ90ZR	00063690	17/01/2024	CUMAE5	01	LABOUR	MECH			

PM169	XQ90ZR	00063690	17/01/2024	CUMAE5		SERVICE COMPLETED.			
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	01	LABOUR MECH 4			
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5		SERVICE COMPLETED BY AARON, JOE & MATT ON 17/01/202			
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	00	LABOUR APPRENJ			
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	00	LABOUR MECH 3			
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	16		CON	YAT	
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	06		MK13584	YAT	
PM169	XQ90ZR	00063690	17/01/2024	CUMBE5	40		3413005	YAT	
PM169	XQ90ZR	00064122	1/02/2024	CUMAE5	01	LABOUR MECH 3			
PM169	XQ90ZR	00064122	1/02/2024	CUMAE5		SERVICE COMPLETED BY MATT & TYLER ON 01.02.2024.			
						REPLACED AIR TANK DRAIN CABLE REPLACED RH INDICATC			
						NOTED:			
						* REAR DIFF STARTED TO SEEP @ BANJO TO CARRIER. DEFECT NC			
PM169	XQ90ZR	00064122	1/02/2024	CUMAE5	00	LABOUR APPREN			
PM169	XQ90ZR	00064122	1/02/2024	CUMAE5	16		CON	YAT	
PM169	XQ90ZR	00064122	1/02/2024	CUMAE5	14		2110-12V	YAT	
PM169	XQ90ZR	00064738	10/02/2024	DEFECT	01	LABOUR MECH			
PM169	XQ90ZR	00064738	10/02/2024	DEFECT					
PM169	XQ90ZR	00064738	10/02/2024	DEFECT		DEFECT CLEARED.			
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABOUR			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00064738	10/02/2024	GE		REPAIR COMPLETED BY CUMMINS SOUTH PACIFIC ON 10/(				

Complaint: Fault Lights
Cause: Aftertreatment doser pump clogged Correction: 578713Km / 7299H

Receive call-out.
Travel to branch and pick parts / pack tooling.
Travel to site.
Gain access to vehicle.
Complete Job Safety Analysis (JSA).
Download ECM to find active faults 3738, 3548, and recent counts of 3575.
Remove aftertreatment injector, flush pump, and replace airwater separato
Perform override test, flowing 100ml OK.
Lower cab and clear inactive faults, check over, all OK. Travel back and co

PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	06	AS2474	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	ENVLEV	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	CON	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	CON	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	TRAVEL FEE	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	06	AS2474	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	ENVLEV	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	CON	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	16	CON	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	LABEXT	CUM
PM169	XQ90ZR	00064738	10/02/2024	GEN	39	TRAVEL FEE	CUM
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	99015526	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000084	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000517	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000085	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000118	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000085	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	33000540	BRI/
PM169	XQ90ZR	00064625	15/02/2024	GEN	15	99015526	BRI/

PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000084		BRI
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000517		BRIAUS
PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000085		BRIAUS
PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000085		BRIAUS
PM169	XQ90ZR	00064625	15/02/2024	GEN	15			33000540		BRIAUS
PM169	XQ90ZR	00064866	21/02/2024	CUMAE5	01	LABOUR MECH 1				
PM169	XQ90ZR	00064866	21/02/2024	CUMAE5		SERVICE COMPLETED BY NICK ON 21.02.24 Rear diff head bolts loose checked all off them - check next servic Replaced trailer light plug and swapped reverse from 5 to 2				
PM169	XQ90ZR	00064866	21/02/2024	CUMAE5	16	CON	YAT			
PM169	XQ90ZR	00064832	21/02/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00064866	21/02/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00064832	21/02/2024	DEFECT						
PM169	XQ90ZR	00064866	21/02/2024	DEFECT						
PM169	XQ90ZR	00064832	21/02/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00064866	21/02/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00064832	21/02/2024	ECO	01	LABOUR APPRENJ				
PM169	XQ90ZR	00064832	21/02/2024	ECO		SERVICE COMPLETED BY JOSEPH ON 21/02/2024.				
PM169	XQ90ZR	00064832	21/02/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00064832	21/02/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00064832	21/02/2024	ECO	06			ED002175254-S	YAT	
PM169	XQ90ZR	00065323	8/03/2024	CUMAE5	01	LABOUR MECH 1				
PM169	XQ90ZR	00065323	8/03/2024	CUMAE5		SERVICE COMPLETED BY NICK & BEN ON 08/03/2024.				
PM169	XQ90ZR	00065323	8/03/2024	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00065323	8/03/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00065323	8/03/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00065323	8/03/2024	DEFECT						
PM169	XQ90ZR	00065323	8/03/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00065383	12/03/2024	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00065383	12/03/2024	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00065383	12/03/2024	CUMBE5	01	LABOUR MECH				
PM169	XQ90ZR	00065383	12/03/2024	CUMBE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	01	LABOUR MECH 4				
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5		SERVICE COMPLETED BY ETHAN & TYLER ON 12/03/2024. RE				
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	00	TENSIONER LABOUR APPREN				
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	16			CON	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	11			12PK2380	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	40			3372765	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	40			3334800	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	16			UF110	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	06			T224P	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	06			A-3380W1687	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	06			TRPCAF0001	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	06			WF2127	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	06			FS19764	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	11			89440	YAT	
PM169	XQ90ZR	00065383	12/03/2024	CUMCE5	11			6PK1590	YAT	
PM169	XQ90ZR	00065383	12/03/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00065385	12/03/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00065386	12/03/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00065383	12/03/2024	DEFECT						
PM169	XQ90ZR	00065385	12/03/2024	DEFECT						
PM169	XQ90ZR	00065386	12/03/2024	DEFECT						
PM169	XQ90ZR	00065383	12/03/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00065385	12/03/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00065386	12/03/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00065386	12/03/2024	ECO	01	LABOUR APPREN				
PM169	XQ90ZR	00065386	12/03/2024	ECO		SERVICE COMPLETED BY TYLER ON			12/03/2024.	
PM169	XQ90ZR	00065386	12/03/2024	ECO	16			CON	YAT	

PM169	XQ90ZR	00065386	12/03/2024	ECO	06			ED002175254-S	YAT
PM169	XQ90ZR	00065386	12/03/2024	ECO	06			0021751550	YAT
PM169	XQ90ZR	00065386	12/03/2024	ECO	40			10W50	YAT
PM169	XQ90ZR	00065386	12/03/2024	ECO	06			FS1251	YAT
PM169	XQ90ZR	00065386	12/03/2024	ECO	06			Z15	YAT
PM169	XQ90ZR	00065385	12/03/2024	EXOINS	01	LABOUR MECH 4			
PM169	XQ90ZR	00065385	12/03/2024	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATT 1			
						INSPECTION COMPLETED BY ETHAN ON 12/03/2024 NO DEFE IDENTIFIED			
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			11001472	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			11006520	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			77000232	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000084	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000084	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000370	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000370	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000518	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000517	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000118	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000518	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			11006520	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000118	BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000084	BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			11001472	BRIAUS

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000370		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			77000232		BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000518		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000084		BRIAUS
PM169	XQ90ZR	00065650	20/03/2024	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000370		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000517		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000518		BRIAUS
PM169	XQ90ZR	00065643	20/03/2024	GEN	15			33000118		BRIAUS
PM169	XQ90ZR	00065848	26/03/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00065848	26/03/2024	DEFECT						
PM169	XQ90ZR	00065848	26/03/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00065848	26/03/2024	GEN	39	LABOUR				
PM169	XQ90ZR	00065848	26/03/2024	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 26/03/2024.				
						Cause: Brake booster line rubbed through on torque rod bracket				
						Correction: Bring vehicle into workshop and release brakes Remove rear chec air leak Found rub through hose for brake booster lines Remove dc hose Replace hose and secure. Fit new double zip ties Start vehicle up a ok Refit checker plate covers				
						LABEXT		BROHUR01	EX00033531	
PM169	XQ90ZR	00065848	26/03/2024	GEN	39					
PM169	XQ90ZR	00065848	26/03/2024	GEN	39			PART	BROHUR01	E
PM169	XQ90ZR	00065848	26/03/2024	GEN	16			CON	BROHUR01	E
PM169	XQ90ZR	00065848	26/03/2024	GEN	16			ENVLEV	BROHUR01	E
PM169	XQ90ZR	00065848	26/03/2024	GEN	39			LABEXT	BROHUR01	3
PM169	XQ90ZR	00065848	26/03/2024	GEN	39			PART	BROHUR01	3
PM169	XQ90ZR	00065848	26/03/2024	GEN	16			CON	BROHUR01	3
PM169	XQ90ZR	00065848	26/03/2024	GEN	16			ENVLEV	BROHUR01	3

PM169	XQ90ZR	00065977	28/03/2024	GEN	39			LABEXT	KENAUT01 E
PM169	XQ90ZR	00065977	28/03/2024	GEN	16			CON	KENAUT01 E

PM169	XQ90ZR	00065977	28/03/2024	GEN	03			PART	KENAUT01 E

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00065977	28/03/2024	GEN	39			LABEXT		KENAU
PM169	XQ90ZR	00065977	28/03/2024	GEN	16			CON		KENAU
PM169	XQ90ZR	00065977	28/03/2024	GEN	03			PART		KENAU
PM169	XQ90ZR	00066010	4/04/2024	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00066010	4/04/2024	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5	01	LABOUR MECH 4				
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5		'B' SERVICE COMPLETED BY ETHAN, TYSON & BEN ON 04/04				
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5	00	LABOUR APPRENT2				
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00066010	4/04/2024	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00066010	4/04/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00066010	4/04/2024	DEFECT						
PM169	XQ90ZR	00066010	4/04/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5	01	LABOUR APPREN				
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER, ETHAN & NICK ON 26/04				
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5	00	BELLY BAR BOLTS FITTED 12V / 24V INVERTER REPLACED COOLANT FILTER DUE TO LEAKING SLEEPER AIF COMPLETED. LABOUR MECH 4				
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5	00	LABOUR MECH 1				
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00066677	26/04/2024	CUMAE5	06			WF2127	YAT	
PM169	XQ90ZR	00066677	26/04/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00066678	26/04/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00066677	26/04/2024	DEFECT						
PM169	XQ90ZR	00066678	26/04/2024	DEFECT						
PM169	XQ90ZR	00066677	26/04/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00066678	26/04/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00066678	26/04/2024	ECO	01	LABOUR APPREN				
PM169	XQ90ZR	00066678	26/04/2024	ECO		SERVICE COMPLETED BY TYLER ON 26/04/2024.				
PM169	XQ90ZR	00066678	26/04/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00066678	26/04/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00066678	26/04/2024	ECO	06			ED2175254-S	YAT	
PM169	XQ90ZR	00066930	9/05/2024	CUMAE5	00	LABOUR APPRENB				
PM169	XQ90ZR	00066930	9/05/2024	CUMAE5		SERVICE COMPLETED BY WORKSHOP 09/05/2024				
PM169	XQ90ZR	00066930	9/05/2024	CUMAE5	00	REPLACED LHS STEERING HUB SEAL LABOUR APPRENJ				
PM169	XQ90ZR	00066930	9/05/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00066930	9/05/2024	CUMAE5	11			43764	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00066930	9/05/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00066930	9/05/2024	DEFECT						
PM169	XQ90ZR	00066930	9/05/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00067080	14/05/2024	GEN	39			LABEXT		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	39			CALL OUT FEE		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	14			BATTERY		BDSM
PM169	XQ90ZR	00067080	14/05/2024	GEN	16			CON		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	16			ENVLEV		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	39			LABEXT		BDSM

PM169	XQ90ZR	00067080	14/05/2024	GEN	39			CALL OUT FEE		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	14			BATTERY		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	16			CON		BDSME
PM169	XQ90ZR	00067080	14/05/2024	GEN	16			ENVLEV		BDSME
PM169	XQ90ZR	00067614	28/05/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00067614	28/05/2024	DEFECT						
PM169	XQ90ZR	00067614	28/05/2024	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00067614	28/05/2024	GEN	39	LABOUR MECH 4				
PM169	XQ90ZR	00067614	28/05/2024	GEN		REPAIR COMPLETED BY ETHAN ON 28/05/2024. REMOVED AI				
PM169	XQ90ZR	00067614	28/05/2024	GEN		REPLACED GOVERNOR VALVE FITTED TAP ON AIR DRYER (STOCK)				
					16	CON	YAT			
PM169	XQ90ZR	00067614	28/05/2024	GEN	03			275707	YAT	
PM169	XQ90ZR	00067971	8/06/2024	CUMAE5	01	LABOUR MECH 4				
PM169	XQ90ZR	00067971	8/06/2024	CUMAE5		'A' SERVICE COMPLETED BY ETHAN ON 08/06/2024. NO ISSUI				
PM169	XQ90ZR	00067971	8/06/2024	CUMAE5	16	DIFF				
						CON	YAT			
PM169	XQ90ZR	00067971	8/06/2024	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00067971	8/06/2024	DEFECT						
PM169	XQ90ZR	00067971	8/06/2024	DEFECT		DEFECT CLEARED.				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00067971	8/06/2024	DEFECT		Reported Defect :-Defect Code : 00010800 Defect Reference : PM169 Date : 01/02/2024 Description of Defect REAR DIFF STARTED TO SEEP @ BANJO TO CARRIER				
PM169	XQ90ZR	00068025	8/06/2024	ECO	01	DEFECT CLEARED ON 08/06/2024 NO ISSUE WITH DIFF LABOUR APPRENJ				
PM169	XQ90ZR	00068025	8/06/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY JOSEPH ON 08/06/2(				
PM169	XQ90ZR	00068025	8/06/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00068025	8/06/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00068025	8/06/2024	ECO	06			ED002175254-S	YAT	
PM169	XQ90ZR	00068484	21/06/2024	CUMAE5	01	LABOUR MECH				
PM169	XQ90ZR	00068484	21/06/2024	CUMAE5		SERVICE COMPLETED.				
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5	01	LABOUR MECH				
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5		'B' SERVICE COMPLETED BY MICK & NICK ON 21/06/2024. TEI				
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5	00	WASHER BOTTLE NECK BOLTS LABOUR MECH 1				
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5	06			MK13584	YAT	
PM169	XQ90ZR	00068484	21/06/2024	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00069181	15/07/2024	GEN	15			33000096		BRI/
PM169	XQ90ZR	00069181	15/07/2024	GEN	15			33000188		BRI/
PM169	XQ90ZR	00069181	15/07/2024	GEN	15			33000096		BRI/
PM169	XQ90ZR	00069181	15/07/2024	GEN	15			33000188		BRI/
PM169	XQ90ZR	00069264	18/07/2024	CUMAE5	01	LABOUR APPREN				
PM169	XQ90ZR	00069264	18/07/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER & ETHAN (WORKSHOP) ON 18/07/2				
						REPLACED LH CAB SHOCK TIGHTENED GRILL BOLTS & GUARD BOLTS TOPPED UP COC LABOUR MECH 4				
PM169	XQ90ZR	00069264	18/07/2024	CUMAE5	00					
PM169	XQ90ZR	00069264	18/07/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00069264	18/07/2024	CUMAE5	13			CH6030B	YAT	
PM169	XQ90ZR	00069265	18/07/2024	ECO	01	LABOUR MECH 4				
PM169	XQ90ZR	00069265	18/07/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY ETHAN (WORKSHOI				
PM169	XQ90ZR	00069265	18/07/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00069265	18/07/2024	ECO	06			ED002175254-S	YAT	
PM169	XQ90ZR	00069265	18/07/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	01	LABOUR MECH 6				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code

PM169	XQ90ZR	00069620	31/07/2024	CUMAE5		'A' SERVICE COMPLETED BY JOSEPH, COREY & ALEX (WORKSH			
						ADJUSTED TURNTABLE ADJUSTED CLUTCH ADDED 5L OF ENGINE (			
						RE-KITTED HORTON FAN AND REPLACED FAN BELT			
						NOTED:			
						* TOP MIDDLE RADIATOR STAY NEEDS NEW RUBBERS			
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	00	LABOUR APPRENJ			
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	00	LABOUR APPRENA			
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	16		CON	YAT	
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	40		3413005	YAT	
PM169	XQ90ZR	00069620	31/07/2024	CUMAE5	03		F35008SD	YAT	
PM169	XQ90ZR	00069620	31/07/2024	DEFECT	01	LABOUR MECH			
PM169	XQ90ZR	00069620	31/07/2024	DEFECT					
PM169	XQ90ZR	00069620	31/07/2024	DEFECT		DEFECT CLEARED.			
PM169	XQ90ZR	00069620	31/07/2024	DEFECT		Reported Defect :-			
						Defect Code : 00012064 Defect Reference : 42421 Date : 29/07/20			
						Description of Defect :			
						AIR LEAK HORTON FAN BAD			
PM169	XQ90ZR	00069620	31/07/2024	DEFECT		DEFECT CLEARED ON 31/07/2024			
						RE-KITTED HORTON FAN AND REPLACED FAN BELT			
						Reported Defect :-			
						Defect Code : 00012065 Defect Reference : 42422 Date : 31/07/20			
						Description of Defect :			
						A SERVICE + HORTON AIR LEAK. AFTER TREAT LIGHT ON AC			
PM169	XQ90ZR	00069729	6/08/2024	GEN	39	DEFECT CLEARED ON 31/07/2024			
						RE-KITTED HORTON FAN AND REPLACED FAN BELT			
						LABEXT KENAUT01			
PM169	XQ90ZR	00069729	6/08/2024	GEN	13		PART	KENAUT01	
PM169	XQ90ZR	00069729	6/08/2024	GEN	39		LABEXT	KENAUT01	
PM169	XQ90ZR	00069729	6/08/2024	GEN	13		PART	KENAUT01	
PM169	XQ90ZR	00070155	20/08/2024	CUMAE5	01	LABOUR MECH 6			
PM169	XQ90ZR	00070155	20/08/2024	CUMAE5		'A' SERVICE COMPLETED BY COREY (WORKSHOP) 20/08/202			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00070155	20/08/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00070155	20/08/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00070156	20/08/2024	DEFECT	01	LABOUR	MECH			
PM169	XQ90ZR	00070155	20/08/2024	DEFECT						
PM169	XQ90ZR	00070156	20/08/2024	DEFECT						
PM169	XQ90ZR	00070155	20/08/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00070156	20/08/2024	DEFECT		DEFECT	CLEARED.			
PM169	XQ90ZR	00070156	20/08/2024	ECO	01	LABOUR	MECH 5			
PM169	XQ90ZR	00070156	20/08/2024	ECO		SLEEER AIR SERVICE COMPLETED BY BEN (WORKSHOP) ON 20/08/20				
PM169	XQ90ZR	00070156	20/08/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00070156	20/08/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00070180	21/08/2024	TYRES	15			33000096		BRIAU
PM169	XQ90ZR	00070180	21/08/2024	TYRES	15			33000118		BRIAU
PM169	XQ90ZR	00070180	21/08/2024	TYRES	15			33000096		BRIAU
PM169	XQ90ZR	00070180	21/08/2024	TYRES	15			33000118		BRIAU
PM169	XQ90ZR	00070446	29/08/2024	CUMAE5	01	LABOUR MECH 5				
PM169	XQ90ZR	00070446	29/08/2024	CUMAE5		"A" SERVICE COMPLETED BY WORKSHOP 29/08/2024				
PM169	XQ90ZR	00070446	29/08/2024	CUMAE5	00	COMPLETED DOSA FLUSH REPLACED WIPER BLADE ASSEM				
						LABOUR APPRENJ				

PM169	XQ90ZR	00070446	29/08/2024	CUMAE5	16		CON	YAT
PM169	XQ90ZR	00070446	29/08/2024	CUMAE5	16		WW600B8B	YAT
PM169	XQ90ZR	00070446	29/08/2024	DEFECT	01	LABOUR MECH		
PM169	XQ90ZR	00070446	29/08/2024	DEFECT				
PM169	XQ90ZR	00070446	29/08/2024	DEFECT		DEFECT CLEARED.		
PM169	XQ90ZR	00070719	5/09/2024	CUMAE5	01	LABOUR MECH		
PM169	XQ90ZR	00070719	5/09/2024	CUMAE5		SERVICE COMPLETED.		
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5	01	LABOUR MECH 1		
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5		'A' SERVICE COMPLETED BY NICK & BEN ON 05/09/2024. REP		
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5	00	BOTTOM STAY RUBBERS FOR RADIATOR LABOUR MECH 5		
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5	16		CON	YAT
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5	06		MK13584	YAT
PM169	XQ90ZR	00070719	5/09/2024	CUMBE5	40		3413005	YAT
PM169	XQ90ZR	00070719	5/09/2024	DEFECT	01	LABOUR MECH		
PM169	XQ90ZR	00070719	5/09/2024	DEFECT				
PM169	XQ90ZR	00070719	5/09/2024	DEFECT		DEFECT CLEARED.		
PM169	XQ90ZR	00070719	5/09/2024	DEFECT		Reported Defect :-		

Defect Code : 00012066 Defect Reference : PM169 Date : 31/07/20
Description of Defect :
TOP MIDDLE RADIATOR STAY NEEDS NEW RUBBERS

PM169	XQ90ZR	00070822	10/09/2024	TYRES	15		11003134	BRIAUS

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			99015526		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33000524		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000522		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			11003134		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000118		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			99015526		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00070822	10/09/2024	TYRES	15			33000524		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000522		BRIA
PM169	XQ90ZR	00070856	10/09/2024	TYRES	15			33000118		BRIA
PM169	XQ90ZR	00070875	11/09/2024	GEN	13			P27-1084-015		BROH
PM169	XQ90ZR	00070875	11/09/2024	GEN	13			P27-1084-002		BROH
PM169	XQ90ZR	00070875	11/09/2024	GEN	13			P27-1084-015		BROH
PM169	XQ90ZR	00070891	11/09/2024	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 11/09/2024. II				

WILDLIFE IMPACT-CHECK ALL AIRBAGS AS VEHICLE LOSING
-Inspected all airbags, air lines, air fittings and valves with soapy wa
RHS tank.

-Driver stated air tank would drop when going over bumps.
-Buillt up air and drove over speed bump approx 10 times. Found r
bump but would build up to 800kpa within 10 seconds.
-Unable to test driver vehicle on road due to front drive RHS inner t

AIR DRYER IS EXHAUSTING MORE THAN NORMAL AND HAS
-Fully opened tap at bottom of air dryer.
-Built up air and found governor set to 850kpa.
-No abnormal sound present and frequency of exhausting found to

						P27-1084-002	BROHUR01	3317787	SWITCH-R	
PM169	XQ90ZR	00070875	11/09/2024	GEN	13					
PM169	XQ90ZR	00070891	11/09/2024	GEN	39			LABEXT	BROHUR01	E
PM169	XQ90ZR	00070891	11/09/2024	GEN	16			VEHICLE LOSING AIR - WILDLIFE IMPA		
								CON	BROHUR01	E
PM169	XQ90ZR	00070891	11/09/2024	GEN	16					
								ENVLEV		BROH

PM169	XQ90ZR	00070891	11/09/2024	GEN	39			LABEXT	BROHUR01	3
								VEHICLE LOSING AIR - WILDLIFE IMPA		

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00070891	11/09/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00070891	11/09/2024	GEN	16			ENVLEV		BROHU
PM169	XQ90ZR	00071878	2/10/2024	CUMAE5	01	LABOUR	APPRENJ			
PM169	XQ90ZR	00071878	2/10/2024	CUMAE5		'A' SERVICE COMPLETED BY JOSEPH & NICK (WORKSHOP) C				
PM169	XQ90ZR	00071878	2/10/2024	CUMAE5	00	LABOUR MECH 1				
PM169	XQ90ZR	00071878	2/10/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00071879	2/10/2024	ECO	01	LABOUR APPRENJ				
PM169	XQ90ZR	00071879	2/10/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY JOSEPH (WORKSHC				
PM169	XQ90ZR	00071879	2/10/2024	ECO	16			CON	YAT	
PM169	XQ90ZR	00071879	2/10/2024	ECO	06			ED002175254-S	YAT	
PM169	XQ90ZR	00071879	2/10/2024	ECO	40			10W50	YAT	
PM169	XQ90ZR	00072922	24/10/2024	CUMAE5	01	LABOUR APPREN				
PM169	XQ90ZR	00072922	24/10/2024	CUMAE5		"A" SERVICE COMPLETED BY WORKSHOP 24/10/2024.				
PM169	XQ90ZR	00072922	24/10/2024	CUMAE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00072922	24/10/2024	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00073075	28/10/2024	GEN	15			LABEXT		NABQA
PM169	XQ90ZR	00073075	28/10/2024	GEN	15			LABEXT		NABQA
PM169	XQ90ZR	00073057	29/10/2024	GEN	13			89U631DB		BROH
PM169	XQ90ZR	00073057	29/10/2024	GEN	13			PART		BROH
PM169	XQ90ZR	00073057	29/10/2024	GEN	13			89U631DB		BROH
PM169	XQ90ZR	00073057	29/10/2024	GEN	13			PART		BROH
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			99015526		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000370		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			22001381		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000518		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			99015526		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000370		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			22001381		BRIA
PM169	XQ90ZR	00073015	29/10/2024	TYRES	15			33000518		BRIA
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			11006520		BRIA
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000370		BRIA
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000536		BRIA
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000118		BRIA

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			11006520		BRIAU
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000536		BRIAU
PM169	XQ90ZR	00073326	7/11/2024	TYRES	15			33000118		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			98000120		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237		BRIAU

PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			33000237	BRIAUS
PM169	XQ90ZR	00073420	11/11/2024	TYRES	15			98000120	BRIAUS
PM169	XQ90ZR	00073415	14/11/2024	ECO	01	LABOUR MECH 5			
PM169	XQ90ZR	00073415	14/11/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY WORKSHOP 14/11/2024 SLEEF			
PM169	XQ90ZR	00073415	14/11/2024	ECO	16		CON	YAT	
PM169	XQ90ZR	00073415	14/11/2024	ECO	40		10W50	YAT	
PM169	XQ90ZR	00073783	21/11/2024	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 21/11/2024. IN			

Afterhours Service Call Out to Vehicle Breakdown at Maryborough T

Receive afterhours call out request reporting vehicle fault; gather pa troubleshoot active aftertreatment light & engine derate; connect dia Data Valid but Below Normal Operating Range ? Moderately Severe Operating Range ? Moderately Severe Level.
Carry out air solenoid click test; found air solenoid failing to click; ren of air present coming out of pump; carry out air side flush; pump still transfer job to Brown and Hurley Caboolture as per customer reques travel back to workshop.

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00074247	21/11/2024	GEN		REPAIR COMPLETED BY BROWN & HURLEY ON 21/11/2024. II				

Afterhours Service Call Out to Vehicle Breakdown at Maryborough

Troubleshoot Active Aftertreatment Light & Engine Derate

Receive afterhours call out request reporting vehicle fault; gather p at Maryborough Pads; arrive on site; troubleshoot active aftertreatn download fault log & analyse data; found active codes 3738 ? Air S Moderately Severe Level & 3575 ? Aftertreatment 1 Diesel Exhaus Moderately Severe Level. Carry out air solenoid click test; found air pressure present at pump; remove injector line from pump; sight ar pump still failing to click; believe dosing pump failed; new pump no and Hurley Caboolture as per customer request; pack up gear & tra REPAIR COMPLETED BY BROWN & HURLEY ON 21/11/2024

PM169	XQ90ZR	00074451	21/11/2024	GEN					

INVOICE NO. 3409765

Break down call out, Travel to Maryborugh show grounds, reported Break
Received call at 03:00 from Daniel at Exodus stating that Bundaber derate. Call Brown and Hurley Bundaberg to confirm and receive s the doser to prime. Call parts to organise part for job, come into wo complete download. Driver stated the aftertreatment light has been fault, follow diagnostic troubleshooting tree. Check power and grou Remove AdBlue injector from exhaust. Complete AdBlue override i workshop, complete all paperwork.

.
*** Due to nil parts in stock at Bundaberg and a second call out hac
.

BREAKDOWN		BROHUR01	EX00037438	AFTERHO					
PM169	XQ90ZR	00073783	21/11/2024	GEN	39				VEHICL
PM169	XQ90ZR	00074247	21/11/2024	GEN	39		LABEXT		BROHU

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00074451	21/11/2024	GEN	39			LABEXT		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00074247	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	03			5273337RX		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	06			AS2474		BROH
PM169	XQ90ZR	00074247	21/11/2024	GEN	06			AS2474		BROH
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			OF		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			TRAVEL FEE		BROH
PM169	XQ90ZR	00074247	21/11/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			LABEXT		BROH
PM169	XQ90ZR	00074247	21/11/2024	GEN	16			ENVLEV		BROH
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			ENVLEV		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00074247	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	39			LABEXT		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	16			ENVLEV		BROH
PM169	XQ90ZR	00074247	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	03			5273337RX		BROHU
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			BREAKDOWN		BROHU
PM169	XQ90ZR	00074247	21/11/2024	GEN	06			AS2474		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			OF		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00074247	21/11/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			CON		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	06			AS2474		BROH
PM169	XQ90ZR	00074247	21/11/2024	GEN	16			ENVLEV		BROH
PM169	XQ90ZR	00074451	21/11/2024	GEN	16			ENVLEV		BROH
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			TRAVEL FEE		BROH

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00073783	21/11/2024	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00073783	21/11/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00073783	21/11/2024	GEN	16			ENVLEV		BROHU
PM169	XQ90ZR	00074058	26/11/2024	GEN		REPAIR COMPLETED BY NQFM ON 26/11/2024. INVOICE NO. 3				
						Travel from NQFM Workshop to Exodas Depot . Called out as ABS been damaged On inspection found Light Leads and ABS Leads damaged and wir Removed damaged leads replaced with new ones and secured On tested operation with the trailer All leads working - all ok Travel from Exodas Depot back to NQFM Workshop .				
						LABEXT		RCCLOW01 EX00037627		
PM169	XQ90ZR	00074058	26/11/2024	GEN	39					
PM169	XQ90ZR	00074058	26/11/2024	GEN	31			PART	RCCLOW01	E

PM169	XQ90ZR	00074058	26/11/2024	GEN	31			PART	RCCLOW01	E
PM169	XQ90ZR	00074058	26/11/2024	GEN	16			CON	RCCLOW01	E
PM169	XQ90ZR	00074058	26/11/2024	GEN	39			LABEXT	RCCLOW01	3
PM169	XQ90ZR	00074058	26/11/2024	GEN	31			PART	RCCLOW01	3
PM169	XQ90ZR	00074058	26/11/2024	GEN	31			PART	RCCLOW01	3
PM169	XQ90ZR	00074058	26/11/2024	GEN	16			CON	RCCLOW01	3
PM169	XQ90ZR	00074121	16/12/2024	GEN	39			LABEXT	RCCLOW01	E
PM169	XQ90ZR	00074121	16/12/2024	GEN	39			LABEXT	RCCLOW01	3
PM169	XQ90ZR	00074160	17/12/2024	GEN	06			AS2474	BROHUR01	E
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			TRAVEL FEE	BROHUR01	E
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			CON	BROHUR01	E
PM169	XQ90ZR	00074160	17/12/2024	GEN	39			LABEXT	BROHUR01	E
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			CON	BROHUR01	E
PM169	XQ90ZR	00074160	17/12/2024	GEN	06			AS2474	BROHUR01	3
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			TRAVEL FEE	BROHUR01	3
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			CON	BROHUR01	3
PM169	XQ90ZR	00074160	17/12/2024	GEN	39			LABEXT	BROHUR01	3

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00074160	17/12/2024	GEN	16			CON		BROHU
PM169	XQ90ZR	00074724	7/01/2025	GEN		REPAIR COMPLETED BY NQFM ON 07/01/2025. INVOICE NO. 39				
						Called out to test batteries. Found unserviceable. Sourced new ones				
PM169	XQ90ZR	00074724	7/01/2025	GEN	39			LABEXT		RCCLC
PM169	XQ90ZR	00074724	7/01/2025	GEN	14			BATTERY		RCCLC
PM169	XQ90ZR	00074724	7/01/2025	GEN	16			CON		RCCLC
PM169	XQ90ZR	00074724	7/01/2025	GEN	39			LABEXT		RCCLC
PM169	XQ90ZR	00074724	7/01/2025	GEN	14			BATTERY		RCCLC
PM169	XQ90ZR	00074724	7/01/2025	GEN	16			CON		RCCLC
PM169	XQ90ZR	00074922	13/01/2025	GEN		REPAIR COMPLETED BY NQFM ON 13/01/2025. INVOICE NO. 3				

Drove to Exodas depot for no clutch pedal issue. Vehicle needed j
won't start, returned to workshop to bring the Hino back. Charged l
codes off sleeper air and attempted to start . Eventually started.
Drove Hino back and returned with work ute.
Dropped bullbar and tilted cab to look at rods and linkages, found c
Removed front grill to gain access and remove rod. Attemped to fit
length but would not fit.
Traced back to a double link being flipped over the wrong way . Pul
bearing then flip back over and put back together.
Fit rod, test link, flipped over again.
Pulled apart again then traced back to rear link being out of adjustn
Adjusted all links, popped clutch cover and checked over. All good.
Placed links all back together and clutch working.
Fit grill and bullbar. Test drove (up to 100klms on highway) all gooc
Returned truck to Exodas
LABEXT RCCLOW01 EX00038122

PM169	XQ90ZR	00074922	13/01/2025	GEN	39				
PM169	XQ90ZR	00074922	13/01/2025	GEN	16		PART	RCCLOW01	E
PM169	XQ90ZR	00074922	13/01/2025	GEN	39		PART	RCCLOW01	E
PM169	XQ90ZR	00074922	13/01/2025	GEN	16		CON	RCCLOW01	E

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00074922	13/01/2025	GEN	39			LABEXT		RCCLC
PM169	XQ90ZR	00074922	13/01/2025	GEN	16			PART		RCCLC
PM169	XQ90ZR	00074922	13/01/2025	GEN	39			PART		RCCL
PM169	XQ90ZR	00074922	13/01/2025	GEN	16			CON		RCCLC
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			11004493		BRIAU
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000527		BRIAU
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			11004493		BRIA
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000084		BRIA
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33001507		BRIA
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000527		BRIAU
PM169	XQ90ZR	00075727	17/02/2025	TYRES	15			33000237		BRIAU
PM169	XQ90ZR	00075885	21/02/2025	ECO	01	LABOUR APPRENJ				
PM169	XQ90ZR	00075885	21/02/2025	ECO		ECO WIND SERVICE COMPLETED BY JOSEPH (WORKSHOP)				
PM169	XQ90ZR	00075885	21/02/2025	ECO	06			ED002175254-S	YAT	
PM169	XQ90ZR	00075885	21/02/2025	ECO	40			10W50	YAT	
PM169	XQ90ZR	00075885	21/02/2025	ECO	16			CON	YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMAE5	00	LABOUR MECH				
PM169	XQ90ZR	00075884	22/02/2025	CUMAE5		A SERVICE COMPLETED.				
PM169	XQ90ZR	00075884	22/02/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	01	LABOUR APPRENJ				
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5		B SERVICE COMPLETED BY JOSEPH & JOSH (WORKSHOP)				
						FIRE EXT EXP: AUGUST 2025				
						REPLACED 1KG FIRE EXTINGUISHER				
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	16			CON	YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	06			RSK154	YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	06			Z1006	YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	19			FIREEXT1KG	YAT	
PM169	XQ90ZR	00075884	22/02/2025	CUMBE5	40			3413005	YAT	

PM169	XQ90ZR	00075908	24/02/2025	GEN	39	LABOUR APPREN					
PM169	XQ90ZR	00075908	24/02/2025	GEN		MIDLIFE SERVICE COMPLETED BY TYLER ON 24/02/2025.					
PM169	XQ90ZR	00075908	24/02/2025	GEN	16	CARRIED OUT MIDLIFE CON YAT					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00075908	24/02/2025	GEN	03			5607734RX	YAT	
PM169	XQ90ZR	00075908	24/02/2025	GEN	03			3690864RX	YAT	
PM169	XQ90ZR	00075908	24/02/2025	GEN	03			5273337	YAT	
PM169	XQ90ZR	00076861	7/04/2025	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00076861	7/04/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 05/04/2025				
						FIRE EXT EXP: AUGUST 2025				
						REPLACED HEATER TAP AND TOPPED UP COOLANT ADJUS CLUTCH REPLACED TURNTABLE PULL CORD FIXED TANK LIGHT CON YAT				
PM169	XQ90ZR	00076861	7/04/2025	CUMAE5	16					
PM169	XQ90ZR	00076861	7/04/2025	CUMAE5	00	LABOUR APPRENJ				
PM169	XQ90ZR	00076861	7/04/2025	CUMAE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00076861	7/04/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00076861	7/04/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00076861	7/04/2025	DEFECT		Reported Defect :-Defect Code : 00013945				
PM169	XQ90ZR	00076861	7/04/2025	DEFECT		Defect Reference : 40473A Date : 31/03/2025 Description of Defec GREASE SKID PLATE Reported Defect :-				
						Defect Code : 00013944 Defect Reference : 40473 Date : 04/04/20 Description of Defect : NO FREE TRAVEL IN CLUTCH PEDAL				
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			99015526		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000370		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000518		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000518		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000370		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00076997	8/04/2025	TYRES	15			99015526		BRIAUS
PM169	XQ90ZR	00077144	15/04/2025	GEN	39			LAB		QUAWI
PM169	XQ90ZR	00077144	15/04/2025	GEN	39			LAB		QUAWI
PM169	XQ90ZR	00077504	6/05/2025	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00077504	6/05/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 06/05/2025				
						FIRE EXT EXP: AUGUST 2025				
						REPLACED WIPER STALK				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00077504	6/05/2025	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00077504	6/05/2025	CUMAE5	00	LABOUR	MECH 5			
PM169	XQ90ZR	00077504	6/05/2025	CUMAE5	16			202-841	YAT	
PM169	XQ90ZR	00077504	6/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077504	6/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077681	13/05/2025	CUMAE5	00	LABOUR APPREN				
PM169	XQ90ZR	00077681	13/05/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 13.05.2025				
						FIRE EXT EXP: SEPTEMBER 2025				
PM169	XQ90ZR	00077681	13/05/2025	CUMAE5	16	REPLACED LHS DRIVE SHOCK BUSH CON YAT				
PM169	XQ90ZR	00077681	13/05/2025	CUMAE5	00	LABOUR MECH 5				
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	01	LABOUR MECH 5				
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5		C SERVICE COMPLETED BY WORKSHOP 13.05.2025				

						FIRE EXT EXP SEPTEMBER 2025				
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16	REPLACED EXHAUST FLEX CON		YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	00	LABOUR APPREN				
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		T224P	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		WF2127	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		LF637	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		A-3380W1687	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		17237	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	40		3430284	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	40		3430336	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		12PK2380	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		6PK1590	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	06		AF1969M	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	06		UF110	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	06		TRPCAF0001	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		89440	YAT		
PM169	XQ90ZR	00077674	13/05/2025	CUMCE5	16		M66-6542-0440	YAT		
PM169	XQ90ZR	00077673	13/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077674	13/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077677	13/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077681	13/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077673	13/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077674	13/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077677	13/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077681	13/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077677	13/05/2025	EXOINS	01	LABOUR MECH 5				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00077677	13/05/2025	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATT 1ST				
PM169	XQ90ZR	00077677	13/05/2025	EXOINS	00	INSPECTION COMPLETED BY WORKSHOP 13.05.2025 LABOU APPREN				
PM169	XQ90ZR	00077673	13/05/2025	GEN	39	LABOUR MECH 5				
PM169	XQ90ZR	00077673	13/05/2025	GEN		REPAIR COMPLETED BY WORKSHOP 13.05.2025				
PM169	XQ90ZR	00077673	13/05/2025	GEN	16			CON	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	06			ED002175254-S	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	06			ED002175254-S	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	06			ED0037300960	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	06			FS1251	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	40			10W50	YAT	
PM169	XQ90ZR	00077673	13/05/2025	GEN	16			CON	YAT	
PM169	XQ90ZR	00077952	22/05/2025	GEN	39			LAB		NABQAN01
PM169	XQ90ZR	00077952	22/05/2025	GEN	39			PART		NABQAN01
PM169	XQ90ZR	00077952	22/05/2025	GEN	39			LAB		NABQAN01
PM169	XQ90ZR	00077952	22/05/2025	GEN	39			PART		NABQAN01
PM169	XQ90ZR	00077989	26/05/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00077989	26/05/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00077989	26/05/2025	DEFECT		Reported Defect :-Defect Code : 00014283 Defect Reference : 58756 Date : 26/05/2025 Description of Defect				
PM169	XQ90ZR	00077989	26/05/2025	GEN	39	R/H SUN VISOR MOUNTING SCREWS ARE MISSING, PLEAS LABOUR MECH				
PM169	XQ90ZR	00077989	26/05/2025	GEN		REPAIR COMPLETED BY WORKSHOP 26.05.2025 FIRE EXT EXP: N/A				
PM169	XQ90ZR	00077989	26/05/2025	GEN	16	REPLACED MISSING SCREWS IN RHS SUN VISOR MOUNT A		CON	YAT	
PM169	XQ90ZR	00078067	27/05/2025	CUMAE5	00	LABOUR MECH				
PM169	XQ90ZR	00078067	27/05/2025	CUMAE5		A SERVICE COMPLETED.				
PM169	XQ90ZR	00078067	27/05/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT	
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	01	LABOUR MECH 5				

PM169	XQ90ZR	00078067	27/05/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 27.05.2025					
						FIRE EXT EXP: AUGUST 2025					
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	16			REPLASCE EXHAUST CLAMP BRACKET CON		YAT	
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	00	LABOUR APPRENJC					
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	06			RSK154		YAT	
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	06			Z1006		YAT	
PM169	XQ90ZR	00078067	27/05/2025	CUMBE5	40			3413005		YAT	
PM169	XQ90ZR	00078067	27/05/2025	DEFECT	01	LABOUR MECH					
PM169	XQ90ZR	00078067	27/05/2025	DEFECT		DEFECT CLEARED.					
PM169	XQ90ZR	00078067	27/05/2025	DEFECT		Reported Defect :-Defect Code : 00014022					
PM169	XQ90ZR	00078468	14/06/2025	CUMAE5	00	Defect Reference : PM169 Date : 16/04/2025 Description of Defect EXHAUST BRACKET BROKEN AT GANTRY LABOUR MECH 1					
PM169	XQ90ZR	00078468	14/06/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 14.06.2025					
						FIRE EXT EXP: JULY 2025					
						TERMINAL ON ALTERNATOR POSITIVE LEAD NEEDA TO BE REPLAC REPLACED NEXT SERVICE CLUTCH ROD AT BELL CRANK BENT + NEEDS TO BE STRIGHTENED MONITER MOVEMENT AT POWDER DIVIDER D # 14449					
PM169	XQ90ZR	00078468	14/06/2025	CUMAE5	16			CON		YAT	
PM169	XQ90ZR	00078468	14/06/2025	CUMAE5	00	LABOUR APPRENJC					
PM169	XQ90ZR	00079243	12/07/2025	CUMAE5	00	LABOUR MECH 1					
PM169	XQ90ZR	00079243	12/07/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 12.07.2025					
						FIRE EXT EXP:AUGUST 2025					
						AFTER THREAD FAULT - WIRING ALTERNATOR POSITIVE WI SPREADER DOOR BENT L/H FRONT FUEL TANK STRAP RUBBER U/S TOP L/H SIDE GRILL RETAINING BOLT / STRIPPED REPLACED POSITIVE WIRE FROM ALTERNATOR TO BATTER SENSOR CON YAT					
PM169	XQ90ZR	00079243	12/07/2025	CUMAE5	16						
PM169	XQ90ZR	00079243	12/07/2025	CUMAE5	00	LABOUR APPREN					
PM169	XQ90ZR	00079243	12/07/2025	CUMAE5	16			5462439RX		YAT	
PM169	XQ90ZR	00079243	12/07/2025	DEFECT	01	LABOUR MECH					
PM169	XQ90ZR	00079243	12/07/2025	DEFECT		DEFECT CLEARED.					
PM169	XQ90ZR	00079243	12/07/2025	DEFECT		Reported Defect :-Defect Code : 00014449 Defect Reference : PM169 Date : 14/06/2025 Description of Defect :					
						TERMINAL ON ALTERNATOR POSITIVE LEAD NEEDA TO BE REPLACED NEXT SERVICE CLUTCH ROD AT BELL CRANK BENT + NEEDS TO BE STRIC					
PM169	XQ90ZR	00079592	28/07/2025	CUMAE5	00	LABOUR APPRENJ					
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00079592	28/07/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 28/7/2025					
						FIRE EXT EXP: AUGUST 2025					
						ADDED ENG OIL 15W 40 5L REPLACED PULL CABLE FOR TUF LOOSE JOINT MOVING FOR THE HEIGHT CONTROL VALVE MOVEMENT IN FRONT INPUT SHAFT					
PM169	XQ90ZR	00079592	28/07/2025	CUMAE5	16			CON		YAT	
PM169	XQ90ZR	00079592	28/07/2025	CUMAE5	00	LABOUR APPREND					
PM169	XQ90ZR	00079734	1/08/2025	GEN	39			LABEXT			ANDM
PM169	XQ90ZR	00079734	1/08/2025	GEN	39			CON			ANDMC
PM169	XQ90ZR	00079734	1/08/2025	GEN	39			MATERIALS			ANDMC

PM169	XQ90ZR	00079734	1/08/2025	GEN	39			LABEXT	ANDM
PM169	XQ90ZR	00079734	1/08/2025	GEN	39			CON	ANDMC
PM169	XQ90ZR	00079734	1/08/2025	GEN	39			MATERIALS	ANDMC
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			LABEXT	RCCL
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			CON	RCCL
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			CON	RCCL
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			ENVLEV	RCCL
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			LABEXT	RCCLC
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			CON	RCCLC
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			CON	RCCL
PM169	XQ90ZR	00080111	19/08/2025	GEN	39			ENVLEV	RCCL
PM169	XQ90ZR	00080194	21/08/2025	CUMAE5	00	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00080194	21/08/2025	CUMAE5		A SERVICE COMPLETED.				
						FIRE EXT EXP:				
PM169	XQ90ZR	00080194	21/08/2025	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	01	LABOUR MECH 1				
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 21/8/2025				
						FIRE EXT EXP: JANUARY 2026				
						REPLACE FIRE EXT				
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	16	REPLACE SALINE BOTTLE		CON	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	00	LABOUR APPREND				
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	19			FIREEXT1KG	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	16			3413005	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	06			RSK154	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	16			Z1006	YAT	
PM169	XQ90ZR	00080194	21/08/2025	CUMBE5	16			FS19764	YAT	
PM169	XQ90ZR	00080206	21/08/2025	GEN	39			LABEXT		DLLAS
PM169	XQ90ZR	00080206	21/08/2025	GEN	39			LABEXT		DLLAS
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			11006520		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000118		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			11006520		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000370		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000518		BRIAU
PM169	XQ90ZR	00080322	21/08/2025	TYRES	15			33000118		BRIAU
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			11003134		BRIAU
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			77000232		BRIAU
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000084		BRIAU
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000517		BRIAU

PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			11003134		BRIAUS
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			77000232		BRIAUS
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000084		BRIAUS
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000517		BRIAUS
PM169	XQ90ZR	00080870	15/09/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00080860	17/09/2025	CUMAE5	00	LABOUR APPRENJC				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00080860	17/09/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 17/9/2025 FIRE EXT EXP: JANUARY 2026 REPLACED WIPER BLADES REPLACED FEMALE FITTING TIG CON YAT				
PM169	XQ90ZR	00080860	17/09/2025	CUMAE5	16					
PM169	XQ90ZR	00080861	17/09/2025	ECO	01	LABOUR APPRENJC				
PM169	XQ90ZR	00080861	17/09/2025	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 17/9/2025				
PM169	XQ90ZR	00080861	17/09/2025	ECO	16			CON	YAT	
PM169	XQ90ZR	00080861	17/09/2025	ECO	16			3413005	YAT	
PM169	XQ90ZR	00080861	17/09/2025	ECO	06			SA17117	YAT	
PM169	XQ90ZR	00080861	17/09/2025	ECO	16			13A0990	YAT	
PM169	XQ90ZR	00081653	1/10/2025	TYRES	15			33000096		BRIAUS
PM169	XQ90ZR	00081653	1/10/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00081653	1/10/2025	TYRES	15			33000096		BRIAUS
PM169	XQ90ZR	00081653	1/10/2025	TYRES	15			33000118		BRIAUS
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5	00	LABOUR MECH 1				
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 08/10/2025 FIRE EXT EXP: JANUARY 2026 TOP UP FRONT DIFF OIL REPLACE LH BULLBAR INDICATOR LIGHT CON YAT				
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5	16					
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5	00	LABOUR APPRENJ				
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5	00	LABOUR APPREND				
PM169	XQ90ZR	00081341	8/10/2025	CUMAE5	16			2110-12V	YAT	
PM169	XQ90ZR	00081484	9/10/2025	GEN	39	LABOUR APPRENJ				
PM169	XQ90ZR	00081484	9/10/2025	GEN		REPAIR COMPLETED BY WORKSHOP 15/10/2025 DIFF LEAD REPAIR REPLACE WHEEL SEAL AND BRAKE LININGS AT 1ST DRIVE L BEARING FAILURE AND REMOVE 1ST DRIVE DIFF REPLACE AT JACK SHAFT REPLACE THRU SHAFT SEAL SEND FRONT DIFF HEAD TO GIBBS FOR REPAIRS CON YAT				
PM169	XQ90ZR	00081484	9/10/2025	GEN	16					
PM169	XQ90ZR	00081484	9/10/2025	GEN	00	LABOUR MECH 1				
PM169	XQ90ZR	00081484	9/10/2025	GEN	00	LABOUR APPRENJC				
PM169	XQ90ZR	00081484	9/10/2025	GEN	00	LABOUR APPRENJ				
PM169	XQ90ZR	00081484	9/10/2025	GEN	00	LABOUR APPRENJC				
PM169	XQ90ZR	00081484	9/10/2025	GEN	00	LABOUR MECH 1				
PM169	XQ90ZR	00081484	9/10/2025	GEN	16			47697S	YAT	
PM169	XQ90ZR	00081484	9/10/2025	GEN	16			KSMA2124707Q	YAT	
PM169	XQ90ZR	00081484	9/10/2025	GEN	16			r945008	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00081484	9/10/2025	GEN	16			CP25RPLS1	YAT	
PM169	XQ90ZR	00081484	9/10/2025	GEN	16			K1T2637	YAT	
PM169	XQ90ZR	00081449	14/10/2025	GEN	39			LABEXT		GIBGEA
PM169	XQ90ZR	00081449	14/10/2025	GEN		REPAIR COMPLETED BY GIBBS GEARBOX AND DIFF 14/10/20 INVOICE #1640134 REPAIR P/DIVDER 160 FRONT REAPLACE: INPUT BEARINGS, SEAL, NUT/WASHER, THRUST SIDE GEAR, OIL PUMP, INPUT DRIVE GEAR, PWR DVDR KIT, LABEXT GIBGEA01 1640134 Labour Ext				
PM169	XQ90ZR	00081449	14/10/2025	GEN	39					

PM169	XQ90ZR	00082261	12/11/2025	GEN	39			LABEXT	O
PM169	XQ90ZR	00082261	12/11/2025	GEN		REPAIR COMPLETED BY ONTRACK AUTO ELECTRICAL AND			
						INVOICE #11560			
						Travel to			
						Connected gauges and checked A/C operation ?			
						Performed pressure test ? located			
						Returned to workshop to source required fittings and hose. Remov			
						Drier			
						Pressure tested system ? held pressure with no leaks. Vacuumed			
						? gauge readings within spec, compres			
								LABEXT	O
PM169	XQ90ZR	00082261	12/11/2025	GEN	39				
PM169	XQ90ZR	00082415	17/11/2025	CUMAE5	00	LABOUR APPREN			
PM169	XQ90ZR	00082415	17/11/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 17/11/2025			
						FIRE EXT EXP: JANUARY 2026			
						RADIATOR MESH HAS BEEN REFITTED POWER DIVIDER DOI			
						COULDNT FAULT ECO WIND FAN (BEEN REPLACED I BELIEV			
						CON YAT Consuma			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00082415	17/11/2025	CUMAE5	16					
PM169	XQ90ZR	00082415	17/11/2025	CUMAE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT		Reported Defect :-Defect Code : 00015300				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT		Defect Reference : PM169 Date : 08/10/2025 Description of Defect				
						FRONT DIFF POWER DIVIDER SEAL LEAKING				
						Reported Defect :-				
						Defect Code : 00015302 Defect Reference : PM169 Date : 08/10/2				
						:				
						ECOWIND - LOW REFRIGERANT FAULT				
						Reported Defect :-				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT						
						Defect Code : 00015132 Defect Reference : PM169 Date : 17/09/2				
						:				
						NEEDS BEARINGS IN POWER DIVIDER AND INPUT SHAFT				
						Reported Defect :-				
PM169	XQ90ZR	00082415	17/11/2025	DEFECT						
				GEN	39	Defect Code : 00015133 Defect Reference : PM169 Date : 17/09/2				
						:				
						NEEDS MESH OVER RADIATOR PUT ON				
						LABOUR MECH 1				
PM169	XQ90ZR	00082488	19/11/2025							
PM169	XQ90ZR	00082488	19/11/2025	GEN		REPAIR COMPLETED BY WORKSHOP 19/11/2025				
						FIRE EXT EXP:				
						REPLACE GRUB SCREWS IN LH MUDGUARD AND ALIGN AND TIGHTE				
PM169	XQ90ZR	00082488	19/11/2025	GEN	16			CON	YAT	
PM169	XQ90ZR	00085242	5/03/2026	GEN	39	LABOUR APPRENJC				
PM169	XQ90ZR	00085242	5/03/2026	GEN		REPAIR COMPLETED BY WORKSHOP 05/03/2026				

						JOB COMPLAINT -NEW BATTERIES					
						FITTED 4 X NEW BATTERIES AND SWAPPED GEAR BOX LINES AROU					
PM169	XQ90ZR	00085242	5/03/2026	GEN	16			CON		YAT	
PM169	XQ90ZR	00085242	5/03/2026	GEN	16			mf70zzdt		YAT	
PM169	XQ90ZR	00085261	7/03/2026	CUMAE5	00	LABOUR MECH					
PM169	XQ90ZR	00085261	7/03/2026	CUMAE5		A SERVICE COMPLETED.					
PM169	XQ90ZR	00085261	7/03/2026	CUMAE5	16	FIRE EXT EXP: CON				YAT	
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	01	LABOUR APPREN					
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 07/03/2026					
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	16	FIRE EXT EXP: SEPTEMBER 2026 EYEWASH EXP - MAY 2030 CON	YAT				
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	00	LABOUR APPRENJC					
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	00	LABOUR APPRENJ					
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	06			MK13555	YAT		
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	40			3413005	YAT		
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	06			Z1006	YAT		
PM169	XQ90ZR	00085261	7/03/2026	CUMBE5	06			HDA5979	YAT		
PM169	XQ90ZR	00085793	28/03/2026	CUMAE5	00	LABOUR MECH 1					
PM169	XQ90ZR	00085793	28/03/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 28/03/2026					
						FIRE EXT EXP: OCTOBER 2026					
						ADJUST CLUTCH					
PM169	XQ90ZR	00085793	28/03/2026	CUMAE5	16	DEFECT 16613 - REPLACED SIM CARD CON	YAT				
PM169	XQ90ZR	00085793	28/03/2026	CUMAE5	00	LABOUR MECH 5					
PM169	XQ90ZR	00085793	28/03/2026	DEFECT	01	LABOUR MECH					
PM169	XQ90ZR	00085793	28/03/2026	DEFECT		DEFECT CLEARED.					
PM169	XQ90ZR	00085793	28/03/2026	DEFECT		Reported Defect :-Defect Code : 00016613					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	00	Defect Reference : PM169 Date : 11/03/2026 Description of Defect REPLACE SIM CARDS FOR CAMERA - BRISBANE 8200 1434 5 LABOUR MECH 7					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 13/04/2026					
						FIRE EXT EXP: OCTOBER 2026					
						ADJUSTED MICRO SWITCHES ON GEAR BOX REPLACED GEARBOX INSPECT GEARBOX PRESSURE LIGHT ON ADJUSTED MICRO SWITC OUT					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	16			CON		YAT	
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	00	LABOUR MECH 6					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	00	LABOUR MECH 5					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	00	LABOUR APPRENJC					
PM169	XQ90ZR	00086080	13/04/2026	CUMAE5	16			FD20-2111-4PS1		YAT	
PM169	XQ90ZR	00086081	13/04/2026	ECO	01	LABOUR APPRENJC					
PM169	XQ90ZR	00086081	13/04/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 13/04/202					
PM169	XQ90ZR	00086081	13/04/2026	ECO	16			CON	YAT		
PM169	XQ90ZR	00086081	13/04/2026	ECO	40			10W50	YAT		
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	Supplie Code
PM169	XQ90ZR	00086081	13/04/2026	ECO	06			SA17117		YAT	
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15			99015526			BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15			33000084			BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15			33000370			BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15			22023351			BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15			33000518			BRIAU

PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		33000115	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		99015526	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		33000084	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		33000370	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		22023351	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		33000518	BRIAU
PM169	XQ90ZR	00086194	14/04/2026	TYRES	15		33000115	BRIAU
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		LABEXT	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		GENERAL PART	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		FREIGHT	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		SCANG2	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		TOWING	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		WRKSCONS	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39	REPAIR COMPLETED BY AEM 08/05/2026		

INVOICE #00014865

Attend call out to Byrnes Street - vehicle shut down and not able to restart.
*Suspected fuel pump fault. Arrange towing from Byrnes Street to worksho
Assist tow truck operator to direct traffic , load and clear road. Return to wo
Complete further testing at workshop. Liaise with Mick B & Cummins tech s
control valve wiring and suction control valve not meeting resistance check
Prime up system. Vehicle not starting. Liaise with Cummins. Suspected fue
Remove output line from fuel pump - fault with pressure still present. Liaise
warranty. Prep for towing to Cummins, Cairns for warranty repairs.
Fuel burn: 510231.0L

PM169	XQ90ZR	00089015	8/05/2026	GEN	39		LABEXT	AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39		GENERAL PART	AUTEL

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00089015	8/05/2026	GEN	39			FREIGHT		AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39			SCANG2		AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39			TOWING		AUTEL
PM169	XQ90ZR	00089015	8/05/2026	GEN	39			WRKSCONS		AUTEL
PM169	XQ90ZR	00086968	20/05/2026	CUMAE5	00	LABOUR MECH 7				
PM169	XQ90ZR	00086968	20/05/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 20/05/2026				

FOUND COOLEANT LEAK ON BOTTOM RHS OF RADIATOR
CLEAN DRY OFF AND PRESSURE CHECK, FOUND LEAK TO BE SUSI
REPLACE ADBLUE INJECTOR FITTINGS (MALE AND FEMALS) ON DO

PM169	XQ90ZR	00086968	20/05/2026	CUMAE5	16	FIRE EXT EXP: OCT 2026 CON		YAT
PM169	XQ90ZR	00086968	20/05/2026	CUMAE5	00	LABOUR APPRENL		
PM169	XQ90ZR	00086968	20/05/2026	DEFECT	01	LABOUR MECH		
PM169	XQ90ZR	00086968	20/05/2026	DEFECT		DEFECT CLEARED.		
PM169	XQ90ZR	00086968	20/05/2026	DEFECT		Reported Defect :-Defect Code : 00015605		
PM169	XQ90ZR	00086968	20/05/2026	DEFECT		Defect Reference : pm169 Date : 17/11/2025 Description of Defect : NEEDS A NEW NHVR LABEL Reported Defect :-		
						Defect Code : 00015606 Defect Reference : PM169 Date : 17/11/2025 Description of Defect : NEEDS TO HAVE SUMP GASKET		

DONE UNDER WAI

PM169	XQ90ZR	00086958	21/05/2026	GEN	16			SB30F-L		BROHU
PM169	XQ90ZR	00086958	21/05/2026	GEN	16			SB30F-L		BROHU
PM169	XQ90ZR	00087266	28/05/2026	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00087266	28/05/2026	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00087266	28/05/2026	DEFECT		Reported Defect :-Defect Code : 00017436				
PM169	XQ90ZR	00087262	28/05/2026	EXOINS	01	Defect Reference : 40476 Date : 18/05/2026 Description of Defect DRIVERS SIDE FRIDGE STOPPED WORKING, NOT GETTING C NEEDED REAR RIGHT AIR BAG LEAKING LABOUR APPRENJC				
PM169	XQ90ZR	00087262	28/05/2026	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATT INSPECTION COMPLETED BY WORKSHOP 28/05/2026 FIRE EXT EXP - AUGUST 2026				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00087262	28/05/2026	EXOINS	00	LABOUR MECH 7				
PM169	XQ90ZR	00087266	28/05/2026	GEN	39	LABOUR MECH 7				
PM169	XQ90ZR	00087266	28/05/2026	GEN		REPAIR COMPLETED BY WORKSHOP 28/05/2026 JOB COMPLAINT -REPAIRS -RADIATOR -FRIDGE REMOVE AND FIT REPAIRED RADIATOR AS NEEDED WITH NEW TOI HOSES, REPACE -4 BREATHER HOSE AND HORTON HOSE REPLACE BOTH I REPLACE U/S FRIDGE RHS REPLACE RH SPOT MIRRORS				
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			CON	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	00	LABOUR APPRENJC				
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			MX1-7S	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			HT53-3-008	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	11			FH50L600	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			829310	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			SB30F-L	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			201-4/1	YAT	
PM169	XQ90ZR	00087266	28/05/2026	GEN	16			70-250	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	01	LABOUR MECH 7				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5		C SERVICE COMPLETED.BY WORKSHOP 28/05/26				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	16	FIRE EXT EXP:AUG 2026 CON YAT				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	00	LABOUR APPRENL				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	00	LABOUR APPREND				
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	16			T224P	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	06			F37-TP-1000	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	06			WF2127	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	06			17237	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	12			R2788P	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	06			Z89AST	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	40			85W140	YAT	
PM169	XQ90ZR	00087250	29/05/2026	CUMCE5	40			3430336	YAT	
PM169	XQ90ZR	00088414	3/06/2026	TYRES	15			YFSFTB	YOKTYR01	
PM169	XQ90ZR	00088414	3/06/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 03/06/2026 - FIT OWN				
PM169	XQ90ZR	00088414	3/06/2026	TYRES	15	YFSFTB		YOKTYR01	IN-98732-2026	TRUCK TY
PM169	XQ90ZR	00088031	12/06/2026	TYRES	15			YFPSI	YOKTYR01	E

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00088031	12/06/2026	TYRES		REPAIR COMPLETED BY YOKOHAMA 12/06/2026 INVOICE #IN-89592-2026				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code	Supplier Code
PM169	XQ90ZR	00088031	12/06/2026	TYRES	15			PO:PM169 - YFS:1026 - REGO:XQ90ZR - ODO:1KM - FN:PM169 YFPSI YOKTYR01 IN-89592-2026PRESSUR		
PM169	XQ90ZR	00087683	17/06/2026	CUMAE5	00			LABOUR MECH		
PM169	XQ90ZR	00087683	17/06/2026	CUMAE5				A SERVICE COMPLETED.		
PM169	XQ90ZR	00087683	17/06/2026	CUMAE5	16			FIRE EXT EXP: CON YAT Consuma		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	01			LABOUR MECH 7		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5				B SERVICE COMPLETED BY WORKSHOP 17/06/2026		
								FIRE EXT EXP: OCTOBER 2026 EYEWASH EXP - FEBRUARY 2		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	16			REPLACE 2 X AIRBAGS CON YAT Consuma		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	00			LABOUR MECH 7		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	06			mk13555 YAT		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	06			FS19764 YAT		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	06			AS2474 YAT		
PM169	XQ90ZR	00087683	17/06/2026	CUMBE5	16			1K9541 YAT		
PM169	XQ90ZR	00087683	17/06/2026	DEFECT	01			LABOUR MECH		
PM169	XQ90ZR	00087683	17/06/2026	DEFECT				DEFECT CLEARED.		
PM169	XQ90ZR	00087730	17/06/2026	ECO	01			LABOUR MECH 7		
PM169	XQ90ZR	00087730	17/06/2026	ECO				ECO WIND SERVICE COMPLETED BY WORKSHOP 17/06/2026		
PM169	XQ90ZR	00087730	17/06/2026	ECO	00			LABOUR APPRENL		
PM169	XQ90ZR	00087730	17/06/2026	ECO	16			CON YAT		
PM169	XQ90ZR	00087730	17/06/2026	ECO	06			SA17117 YAT		
PM169	XQ90ZR	00087730	17/06/2026	ECO	40			10W50 YAT		
PM169	XQ90ZR	00087872	26/06/2026	GEN	39			LABOUR MECH 7		
PM169	XQ90ZR	00087872	26/06/2026	GEN				REPAIR COMPLETED BY WORKSHOP 26/06/2026		
								JOB COMPLAINT -SPOT MIRROR		
								REPLACED LH LOWER SPOT MIRROR		
PM169	XQ90ZR	00087872	26/06/2026	GEN	16			CON YAT		
PM169	XQ90ZR	00087872	26/06/2026	GEN	16			MX1-7S YAT		
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			LABEXT		BROH
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			LBP2189GH		BROH
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			12PK2380		BROH
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			TRAVEL FEE		BROH
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			MISCON		BROH
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			ENVLEV		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN				REPAIR COMPLETED BY BROWN N HURLEY BURPENGARY 02		
								INVOICE #3925382		
								ATTEND VEHICLE BREAKDOWN JUST BEFORE PUMICESTONE		
								Receive call out for breakdown. Collect parts. Travel from workshop Pumicestone Rd exit. Cab was already jacked up. Remove fan belt t Remove alternator. Swap pulley from old to new alternator. Fit altern ok. Pack up tooling and return travel to workshop.		
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			LABEXT		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			LBP2189GH		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			12PK2380		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			TRAVEL FEE		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			MISCON		BROHU
PM169	XQ90ZR	00088157	2/07/2026	GEN	39			ENVLEV		BROHU
PM169	XQ90ZR	00088168	7/07/2026	CUMAE5	00			LABOUR MECH 1		
PM169	XQ90ZR	00088168	7/07/2026	CUMAE5				A SERVICE COMPLETED BY WORKSHOP 07/07/2026		
								FIRE EXT EXP: OCTOBER 2026		

PM169	XQ90ZR	00088168	7/07/2026	CUMAE5	16	DEFECT 17436 - BEEN DONE OK CON		YAT			Consuma
PM169	XQ90ZR	00088168	7/07/2026	CUMAE5	00	LABOUR APPRENJC					
PM169	XQ90ZR	00088756	13/07/2026	TYRES	15			YFPSI		YOKTYR01	E
PM169	XQ90ZR	00088756	13/07/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 13/07/2026 - PRESSUR					
PM169	XQ90ZR	00088756	13/07/2026	TYRES	15			YFPSI		YOKTYR01	IN
PM169	XQ90ZR	00088544	22/07/2026	CUMAE5	00	LABOUR MECH 7					
PM169	XQ90ZR	00088544	22/07/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 22/07/2026					
						FIRE EXT EXP: SEPTEMBER 2026					
PM169	XQ90ZR	00088544	22/07/2026	CUMAE5	16	TOP UP SPARE COOLANT AND OIL BOTTLES CON		YAT			Consuma
PM169	XQ90ZR	00088544	22/07/2026	CUMAE5	00	LABOUR BILLY					
PM169	XQ90ZR	00088544	22/07/2026	CUMAE5	40				3413005	YAT	
PM169	XQ90ZR	00088611	23/07/2026	GEN	39	LABOUR MECH 7					
PM169	XQ90ZR	00088611	23/07/2026	GEN		REPAIR COMPLETED BY WORKSHOP 23/07/2026					
						JOB COMPLAINT -SLEEPER					
						DIAGNOSE SLEEPER ISSUE, REMOVE/REPLACE CONDENSO					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00088611	23/07/2026	GEN	16			CON	YAT	
PM169	XQ90ZR	00088611	23/07/2026	GEN	16			FA0023	YAT	
PM169	XQ90ZR	00088647	27/07/2026	ECO	01	LABOUR MECH 7				
PM169	XQ90ZR	00088647	27/07/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 27/07/2026				
PM169	XQ90ZR	00088647	27/07/2026	ECO	16	AIR FILTER OK, CLEAN AND CHECK REPLACE PRIMER PUMP, O'RING, CLEAN DOWN ENGINE CON		YAT		
PM169	XQ90ZR	00088647	27/07/2026	ECO	40			10W50	YAT	
PM169	XQ90ZR	00089043	10/08/2026	CUMAE5	00	LABOUR MECH 7				
PM169	XQ90ZR	00089043	10/08/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 10/08/2026				
						FIRE EXT EXP: OCTOBER 2026				
PM169	XQ90ZR	00089043	10/08/2026	CUMAE5	16	REPLACED JAW KIT AS REQUIRED - KEIRAN CON		YAT		
PM169	XQ90ZR	00089043	10/08/2026	CUMAE5	00	LABOUR BILLY				
PM169	XQ90ZR	00089043	10/08/2026	CUMAE5	16			SK3221/52Z	YAT	
PM169	XQ90ZR	00089429	13/08/2026	TYRES	15			YFPSI	YOKTYR01	E
PM169	XQ90ZR	00089429	13/08/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 13/08/2026 - PRESSURE CHECK				
PM169	XQ90ZR	00089429	13/08/2026	TYRES	15			YFPSI		YOKTY
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			LABEXT		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			GENERAL PART		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			GENERAL PART		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			22		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN		COMPLETED BY NORTHEAST TRUCK CENTRE 21/08/26 INV 12				
						BREAKDOWN CALLOUT OFF SITE - WONGI TURNOFF ON HIGH TRAVEL TO TRUCK AT WONGI TURNOFF TILT CAB FOUND TENSIONER BROKEN REMOVE TENSIONER AND BELT FIT NEW TENSIONER START AND CHECK LOWER CAB LIFT BULLBAR RETURN HOME				
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			LABEXT		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			GENERAL PART		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			GENERAL PART		NABQA
PM169	XQ90ZR	00089367	21/08/2026	GEN	39			22		NABQA
PM169	XQ90ZR	00089412	26/08/2026	CUMAE5	00	LABOUR MECH				

Asset	Registratio	Work Order	Work Order	Service	RM	Task	Employee	Product	W/H	Supplie

Code	n	Code	Date	Code	Categor	Code	Code	Code	Code	Code
PM169	XQ90ZR	00089412	26/08/2026	CUMAE5		A SERVICE COMPLETED.				
						FIRE EXT EXP:				
PM169	XQ90ZR	00089412	26/08/2026	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	01	LABOUR BILLY				
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 26/08/26				
						FIRE EXT EXP:OCT 26				
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	16	REPLACED SUNVISOR AS IT HAS CRACKED CON YAT				
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	00	LABOUR 4THYEARA				
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	06			as2474	YAT	
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	06			MK13555	YAT	
PM169	XQ90ZR	00089412	26/08/2026	CUMBE5	40			3413005	YAT	
PM169	XQ90ZR	00089595	3/09/2026	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00089595	3/09/2026	DEFECT		DEFECT CLEARED.				
PM169	XQ90ZR	00089595	3/09/2026	DEFECT		Reported Defect :-Defect Code : 00018520 Defect Reference : 40477 Date : 01/09/2026 Description of Defect :				
						PASSENGER SIDE FRIDGE DIED, NOT GETTING COLD ANYMORE. W				
PM169	XQ90ZR	00089595	3/09/2026	ECO	01	LABOUR 4THYEARA				
PM169	XQ90ZR	00089595	3/09/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 03/09/2026				
PM169	XQ90ZR	00089595	3/09/2026	ECO	16			CON	YAT	
PM169	XQ90ZR	00089595	3/09/2026	ECO	06			SA17117	YAT	
PM169	XQ90ZR	00089595	3/09/2026	ECO	40			10W50	YAT	
PM169	XQ90ZR	00089594	3/09/2026	GEN	39	LABOUR 4THYEARA				
PM169	XQ90ZR	00089594	3/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP 03/09/2026				
						JOB COMPLAINT -TEMP GAUGE STICKING -LEFT FRIDGE -SLEEPER AIR SERVICE DUE -SPOT LIGHT FLICKERING				
						REPLACED FRIDGE WITH SPARE REPLACED TEMP GUAGE S AIR CON YAT				
PM169	XQ90ZR	00089594	3/09/2026	GEN	16					
PM169	XQ90ZR	00089594	3/09/2026	GEN	16			A22-63906-002	YAT	
PM169	XQ90ZR	00089594	3/09/2026	GEN	06			SA17117	YAT	
PM169	XQ90ZR	00089784	5/09/2026	GEN	16			Q43-1229-002	BROHUR01	EX
PM169	XQ90ZR	00089784	5/09/2026	GEN	16			Q43-1229-002	BROHUR01	39
PM169	XQ90ZR	00089770	9/09/2026	DEFECT	01	LABOUR MECH				
PM169	XQ90ZR	00089770	9/09/2026	DEFECT		DEFECT CLEARED.				

Asset Code	Registratio n	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code
PM169	XQ90ZR	00089770	9/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP ON 09/09/2026				
PM169	XQ90ZR	00089770	9/09/2026	GEN	16	REPLACED DRAW FRIDGE AND FIX WIRING TO FRIDGE CON YAT				
PM169	XQ90ZR	00089770	9/09/2026	GEN	00	LABOUR 4THYEARA				
PM169	XQ90ZR	00089770	9/09/2026	GEN	16			SB30F-L	YAT	
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5	00	LABOUR BILLY				
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5		A SERVICE COMPLETED BY WROKSHOP ON 15/09/2026				
						FIRE EXT EXP: OCT 2026				
						INSPECT FAULT WITH FRONT DIFF OIL TEMP. FOUND CORROSION I AND WILL REFER TO DAN NEXT SERVICE IF REQUIRED OR NOT (PI				
						REMOVE AND CLEAN RH STEER HUB, INSPECT BRAKES/BEARINGS				
						REPLACED BOTH FRONT MUD FLAPS (EXODAS TRAILER FLAPS CU				
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5	16			CON	YAT	
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5	00	LABOUR APPRENJC				
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5	00	LABOUR MECH 7				
PM169	XQ90ZR	00089899	15/09/2026	CUMAE5	16			43764	YAT	

PM169	XQ90ZR	00089899	15/09/2026	DEFECT	01	LABOUR MECH					
PM169	XQ90ZR	00089899	15/09/2026	DEFECT		DEFECT CLEARED.					
PM169	XQ90ZR	00090863	29/09/2026	TYRES	15	YFPSI YOKTY					
PM169	XQ90ZR	00090863	29/09/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 29/09/2026 - PO:PM169					
PM169	XQ90ZR	00090863	29/09/2026	TYRES	15	026139 - PRESSURE CHECKS YFPSI YOKTYR01 IN-158630-202PRESSUR					
PM169	XQ90ZR	00090505	12/10/2026	CUMAE5	00	LABOUR 4THYEARA					
PM169	XQ90ZR	00090505	12/10/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 12/10/2026					
PM169	XQ90ZR	00090505	12/10/2026	CUMAE5	16	FIRE EXT EXP: SEPTEMBER 2026 (DONT HAVE ANY TO REPL CON YAT Consuma					
PM169	XQ90ZR	00090505	12/10/2026	DEFECT	01	LABOUR MECH					
PM169	XQ90ZR	00090505	12/10/2026	DEFECT		DEFECT CLEARED.					
PM169	XQ90ZR	00090505	12/10/2026	DEFECT		Reported Defect :-Defect Code : 00018756 Defect Reference : PM169 Date : 08/10/2026 Description of Defect : ODOMETER STOPPED AT 999,999, ENGINE HOURS STOPPED AT 99					
PM169	XQ90ZR	00090506	12/10/2026	ECO	01	LABOUR 4THYEARA					
PM169	XQ90ZR	00090506	12/10/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 1					
PM169	XQ90ZR	00090506	12/10/2026	ECO	16	CON YAT					
PM169	XQ90ZR	00090506	12/10/2026	ECO	06	SA17117 YAT					
PM169	XQ90ZR	00090506	12/10/2026	ECO	40	10W50 YAT					
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5	00	LABOUR BILLY					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplier Code
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 02/11/2026				
						FIRE EXT EXP: JUNE 2027				
						FIND FAULT WITH NO REVERSE TO TRAILER PLUG, FOUND T				
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5	16	KEIRAN		CON	YAT	
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5	00	LABOUR MECH 7				
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5	19			FIREEXT1KG	YAT	
PM169	XQ90ZR	00091085	2/11/2026	CUMAE5	16			T2430DD	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Supplie Code

Report Options:

Sort By	- AssetCode
Starting Asset Code	- PM169
To	- PM169
Starting Registration	-
To	-
Starting Operations No	-
To	-
From: Work Order Location	-
To	-
From: Work Order Date	- 01/01/1901
To	- 31/12/9999
From: Completion Date	-
To	-
From: RM Category Code	-
To	-
Starting Category Code	-
To	-
Starting Owned By	-
To	-
Starting Based By	-
To	-
Starting Location	-
To	-
Assets For	- All Assets
Include Disposed Assets	- no
Warranty Items Only	- no
Include Non Active Assets	- no
Exclude Estimates	- no
Fleet Assets Only	- no
Service Code	-
Task Code	-

Mechanic Code	-
Product Code	-
Warehouse	-
WO Supplier Code	-
Include All	- yes
Labour	- yes
Parts	- yes
Supplies	- yes
Tyres	- yes
Comments	- yes

ɨr	Invoice	Details	Purchase Order
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	EX00021193	Labour,PM169	EX0002119
TRU01	EX00021193	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	Labour,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
TRU01	131763	GENERAL PART CODE,PM169	EX0002119
ʌUS01	EX00021253	BALANCE TBR,PM169	EX0002125
ʌUS01	86772141	BALANCE TBR,PM169	EX0002125
		Labour	
		Consumables	
		MAINTENANCE KIT	
		Filter Diff	
		Filter Element Gearbox Eaton	
		ES Water Filter	
RAC01	EX00021448	Labour,XQ48UH	EX0002144
RAC01	INV-4683	Labour,XQ48UH	EX0002144
		Labour	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Labour	
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
ʌUS01	EX00021910	BALANCE TBR,PM169	EX0002191
ʌUS01	87070316	BALANCE TBR,PM169	EX0002191

ɨr	Invoice	Details	Purchase Order
		Labour	1.00
		Labour - Internal	0.25
		Labour - Internal	1.00
		Consumables	4.00
		Labour	0.75
		Consumables	3.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
		Consumables	4.00
		Labour	0.00
		Labour	1.00

		Labour - Internal	1.00
		Labour - Internal	1.00
		Consumables	4.00
		MAINTENANCE KIT	1.00
		Element 10 Micron	1.00
		OIL 15W-40, CK 4/E9	47.00
		Labour	1.00

RADEA

		Labour - Internal	1.00
		Consumables	4.00
S01	EX00022823	GENERAL PART CODE,XQ48UH	EX0002282
S01	EX00022823	SCRAP TYRES TBR,XQ48UH	EX0002282
S01	EX00022823	ETA MIN FEE,XQ48UH	EX0002282
S01	4720104968	ETA MIN FEE,XQ48UH	EX0002282
S01	4720104968	SCRAP TYRES TBR,XQ48UH	EX0002282
S01	4720104968	GENERAL PART CODE,XQ48UH	EX0002282
S01	EX00022847	case stock 295/80-22.5,PM169	EX0002284
S01	EX00023304	case stock 295/80-22.5,PM169	EX0002330
S01	87386339A	case stock 295/80-22.5,PM169	EX0002284

r	Invoice	Details	Purchase Order
AUS01	EX00023304	BALANCE TBR,PM169	EX0002330
AUS01	87386339	case stock 295/80-22.5,PM169	EX0002330
AUS01	87386339	BALANCE TBR,PM169	EX0002330
TRU01	EX00022894	Labour,XQ48UH	EX0002289
TRU01	EX00022894	GENERAL PART CODE,PM169	EX0002289
TRU01	EX00022894	GENERAL PART CODE,PM169	EX0002289
TRU01	177160	GENERAL PART CODE,PM169	EX0002289
TRU01	177160	GENERAL PART CODE,PM169	EX0002289
TRU01	177160	Labour,XQ48UH	EX0002289
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		Labour	1.00

LEANED, COULD NOT

		0.25
	Consumables	4.00
	OIL 15W-40, CK 4/E9	1.00
	HITECH SYNPLUS 10W50	1.00
	Labour	0.50
	Labour - Internal	0.50
	Labour - Internal	0.50
	Consumables	4.00
	Labour	0.00
	Labour	3.00

RAINED OIL RHS STEER

	Labour - Internal	1.00
		1.50
	Consumables	5.00
	MAINTENANCE KIT	1.00
	OIL 15W-40, CK 4/E9	50.00

		Filter Element Gearbox Eaton		1.00
		5.5" BOLT CIRCLE GASKET STEMCO		1.00
ɛr	Invoice	Details	Purchase Order	
QAN01	EX00023512	Labour,XQ48UH	EX0002351	
QAN01	00078465	Labour,XQ48UH	EX0002351	
		Labour		
		Consumables		
		Labour		
		Labour		
		Consumables		
		HITECH SYNPLUS 10W50		
		AIR CLEANER CARTRIDGE KOHLER SLEEPER AIR		
MIN01	EX00023612	Labour,XQ48UH	EX0002361	
MIN01	EX00023612	Oil Filter (was LF9080),PM169	EX0002361	
MIN01	9351422	Oil Filter (was LF9080),PM169	EX0002361	
MIN01	9351422	Labour,XQ48UH	EX0002361	
		Labour		
UMBER PLATE WAS MISSING				
		Consumables		1.00
		Labour		0.75
		Labour - Internal		0.75
		Consumables		3.00
		Labour		2.00
REPLACED RHS				
		Labour - Internal		1.00
		Consumables		5.00
		Mudguard Blue		1.00
ɛr	Invoice	Details	Purchase Order	
ɔB01	EX00023941	Labour,XQ90ZR	EX0002394	
ɔB01	EX00023941	GENERAL PART CODE,PM169	EX0002394	
ɔB01	EX00023941	Consumables	EX0002394	
ɔB01	6022	,PM169	EX0002394	
		Consumables		
ɔB01	6022	,PM169	EX0002394	
		GENERAL PART CODE,PM169		
ɔB01	6022	Labour,XQ90ZR	EX0002394	
		Labour		0.00
		Labour		2.00

RES) DRIVERS DOOR

		Labour - Internal	2.00
		Consumables	5.00
		Oil Filter (was LF9080)	1.00
		FF5776 Fuel Filter	1.00
		Ad Blue filter Kenworth	1.00
		OIL 15W-40, CK 4/E9	48.00
		Labour	0.50
		Labour - Internal	0.50
		Consumables	3.00
		Labour	
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
RI01	EX00024370	Labour,PM169	EX0002437

r	Invoice	Details	Purchase Order
RI01	INV-10127	Labour,PM169	EX0002437
		Labour	0.50

COVER DONE A CLUTCH ADJUSTMENT
URLEY

		Labour - Internal	
		Labour - Internal	
		Consumables	
SO1	EX00024526	BALANCE TBR,PM169	EX0002452
SO1	88121591	BALANCE TBR,PM169	EX0002452
		Labour	0.00

OUR

		Labour - Internal	0.75
		Consumables	3.00
		Labour	0.00
		Labour - Internal	1.00
		Consumables	3.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.50

CH

		Labour - Internal	1.50
		Labour - Internal	0.25
		Consumables	4.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	48.00

OUR

		Labour	0.75

ERATIONS
RRANTY ENDS - AWAITING REPLY FROM OPERATIONS

		Labour - Internal	0.75
		Consumables	3.00

r	Invoice	Details	Purchase Order

fect :
RES) DRIVERS DOOR

		Labour - Internal	0.00

135527

ESTED. UPDATED SYSTEM

SLEEPER AIR)

		Labour	

1

		Labour - Internal	
		Labour - Internal	
		Consumables	
		Labour	
		Consumables	
	EX00025260	CASE STOCK 11-22.5,PM169	EX0002526
	EX00025260	case stock 295/80-22.5,PM169	EX0002526
	EX00025260	BALANCE TBR,PM169	EX0002526
	88423140	BALANCE TBR,PM169	EX0002526
	88423140	case stock 295/80-22.5,PM169	EX0002526
	88423140	CASE STOCK 11-22.5,PM169	EX0002526
	EX00025348	Labour,PM169	EX0002534
	6242	Labour,PM169	EX0002534
		Labour	
		Labour - Internal	
		Consumables	
		Labour	
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
		Labour	

r	Invoice	Details	Purchase Order
		Labour	2.00
		Labour - Internal	2.00
		Consumables	4.00
		Air Filter	1.00
		MAINTENANCE KIT	1.00
		ENGINE OIL	48.00

:

'HE DOOR HORN

)22 Description of Defect :

T01	EX00025790	Labour,XQ90ZR	EX0002579
T01	INV-0015	Labour,XQ90ZR	EX0002579
:C01	EX00025976	Labour,XQ90ZR	EX0002597
:C01	EX00025976	LF14000NN - LUBE FILTER,XQ90ZR	EX0002597
:C01	EX00025976	ENVIRONMENTAL LEVY,XQ90ZR	EX0002597
:C01	00020561	ENVIRONMENTAL LEVY,XQ90ZR	EX0002597
:C01	00020561	LF14000NN - LUBE FILTER,XQ90ZR	EX0002597
:C01	00020561	Labour,XQ90ZR	EX0002597
U01	EX00026495	Labour,PM169	EX0002649
U01	EX00026495	4MM TWIN CORE CABLE & CONDUIT,PM169	EX0002649
U01	EX00026495	Consumables	EX0002649
U01	INV-10940	,PM169 Labour,PM169	EX0002649
U01	INV-10940	4MM TWIN CORE CABLE & CONDUIT,PM169	EX0002649
U01	INV-10940	Consumables	EX0002649
		,PM169 Labour	

r	Invoice	Details	Purchase Order
		Consumables	
		Labour	
		AIR FILTER SLEEPER AIR	
		OIL 15W-40, CK 4/E9	
		Consumables	
		Labour	

J REPLACED WIPER

FRONT SERVICE

		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		Consumables	

:

IPERS
:R TYRE ROTATION IF

		4 PREMIUM CAMERA,XQ90ZR	EX0002636

EX00026367		STANDARD VEHICLE CCTV INSTALLATION,XQ90ZR	EX0002636
EX00026367		STEP UP INVERTER,XQ90ZR	EX0002636
EX00026367		STAINLESS STEEL CAMERA BRACKETS,XQ90ZR	EX0002636
NV-0239		STAINLESS STEEL CAMERA	EX0002636
NV-0239		BRACKETS,XQ90ZR STEP UP INVERTER,XQ90ZR	EX0002636
NV-0239		STANDARD VEHICLE CCTV INSTALLATION,XQ90ZR	EX0002636
NV-0239		4 PREMIUM CAMERA,XQ90ZR	EX0002636
		Labour	
		Labour	

r	Invoice	Details	Purchase Order
		Labour - Internal	2.50
		Consumables	5.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	50.00

:

575

		Labour	0.00
		Labour - Internal	0.50
		HITECH SYNPLUS 10W50	1.00
		Consumables	2.00
		Labour	5.00
RENK			
		Labour - Internal	1.50
		Labour - Internal	1.50
		Labour - Internal	1.00
		GENERAL PART CODE - 1224-P AIR DRYER	1.00
		Coolent Filter Kenworth	1.00
		Filter Element Gearbox Eaton	1.00
		DIFF FILTER	1.00
		DIFF OIL AEM	32.00
		Power Steer Filter LF637	1.00
		Filter, Adblue	1.00
		BATTERY DEEP CYCLE & TRUCK	4.00
		Consumables	8.00
		Labour	0.00
		Labour	0.00

r	Invoice	Details	Purchase Order

:

9/2022 Description of Defect :
ɔM OPERATIONS
RE WARRANTY ENDS - AWAITING REPLY FROM OPERATIONS

	Labour	
		2.00
	AIR FILTER SLEEPER AIR	1.00
	GENERAL PART CODE - TS1251 FUEL FILTER	1.00
	GENERAL PART CODE - O'RING	1.00
	Consumables	4.00
	Labour	5.00

TEMPT # 2

		Consumables	
TRU01	EX00027182	Labour External,	EX0002718
RU01	EX00027182	GENERAL PART CODE - E57-S01-050 VOLTAGE	EX0002718
RU01	137199	INVERTER,	EX0002718
TRU01	137199	GENERAL PART CODE - E57-S01-050 VOLTAGE INVERTER, Labour External,	EX0002718
HUR01	EX00027399	GENERAL PART CODE,	EX0002739
HUR01	EX00027399	Labour External,	EX0002739
HUR01	EX00027399	MISCELLANEOUS CONSUMABLES,	EX0002739
HUR01	EX00027399	ENVIRONMENTAL LEVY,	EX0002739
HUR01	2769747	ENVIRONMENTAL LEVY,	EX0002739
HUR01	2769747	MISCELLANEOUS CONSUMABLES,	EX0002739
HUR01	2769747	Labour External,	EX0002739
HUR01	2769747	GENERAL PART CODE,	EX0002739
		Labour	
		Labour - Internal	

ır	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
		Labour	
JT01	EX00027256	GENERAL PART CODE - FAN ELEC 12IN 12 V	EX0002725
JT01	EX00027256	REVERSIBLE,	EX0002725
		Consumables	
JT01	EX00027256	, Labour External,	EX0002725
S01	EX00027453	BALANCE TBR,	EX0002745
S01	EX00027470	11R22.5 148/145L BS M866,PM169	EX0002747
S01	EX00027453	ROTATE TBR TYRE,	EX0002745
S01	EX00027470	FIT TBR TYRE,PM169	EX0002747
S01	89265456	BALANCE TBR,	EX0002745
S01	EX00027470	SCRAP TYRES TBR,PM169	EX0002747
S01	89265456	ROTATE TBR TYRE,	EX0002745
S01	89266550	SCRAP TYRES TBR,PM169	EX0002747
S01	89266550	FIT TBR TYRE,PM169	EX0002747
S01	89266550	11R22.5 148/145L BS M866,PM169	EX0002747
S01	EX00027462	11R22.5 148/145L BS M866,PM169	EX0002746
S01	EX00027462	FIT TBR TYRE,RM169	EX0002746
S01	EX00027462	TYRE HELD FOR RUNOUT,PM169	EX0002746
S01	EX00027462	ROTATE TBR TYRE,PM169	EX0002746
S01	EX00027462	REMOVAL: CUSTOMER REQUEST,PM169	EX0002746
S01	EX00027462	295/80R22.5 152M BS R154,PM169	EX0002746
S01	EX00027462	FIT TBR TYRE,PM169	EX0002746

S01	EX00027462	TYRE HELD FOR RUNOUT,PM169	EX0002746
S01	EX00027462	REMOVAL: CUSTOMER REQUEST,PM169 BALANCE	EX0002746
S01	EX00027462	TBR,PM169	EX0002746
S01	89271155	BALANCE TBR,PM169	EX0002746
S01	89271155	REMOVAL: CUSTOMER REQUEST,PM169	EX0002746
S01	89271155	TYRE HELD FOR RUNOUT,PM169	EX0002746
S01	89271155	FIT TBR TYRE,PM169	EX0002746
S01	89271155	295/80R22.5 152M BS R154,PM169	EX0002746
S01	89271155	REMOVAL: CUSTOMER REQUEST,PM169	EX0002746
S01	89271155	ROTATE TBR TYRE,PM169	EX0002746
S01	89271155	TYRE HELD FOR RUNOUT,PM169	EX0002746
S01	89271155	FIT TBR TYRE,RM169	EX0002746
S01	89271155	11R22.5 148/145L BS M866,PM169	EX0002746
		Labour	

er	Invoice	Details	Purchase Order
		Labour	2.00
		Labour - Internal	2.00
		MAINTENANCE KIT	1.00
		Element 10 Micron	1.00
		OIL 15W-40, CK 4/E9	49.00
		Consumables	5.00
		Labour	0.00
		Labour	0.00
		Labour	0.50
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		Consumables	3.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		Labour	0.00
		Labour	0.00
		Labour	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
		Consumables	
01	EX00027948	Wheel Alignment,	EX0002794
01	EX00027948	Tyre Repair,	EX0002794
01	Q619701	Tyre Repair,	EX0002794
01	Q619701	Wheel Alignment,	EX0002794
		Labour	1.00

AD

er	Invoice	Details	Purchase Order
		Consumables	
		Labour	

S01	EX00028018	11R22.5 148/145L BS M866,	EX0002801
S01	EX00028018	CASE STOCK 11-22.5,	EX0002801
S01	EX00028018	FIT TBR TYRE,	EX0002801
S01	EX00028018	REMOVAL: CUSTOMER PULL POINT,	EX0002801
S01	EX00028018	ROTATE TBR TYRE,	EX0002801
S01	89475366	ROTATE TBR TYRE,	EX0002801
S01	89475366	REMOVAL: CUSTOMER PULL POINT,	EX0002801
S01	89475366	FIT TBR TYRE,	EX0002801
S01	89475366	CASE STOCK 11-22.5,	EX0002801
S01	89475366	11R22.5 148/145L BS M866,	EX0002801
		Labour	

Labour - Internal
Consumables
Labour

S01	EX00028113	B FLEET PRESSURE CHECK,	EX0002811
S01	EX00028127	295/80R22.5 152M BS R154,	EX0002812
S01	89512649	B FLEET PRESSURE CHECK,	EX0002811
S01	EX00028127	FIT TBR TYRE,	EX0002812
S01	EX00028127	TYRE HELD FOR RUNOUT,	EX0002812
S01	EX00028127	REMOVAL: MATCH OTD OR PATTERN,	EX0002812
S01	EX00028127	BALANCE TBR,	EX0002812
S01	EX00028127	ROTATE TBR TYRE,	EX0002812
S01	89512668	ROTATE TBR TYRE,	EX0002812
S01	89512668	BALANCE TBR,	EX0002812
S01	89512668	REMOVAL: MATCH OTD OR PATTERN,	EX0002812
S01	89512668	TYRE HELD FOR RUNOUT,	EX0002812
S01	89512668	FIT TBR TYRE,	EX0002812

ır	Invoice	Details	Purchase Order
S01	89512668	295/80R22.5 152M BS R154,	EX0002812
		Labour	

Labour	1.00
Labour - Internal	1.00
Ad Blue filter Kenworth	1.00
Consumables	3.00
Labour	0.00

Labour 0.75

FROM COMING LOOSE TIGHTENED GEAR SHIFT KNOB
ELTS WERE CRACKING SO REPLACED THEM

	Labour - Internal	0.75
	DAYCO BLUE LABEL BELT	2.00
	Consumables	3.00
	Labour	0.00
	Labour	2.50

PLACED WIPERS
BRAKE RELINE ASAP

	Labour - Internal	2.50
	MAINTENANCE KIT	1.00
	ENGINE OIL	49.00
	Fan Belt	1.00
	Belt-Fan Drive	1.00
	Consumables	5.00
	Labour	0.00

r	Invoice	Details	Purchase Order
RU01	EX00028695	SUPPLY AND FIT 700W 240V 20L	EX0002869
RU01	EX00028695	MICROWAVE, K200 BIG CAB MICROWAVE BRACKET,	EX0002869
RU01	EX00028695	SUPPLY AND FIT PROJECTA 1800W PURE SINE	EX0002869
RU01	EX00028695	WAVE INVERTER, SUPPLY AND FIT GPO,	EX0002869
RU01	138120	SUPPLY AND FIT 700W 240V 20L MICROWAVE,	EX0002869
RU01	138120	K200 BIG CAB MICROWAVE BRACKET,	EX0002869
RU01	138120	SUPPLY AND FIT PROJECTA 1800W PURE SINE	EX0002869
RU01	138120	WAVE INVERTER, SUPPLY AND FIT GPO,	EX0002869
		Labour	0.00
		Labour	0.00

: :

023 Description of Defect

ABOUR APPREN

	Labour	1.00
	AIR FILTER SLEEPER AIR	1.00
	HITECH SYNPLUS 10W50	1.00
	Consumables	3.00

		Labour	2.00

r	Invoice	Details	Purchase Order
) REAR			
		Labour - Internal	2.00
		Kit Q-Plus Brake Shoe	4.00
		BRAKE DRUMS DBO17TRP	2.00
		Consumables	5.00
		Labour	0.00
		Labour	0.50
		LED SLIM SURFACE COMBI LAMF	1.00
		Consumables	3.00
		Labour	1.00
FIXED WITH LAGER DIAMETER SCREWS			
		Labour - Internal	1.00
		1KG FIRE EXTINGUISHER	1.00
		Consumables	3.00
		Labour	0.00
		Labour	1.00
AIR.			
		Consumables	
		Labour	
\US01	EX00029340	BALANCE TBR,	EX0002934
\US01	EX00029340	ROTATE TBR TYRE,	EX0002934
\US01	89916259	BALANCE TBR,	EX0002934
\US01	89916259	ROTATE TBR TYRE,	EX0002934
JR01	EX00029395	RANGE VALVE ERGONOMIC 18 SPP2-01,	EX0002939
JR01	EX00029396	RANGE VALVE ERGONOMIC 18	EX0002939
HUR01	2923374	SPP2-01, RANGE VALVE ERGONOMIC 18	EX0002939
HUR01	2923379	SPP2-01, RANGE VALVE ERGONOMIC 18	EX0002939
/RI01	EX00029554	SPP2-01, PREPARE/REPAINT LHS GUARD AND APPLY PIN LINES,	EX0002955

r	Invoice	Details	Purchase Order
RI01	INV-11260	PREPARE/REPAINT LHS GUARD AND APPLY PIN	EX0002955
S01	EX00029526	LINES, ROTATE TBR TYRE,	EX0002952
S01	EX00029526	SCHEDULED DEPOT SERVICE 15MIN,	EX0002952
S01	89986154	ROTATE TBR TYRE,	EX0002952
S01	89986154	SCHEDULED DEPOT SERVICE 15MIN,	EX0002952
		Labour	
		Labour - Internal	
		Consumables	
		Labour	
		Labour	
		Consumables	
		OIL 15W-40, CK 4/E9	
		AIR FILTER SLEEPER AIR	
JR01	EX00030149	ALTERNATOR-L/N 160A PAD MT,	EX0003014

JR01	2968212	ALTERNATOR-L/N 160A PAD MT,	EX0003014
		Labour	0.00
		Labour	2.00
:			
		Labour - Internal	2.00
		Consumables	3.00
		Fuel Filter Kenworth	1.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	49.00
		Shock Absorber, Drive, K200	2.00
		Labour	0.00

023

ED

	EX00030194	PINLINE FRONT OF K200 AS REQUESTED,	EX0003019

ır	Invoice	Details	Purchase Order
RI01	INV-11390	PINLINE FRONT OF K200 AS REQUESTED,	EX0003019
		Labour	1.00

:AR

		Labour - Internal	2.00
		Consumables	5.00
		SLACK ADJUSTER, ASA 1.5x28 5.5	1.00
S01	EX00030324	11R22.5 148/145L BS M866,	EX0003032
S01	EX00030324	CASE STOCK 11-22.5,	EX0003032
S01	EX00030324	FIT TBR TYRE,	EX0003032
S01	EX00030324	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0003032
S01	EX00030324	SCHEDULED DEPOT SERVICE 15MIN,	EX0003032
S01	187270962	11R22.5 148/145L BS M866,	EX0003032
S01	187270962	CASE STOCK 11-22.5,	EX0003032
S01	187270962	FIT TBR TYRE,	EX0003032
S01	187270962	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0003032
S01	187270962	SCHEDULED DEPOT SERVICE 15MIN,	EX0003032
1	EX00030526	5800 SERIES TRUCK KIT DUAL HEIGHT CONTROL,	EX0003052
1	EX00030526	Transtech lead for IVU,	EX0003052
1	EX00030526	12V BYPASS KIT,	EX0003052
1	EX00030526	Airweigh Airline Fitting for Kenworth,	EX0003052
1	EX00030526	Airweigh Truck Installation,	EX0003052
1	7129724	Airweigh Truck Installation,	EX0003052
1	7129724	Airweigh Airline Fitting for Kenworth,	EX0003052
1	7129724	12V BYPASS KIT,	EX0003052
1	7129724	Transtech lead for IVU,	EX0003052
1	7129724	5800 SERIES TRUCK KIT DUAL HEIGHT CONTROL,	EX0003052
		Labour	1.00

CORD

		Labour - Internal	1.00
		Consumables	5.00
		OIL 15W-40, CK 4/E9	4.00
		Labour - Internal	1.00

		AIR FILTER SLEEPER AIR		1.00
		Consumables		3.00
		OIL 15W-40, CK 4/E9		1.00
		Labour		1.00

r	Invoice	Details	Purchase Order	
)23.				
ER AIR ES				
		Labour - Internal		1.00
		Labour - Internal		1.00
		Consumables		4.00
		Labour		0.00

t :

)23 Description of Defect :

)UR MECH 3		Labour		0.50
LT AND REPAIR				
		Labour - Internal		0.50
		Consumables		4.00
		Labour		0.00
		Labour		1.50

r	Invoice	Details	Purchase Order	
2023.				
		Labour - Internal		1.50
		Labour - Internal		1.50
		Consumables		
		MAINTENANCE KIT		
		OIL 15W-40, CK 4/E9		
S01	EX00031127	RUNOUT TYRE,	EX0003112	
S01	EX00031127	FIT TBR TYRE,	EX0003112	
S01	EX00031127	REMOVAL: CUSTOMER PULL POINT,	EX0003112	
S01	EX00031127	SCHEDULED DEPOT SERVICE 15MIN,	EX0003112	
S01	187550830	RUNOUT TYRE,	EX0003112	
S01	187550830	FIT TBR TYRE,	EX0003112	
S01	187550830	REMOVAL: CUSTOMER PULL POINT,	EX0003112	
S01	187550830	SCHEDULED DEPOT SERVICE 15MIN,	EX0003112	

IR

Labour		0.00

h air side flush and cleaned
k for test drive and fault code was gone.

Labour		2.00

ANK CABLE RHS TANK

R FITTINGS OVER ON SUZI COILS AS THEY WERE PUT ON INCORRECTLY

CREEN. DEFECT NO. 10325 CREATED

Labour - Internal		2.00
Consumables		5.00
MALE TRAILER PLUG		1.00
WIPER BLADE		2.00

r	Invoice	Details	Purchase Order
		Labour	
		Labour	1.00
		Consumables	
		HITECH SYNPLUS 10W50	
		AIR FILTER SLEEPER AIR	
IND01	EX00031570	SUPPLY AND FIT RHS FRONT WINDSCREEN	EX0003157
IND01	EX00031661	KENWORTH K200, Labour External,	EX0003166
IND01	7032	SUPPLY AND FIT RHS FRONT WINDSCREEN	EX0003157
IND01	7035	KENWORTH K200, Labour External,	EX0003166
		Labour	
		Labour	

r	Invoice	Details	Purchase Order

w strap lining from parts. disconnect lh tank light panel. Unbolt
. Fit new lining. Refit strap. Refit lh tank light panel.

INING-TANK STRAP 1.00

pect inside door. Found adhesive holders on harness had
e harness to frame as it is stronger than the adhesive ones.
r hear it rubbing on anything. Refit trim pieces. Tidied work

for repair when truck returns CB. SUBLET TO COSTLESS WINDOW TINTING #W503372
SE 4.00

N AND VISIBLE
ecured electrical harnessing and refitted door card.

LEAKING. STILL DIAGNOSE IF IT IS FAULT AND REPAIR
w tp5 valve from parts. marked and disconnected airlines.
efit airlines. Built up air. Sprayed for leaks

GAUGE: 16.680

		Labour	1.00

CED 1.5KG FIRE

		Labour - Internal	1.00
		Consumables	4.00
		1.5KG FIRE EXTINGUISHER	1.00
		Labour	0.00

r	Invoice	Details	Purchase Order

scription of Defect :
SCREEN

		Labour	0.00

still not cold

ching in Recover gas from system

compressor Refitted A/c belt and drive belt

OHUR01	EX00031861	A/C BLOWS HOT AIR,	EX0003186
OHUR01	EX00031861	Receiver Drier, K200,	EX0003186
OHUR01	EX00031861	0R9303 - O-RING,	EX0003186
OHUR01	EX00031861	COMPRESSOR - REFRIGERANT,	EX0003186
OHUR01	EX00031861	0R9304 O-RING,	EX0003186
OHUR01	EX00031861	0R9305 O-RING,	EX0003186
OHUR01	EX00031861	R134A, A/C GAS,	EX0003186
OHUR01	EX00031861	Consumables	EX0003186

OHUR01	EX00031861	, ENVIRONMENTAL LEVY,	EX0003186
OHUR01	EX00031861	ROUNDING,	EX0003186
OHUR01	3071644	A/C BLOWS HOT AIR,	EX0003186
OHUR01	3071644	Receiver Drier, K200,	EX0003186
OHUR01	3071644	0R9303 - O-RING,	EX0003186

:r	Invoice	Details	Purchase Order
HUR01	3071644	COMPRESSOR - REFRIGERANT,	EX0003186
HUR01	3071644	0R9304 O-RING,	EX0003186
HUR01	3071644	0R9305 O-RING,	EX0003186
HUR01	3071644	R134A, A/C GAS,	EX0003186
JR01	3071644	Consumables	EX0003186
JR01	3071644	, ENVIRONMENTAL LEVY,	EX0003186
HUR01	3071644	ROUNDING,	EX0003186
\US01	EX00031913	11R22.5 148/145L BS M866,FITTED FROM CUSTOMER'S OWN STOCK Labour	EX0003191
\US01	EX00031913	CASE STOCK 11-22.5,	EX0003191
D CABIN AIR FILTER			
\US01	EX00031913	FIT TBR TYRE, Consumables	EX0003191
\US01	EX00031913	TYRE HELD FOR RUNOUT, TRP KW CAB AIR FILTER	EX0003191
\US01	EX00031913	REMOVAL: CUSTOMER PULL POINT,	EX0003191
\US01	EX00031913	REMOVAL: CUSTOMER REQUEST,	EX0003191
\US01	EX00031913	SCHEDULED DEPOT SERVICE 15MIN,	EX0003191
S01	187812773	11R22.5 148/145L BS M866,FITTED FROM	EX0003191
S01	187812773	CUSTOMER'S OWN STOCK CASE STOCK 11-22.5,	EX0003191
\US01	187812773	FIT TBR TYRE,	EX0003191
\US01	187812773	TYRE HELD FOR RUNOUT,	EX0003191
\US01	187812773	REMOVAL: CUSTOMER PULL POINT,	EX0003191
\US01	187812773	REMOVAL: CUSTOMER REQUEST,	EX0003191
\US01	187812773	SCHEDULED DEPOT SERVICE 15MIN,	EX0003191
		Labour	1.00
		Consumables	4.00
		Labour	1.50
		Labour	1.00
CED			
		Labour - Internal	0.25
		Consumables	3.00
		Consumables	4.00
		AIR FILTER SLEEPER AIR	1.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		HITECH SYNPLUS 10W50	1.00

:r	Invoice	Details	Purchase Order
		5 BLADE COOLING FAN	
HUR01	EX00032094	CLUTCH KIT INC KW X SHAFTS,	EX0003209
HUR01	EX00032094	PACGEN EP ADV CLUTCH,	EX0003209
HUR01	3087430	CLUTCH KIT INC KW X SHAFTS,	EX0003209
HUR01	3087430	PACGEN EP ADV CLUTCH,	EX0003209
		Labour	10.00
REPLACED CLUTCH			
		Labour - Internal	10.00
		Labour - Internal	1.00
		Consumables	10.00
		PACGEN EP ADV CLUTCH	1.00
		CLUTCH KIT INC KW X SHAFTS	1.00
		Labour	0.00

Labour	1.50

4.

Labour - Internal	1.50
Labour - Internal	0.50
Consumables	5.00
MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	50.00
Labour	1.00

)R ON BULLBAR

). 00010800 CREATED

Labour - Internal	1.00
Consumables	6.00
LED FRONT DIRECTION LAMP	1.00
Labour	0.00

Labour	0.00

r	Invoice	Details	Purchase Order

)2/2024 INVOICE NO. 1144243

łrs

. Jack cab and check air pressure to doser pump (OK).
r filter. All faults become inactive, and pump is flowing 30LPM of air.

mplete paperwork.

MIN01	EX00032852	AFTERTREATMENT DOSER PUMP CLOGGED,	EX0003285
MIN01	EX00032852	Ad Blue filter Kenworth,	EX0003285
MIN01	EX00032852	ENVIRONMENTAL LEVY,	EX0003285
MIN01	EX00032852	ROAD TOLLS,	EX0003285
MIN01	EX00032852	OVERTIME,	EX0003285
MIN01	EX00032852	Consumables	EX0003285
MIN01	EX00032852	, TRAVEL LABOUR,	EX0003285
MIN01	EX00032852	Travel Fee to Breakdowns,	EX0003285
MIN01	1144243	AFTERTREATMENT DOSER PUMP	EX0003285
MIN01	1144243	CLOGGED, Ad Blue filter Kenworth,	EX0003285
MIN01	1144243	ENVIRONMENTAL LEVY,	EX0003285
MIN01	1144243	ROAD TOLLS,	EX0003285
MIN01	1144243	OVERTIME,	EX0003285
MIN01	1144243	Consumables	EX0003285
MIN01	1144243	, TRAVEL LABOUR,	EX0003285
MIN01	1144243	Travel Fee to Breakdowns,	EX0003285
\US01	EX00032789	RUNOUT TYRE,	EX0003278
\US01	EX00032789	FIT TBR TYRE,	EX0003278
\US01	EX00032789	REMOVAL: CUSTOMER PULL POINT,	EX0003278
\US01	EX00032789	ROTATE TBR TYRE,	EX0003278
\US01	EX00032789	SCHEDULED DEPOT SERVICE 15MIN,	EX0003278
\US01	EX00032789	ROTATE TBR TYRE,	EX0003278
\US01	EX00032789	FLIP TRUCK TYRE OR RETREAD,	EX0003278
\US01	188127500	RUNOUT TYRE,	EX0003278

AUS01	188127500	FIT TBR TYRE,	EX0003278

er	Invoice	Details	Purchase Order
S01	188127500	REMOVAL: CUSTOMER PULL POINT,	EX0003278
S01	188127500	ROTATE TBR TYRE,	EX0003278
S01	188127500	SCHEDULED DEPOT SERVICE 15MIN,	EX0003278
S01	188127500	ROTATE TBR TYRE,	EX0003278
S01	188127500	FLIP TRUCK TYRE OR RETREAD,	EX0003278
		Labour	1.00

e for leak.

	Consumables	3.00
	Labour	0.00
	Labour	0.00
	Labour	0.50
	Consumables	3.00
	HITECH SYNPLUS 10W50	1.00
	Air Filter Sleeper Air	1.00
	Labour	1.00
	Labour - Internal	1.00
	Consumables	3.00
	Labour	0.00
	Labour	0.00
	Labour	0.00
	Labour	4.00

EPLACED BELTS &

	Labour - Internal	4.00
	Consumables	5.00
	Drive Belt, K200	1.00
	Syntrans Gear Oil 75w-90	11.00
	Diff/Gear Oil 80W90 Castrol	28.00
	REPLACEMENT ELEMENT INLINE FILTER Turbo 2000 Air dryer	

er	Invoice	Details	Purchase Order
		DIFF FILTER	
		TRP KW CAB AIR FILTER	
		ES Water Filter	
		Element 10 Micron	
		BELT TENSIONER	
		Fan Belt	
		Labour	
		Labour	
		Labour	
		Labour	0.50
		Consumables	2.00

Air Filter Sleeper Air		1.00
Eco Oil Filter Cartridge		1.00
HITECH SYNPLUS 10W50		1.00
Fuel/Water seperator filter		1.00
FUEL FILTER ECOWIND		1.00
Labour		2.00

TEMPT #

ECTS

S01	EX00033381	11R22.5 148/145L BS M749,	EX0003338
S01	EX00033388	295/80R22.5 152/148M BS R154 ECO,	EX0003338
S01	EX00033381	CASE STOCK 11R22.5 ECOPIA,	EX0003338
S01	EX00033388	FIT TBR TYRE,	EX0003338
S01	EX00033381	FIT TBR TYRE,	EX0003338
S01	EX00033388	TYRE HELD FOR RUNOUT,	EX0003338
S01	EX00033381	TYRE HELD FOR RUNOUT,	EX0003338
S01	EX00033388	REMOVAL: CUSTOMER REQUEST,	EX0003338
S01	EX00033381	REMOVAL: CUSTOMER PULL POINT,	EX0003338
S01	EX00033388	SCHEDULED DEPOT SERVICE 15MIN,	EX0003338
S01	EX00033381	REMOVAL: CUSTOMER REQUEST,	EX0003338
S01	188316441	295/80R22.5 152/148M BS R154 ECO,	EX0003338
S01	EX00033381	SCHEDULED DEPOT SERVICE 15MIN,	EX0003338
S01	188316441	FIT TBR TYRE,	EX0003338
S01	188316284	11R22.5 148/145L BS M749,	EX0003338

r	Invoice	Details	Purchase Order
S01	188316441	TYRE HELD FOR RUNOUT,	EX0003338
S01	188316284	CASE STOCK 11R22.5 ECOPIA,	EX0003338
S01	188316441	REMOVAL: CUSTOMER REQUEST,	EX0003338
S01	188316284	FIT TBR TYRE,	EX0003338
S01	188316441	SCHEDULED DEPOT SERVICE 15MIN,	EX0003338
S01	188316284	TYRE HELD FOR RUNOUT,	EX0003338
S01	188316284	REMOVAL: CUSTOMER PULL POINT,	EX0003338
S01	188316284	REMOVAL: CUSTOMER REQUEST,	EX0003338
S01	188316284	SCHEDULED DEPOT SERVICE 15MIN,	EX0003338
		Labour	

Labour

ker plate and inspect for
uble zip ties and remove

again. Check for leaks. All

	INVESTIGATE & REPAIR LARGE AIR	EX0003353
X00033531	LEAK AROUND REAR AXLE BRAKE BOOSTERS, HOSE ASSEMBLY - AIR BRAKE,	EX0003353
X00033531	Consumables	EX0003353
X00033531	, ENVIRONMENTAL LEVY,	EX0003353
161212	INVESTIGATE & REPAIR LARGE AIR LEAK AROUND	EX0003353
161212	REAR AXLE BRAKE BOOSTERS, HOSE ASSEMBLY - AIR BRAKE,	EX0003353
L61212	Consumables	EX0003353
L61212	, ENVIRONMENTAL LEVY,	EX0003353

X00033622		REMOVE COVERS & DEGREASE ENGINE. NOTICE	EX0003362
X00033622		PRESSURE SWITCH LEAKING. REMOVE & REPLACE PRESSURE SWITCH., Consumables	EX0003362
:X00033622		, PRESSURE SWITCH ADJ 8-13 PSI,	EX0003362

ır	Invoice	Details	Purchase Order
JT01	56893	REMOVE COVERS & DEGREASE ENGINE. NOTICE	EX0003362
JT01	56893	PRESSURE SWITCH LEAKING. REMOVE & REPLACE PRESSURE SWITCH., Consumables	EX0003362
JT01	56893	, PRESSURE SWITCH ADJ 8-13 PSI,	EX0003362
		Labour	0.00
		Labour	1.00
/2024.			
		Labour - Internal	1.00
		Labour - Internal	1.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	51.00
		Labour	0.00
		Labour	1.00
/2024. TIGHTENED			
R SERVICE			
		Labour - Internal	1.00
		Labour - Internal	1.00
		Consumables	5.00
		ES Water Filter	1.00
		Labour	0.00
		Labour	0.00
		Labour	1.00
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		AIR FILTER SLEEPER AIR	1.00
		Labour	1.50
		Labour - Internal	1.50
		Consumables	5.00
		CR SEAL - HUB SEAL	1.00

ır	Invoice	Details	Purchase Order
		Labour	
EC01	EX00034229	TRAVELLED TO WORKSHOP AND COLLECTED 4 X	EX0003422
EC01	EX00034229	N70ZZ BATTERIES. TRAVELLED TO BP PAGET LOCATED TRUCK. JACKED UP CAB. REMOVE & REFIT BATTERIES. START AND CHECK CHARGE RATE, Call Out After Hours/Off Site,	EX0003422
MEC01	EX00034229	N70ZZ BATTERY,	EX0003422
EC01	EX00034229	Consumables	EX0003422
EC01	EX00034229	, ENVIRONMENTAL LEVY,	EX0003422
MEC01	MK-RIN10743	TRAVELLED TO WORKSHOP AND	EX0003422

COLLECTED 4 X N70ZZ BATTERIES. TRAVELLED TO BP PAGET LOCATED TRUCK. JACKED UP CAB. REMOVE & REFIT BATTERIES. START AND CHECK CHARGE RATE,

:C01	MK-RIN10743	Call Out After Hours/Off Site,	EX0003422
:C01	MK-RIN10743	N70ZZ BATTERY,	EX0003422
:C01	MK-RIN10743	Consumables	EX0003422
:C01	MK-RIN10743	, ENVIRONMENTAL LEVY,	EX0003422
		Labour	
		Labour	1.00
ND OLD			
		Consumables	3.00
		Valve Governor	1.00
		Labour	1.00
E WITH			
		Consumables	3.00
		Labour	0.00

r	Invoice	Details	Purchase Order
: :			
		Labour	1.00
)24.			
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		Air Filter Sleeper Air	1.00
		Labour	0.00
		Labour	1.50
NSIONED LOOSE			
		Labour - Internal	1.50
		Consumables	3.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	50.00
AUS01	EX00035288	PUNCTURE REPAIR TBR,	EX0003528
AUS01	EX00035288	B FLEET PRESSURE CHECK,	EX0003528
AUS01	188941999	PUNCTURE REPAIR TBR,	EX0003528
AUS01	188941999	B FLEET PRESSURE CHECK,	EX0003528
		Labour	
:024.			
)LANT			
		Labour - Internal	1.50
		Consumables	5.00
		Cab Shock K200 KONI	1.00
		Labour	1.00
P) ON		18/07/2024.	
		Consumables	3.00
		Air Filter Sleeper Air	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	6.00

r	Invoice	Details	Purchase Order

HOP) ON 31/07/2024.

OIL

		Labour - Internal	0.50
		Labour - Internal	0.50
		Consumables	3.00
		OIL 15W-40, CK 4/E9	5.00
		HT/S SUPER DUTY OEM KIT	1.00
		Labour	0.00

024

024

GAIN

	EX00035574	INSPECT SLEEPER AIR GAS	EX0003557
		PRESSURE FAULT. CHECK AND FIND CONDENSER FAN FAULTY. SOURCE REPLACEMENT FAN AND CHANGE OUT. TEST OPERATION, OKAY,	
	EX00035574	FAN ELEC 12IN 12V REVERSIBLE,	EX0003557
	58049	INSPECT SLEEPER AIR GAS PRESSURE FAULT.	EX0003557
	58049	CHECK AND FIND CONDENSER FAN FAULTY. SOURCE REPLACEMENT FAN AND CHANGE OUT. TEST OPERATION, OKAY, FAN ELEC 12IN 12V REVERSIBLE,	EX0003557
		Labour	2.00

4. FIT WIPER BLADES

er	Invoice	Details	Purchase Order
		Consumables	
		Labour	
		Labour	
		Labour	
24.			
		Consumables	
		HITECH SYNPLUS 10W50	
S01	EX00035834	PUNCTURE REPAIR TBR,	EX0003583
S01	EX00035834	SCHEDULED DEPOT SERVICE 15MIN,	EX0003583
S01	189141867	PUNCTURE REPAIR TBR,	EX0003583
S01	189141867	SCHEDULED DEPOT SERVICE 15MIN,	EX0003583
		Labour	1.00

MBLY

		Labour - Internal	1.00

	Consumables	4.00
	WIPER BLADE 600x8mm B-FIX	2.00
	Labour	0.00
	Labour	0.00
	Labour	2.00
'LACED		
	Labour - Internal	2.00
	Consumables	6.00
	MAINTENANCE KIT	1.00
	OIL 15W-40, CK 4/E9	50.00
	Labour	0.00

24

501	EX00036106	11R22.5 148/145L BS M749II ECO,	EX0003610

	Invoice	Details	Purchase Order
AUS01	EX00036129	RUNOUT TYRE,	EX0003612
AUS01	EX00036106	FIT TBR TYRE,	EX0003610
AUS01	EX00036129	FIT TBR TYRE,	EX0003612
AUS01	EX00036106	CUSTOMER SCRAPPED OWN TYRE,	EX0003610
AUS01	EX00036129	CUSTOMER SCRAPPED OWN TYRE,	EX0003612
AUS01	EX00036106	REMOVAL: TREAD CUT OR CHUNKING,	EX0003610
AUS01	EX00036129	REMOVAL: PUNCTURED,	EX0003612
AUS01	189249797	11R22.5 148/145L BS M749II ECO,	EX0003610
AUS01	EX00036129	SCHEDULED DEPOT SERVICE 15MIN,	EX0003612
AUS01	189249797	FIT TBR TYRE,	EX0003610
AUS01	189257383	RUNOUT TYRE,	EX0003612
AUS01	189249797	CUSTOMER SCRAPPED OWN TYRE,	EX0003610
AUS01	189257383	FIT TBR TYRE,	EX0003612
AUS01	189249797	REMOVAL: TREAD CUT OR CHUNKING,	EX0003610
AUS01	189257383	CUSTOMER SCRAPPED OWN TYRE,	EX0003612
AUS01	189257383	REMOVAL: PUNCTURED,	EX0003612
AUS01	189257383	SCHEDULED DEPOT SERVICE 15MIN,	EX0003612
HUR01	EX00036148	SWITCH ROCKER DOME LAMP KW,	EX0003614
HUR01	EX00036148	SWITCH-ROCKER ENGINE FAN,	EX0003614
HUR01	3317787	SWITCH ROCKER DOME LAMP KW,	EX0003614

NVOICE NO. 3318055

; AIR.
aters. Only major air leak found at front pressure relief valve on

ear tank would drop from 800kpa to 750kpa when going over

yre off bead

A LOUDER THAN NORMAL NOISE.

be normal.
OCKER ENGINE FAN,
EX0003614

X00036160		INSPECT, DIAGNOSE AND REPAIR	EX0003616
CT,			EX0003616
X00036160	Consumables		
JR01	EX00036160	ENVIRONMENTAL LEVY,	EX0003616

3318055 INSPECT, DIAGNOSE AND REPAIR EX0003616
.CT,

:r	Invoice	Details	Purchase Order
JR01	3318055	Consumables	EX0003616
JR01	3318055	,	EX0003616
		ENVIRONMENTAL LEVY,	
		Labour	
ON 02/10/2024. REPLACE BOLT IN GRILL			
		Labour - Internal	1.00
		Consumables	3.00
		Labour	0.50
OP) ON 02/10/2024.			
		Consumables	3.00
		Air Filter Sleeper Air	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	
AN01	EX00036956	CALLOUT TO GUMLU. STRIP RHF STEER TYRE	EX0003695
AN01	262267	(POS 2) AND INSPECT FOR SLOW LEAK. RIM HAS APPROX 3 INCH CRACK. REFIT TYRE AND INFLATE @ 120PSI,	EX0003695
		CALLOUT TO GUMLU. STRIP RHF	
		STEER TYRE (POS 2) AND INSPECT FOR SLOW LEAK. RIM HAS APPROX 3 INCH CRACK. REFIT TYRE AND INFLATE @ 120PSI,	
		WHEEL OFFSET,	
HUR01	EX00036943		EX0003694
HUR01	EX00036943	WHEEL OFFSET - DISCOUNT,	EX0003694
HUR01	3362520	WHEEL OFFSET,	EX0003694
HUR01	3362520	WHEEL OFFSET - DISCOUNT,	EX0003694
AUS01	EX00036918	RUNOUT TYRE,	EX0003691
AUS01	EX00036918	FIT TBR TYRE,	EX0003691
AUS01	EX00036918	TYRE HELD FOR RUNOUT,	EX0003691
AUS01	EX00036918	EQUAL POWDER - DROP IN,	EX0003691
AUS01	EX00036918	REMOVAL: CUSTOMER REQUEST,	EX0003691
AUS01	189535749	RUNOUT TYRE,	EX0003691
AUS01	189535749	FIT TBR TYRE,	EX0003691
AUS01	189535749	TYRE HELD FOR RUNOUT,	EX0003691
AUS01	189535749	EQUAL POWDER - DROP IN,	EX0003691
AUS01	189535749	REMOVAL: CUSTOMER REQUEST,	EX0003691
AUS01	EX00037130	295/80R22.5 152/148M BS R154 ECO,	EX0003713
AUS01	EX00037130	FIT TBR TYRE,	EX0003713
AUS01	EX00037130	TYRE HELD FOR RUNOUT,	EX0003713
AUS01	EX00037130	REMOVAL: MATCH OTD OR PATTERN,	EX0003713
AUS01	EX00037130	SCHEDULED DEPOT SERVICE 15MIN,	EX0003713

:r	Invoice	Details	Purchase Order
S01	189589684	295/80R22.5 152/148M BS R154 ECO,	EX0003713
S01	189589684	FIT TBR TYRE,	EX0003713
S01	189589684	TYRE HELD FOR RUNOUT,	EX0003713
S01	189589684	REMOVAL: MATCH OTD OR PATTERN,	EX0003713
S01	189589684	SCHEDULED DEPOT SERVICE 15MIN,	EX0003713
S01	EX00037174	ISS AFTER HOURS CALL OUT #161368,	EX0003717
S01	EX00037174	CALLED OUT TO SARINA QLD 271024 CALLER	EX0003717
S01	EX00037174	ANDREW BUCKLE 0408556535,	EX0003717
		DRIVER DANIEL SNOWDEN	
		0474723544 1 X MICH 295/80R22.5 Z MULTI,	
S01	EX00037174	1 X SCRAP STEER NO POSITION	EX0003717
S01	189604081	GIVEN R162580,	EX0003717
		1 X SCRAP STEER NO POSITION	
S01	189604081	GIVEN R162580,	EX0003717
		DRIVER DANIEL SNOWDEN	

0474723544 1 X MICH 295/80R22.5 Z MULTI,
SO1 189604081 CALLED OUT TO SARINA QLD 271024 EX0003717

CALLER ANDREW BUCKLE 0408556535,
ISS AFTER HOURS CALL OUT #161368,
SO1 189604081 EX0003717
Labour 0.50
PER AIR HOURS 8065

Consumables 3.00
HITECH SYNPLUS 10W50 1.00
VOICE NO. 3391554

Truck Pads & Troubleshoot Active Aftertreatment Light & Engine Derat

rts & equipment to carry out repair; travel out to vehicle located at Maryborough Pads; arrive on site;
gnostic computer; download fault log & analyse data; found active codes 3738 ? Air Supply Actuator
e Level & 3575 ? Aftertreatment 1 Diesel Exhaust Fluid Pressure Data Valid but Above Normal

nove air supply line; confirm air pressure present at pump; remove injector line from pump; sight amount
failing to click; believe dosing pump failed; new pump not available at Brown and Hurley Bundaberg;
it; pack up gear &

r	Invoice	Details	Purchase Order

NVOICE NO. 3411535

Truck Pads & Troubleshoot Active Aftertreatment Light & Engine Derate

arts & equipment to carry out repair; travel out to vehicle located
nent light & engine derate; connect diagnostic computer;
Supply Actuator Data Valid but Below Normal Operating Range ?
st Fluid Pressure Data Valid but Above Normal Operating Range ?
solenoid failing to click; remove air supply line; confirm air
nount of air present coming out of pump; carry out air side flush;
t available at Brown and Hurley Bundaberg; transfer job to Brown
avel back to workshop

Check Engine light on and truck in de-rate, take over breakdown from B&H Bundy

rg Brown and Hurley have attended a breakdown at Maryborough for aftertreatment
story of what had happened, they attempted to flush the system, but could not get
rkshop, load ute, drive to Maryborough. Plug in Cummins insite to truck and
on prior for some time. Check fault codes, found aftertreatment fluid pressure
nd to doser, clear all lines from tank to doser. Remove and replace doser.
in Insite and confirm doser operating correctly . Wipe down vehicle. Drive back to

d to be organised travel per km & connection fees are not charged as goodwill.

URS SERVICE CALL OUT TO

EX0003743
LE BREAKDOWN AT MARYBOROUGH,
JR01 EX00037763 AFTERHOURS SERVICE CALL OUT TO EX0003776

		VEHICLE AT MARYBOROUGH TRUCK PADS & TROUBLESHOOT ACTIVE AFTERTREATMENT LIGHT AND ENGINE DERATE,	
‹r	Invoice	Details	Purchase Order
⊣UR01	EX00037881	BREAK DOWN CALL OUT,	EX0003788
JR01	EX00037438	TROUBLESHOOT ACTIVE AFTERTREATMENT	EX0003743
JR01	EX00037763	LIGHT & ENGINE DERATE, TROUBLESHOOT ACTIVE	EX0003776
⊣UR01	EX00037881	AFTERTREATMENT LIGHT AND ENGINE DERATE, RECON DOSER PUMP 12 V KW,	EX0003788
⊣UR01	EX00037438	Ad Blue filter Kenworth,	EX0003743
⊣UR01	EX00037763	Ad Blue filter Kenworth,	EX0003776
⊣UR01	EX00037881	OPENING FEE,	EX0003788
⊣UR01	EX00037438	Travel Fee to Breakdowns,	EX0003743
JR01	EX00037763	Consumables	EX0003776
JR01	EX00037881	, Consumables	EX0003788
⊣UR01	EX00037438	, HOOKUP FEE,	EX0003743
⊣UR01	EX00037763	ENVIRONMENTAL LEVY,	EX0003776
⊣UR01	EX00037881	ENVIRONMENTAL LEVY,	EX0003788
JR01	EX00037438	Consumables	EX0003743
JR01	3411535	, AFTERHOURS SERVICE CALL OUT TO VEHICLE AT MARYBOROUGH TRUCK PADS & TROUBLESHOOT ACTIVE AFTERTREATMENT LIGHT AND ENGINE DERATE, BREAK DOWN CALL OUT,	EX0003776
⊣UR01	3409765		EX0003788
⊣UR01	EX00037438	ENVIRONMENTAL LEVY,	EX0003743
JR01	3411535	TROUBLESHOOT ACTIVE AFTERTREATMENT	EX0003776
JR01	3409765	LIGHT AND ENGINE DERATE, RECON DOSER PUMP 12 V KW,	EX0003788
JR01	3391554	AFTERHOURS SERVICE CALL OUT TO VEHICLE	EX0003743
JR01	3411535	BREAKDOWN AT MARYBOROUGH, Ad Blue filter Kenworth,	EX0003776
⊣UR01	3409765	OPENING FEE,	EX0003788
JR01	3391554	TROUBLESHOOT ACTIVE AFTERTREATMENT	EX0003743
JR01	3411535	LIGHT & ENGINE DERATE, Consumables	EX0003776
⊣UR01	3409765	, Consumables	EX0003788
⊣UR01	3391554	, Ad Blue filter Kenworth,	EX0003743
⊣UR01	3411535	ENVIRONMENTAL LEVY,	EX0003776
⊣UR01	3409765	ENVIRONMENTAL LEVY,	EX0003788
⊣UR01	3391554	Travel Fee to Breakdowns,	EX0003743
‹r	Invoice	Details	Purchase Order
JR01	3391554	HOOKUP FEE,	EX0003743
JR01	3391554	Consumables	EX0003743
JR01	3391554	, ENVIRONMENTAL LEVY,	EX0003743

39245

S and Light Leads had

es to be exposed.
ce leads were secured -

		ABS & LIGHT LEADS DAMAGED.	EX0003762
EX00037627		REMOVED & REPLACED DAMAGED LEADS, SUZI COIL LIGHT LEAD,	EX0003762

EX00037627		ABS SUZI COIL LEAD,	EX0003762
X00037627		Consumables	EX0003762
9245		,	EX0003762
		ABS & LIGHT LEADS DAMAGED.	
		REMOVED & REPLACED DAMAGED LEADS,	
9245		SUZI COIL LIGHT LEAD,	EX0003762
9245		ABS SUZI COIL LEAD,	EX0003762
9245		Consumables	EX0003762
X00037650		,	EX0003765
		CALLED OUT TO TEST BATTERIES	
		AND JUMP START TRUCK. DROPPED BULLBAR TO TILT CAB. JUMP STARTED TRUCK, TESTED AND ALL OK.,	
		CALLED OUT TO TEST BATTERIES	
9304			EX0003765
		AND JUMP START TRUCK. DROPPED BULLBAR TO TILT CAB. JUMP STARTED TRUCK, TESTED AND ALL OK.,	
		Ad Blue filter Kenworth,	
X00037703			EX0003770
X00037703		Travel Fee to Breakdowns,	EX0003770
X00037703		HOOKUP FEE,	EX0003770
X00037703		Labour External,	EX0003770
X00037703		Consumables	EX0003770
411527		,	EX0003770
		Ad Blue filter Kenworth,	
411527		Travel Fee to Breakdowns,	EX0003770
411527		HOOKUP FEE,	EX0003770
411527		Labour External,	EX0003770

r	Invoice	Details	Purchase Order
JR01	3411527	Consumables	EX0003770
		,	
9470			

. Cleaned terminals and fitted new batteries. Tested charging. All OK

W01	EX00038033	CALLED OUT TEST BATTERIES. REPLACED	EX0003803
W01	EX00038033	BATTERIES, CLEANED TERMINALS.,	EX0003803
		BATTERY,	
W01	EX00038033	Consumables	EX0003803
W01	39470	,	EX0003803
		CALLED OUT TEST BATTERIES.	
		REPLACED BATTERIES, CLEANED TERMINALS.,	
W01	39470	BATTERY,	EX0003803
W01	39470	Consumables	EX0003803
		,	
39535			

ump starting. Icepack
batteries and cleared

ne rod bent at 90degs.
a new one at same

lled both links off and pull

nent by 20mm.
.

l.

		INVESTIGATE, DIAGNOSE & REPAIR	EX0003812
EX00038122		NO CLUTCH PEDAL ISSUE, THRED ROD,	EX0003812
EX00038122		ROD END & LINK BALL,	EX0003812
X00038122		Consumables ,	EX0003812

r	Invoice	Details	Purchase Order
OW01	39535	INVESTIGATE, DIAGNOSE & REPAIR NO CLUTCH	EX0003812
OW01	39535	PEDAL ISSUE, THRED ROD,	EX0003812
LOW01	39535	ROD END & LINK BALL,	EX0003812
OW01	39535	Consumables	EX0003812
S01	EX00038522	, 11R22.5 148/145L BS M866,	EX0003852
AUS01	EX00038522	FIT TBR TYRE,	EX0003852
AUS01	EX00038522	CUSTOMER SCRAPPED OWN TYRE,	EX0003852
S01	EX00038522	REMOVAL: SIDEWALL CUT OR STAKED,	EX0003852
S01	EX00038522	POS 5 WORK COMPLETE 17/02/2025	EX0003852
AUS01	190155175	DEALER REFERENCE: 2320797, 11R22.5 148/145L BS M866,	EX0003852
AUS01	190155175	FIT TBR TYRE,	EX0003852
AUS01	190155175	CUSTOMER SCRAPPED OWN TYRE,	EX0003852
S01	190155175	REMOVAL: SIDEWALL CUT OR STAKED,	EX0003852
S01	190155175	POS 5 WORK COMPLETE 17/02/2025	EX0003852
	Labour	DEALER REFERENCE: 2320797,	0.50

ON 21/02/2025.

Air Filter Sleeper Air	1.00
HITECH SYNPLUS 10W50	1.00
Consumables	3.00
Labour - Internal	0.00
Consumables	0.00
Labour - Internal	2.00

) ON 21/02/2025.

Consumables	4.00
Labour - Internal	2.00
SERVICE KIT	1.00
AIR OIL FILTER	1.00
1KG FIRE EXTINGUISHER	1.00
OIL 15W-40, CK 4/E9	50.00

		Labour	7.00
		Consumables	5.00

r	Invoice	Details	Purchase Order
		RECON TURBOCHARGER KIT	
		AIR COMPRESSOR SX, RECONDITIONED DOSER PUMP, K200	
		Labour - Internal	1.00

TED

		Consumables	5.00
		Labour - Internal	1.00
		Labour - Internal	0.50
		Labour	0.00

t :

)25

S01	EX00039367	RUNOUT TYRE,	EX0003936
S01	EX00039367	FIT TBR TYRE,	EX0003936
S01	EX00039367	TYRE HELD FOR RUNOUT,	EX0003936
S01	EX00039367	REMOVAL: CUSTOMER REQUEST,	EX0003936
S01	EX00039367	SCHEDULED DEPOT SERVICE 15MIN,	EX0003936
S01	190444764	SCHEDULED DEPOT SERVICE 15MIN,	EX0003936
S01	190444764	REMOVAL: CUSTOMER REQUEST,	EX0003936
S01	190444764	TYRE HELD FOR RUNOUT,	EX0003936
S01	190444764	FIT TBR TYRE,	EX0003936
S01	190444764	RUNOUT TYRE,	EX0003936
ND01	EX00039472	Labour,	EX0003947
ND01	7899	Labour,	EX0003947
		Labour - Internal	1.00

r	Invoice	Details	Purchase Order
		Consumables	
		Labour - Internal	
		Wiper Control Stalk	
		Labour	0.00
		Labour - Internal	1.00
		Consumables	4.00
		Labour - Internal	1.00
		Labour - Internal	3.00

		Consumables		8.00
		Labour - Internal		3.00
		Turbo 2000 Air Drier		1.00
		ES Water Filter		1.00
		Power Steer Filter LF637		1.00
		DIFF FILTER		1.00
		Filter Element Gearbox Eaton		1.00
		TRANS DYNADRIVE LL 80W90		13.00
		TRANS MAN HVY DUTY 75W90 205L		12.00
		Drive Belt, K200		1.00
		Fan Belt		1.00
		Air Filter		1.00
		REPLACEMENT ELEMENT INLINE FILTER		1.00
		TRP KW CAB AIR FILTER		1.00
		BELT TENSIONER		1.00
		PIPE FLEX EXH DSS 5 IN		1.00
		Labour		0.00
		Labour		0.00
		Labour		0.00
		Labour		0.00
		Labour		3.00

r	Invoice	Details	Purchase Order
TEMPT #			
IR			
		Labour - Internal	
		Labour	
		Consumables	
		Air Filter Sleeper Air	
		Air Filter Sleeper Air	
		Fuel Filter (Sleeper Air)	
		Fuel/Water seperator filter	
		HITECH SYNPLUS 10W50	
		O-RING	
	EX00040007	Labour,	EX0004000
	EX00040007	TWO SLEVES REQUIRED,	EX0004000
	149435	Labour,	EX0004000
	149435	TWO SLEVES REQUIRED,	EX0004000
		Labour	
:			
SE REPLACE			
		Labour	0. 50 10 5.
AND TENSIONED			
		Consumables	3.00
		Labour - Internal	0.00
		Consumables	0.00
		Labour - Internal	3.00

		Consumables	5.00
		Labour - Internal	3.00
		SERVICE KIT	1.00

r	Invoice	Details	Purchase Order
		AIR OIL FILTER	
		OIL 15W-40, CK 4/E9	
		Labour	0.00

: :

	Labour - Internal	1.00

ED NEXT SERVICE D # 14449 RIGHT SIDE LOWER RADATOR TANK BOLTS NEED TO BE

NEXT SERVUCE

	Consumables	4.00
	Labour - Internal	1.00
	Labour - Internal	2.00

RE - U/S FUEL TANK

IES REPLACED NOX

	Consumables	7.00
	Labour - Internal	5.00
	RECON NOX SENSOR	1.00
	Labour	0.00

E REPLACED NEXT SERVICE RIGHT SIDE LOWER RADATOR TANK BOLTS NEED TO BE

GHTENED NEXT SERVICE

		Labour - Internal	1

r	Invoice	Details	Purchase Order

RN

		Consumables	
		Labour - Internal	
MOB01	EX00041251	Labour External,	EX0004125
OB01	EX00041251	Consumables	EX0004125
OB01	EX00041251	,	EX0004125
		MATERIALS - SUPPLY AND FIT LHS	

		WINDSCREEN ON KENWORTH K200 F/C,(CAB OVER) (1/2 SCREEN, OEM R44-1125) 06/2013 Labour External,	
MOB01	55732A		EX0004125
OB01	55732A	Consumables	EX0004125
OB01	55732A	, MATERIALS - SUPPLY AND FIT LHS WINDSCREEN ON KENWORTH K200 F/C,(CAB OVER) (1/2 SCREEN, OEM R44-1125) 06/2013 Labour External,TRAVEL TO ANDREWS	EX0004125
OW01	EX00041496	WINDSCREENS. REMOVE BUG SCREEN FROM FRONT OF W/SCREEN TO BE ABLE TO REMOVE AND REFIT W/SCREEN. ON COMPLETION, VEHICLE BROUGHT TO WORKSHOP TO REFIT SCREEN Consumables	EX0004149
OW01	EX00041496		EX0004149
OW01	EX00041496	,BOLTS AND NUTS Consumables	EX0004149
OW01	EX00041496	, ENVIRONMENTAL LEVY,	EX0004149
W01	41170	Labour External,TRAVEL TO ANDREWS	EX0004149
W01	41170	WINDSCREENS. REMOVE BUG SCREEN FROM FRONT OF W/SCREEN TO BE ABLE TO REMOVE AND REFIT W/SCREEN. ON COMPLETION, VEHICLE BROUGHT TO WORKSHOP TO REFIT SCREEN Consumables	EX0004149
OW01	41170	,BOLTS AND NUTS Consumables	EX0004149
OW01	41170	, ENVIRONMENTAL LEVY, Labour - Internal	EX0004149

r	Invoice	Details	Purchase Order

Consumables	0.00
Labour - Internal	2.00

		Consumables	
		Labour - Internal	
		Labour - Internal	
		1KG FIRE EXTINGUISHER	
		OIL 15W-40, CK 4/E9	
		SERVICE KIT	
		AIR OIL FILTER	
		Element 10 Micron	
01	EX00041583	Labour External,ALIGNMENT OF TRUCK	EX0004158
01	Q630108	Labour External,ALIGNMENT OF TRUCK	EX0004158
S01	EX00041674	295/80R22.5 152/148M BS R154 ECO,	EX0004167
S01	EX00041674	FIT TBR TYRE,	EX0004167
S01	EX00041674	TYRE HELD FOR RUNOUT,	EX0004167
S01	EX00041674	REMOVAL: CUSTOMER REQUEST,	EX0004167
S01	EX00041674	SCHEDULED DEPOT SERVICE 15MIN,	EX0004167
S01	191233415	295/80R22.5 152/148M BS R154 ECO,	EX0004167
S01	191233415	FIT TBR TYRE,	EX0004167
S01	191233415	TYRE HELD FOR RUNOUT,	EX0004167
S01	191233415	REMOVAL: CUSTOMER REQUEST,	EX0004167
S01	191233415	SCHEDULED DEPOT SERVICE 15MIN,	EX0004167
S01	EX00042018	11R22.5 148/145L BS M749II ECO,	EX0004201
S01	EX00042018	CASE STOCK 11R22.5 ECOPIA,	EX0004201
S01	EX00042018	FIT TBR TYRE,	EX0004201
S01	EX00042018	REMOVAL: CUSTOMER PULL POINT,	EX0004201

S01	EX00042018	SCHEDULED DEPOT SERVICE 15MIN,	EX0004201
S01	191351465	11R22.5 148/145L BS M749II ECO,	EX0004201
S01	191351465	CASE STOCK 11R22.5 ECOPIA,	EX0004201
S01	191351465	FIT TBR TYRE,	EX0004201
S01	191351465	REMOVAL: CUSTOMER PULL POINT,	EX0004201
S01	191351465	SCHEDULED DEPOT SERVICE 15MIN,	EX0004201
		Labour - Internal	

r	Invoice	Details	Purchase Order

HTENED GRILL

		Consumables	6.00
		Labour	0.75
		Consumables	
		OIL 15W-40, CK 4/E9	
		KOHLER AIR FILTER	
		DAYCO BLUE LABEL BELT	
S01	EX00042558	PUNCTURE REPAIR TBR,	EX0004255
S01	EX00042558	SCHEDULED DEPOT SERVICE 15MIN,	EX0004255
S01	191515796	PUNCTURE REPAIR TBR,	EX0004255
S01	191515796	SCHEDULED DEPOT SERVICE 15MIN,	EX0004255
		Labour - Internal	1.00
		Consumables	4.00
		Labour - Internal	1.00
		Labour - Internal	0.50
		LED FRONT DIRECTION LAMP	1.00
		Labour	3.00

LHS DIAGNOSE DIFF
2 X UNIVERSAL JOINTS

		Consumables	3.00
		Labour - Internal	4.00
		Labour - Internal	4.00
		Labour - Internal	3.50
		Labour - Internal	5.00
		Labour - Internal	3.00
		Seal - Drive	1.00
		Kit Q-Plus Brake Shoe	1.00
		Seal - Thru RP23160	1.00

r	Invoice	Details	Purchase Order
		UNI JOINT	
		Thru shaft Nut Kit	
A01	EX00042418	Labour External,	EX0004241
25			

WASHER, NEST ASSEMBLY, INPUT SHAFT,
OIL FILTER. LABOUR & CONSUMABLES.
ernal,

EX0004241

NTRAC01 EX00042939 Labour External, EX0004293

AIR 12/11/2025

site to inspect A/C system.
refrigerant found low; customer reported bubbling from one fitting.
leak in discharge hose inside sleeper air motor box.
ed faulty hose, fabricated and installed new hose. Removed and replaced Receiver
(customer supplied).
system for 30 minutes and added oil/dye. Re-gassed system and verified operation
ssor cycling correctly, and vent air temperature icy cold.
- A/C Charge
- Pressure Tests
- No.8 Fittings
- No.8 Hose
- Consumables
- Labour

NTRAC01 INV-11560 Labour External,

EX0004293

Labour - Internal

NE WHEN DIFF WAS OUT
E) STILL NEEDS TO HAVE SUMP GASKET DONE UNDER WARRANTY
ables

r	Invoice	Details	Purchase Order
		Labour - Internal	1.00
		Labour	0.00

: :

025 Description of Defect

025 Description of Defect

025 Description of Defect

Labour 0.50

N MOUNTING POSTS

Consumables 2.00
Labour 1.00

JND

		Consumables	0.00
		BATTERY DEEP CYCLE & TRUCK	4.00
		Labour - Internal	0.00
		Consumables	0.00
		Labour - Internal	1.00

r	Invoice	Details	Purchase Order
		Consumables	3.00
		Labour - Internal	1.00
		Labour - Internal	1.00
		FILTER KIT, OIL & FUEL FILTER, (E5)	1.00
		OIL 15W-40, CK 4/E9	51.00
		AIR OIL FILTER	1.00
		AIR FILTER	1.00
		Labour - Internal	1.00
		Consumables	3.00
		Labour - Internal	1.00
		Labour	0.00

: :
620 8N

		Labour - Internal	1.00

PRESSURE SWITCH
CH AND LIGHT HAS NOW GONE

		Consumables	5.00
		Labour - Internal	1.00
		Labour - Internal	0.75
		Labour - Internal	0.75
		SWITCH-PRESSURE	1.00
		Labour	0.50
		Consumables	2.00
		HITECH SYNPLUS 10W50	1.00

r	Invoice	Details	Purchase Order
		KOHLER AIR FILTER	
S01	EX00045576	RUNOUT TYRE,	EX0004557
S01	EX00045576	FIT TBR TYRE,	EX0004557
S01	EX00045576	TYRE HELD FOR RUNOUT,	EX0004557
S01	EX00045576	22.5X8.25 CSA ALLOY MAC 10/285,	EX0004557
S01	EX00045576	REMOVAL: CUSTOMER REQUEST,	EX0004557

S01	EX00045576	SVC CALL OUT NORMAL HOURS/15MINS, RUNOUT	EX0004557
S01	192536528	TYRE,	EX0004557
S01	192536528	FIT TBR TYRE,	EX0004557
S01	192536528	TYRE HELD FOR RUNOUT,	EX0004557
S01	192536528	22.5X8.25 CSA ALLOY MAC 10/285,	EX0004557
S01	192536528	REMOVAL: CUSTOMER REQUEST,	EX0004557
S01	192536528	SVC CALL OUT NORMAL HOURS/15MINS,	EX0004557
E01	EX00047572	Labour External,	EX0004757
E01	EX00047572	Parts Supplied,RECON ACCUATOR (GENUINE)	EX0004757
E01	EX00047572	Freight	EX0004757
E01	EX00047572	, CAN DO SCAN TOOL-TRUCKS,	EX0004757
E01	EX00047572	,	EX0004757
E01	EX00047572	WORKSHOP CONSUMABLES,	EX0004757

Connect scan tool and found low fuel pressure fault. Complete tests and checks at break down site.
p.
rkshop.
support via phone. Complete intense fuel diagnostics per Cummins request. Found melted suction
s. Liaise with Cummins. Replace suction control valve.
el pump internal failure. Complete further tests per Cummins fuel chart as requested by Cummins.
with Cummins - fault within fuel pump. Retrieve fuel burn data. Send to Cummins. Vehicle under

E01	00014865	Labour External,	EX0004757
E01	00014865	Parts Supplied,RECON ACCUATOR (GENUINE)	EX0004757

r	Invoice	Details	Purchase Order
E01	00014865	Freight	EX0004757
E01	00014865	, CAN DO SCAN TOOL-TRUCKS,	EX0004757
E01	00014865	,	EX0004757
E01	00014865	WORKSHOP CONSUMABLES,	EX0004757
		Labour - Internal	2.00

PECTED FROM CORE TO BE REPLACED
SER

Consumables

Labour

RANTY

R01	EX00046156	FRIDGE DRAWER 30LT 12/24V,	EX0004615
R01	3879458	FRIDGE DRAWER 30LT 12/24V,	EX0004615
		Labour	0.00

:
COLD 'A' SERVICE

	Labour	1.00

TEMPT #1

r	Invoice	Details	Purchase Order
		Labour - Internal	1.00
		Labour	8.00

P AND BOTTOM RADIATOR

BELTS AND AC TENSIONER AS NEEDED REPLACE X 4 RUBBERS ON RAD SUPPORT BAR

	Consumables	8.00
	Labour - Internal	8.00
	Spotter mirror 7" inch	1.00
	RADIATOR CORE KW T908	1.00
	FUEL HOSE - 5MM	3.50
	BUSHING	4.00
	FRIDGE DRAWER 30LT 12/24V	1.00
	HOSE REEL 140 METRES	4.00
	HOSE PUROSIL 2.50" 4 PLY	1.00
	Labour - Internal	
	Consumables	
	Labour - Internal	
	Labour - Internal	
	Labour - Internal	
	Turbo 2000 Air Drier	
	FILTER CABIN K200	
	ES Water Filter	
	Filter Element Gearbox Eaton	
	POWER STEERING FILTER	
	DIFF FILTER HIGH SYNTHETIC	
	DIFF OIL AEM	
	TRANS MAN HVY DUTY 75W90 205L	
EX00047106	TRUCK TYRE - STRIP AND FITTING,	EX0004710

TYRES - FITTED 295/80R22.5 BRIDGESTONE EXODAS STOCK - POS 1 & 2
RE - STRIP AND FITTING, EX0004710

X00046807 PRESSURE CHECK PER TYRE, EX0004680

r	Invoice	Details	Purchase Order

- RN:12.06.26 RSD 038680 PRESSURE CHECKS
E CHECK PER TYRE, EX0004680

Labour - Internal

ables

Labour - Internal

:026

ables

Labour - Internal
FILTER KIT, OIL & FUEL FILTER, (E5)
Element 10 Micron
Ad Blue filter Kenworth
KW 10.5" RIDE HEIGHT AG 400
Labour

Labour

Labour - Internal
Consumables
KOHLER AIR FILTER
HITECH SYNPLUS 10W50
Labour

Consumables
Spotter mirror 7" inch

HUR01	EX00046908	Labour External,	EX0004690
HUR01	EX00046908	ALTERNATOR-L/N 160A PAD MT,	EX0004690
HUR01	EX00046908	FAN BELT,	EX0004690
HUR01	EX00046908	Travel Fee to Breakdowns,	EX0004690
HUR01	EX00046908	MISCELLANEOUS CONSUMABLES,	EX0004690

r	Invoice	Details	Purchase Order
JR01	EX00046908	ENVIRONMENTAL LEVY,	EX0004690

/07/2026

E ROAD EXIT SOUTHBOUND REPORTED ALTERNATOR FAILURE

to vehicle on Bruce Highway southbound just before
o find alternator to be seized. Remove leads from alternator.
ator. Fit leads. Fit new belt. Start engine and check charge. All

JR01	3925382	Labour External,	EX0004690
JR01	3925382	ALTERNATOR-L/N 160A PAD MT,	EX0004690
JR01	3925382	FAN BELT,	EX0004690
JR01	3925382	Travel Fee to Breakdowns,	EX0004690
JR01	3925382	MISCELLANEOUS CONSUMABLES,	EX0004690
JR01	3925382	ENVIRONMENTAL LEVY,	EX0004690

Labour - Internal

ables

		Labour - Internal	
X00047394		PRESSURE CHECK PER TYRE,	EX0004739
E CHECKS			
-104440-202		PRESSURE CHECK PER TYRE,	EX0004739
		Labour - Internal	

ables

		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		Labour	

R FAN

r	Invoice	Details	Purchase Order
		Consumables	
		12" 24V 85W REVERSIBLE FAN - CONDENSOR	
		Labour	
		Consumables	
		HITECH SYNPLUS 10W50	
		Labour - Internal	
		Consumables	
		Labour - Internal	
		Jaw Repair Kit JSK37/42	
X00047890		PRESSURE CHECK PER TYRE,	EX0004789
S			
R01	IN-117307-202	PRESSURE CHECK PER TYRE,	EX0004789
N01	EX00047841	Labour External,	EX0004784
N01	EX00047841	Parts Supplied,AUTO PLY RIB BELT	EX0004784
N01	EX00047841	Parts Supplied,TENSIONER GOLD LABEL H/DUTY	EX0004784
N01	EX00047841	TRAVEL,SERVICE MILEAGE	EX0004784

23663

HWAY - BELT TENSIONER BROKEN TRAVEL TO WORKSHOP TO SOURCE PARTS

FIT NEW BELT

N01	1223663	Labour External,	EX0004784
N01	1223663	Parts Supplied,AUTO PLY RIB BELT	EX0004784
N01	1223663	Parts Supplied,TENSIONER GOLD LABEL H/DUTY	EX0004784
N01	1223663	TRAVEL,SERVICE MILEAGE	EX0004784
		Labour - Internal	

r	Invoice	Details	Purchase

			Order
		Consumables	0.00
		Labour - Internal	2.50
		Consumables	3.00
		Labour - Internal	2.50
		Ad Blue filter Kenworth	1.00
		FILTER KIT, OIL & FUEL FILTER, (E5)	1.00
		OIL 15W-40, CK 4/E9	50.00
		Labour	0.00

ATER TEMP GUAGE KEEPS DTICKING. TAP IT A FEW TIMES, COMES BACK TO NORMAL

		Labour	
		Consumables	
		KOHLER AIR FILTER	
		HITECH SYNPLUS 10W50	
		Labour	

SERVICED SLEEPER

		Consumables	
		Western Star Engine exhaust temp guage	
		KOHLER AIR FILTER	
K00048157		GUAGE-WATER TEMP 40-20C,	EX0004815
82690		GUAGE-WATER TEMP 40-20C,	EX0004815
		Labour	

r	Invoice	Details	Purchase Order
		Consumables	4.00
		Labour - Internal	2.50
		FRIDGE DRAWER 30LT 12/24V	1.00
		Labour - Internal	1.50

N SENSOR AND PLUG CLEAN UP
NS IN PLUG MAY BE W/S)

OK REPLACED HUB SEAL AND ADJUST BOTH FRONT BRAKES

T DOWN)

	Consumables
	Labour - Internal
	Labour - Internal
	CR SEAL - HUB SEAL

Labour

'R01 EX00048972 PRESSURE CHECK PER TYRE, EX0004897
) - YFS:1919 - REGO:XQ09ZR - ODO:997025KM - FN:PM169 - RN:29.09.26 RSD

EX0004897

E CHECK PER TYRE,

Labour - Internal

.ACE)
ables

Labour

99.9

Labour 0.50

.2/10/2026

Consumables 4.00
KOHLER AIR FILTER 1.00
HITECH SYNPLUS 10W50 1.10
Labour - Internal 1.00

Invoice	Details	Purchase Order

ΓHAT THE 12 TO 24 BOOSTER WAS U/S -

Consumables 4.00

Labour - Internal 1.50
1KG FIRE EXTINGUISHER 1.00
2430 BRAKE BOOSTER 1.00

Total for Asset

:r	Invoice	Details	Purchase Order