

XQ 19DS.

29/05/26

History Listing

07:04:07

Page 0001

Customer Name : DTC PTY LTD Serial No: 5KKJBBDRXHPJD9455
WS 17 5864 5864SS

R.O No. : S37926 R.O Date : 30/05/23 Dept : S
RO total Kilometres: 73669 Advisor No. : 002655
Cus total 9,706.66 War total 0.00 Int total

Job number : 1 Operation 16WSZZZZZBRE Desc. Breakdown
Sale type : C Technician No(s). 002334 002347 002264
Complaint : BREAKDOWN

-
Coolant leak

-
M1 Wahroonga

Correction : Travelled to site to inspect concern.

Job number : 2 Operation 07WSZZZZZB Desc. ENGINE COOLING
Sale type : C Technician No(s). 002264 002334
Complaint : Truck leaking coolant, Check and advise
Cause : Suspected radiator leak
Correction : Attended breakdown, Checked for coolant leaks. All hoses
and fittings appear to be ok, Topped up with coolant driver
had. Checked and found coolant spraying everywhere, Appears
to be from the radiator assembly, Unable to rectify on side
of road. Truck towed.

Job number : 3 Operation 07WSZZZZZC Desc. ENGINE COOLING
Sale type : C Technician No(s). 002264 002334
Complaint : Truck towed into site for inspection/repairs
Cause : Radiator leak
Correction : Drained coolant from cooling system, Removed all required
components to hoist radiator from truck, Removed and
replaced as required, Filled with new coolant and pressure
tested system all ok.
NOTE: Replaced a/c condenser due to damage when removing
radiator assembly, Gassed and tested all ok as required.

Comments : 04/07/23: Damaged condensor when replacing radiator - BSS

R.O No. : S31782 R.O Date : 04/04/22 Dept : S
RO total 448.72 Kilometres: 829505 Advisor No. : 002182
Cus total 448.72 War total 0.00 Int total 0.00

Job number : 1 Operation 10WSZZZZZ001 Desc. BODY
Sale type : C Technician No(s). 002347
Complaint : R/H/S air bag blown - left side now down as well
Correction : removed and replaced failed cab air bags. found y-piece had
come out of slip joint. removed old clamp and loosed ubolt
clamp to push exhaust pieces together. replaced clamp with
Sinch step clamp as slip joint had been damaged.

Job number : 2 Operation 10WSZZZZZ003 Desc. BODY
Sale type : C Technician No(s). 002347
Complaint : Rose joint bolts

Cause : bolt fell out of LHS bonnet rose joint

Correction : lifted bonnet up and found HS had dropped down. found bolt missing from rose joint. support bonnet with timer. replaced bolt . checked operation of bonnet tilt - all okay.

R.O No. : B16290	R.O Date : 15/05/19	Dept : S
RO total [REDACTED] Kilometres: 277065	Advisor No. : 001412	
Cus total 0.00 War total [REDACTED]	Int total 0.00	

Job number : 1 Operation 03WSZZZZZC Desc. STEERING

Sale type : W Technician No(s). 4458

Complaint : #19884 POWER STEERING PUMP IS LEAKING

Cause : MATERIAL FATIGUE OF POWER STEERING PUMP END PLATE

Correction : INSPECTED POWER STEERING PUMP, FOUND LEAKING FROM END PLATE. REMOVED AND REPLACED POWER STEERING, GASKET, BLED AND TOPPED UP SYSTEM.

DAM 539-001A06609

FPN 14-19401-011

SRT 539-6010A 0.7 + 539-6016A 0.5

Warranty : Claim no. Operation no. Claim no. Operation no.

B16290-1 03WSZZZZZC

R.O No. : B10930	R.O Date : 29/06/18	Dept : S
RO total [REDACTED] Kilometres: 56841	Advisor No. : 001412	
Cus total 0.00 War total [REDACTED]	Int total 0.00	

Job number : 1 Operation 10WSZZZZZA Desc. BODY

Sale type : W Technician No(s). 999604

Complaint : CARRY OUT RECALL AS PER FL756

Cause : OUTSTANDING

Correction : CARRIED OUT RECALL AS PER FL756

CLAIM 18847

Warranty : Claim no. Operation no. Claim no. Operation no.

B10930-1 10WSZZZZZA

R.O No. : B9195	R.O Date : 26/03/18	Dept : F
RO total [REDACTED] Kilometres: 0	Advisor No. : 876	
Cus total 1,696.48 War total 0.00	Int total [REDACTED]	

Job number : 1 Operation 10WSZZZZZA Desc. BODY

Sale type : C Technician No(s). 001436 3130 001430

Complaint : REPLACE FADES SEAT COVERS - Charge to BTC

Correction : Replace faded seat covers

Job number : 2 Operation 01WSZZZZZ1 Desc. General Service
Sale type : C Technician No(s). 001430 001436 3130
Complaint : REPLACE FADED AIR LINES AND TRAILER LEAD AT REAR OF CAB -
 Charge to BTC
Correction : Replace faded suzzie coils and corroded siezed female air fitting
 on red air line

Job number : 3 Operation 06WSZZZZZC Desc. MANUAL TRANSMISSION
Sale type : C Technician No(s). 001430 3130
Complaint : LUBE CLUTCH BEARING DUE TO SITTING AROUND - Charge to BTC
Correction : Grease throw out bearing

Job number : 4 Operation 10WSZZZZZD Desc. BODY
Sale type : C Technician No(s). 001430
Complaint : RH TOOLBOX PAINT SPLIT AND CORROSION RUNNING ONTO STAINLESS
 SKIRT - Charge to BTC - Sales have issued a Po to PJ'S
 directly - NO Charge required to BTC

Job number : 5 Operation 03WSZZZZZD Desc. WHEELS & TYRES
Sale type : C Technician No(s). 3130
Complaint : REPLACE RUSTY NUT COVERS AS REQUIRED - Charge to BTC
Correction : Replace rusty nut covers.

Job number : 6 Operation 09WSZZZZZA Desc. BODY ELECTRICAL
Sale type : C Technician No(s). 3130 001430
Complaint : RE STICK WIRING TAB ON REAR SLEEPER WALL NEAR AUTO GREASER
 AND ALSO AT L/H LOWER SIDE EXTENDER BRACKET - Charge to BTC
Correction : Restick wiring holding tabs on rear of sleeper wall near auto
 graeser, replace L/H lower side extender bracket.

Job number : 7 Operation 10WSZZZZZG Desc. BODY
Sale type : C Technician No(s). 3130 001430
Complaint : L/H HOOD STAY CABLE IS LOOSE WHEN HOOD OPENED SO ALL FORCE
 IS ONTO R/H CABLE - Charge to BTC
Correction : Check bonnet stays and found ok, Stays are safe most weight is
 taken on the springs

Job number : 8 Operation 09WSZZZZZE Desc. BODY ELECTRICAL
Sale type : I Technician No(s). 001430 3130
Complaint : REPLACE AIR HORN COVERS AS THEY WERE NOT SUPPLIED FROM THE
 FACTORY WITH THE WESTERN STAR LOGO ON THEM
Correction : Vehicle left without photos taken and unable to claim WTY - As
 good will this job will be absorbed by PPS and authorised by Kube
 Kunny

Job number : 9 Operation 10WSZZZZZF Desc. INTERIOR TRIM

Sale type : C Technician No(s). 001430 3130
Complaint : RESEAL ROOF LIGHTS - Charge to BTC
Correction : Inspected and removed all roof lights, resealed and refitted,
tested and found ok.

R.O No. : B9056 R.O Date : 16/03/18 Dept : S
RO total [REDACTED] Kilometres: 612 Advisor No. : 001377
Cus total 0.00 War total 0.00 Int total [REDACTED]

Job number : 1 Operation 10WSZZZZZZA Desc. BODY
Sale type : I Technician No(s). 3130
Complaint : bonet blocks missing - inspect
Correction : REPLACED BLOCKS WITH WORKSHOP SUPPLIED (TEFLON BLOCK)
REFER ADRIAN LEGGE

R.O No. : B8896 R.O Date : 08/03/18 Dept : S
RO total 1,000.12 Kilometres: 611 Advisor No. : 001411
Cus total 1,000.12 War total 0.00 Int total 0.00

Job number : 1 Operation 77WSWSDA01 Desc. MISC UPFIT 1
Sale type : C Technician No(s). 001440
Complaint : CARRY OUT 12 MONTH IVM

R.O No. : B6678 R.O Date : 01/11/17 Dept : S
RO total 252.95 Kilometres: 525 Advisor No. : 001411
Cus total 252.95 War total 0.00 Int total 0.00

Job number : 1 Operation 77WSWSDA01 Desc. MISC UPFIT 1
Sale type : C Technician No(s). 001434
Complaint : 9 MONTH IVM

R.O No. : B5272 R.O Date : 17/08/17 Dept : S
RO total 780.18 Kilometres: 525 Advisor No. : 001411
Cus total 780.18 War total 0.00 Int total 0.00

Job number : 1 Operation 78WSZZZZZZ500 Desc. PDI & AFTERMARKET
Sale type : C Technician No(s). 001438
Complaint : CARRY OUT FINAL PD INSPECTIONS

Job number : 2 Operation 77WSWSDA06 Desc. MISC UPFIT 6
Sale type : C Technician No(s). 001438
Complaint : REAR RHS MUDFLAPS - CHEVRON

Job number : 3 Operation 77WSWSDA07 Desc. MISC UPFIT 7
Sale type : C Technician No(s). 001438
Complaint : 30 WHEEL NUT COVERS

Job number : 4 Operation 77WSWSDA08 Desc. MISC UPFIT 8
Sale type : C Technician No(s). 001438
Complaint : REAR RHS UPPER FUEL TANK STEP - SCRATCHED

R.O No. : B5219 R.O Date : 15/08/17 Dept : S
RO total [REDACTED] Kilometres: 525 Advisor No. : 001412
Cus total 0.00 War total [REDACTED] Int total 0.00

Job number : 1 Operation 10WSZZZZZZA Desc. BODY
Sale type : W Technician No(s). 001430
Complaint : EXHAUST UBOLTS ARE CORRODED
Cause : POOR CORROSION PROTECTION FROM SUPPLIER
Correction : REMOVED OUTER EXHAUST GUARDS, REMOVED EXHAUST 6 X UBOLTS, INSTALL
NEW
UBOLTS AND REINSTALL OUTER GUARDS.

DAM 234-100929690
FPN 23-11429-005
SRT 235-6010A 0.3 + 235-6010B 0.3
CLAIM 1740

Warranty : Claim no. Operation no. Claim no. Operation no.
W0342128 10WSZZZZZZA

Comments : 28/8 JW - ADRIAN LEGGE - NEED TO BOOK OUT 4 X CLAMPS TO JOB.
25/8 JW - ADRIAN LEGGE - NEED PHOTOS OF CLAMPS AND CAUSE WRITTEN
ON REPORT

R.O No. : B5203 R.O Date : 14/08/17 Dept : S
RO total 2,106.38 Kilometres: 525 Advisor No. : 001411
Cus total 2,106.38 War total 0.00 Int total 0.00

Job number : 1 Operation 08WSZZZZZZA Desc. FUEL SYSTEM
Sale type : C Technician No(s). 001440
Complaint : 2 X REAR FUEL TANK STRAP SCRATCHED
Correction : FIT NEW FUEL TANK STRAPS

Job number : 2 Operation 05WSZZZZZZB Desc. EXHAUST SYSTEM
Sale type : C Technician No(s). 001430
Complaint : RH EXHAUST SHROUD SCRATCHED
Correction : FIT NEW EXHAUST SHROUD

R.O No. : PCV148306 R.O Date : 07/08/17 Dept : S
RO total [REDACTED] Kilometres: 504 Advisor No. : JENNYW
Cus total War total [REDACTED] Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL01 Desc.
Sale type : W Technician No(s).
Correction : REVERSE BUZZER OR LIGHTS NOT WORKING *** INTERNAL
ELECTRICAL FAILURE IN REVERSE SWITCH ** REMOVED AND
REPLACED REVERSE SWITCH ** DAM 318-000549590 FPN 21465
SRT 318-6040A 0.3 CLAIM 171465

Job number : 2 Operation 88ZZINACTIVE6M SALES Desc.
Sale type : I Technician No(s).
Correction : CARRIED OUT 6 MONTH INACTIVE VEHICLE MAINTENANCE SERVICE AS
PER SALES BULLETIN SV-15-141. ***** COMPLETED FORM:
INACTIVE VEHICLE - MAINTENANCE SCHEDULE AND CONVENTIONAL
COOLANT TEST RECORD *****

Job number : 3 Operation 88ZZ50WS FINAL/INSP Desc.
Sale type : I Technician No(s).
Correction : CHECK OVER VEHICLE AS PER INSPECTION LIST BEFORE DELIVERY
TO SALES
DEPARTMENT

R.O No. : PCV148306 R.O Date : 07/08/17 Dept : S
RO total [REDACTED] Kilometres: 504 Advisor No. : JENNYW
Cus total War total [REDACTED] Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL01 Desc.
Sale type : W Technician No(s).
Correction : REVERSE BUZZER OR LIGHTS NOT WORKING *** INTERNAL
ELECTRICAL FAILURE IN REVERSE SWITCH ** REMOVED AND
REPLACED REVERSE SWITCH ** DAM 318-000549590 FPN 21465
SRT 318-6040A 0.3 CLAIM 171465

Job number : 2 Operation 88ZZINACTIVE6M SALES Desc.
Sale type : I Technician No(s).
Correction : CARRIED OUT 6 MONTH INACTIVE VEHICLE MAINTENANCE SERVICE AS
PER SALES BULLETIN SV-15-141. ***** COMPLETED FORM:
INACTIVE VEHICLE - MAINTENANCE SCHEDULE AND CONVENTIONAL
COOLANT TEST RECORD *****

Job number : 3 Operation 88ZZ50WS FINAL/INSP Desc.
Sale type : I Technician No(s).
Correction : CHECK OVER VEHICLE AS PER INSPECTION LIST BEFORE DELIVERY
TO SALES
DEPARTMENT

29/05/26

History Listing

07:04:07

Page 0007

R.O No. : PCV147715 R.O Date : 21/07/17 Dept : S
RO total [REDACTED] Kilometres: Advisor No. : JENNYW
Cus total War total Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL/AUD Desc.
Sale type : I Technician No(s).
Correction : REPLACE STARTER MOTOR ** SALES REQUEST REMOVED DELCO
STARTER MOTOR AND INSTALLED MITSUBISHI STARTER MOTOR.
PLACED DELCO STATER IN DEREK'S
OFFICE

Job number : 2 Operation 88ZZLIGHTS01 Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED AND FIT 2 X LED LIGHTS AND CARRIED OUT A REGEN

R.O No. : PCV147715 R.O Date : 21/07/17 Dept : S
RO total [REDACTED] Kilometres: Advisor No. : JENNYW
Cus total War total Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL/AUD Desc.
Sale type : I Technician No(s).
Correction : REPLACE STARTER MOTOR ** SALES REQUEST REMOVED DELCO
STARTER MOTOR AND INSTALLED MITSUBISHI STARTER MOTOR.
PLACED DELCO STATER IN DEREK'S
OFFICE

Job number : 2 Operation 88ZZLIGHTS01 Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED AND FIT 2 X LED LIGHTS AND CARRIED OUT A REGEN

R.O No. : PCV147448 R.O Date : 24/05/17 Dept : S
RO total [REDACTED] Kilometres: 485 Advisor No. : JENNYW
Cus total 144.78 War total Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL/AUD Desc.
Sale type : C Technician No(s).
Correction : RHR INDICATOR NOT WORKING ** FOUND LOOSE CONNECTOIN
SOLDERED AND
REPAIRED.

Job number : 2 Operation 88ZZLIGHTS02 Desc.
Sale type : C Technician No(s).
Correction : LHS TAIL LIGHT NOT WORKING ** FOUND LOOSE CONNECTION
SOLDERED AND
REPAIRED

Job number : 3 Operation 88ZZINACTIVE3M SALES Desc.

Sale type : I Technician No(s).

Correction : CARRIED OUT 3 MONTH INACTIVE VEHICLE MAINTENANCE SERVICE AS
PER SALES BULLETIN SV-15-141. ***** COMPLETED FORMS:
INACTIVE VEHICLE - MAINTENANCE SCHEDULE AND CONVENTIONAL
COOLANT TEST RECORD

Job number : 4 Operation 88ZZLIGHTS01 Desc.

Sale type : I Technician No(s).

Correction : INDICATORS FLASHING TOO FAST *** NO RESISTORS AND RELAYS
INSTALLED FIT RESISTOR TO FRONT AND RELAY TESTED
OPERATION ALL
OK

R.O No. : PCV147448 R.O Date : 24/05/17 Dept : S
RO total [REDACTED] Kilometres: 485 Advisor No. : JENNYW
Cus total 144.78 War total Int total [REDACTED]

Job number : 1 Operation 88ZZ15ELECTRICAL/AUD Desc.

Sale type : C Technician No(s).

Correction : RHR INDICATOR NOT WORKING ** FOUND LOOSE CONNECTOIN
SOLDERED AND
REPAIRED.

Job number : 2 Operation 88ZZLIGHTS02 Desc.

Sale type : C Technician No(s).

Correction : LHS TAIL LIGHT NOT WORKING ** FOUND LOOSE CONNECTION
SOLDERED AND
REPAIRED

Job number : 3 Operation 88ZZINACTIVE3M SALES Desc.

Sale type : I Technician No(s).

Correction : CARRIED OUT 3 MONTH INACTIVE VEHICLE MAINTENANCE SERVICE AS
PER SALES BULLETIN SV-15-141. ***** COMPLETED FORMS:
INACTIVE VEHICLE - MAINTENANCE SCHEDULE AND CONVENTIONAL
COOLANT TEST RECORD

Job number : 4 Operation 88ZZLIGHTS01 Desc.

Sale type : I Technician No(s).

Correction : INDICATORS FLASHING TOO FAST *** NO RESISTORS AND RELAYS
INSTALLED FIT RESISTOR TO FRONT AND RELAY TESTED
OPERATION ALL
OK

R.O No. : PCV146260 R.O Date : 10/03/17 Dept : S
RO total [REDACTED] Kilometres: 222 Advisor No. : JENNYW
Cus total War total [REDACTED] Int total [REDACTED]

Job number : 1 Operation 88ZZ01ENGINE01 Desc.

Sale type : W Technician No(s).

Correction : TRUCK WON'T START AFTER SITTING FOR A WHILE *** INTERNAL
FAULT IN FUEL PRO CHECK VALVE *** REMOVED AND INSTALLED
NEW CHECK VALVE TESTED ALL OK **** DAM FPN DVC 482011
SRT 216-6065A 0.3 CLAIM

Job number : 2 Operation 88ZZ14WSW/ALIGN Desc.

Sale type : W Technician No(s).

Correction : P: CHECK IF WHEEL ALIGNMENT SUITS AUSTRALIAN CONDITIONS C:
INCORRECT FACTORY SETTINGS FOR AUSTRALIAN CONDITIONS R:
TOTAL POWER STEERING & ALIGNMENT O/NO: INV NO: 105 TO
CHECK & CARRIED OUT LASER WHEEL ALIGNMENT AS REQD ****
CLAIM NO:

Job number : 3 Operation 88ZZ50WS S&F B/D/F T Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED B/DOUBLE MUDFLAPS TO REAR OF BONNET

Job number : 4 Operation 88ZZ50WS S&F AIR/EL/ Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED AIR & ELECTRICS TO UNDER BUNK - REMOVED
 & REFITTED TP3 VALVE TO BTC PLATE FITTED NEW AIR FITINGS
 AND TAPS. FITTED BTC PLATE TO UNDER BUNK CONNECTED TP3
 VALVE FITTED AND WIRED UP TRAILER PLUG AS
 REQUIRED.

Job number : 5 Operation 88ZZ50WS S&F S/COILS Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED SUZI COILS TO SLIDE BAR

Job number : 6 Operation 88ZZ50WS S&F H/N COV Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT HUB CAPS AND NUT COVERS - BUCKETS ON DRIVE

Job number : 7 Operation 88ZZ50WS S&F ST/GUAR Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT STONE GUARD

Job number : 8 Operation 88ZZ50WS S&F CH/PLAT Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT CHASSIS FRONT WALK PLATE

Job number : 9 Operation 88ZZ50WS ACC (1) Desc.
Sale type : I Technician No(s).
Correction : ABS LEAD IN SLEEPER

Job number : 10 Operation 88ZZ50WS ACC (2) Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT TRIM SLEEPER FAIRINGS

Job number : 11 Operation 88ZZ49EXHAUST01 Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT 6" MITRE CUT EXHAUSTS 60" LONG

29/05/26

History Listing

07:04:07

Page 0010

Job number : 12 Operation 88ZZ50WS S&F C/AIRBL Desc.

Sale type : I Technician No(s).

Correction : SUPPLIED & FITTED IN CAB AIR BLOWER

Job number : 13 Operation 88ZZ15ELECTRICAL Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT TRUCK LITE LED ON REAR SLEEPER WALL

Job number : 14 Operation 88ZZSEAT Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT BURGUNDY SEAT COVERS

Job number : 15 Operation 88ZZ50WS S&F TURNTAB Desc.

Sale type : I Technician No(s).

Correction : FIT JOST JSK GREASLESS TURNTABLE (EASTERS SPEC)

Shop Supplies

Job number : 16 Operation 88ZZ60WS PD/VEH Desc.

Sale type : I Technician No(s).

Correction : CARRIED OUT WSTA PRE DELIVERY AS PER INSPECTION FORM
FITTING ENGINE OVERRIDE SWITCH FITTING LICENSE &
COMPLIANCE PLATES (FITTING MUDDLAPS TO BUMPER/FUPS BAR IF
REQUESTED BY SALES) 2 HOURS TO BE INVOICED OUT AT FINAL
INSPECTION.
FUEL

Job number : 17 Operation 88ZZ50WS M/FLAPS ON Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT FUPS BUMPER MUDDLAPS - FIT BY AJS

Job number : 18 Operation 88ZZ50WS S/S BUG/DEF Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT S/S BUG DEFLECTOR - TOP ONLY

Job number : 19 Operation 88ZZ50WS S&F W/SHIEL Desc.

Sale type : I Technician No(s).

Correction : SUPPLIED AND FITTED WEATHER SHIELDS TO L/H & R/H SIDES OF
VEHICLE

Job number : 20 Operation 88ZZ47FUEL01 Desc.

Sale type : I Technician No(s).

Correction : PLUMB UP FUEL TANKS CROSS OVERS ** FUEL CROSSOVER LINE IS
FIT FROM RH SIDE TANK TO LH SIDE
TANK

R.O No. : PCV146260 R.O Date : 10/03/17 Dept : S
RO total [REDACTED] Kilometres: 222 Advisor No. : JENNYW
Cus total War total [REDACTED] Int total [REDACTED]

Job number : 1 Operation 88ZZ01ENGINE01 Desc.
Sale type : W Technician No(s).
Correction : TRUCK WON'T START AFTER SITTING FOR A WHILE *** INTERNAL
FAULT IN FUEL PRO CHECK VALVE *** REMOVED AND INSTALLED
NEW CHECK VALVE TESTED ALL OK **** DAM FPN DVC 482011
SRT 216-6065A 0.3 CLAIM

Job number : 2 Operation 88ZZ14WSW/ALIGN Desc.
Sale type : W Technician No(s).
Correction : P: CHECK IF WHEEL ALIGNMENT SUITS AUSTRALIAN CONDITIONS C:
INCORRECT FACTORY SETTINGS FOR AUSTRALIAN CONDITIONS R:
TOTAL POWER STEERING & ALIGNMENT O/NO: INV NO: 105 TO
CHECK & CARRIED OUT LASER WHEEL ALIGNMENT AS REQD ****
CLAIM NO:

Job number : 3 Operation 88ZZ50WS S&F B/D/F T Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED B/DOUBLE MUDFLAPS TO REAR OF BONNET

Job number : 4 Operation 88ZZ50WS S&F AIR/EL/ Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED AIR & ELECTRICS TO UNDER BUNK - REMOVED
& REFITTED TP3 VALVE TO BTC PLATE FITTED NEW AIR FITINGS
AND TAPS. FITTED BTC PLATE TO UNDER BUNK CONNECTED TP3
VALVE FITTED AND WIRED UP TRAILER PLUG AS
REQUIRED.

Job number : 5 Operation 88ZZ50WS S&F S/COILS Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED & FITTED SUZI COILS TO SLIDE BAR

Job number : 6 Operation 88ZZ50WS S&F H/N COV Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT HUB CAPS AND NUT COVERS - BUCKETS ON DRIVE

Job number : 7 Operation 88ZZ50WS S&F ST/GUAR Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT STONE GUARD

Job number : 8 Operation 88ZZ50WS S&F CH/PLAT Desc.
Sale type : I Technician No(s).
Correction : SUPPLY & FIT CHASSIS FRONT WALK PLATE

Job number : 9 Operation 88ZZ50WS ACC (1) Desc.
Sale type : I Technician No(s).
Correction : ABS LEAD IN SLEEPER

Job number : 10 Operation 88ZZ50WS ACC (2) Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT TRIM SLEEPER FAIRINGS

Job number : 11 Operation 88ZZ49EXHAUST01 Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT 6" MITRE CUT EXHAUSTS 60" LONG

Job number : 12 Operation 88ZZ50WS S&F C/AIRBL Desc.

Sale type : I Technician No(s).

Correction : SUPPLIED & FITTED IN CAB AIR BLOWER

Job number : 13 Operation 88ZZ15ELECTRICAL Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT TRUCK LITE LED ON REAR SLEEPER WALL

Job number : 14 Operation 88ZZSEAT Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT BURGUNDY SEAT COVERS

Job number : 15 Operation 88ZZ50WS S&F TURNTAB Desc.

Sale type : I Technician No(s).

Correction : FIT JOST JSK GREASLESS TURNTABLE (EASTERS SPEC)
Shop Supplies

Job number : 16 Operation 88ZZ60WS PD/VEH Desc.

Sale type : I Technician No(s).

Correction : CARRIED OUT WSTA PRE DELIVERY AS PER INSPECTION FORM
FITTING ENGINE OVERRIDE SWITCH FITTING LICENSE &
COMPLIANCE PLATES (FITTING MUDEFLAPS TO BUMPER/FUPS BAR IF
REQUESTED BY SALES) 2 HOURS TO BE INVOICED OUT AT FINAL
INSPECTION.
FUEL

Job number : 17 Operation 88ZZ50WS M/FLAPS ON Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT FUPS BUMPER MUDEFLAPS - FIT BY AJS

Job number : 18 Operation 88ZZ50WS S/S BUG/DEF Desc.

Sale type : I Technician No(s).

Correction : SUPPLY & FIT S/S BUG DEFLECTOR - TOP ONLY

29/05/26

History Listing

07:04:07

Page 0013

Job number : 19 Operation 88ZZ50WS S&F W/SHIEL Desc.
Sale type : I Technician No(s).
Correction : SUPPLIED AND FITTED WEATHER SHIELDS TO L/H & R/H SIDES OF
VEHICLE

Job number : 20 Operation 88ZZ47FUEL01 Desc.
Sale type : I Technician No(s).
Correction : PLUMB UP FUEL TANKS CROSS OVERS ** FUEL CROSSOVER LINE IS
FIT FROM RH SIDE TANK TO LH SIDE
TANK

Customer RO history total 16,281.05
Warranty RO history total [REDACTED]
Internal RO history total [REDACTED]

Complete RO history total [REDACTED]
