

**Teds Automotive**  
 BOX 514, 45 NIPEWON ROAD  
 LAC LA BICHE, AB. T0A2C0  
 Phone - 780-623-2202 Fax - - -

X21-1  
 NOV

**Customer and Vehicle Report**  
**PORTAGE VENTURES**

Print Date: 10/13/2026

**Vehicle: 2007 Chevrolet - Silverado Classic 3500, 6.6L,V8 (403CI) VIN(D), CSZ1125**

Invoice: 067772, Posted On: 01/23/2026

Odometer in: 263,764 Odometer Out: 0

| Time                       | Description                                                                                      | Part No.     | Category     | Technician      | Qty             | Sale           | Extd            | Price      | Rate         |
|----------------------------|--------------------------------------------------------------------------------------------------|--------------|--------------|-----------------|-----------------|----------------|-----------------|------------|--------------|
|                            | - ****CHECK BATTERY(NOT CHARGING)**** **CHECK BELTS**** **FUEL FILTER HOUSING**                  |              |              |                 |                 | 0.00           | 0.00            |            | 145.00       |
|                            | - TENSIONER PULLEY FAILED AND BROKE THE TENSIONER ASSEMBLY, WILL REPLACE BELT                    |              |              |                 |                 |                |                 |            |              |
|                            | - REPLACED FUEL FILTER HOUSING, WAS LOSING ENGINE PRIME                                          |              |              |                 |                 |                |                 |            |              |
|                            | - FUEL FILTER HOUSING/Fuel Filter Housing                                                        | 904-517      |              |                 | 1.00            | 305.79         | 305.79          | 305.79     |              |
| 0.67                       | FUEL FILTER HOUSING - Remove & Replace - Diesel Assembly (Complete) - [Includes: Bleed System.]  |              |              |                 | 0.67            | 97.15          | 97.15           |            | 145.00       |
|                            | - TENSIONER/Accessory Drive Belt Tensioner Assembly                                              | 49278        |              |                 | 1.00            | 137.21         | 137.21          | 148.19     |              |
|                            | - POLY-V BELT ELITE/Serpentine Belt                                                              | 4061195      |              |                 | 1.00            | 62.01          | 62.01           | 77.86      |              |
| 1.20                       | SERPENTINE BELT TENSIONER - Remove & Replace - Diesel - [Includes: Replace Belt (if necessary).] |              |              |                 | 1.20            | 174.00         | 174.00          |            | 145.00       |
|                            | <b>Notes</b> - ACTUAL ODOMETER READING IS 155319 MILE                                            |              |              |                 |                 |                |                 |            |              |
| 0.50                       | ****CV AXLE**** **OIL CHANGE**                                                                   |              |              |                 | 0.50            | 72.50          | 72.50           |            | 145.00       |
|                            | REPLACED PASSENGER SIDE CV AXLE AND PREFORMED OIL CHANGE WITH OIL AND FILTER SUPPLIED BY CLIENT  |              |              |                 |                 |                |                 |            |              |
|                            | - HD CV AXLE/CV Axle Shaft                                                                       | GM-8026HDX   |              |                 | 1.00            | 234.81         | 234.81          | 234.81     |              |
| <b>Totals for Invoice:</b> |                                                                                                  | <b>Parts</b> | <b>Labor</b> | <b>Discount</b> | <b>Subtotal</b> | <b>Haz Mat</b> | <b>Supplies</b> | <b>Tax</b> | <b>Total</b> |
|                            |                                                                                                  | 739.82       | 343.65       | 0.00            | 1,083.47        | 0.00           | 0.00            | 54.17      | 1,137.64     |

Invoice: 067628, Posted On: 12/31/2025

Odometer in: 263,763 Odometer Out: 0

| Time | Description | Part No. | Category | Technician | Qty | Sale | Extd | Price | Rate |
|------|-------------|----------|----------|------------|-----|------|------|-------|------|
|------|-------------|----------|----------|------------|-----|------|------|-------|------|

**HIGH CALIBER AUTOMOTIVE & DIESEL REPAIR**  
9002-105TH AVE BOX 2458  
LAC LA BICHE, AB. T0A2C0  
Phone: 780-623-1109

**INVOICE**

**19323**

714748316RT0001

**INVOICE**

Printed Date: 09/25/2026 Work Completed: 09/25/2026

**PORTAGE VENTURES**

2007 Chevrolet - Silverado Classic 3500 - 6.6L, V8 (403CI) VIN:

Lic # :

Odometer In : 254432

VIN # : 1GCJK33D8 7F181399

Office

| Part Description / Number                 | Qty  | Sale   | Ext    | Labor Description                                                                                                                                      | Ex      |
|-------------------------------------------|------|--------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| MASS AIRFLOW SENSOR<br>MAS0280            | 1.00 | 227.03 | 227.03 | SHOP SUPPLIES                                                                                                                                          | 49.9:   |
| AIR FILTER<br>CA5352                      | 1.00 | 114.19 | 114.19 | SHOP SUPPLIES                                                                                                                                          |         |
| FUEL FILTER DURAMAX<br>BAL BF46062(23960) | 1.00 | 107.77 | 107.77 | CHECK ISSUES AS PER CUSTOMER , CHECK NO<br>POWER AND EBRKE DOES NOT WORK                                                                               | 1,472.5 |
| E BRAKE SHOE KIT<br>12-771                | 1.00 | 43.41  | 43.41  | REMOVE AND REPLACE STUCK OPEN EGR VALVE ASSY , NO<br>MORE CODES                                                                                        |         |
| REAR WHEEL SEALS<br>28635                 | 2.00 | 40.34  | 80.68  | REMOVE AND REPLACE FUEL FILTER AND AIR FILTER ASSY<br>4.5HR                                                                                            |         |
| EGR VALVE ASSY<br>2EGR0081                | 1.00 | 737.81 | 737.81 | REMOVE REAR WHEELS, REMOVE REAR AXLES , REMOVE<br>REAR CALIPERS, REMOVE AXLE SHAFTS, REMOVE REAR<br>HUBS , REMOVE REAR ROTORS, REMOVE AND REPLACE PARI |         |
| REAR EMERG CABLE LH<br>C661214            | 1.00 | 104.77 | 104.77 | BRKE SHOES, REPLACE WHEEL SEALS AND ASSEMBLE,<br>REPLACE REAR LH AND RH PARK BRAKE CABLES , PARK<br>BRAKE WORKS TO SPEC 5HR                            |         |
| REAR EMERG CABLE RH<br>C660016            | 1.00 | 93.32  | 93.32  |                                                                                                                                                        |         |

Org. Estimate 3,183.00 Revisions 0.00 Current Estimate 3,183.00

Labor: 1,472.5  
Parts: 1,508.5  
Sublet: 49.9

SubTotal: 3,031.  
Tax: 151.  
Total: 3,183.  
Bal Due: \$3,183.

[ Payments - ]

Vehicle Received: 2026-09-25


Customer Number : 11

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature

Date

Email Address: SHAWN@HIGHCALIBERAUTOMOTIVE.COM



**Teds Automotive**  
BOX 514, 45 NIPEWON ROAD  
LAC LA BICHE, AB. T0A2C0  
Phone: (780)-623-2202

Invoice # **065240**  
Original Est # 20046  
136922390 RT0001

## Invoice

**Balance Due: \$22,531.15**

**PORTAGE VENTURES**

**2007 Chevrolet - Silverado Classic - 3500**

6.6L, V8 (403CI) VIN(D)

VIN: 1GCJK33D8 7F181399

Odometer: In 241,590

License Plate: CSZ1125 AB

Work Complete: 12/20/2024

Service Advisor:

Customer ID: 614

Printed Date: 10/13/2026

| Type             | Description                                                                                                                                                                                  | Part #    | Qty   | Sale       | Total              |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------|------------|--------------------|
| <b>Job Title</b> |                                                                                                                                                                                              |           |       |            | <b>\$22,531.15</b> |
| Labor            | ***** WIRED THE REAR DECK, INSTALLED A CONVERTER SO WE CAN HAVE ONE SET OF LIGHTS DO BOTH JOBS, USED HIGH COUNT LEDS AND DRILLED NEW HOLES TO COMMON LIGHT THAT CAN BE BOUGHT ANYWHERE ***** |           |       |            | \$405.00           |
| Part             | FUEL/WATER SEPARATOR SPIN-/Fuel Filter                                                                                                                                                       | BF46062   | 1.00  | \$109.68   | \$109.68           |
| Part             | TRANSMISSION FI/Transmission Oil Filter                                                                                                                                                      | 20004     | 1.00  | \$58.51    | \$58.51            |
| Part             | TRANSMISSION SP/Transmission Oil Filter                                                                                                                                                      | BT8460    | 1.00  | \$45.31    | \$45.31            |
| Part             | SEAL/Wheel Seal                                                                                                                                                                              | SL260002  | 2.00  | \$52.76    | \$105.52           |
| Part             | CERAMIC PADS W//Disc Brake Pad Set                                                                                                                                                           | 21-909    | 1.00  | \$103.82   | \$103.82           |
| Part             | BRAKE ROTOR/Disc Brake Rotor                                                                                                                                                                 | 662895    | 2.00  | \$127.56   | \$255.12           |
| Labor            | WHEEL SEAL - Remove & Replace - 3500 Both - [Includes: Repack and adjust Bearings (where applicable).]                                                                                       |           |       |            | \$472.50           |
| Labor            | FUEL FILTER - Remove & Replace - 3500,Diesel Element                                                                                                                                         |           |       |            | \$108.00           |
| Part             | DIESEL FUEL CONDITION                                                                                                                                                                        | 992       | 1.00  | \$9.23     | \$9.23             |
| Part             | REMAN STARTER                                                                                                                                                                                | 244-6828  | 1.00  | \$203.54   | \$203.54           |
| Part             | REMAN PUMP                                                                                                                                                                                   | ZZA 35527 | 1.00  | \$1,443.60 | \$1,443.60         |
| Sublet           | FRIEGHT                                                                                                                                                                                      |           |       | \$17.25    | \$17.25            |
| Part             | FUEL                                                                                                                                                                                         | DIESEL    | 60.00 | \$1.51     | \$90.60            |
| Part             | 7 POLE TRAILER SOCKET                                                                                                                                                                        | 82-1058B  | 1.00  | \$14.48    | \$14.48            |
| Note             | PAID \$5000.00 SEPT 5/24                                                                                                                                                                     |           |       |            |                    |
| Part             | BELT IDLER PULLEY                                                                                                                                                                            | 36310     | 1.00  | \$58.88    | \$58.88            |
| Part             | FUEL INJECTOR -/Fuel Injector<br>WO# 871636                                                                                                                                                  | FJ962     | 8.00  | \$845.39   | \$6,763.12         |
| Part             | BELT-SERPENTINE                                                                                                                                                                              | 25-061195 | 1.00  | \$106.59   | \$106.59           |
| Part             | BOLT                                                                                                                                                                                         | 11589040  | 6.00  | \$16.57    | \$99.42            |
| Sublet           | TRANSMISSION FREIGHT                                                                                                                                                                         |           |       | \$198.35   | \$198.35           |
| Part             | BACK UP ALARM                                                                                                                                                                                | 73040     | 1.00  | \$49.12    | \$49.12            |
| Part             | Taillight Converter - Utility Trailer                                                                                                                                                        | 7551086   | 1.00  | \$35.60    | \$35.60            |
| Part             | HUB BEARING ASSEMBLY                                                                                                                                                                         | PBR931000 | 2.00  | \$130.79   | \$261.58           |
| Part             | Trailer Wiring Harness - H/D Truck                                                                                                                                                           | 67090     | 2.00  | \$3.94     | \$7.88             |
| Part             | Lamp / Stop, Turn & Tail 4 in. Round Hi Count, LED Stop, Tail, Turn<br>Lamp, Female Pin Red                                                                                                  | G4002     | 2.00  | \$42.44    | \$84.88            |
| Part             | Lamp Grommet Stop/Turn/Tail Round                                                                                                                                                            | 91740     | 2.00  | \$3.87     | \$7.74             |
| Labor            | TRANSMISSION ASSEMBLY - Remove & Replace - Diesel,4WD -<br>[Includes: Perform Tech2 "FastLearn" procedure.<br>Includes: Confirm Fluid temperature for level check.]                          |           |       |            | \$1,417.50         |
| Labor            | FUEL INJECTION PUMP - Remove & Replace - Diesel                                                                                                                                              |           |       |            | \$1,647.00         |
| Part             | ALLISON HD TRANSMISSION<br>2001-05 TRANSMISSION                                                                                                                                              | 142611    | 1.00  | \$5,076.47 | \$5,076.47         |
| Labor            | FUEL INJECTOR - Remove & Replace - Diesel Both Sides,All Eight<br>FLUSHED ALL FUEL SYSTEM AND DRAINED FUEL TANK AND                                                                          |           |       |            | \$945.00           |

| Type        | Description                                                                                                                              | Part #    | Qty        | Sale    | Total       |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------|---------|-------------|
| [Continued] |                                                                                                                                          |           |            |         | \$22,531.15 |
|             | CLEANED DUE TO POSSIBLE CONTAMINATION                                                                                                    |           |            |         |             |
| Part        | 75W90 SYN GEAR OIL                                                                                                                       | TRE759P20 | 8.00       | \$15.60 | \$124.80    |
| Part        | TOTAL LV MV Size: 1L                                                                                                                     | 219125    | 40.00      | \$15.54 | \$621.60    |
| Part        | BRAKE & PART CLEANER                                                                                                                     | KLE313    | 10.00      | \$8.14  | \$81.40     |
| Part        | 15W 40 DURON HP                                                                                                                          | DHP15DRM  | 10.00      | \$6.84  | \$68.40     |
| Part        | BALDWIN OIL FILTER                                                                                                                       | B1441     | 1.00       | \$22.75 | \$22.75     |
| Part        | EFC FEE                                                                                                                                  | B1441     | 1.00       | \$0.50  | \$0.50      |
| Labor       | ***** INSTALLED SLIP TANK FUEL PUMP AND BUGGY WHIP<br>BACKUP ALARM NEW BATTERY CONNECTIONS TWO WAY RADIO<br>AND HOOKED UP LIGHT BAR***** |           |            |         | \$337.50    |
|             |                                                                                                                                          |           |            |         |             |
| Parts:      | \$15,910.14                                                                                                                              | Labor:    | \$5,548.10 | Tax:    | \$1,072.91  |
|             |                                                                                                                                          |           |            | Total:  | \$22,531.15 |

|                                  |                                                                                                                                                                                                                                                                            |                            |                                   |
|----------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-----------------------------------|
| <b>Original Estimate:</b> \$0.00 |                                                                                                                                                                                                                                                                            | <b>Revisions:</b> \$334.97 | <b>Revised Estimate:</b> \$334.97 |
| <b>Revision # 1</b>              | Previous Estimate Amount: \$0.00   Additional Cost: \$334.97   Revised Estimate: \$334.97  <br>Parts: \$319.02 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$15.95<br>Authorized by: HALITSKY, DAVE on: 6/11/2024 3:52:26 PM, Initiated By - Shop, Written By: ,<br>Reason: |                            |                                   |

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Wheel nuts should be retorqued after 100 km's

|                     |                    |
|---------------------|--------------------|
| Labor               | \$5,332.50         |
| Parts               | \$15,910.14        |
| Sublet              | \$215.60           |
| <b>Subtotal</b>     | <b>\$21,458.24</b> |
| Taxes               | \$1,072.91         |
| <b>Order Total:</b> | <b>\$22,531.15</b> |