	QTY.	PART NO. AND DESCRIPTION	PRICE
	1	SP-3339D VALVE	312.85
	2	¼×2½" bolts, nut, lock+flat washers	1.78
	2	sets brake shoes	112.50
	2	SSKIT12HD	26.70
	2	85064 shocks	170.00
	2	¾×3¼" bolts, stover nuts	9.80

M.K.S. Trailer & Equipment Repairs Ltd.
716 Carter Crest Way
Edmonton, Alberta T6R 2N3
Shop: 780-451-3861
Cell: 780-966-2963

D16-40
MAY

INVOICE 79134

DATE: OCT 23 2025

NAME: BOYD VENTURES

ADDRESS: RR.3, Site 302, Comp 88 CITY: ONOWAY

PROVINCE: AB POSTAL CODE: T0E 1V0

PURCHASE ORDER:

LICENSE NO.	YEAR	MAKE/MODEL
6PX418	2024	Load King

SERIAL NO.: 5OR1034181 UNIT NO.: 051

SERVICE

Checked air & lights

Replaced regulator valve for airbag override

Removed / Replaced LC & RC brake shoes

Removed / Replaced centre axle shocks; removed maxis to access lower shock bolts

Refastened jam nuts on front axle maxi push rods

5.5 Hrs 120.00	TOTAL LABOR	660.00
	TOTAL PARTS	632.63
	SHOP SUPPLIES	33.00
	SUB TOTAL	1325.63
	GST # 877828343	66.28
	TAX	
	TOTAL	1,391.91

	QTY.	PART NO. AND DESCRIPTION	PRICE
	-		

M.K.S. Trailer & Equipment Repairs Ltd.
716 Carter Crest Way
Edmonton, Alberta T6R 2N3
Shop: 780-451-3861
Cell: 780-966-2963

INVOICE 78450

DATE: MAR 29 2025

NAME: BOYD VENTURES

ADDRESS: RR. 3, Site 302, Comp 88 CITY: ONOWAY

PROVINCE: AB POSTAL CODE: T0E 1V0

PURCHASE ORDER:

LICENSE NO.	YEAR	MAKE/MODEL
6PX418	2024	Load King

SERIAL NO.: 5LKL53350R1034181 UNIT NO.: 051

SERVICE CALL TO BOYD yard

SERVICE

Checked air & lights

Find short in wiring; repaired wiring at 7 wire plug

3 Hrs 120.00

TOTAL LABOR	360.00
TOTAL PARTS	
SHOP SUPPLIES	18.00
SUB TOTAL	378.00
GST # 877828343	18.90
TAX	
TOTAL	396.90