

T29-2
NOV

**Industrial Diesel Repair &
Performance Ltd**
4017 Charles Street
Red Deer County, AB T4S2B3, CA
service@idrp.ca
4038963572



Invoice: **INV-26513**
Date: **10/2/2026**

Bill To
CMT Logistics Inc
84 Burnt Park
Red Deer, AB T4P 0L3, CA
P: (403) 348-5848

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-2674	Net 30	11/1/2026			80

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: ROUGH RUNNING - ON START UP

Cause: Customer request

Labor	Correction: Chassis / Chassis / STARTED VEHICLE AFTER IT SAT ALL NIGHT. SMALL STUMBLE AND SMOKE ON START UP. CLEARED UP AFTER 30 SECONDS. CHECKED EXHAUST MANIFOLD TEMPS, ALL ARE CLOSE. REMOVED AIR FILTER COVERS TO INSPECT THE FILTERS-GOOD. FRAME FUEL FILTER IS OLD AND RUSTY. WILL REPLACE BOTH FILTERS BEFORE ANY FURTHER DIAG. INSTALLED CLEAR TEST FUEL LINE IN AFTER THE FRAME MOUNTED FILTER. FUEL HAS ALOT OF AIR MIXED IN. BYPASSED THE FRAME FILTER AND THE TANKS AND RAN THE VEHICLE OUT OF A BUCKET. ENGINE SMOOTHES OUT. RECOMMEND FILTER BASE AND ALL FUEL LINES BE REPLACED. CORY - OBSERVED LONG CRANK TIME BEFORE ENGINE RUNS. CONNECTED TO ECM AND FOUND FUEL PRESSURE RELATED FAULT. UPON VISUAL INSPECTION NOTICED FAULTY LIFT PUMP WIRING. REPAIRED WIRING BY CUTTING BACK AND CRIMPING NEW PINS FOR DEUTSCH CONNECTOR. RAN LIFT PUMP AND MONITORED LIFT PUMP FUEL PRESSURE. PRESSURE VALUE NOT IN SPEC. FAULTY LIFT PUMP IDENTIFIED. AFTER REPAIR, FUEL PRESSURE IN SPEC AND EXCESSIVE CRANK TIME ISSUE RESOLVED. ENGINE STILL RUNS ROUGH. SWAPPED IN TEST TIMING AND METERING ACTUATORS, BLED AIR FROM SYSTEM AND TESTED. ISSUE RESOLVED. SWAPPED ONE ACTUATOR AT A TIME BACK TO ORIGINAL, BLEEDING AND TESTING AFTER EACH, UNTIL FAULTY ACTUATOR IDENTIFIED. REPLACED REAR BANK METERING ACTUATOR WITH GOOD USED PART. BLED AIR FROM FUEL SYSTEM AND TESTED. ROUGH RUNNING ISSUE DRASTICALLY IMPROVED. - Completed: 9/25/2026	16.00000	\$150.00	\$2,400.00
Parts	FILTER- FUEL /WATER SEPARATOR	1.00000	\$27.30	\$27.30
Parts	FUEL FILTER, SPIN-ON	1.00000	\$36.53	\$36.53
Parts	#10 X 1/2NPT 90 FLARE ADPT	1.00000	\$9.71	\$9.71
Parts	10SAE FEMALE CRIMP FITTING	2.00000	\$34.13	\$68.26
Parts	#10 UNIVERSAL SWIVEL 90	2.00000	\$50.92	\$101.84
Parts	#10 MEDIUM PRESSURE HOSE	2.00000	\$17.03	\$34.06

Parts	USED KIT, FUEL ACTUATOR	1.00000	\$651.90	\$651.90
			Subtotal	\$3,329.60

Complaint: REPLACE FUEL LIFT PUMP

Cause: Customer request

Labor	Correction: Chassis / Chassis / UNPLUGGED AND REMOVED LIFT PUMP. CLEANED MATING FACE AND INSTALLED NEW PUMP WITH A NEW GASKET. RAN ENGINE TO VERIFY REPAIR. - Completed: 9/25/2026	2.00000	\$150.00	\$300.00
Parts	GASKET, SUPPORT	1.00000	\$45.14	\$45.14
Parts	PUMP, FUEL TRANSFER	1.00000	\$890.46	\$890.46
Parts	VALVE, CHECK	1.00000	\$213.86	\$213.86
			Subtotal	\$1,449.46

EHC	1.00	\$1.25	\$1.25
EHC	1.00	\$1.25	\$1.25

Unit: 80 (79308887) VIN: 1XKDD40X18J940223

License Plate: (AB) K-98228

2009 Kenworth T8 Series

Chassis: 1,646,748 Kilometers

Engine: 4,452 Hours

Labor	\$2,700.00
Parts	\$2,079.06
Shop Supplies	\$216.20
Pre-Charge Subtotal	\$4,995.26
EHC	\$1.25
EHC	\$1.25
GST (5% of \$4,997.76)	\$249.89
Total	\$5,247.65
Payments & Credits	\$0.00
Balance Due	\$5,247.65

Any warranties on the parts, accessories and labour, sold hereby are made by the manufacturer. There will be NO warranty on aftermarket (non OEM) parts unless paid for by the manufacturer, or high horsepower ECM software files. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: _____

Red Ram Sales Ltd

11210 Winterburn Road NW

Edmonton, AB T5S 2B5

Parts: 780-447-4946 Office: 780-447-3595

Toll Free: 800-361-0234

sales@redramtruck.ca www.redramtruck.ca

Sales Receipt 2506306



Bill To

C.M.T. Ventures Inc.

84 Burnt Park Drive

Red Deer, AB T4P 0L3

Canada

(403) 348-5848

Ship To

C.M.T. Ventures Inc.

84 Burnt Park Drive

Red Deer, AB T4P 0L3

Canada

(403) 348-5848

Sales Receipt 2506306

Sales Person	Robert Lansdell	Payment Method	Mastercard
Ship Via	Customer pick up	Payment Notes	Phone order
		Sold On	07 November 2025
			Paid \$2,362.50

Item	Price	Quantity	Line Total
Used - Radiator Cross Member. Pn# A24-1392	1,300.00	1	1,300.00
Used - Radiator Cross Member. Pn# A24-1213	950.00	1	950.00

Notes

Subtotal	2,250.00
GST @ 5.00 %	112.50
Total Tax	112.50
Paid	\$2,362.50
Balance	\$0.00

GST: R104442389

Unless specified in writing on the invoice or sales receipt, all used parts sales are final and sold as-is with no warranty or guarantee implied. All sales of tested electrical components are final and non-refundable. Warranty forms must be completed and submitted within 30 days on the purchase of all overhauled parts, otherwise a limited 30-day warranty applies. Warranty on new parts sold is limited to the terms provided by the manufacturer. Unless otherwise stated, all parts sold are eligible for refund or exchange within 14 days of purchase, with all approved returns being subject to a 20% restocking fee. A core must be returned within 60 days of purchase to be eligible for a core credit.

Industrial
Diesel
Repair &
Performance
Ltd

4017 Charles
Street

Red Deer

County, AB

T4S2B3, CA

service@idrp.

ca

4038963572

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

Invoice

Date

INV - 25439
July 14/25

SERVICE

Approved to pay

C.M.



Bill To
CMT Logistics Inc
84 Burnt Park
Red Deer, AB T4P 0L3, CA
P: (403) 348-5848

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-1898	Net 30	8/14/2025			80

Item	Description	Quantity	Rate	Amount
Complaint: CHECK ENGINE LIGHT				
Cause: Customer request				

Labor	Correction: Chassis / Chassis / HOOK UP TO THE ECM AND FOUND, NO ACTIVE CODES RELATING TO ROUGH RUNNING. PERFORM A CYLINDER CUTOFF TEST AND FOUND THAT THE SMOKE WOULD GO AWAY ONCE CYL 4 WAS DISABLED. - Completed: 7/15/2025	1.00000	\$150.00	\$150.00
Subtotal				\$150.00

Complaint: REPLACE INJECTOR

Cause: Customer request

Labor	Correction: Chassis / Chassis / REMOVE REAR BANK VALVE AND INJECTOR ROCKERS. FOUND SPRING RETAINER BROKEN ON #4 CYLINDER. THE INJECTOR CAME OUT IN 3 PIECES. REPLACED INJECTOR, REINSTALLED BOTH ROCKER LEVERS. SET RUNNING CLEARANCE. RESET INJECTOR. NOTICED THAT 4 OTHER INJECTOR SET SCREWS ARE TOO HIGH. A FULL VALVE SET WILL HAVE TO BE PERFORMED. - Completed: 7/15/2025	2.00000	\$150.00	\$300.00
Parts	INJECTOR, HD/HPI	1.00000	\$2,092.15	\$2,092.15
Parts	Inherent Core for INJECTOR, HD/HPI	1.00000	\$338.80	\$338.80
Parts	Dirty Core for INJECTOR, HD/HPI	-1.00000	\$338.80	-\$338.80
Subtotal				\$2,392.15

Complaint: VALVE SET**Cause:** Customer request

Labor	Correction:	3.00000	\$150.00	\$450.00
	Chassis / Chassis / SET THE INTAKE, EXHAUST AND ENGINE BRAKES. RUN			
	ENGINE. ALL GOOD AT THIS TIME. - Completed: 7/16/2025			

	Subtotal	\$450.00
--	-----------------	-----------------

Unit: 80 (79308887) **VIN:** 1XKDD40X18J940223**License Plate:** (AB) K-88228**2008 Kenworth T8 Series****Chassis:** 1,593,210 Kilometers**Engine:** 2,947 Hours

Labor	\$900.00
--------------	-----------------

Parts	\$2,092.15
--------------	-------------------

Shop Supplies	\$72.00
----------------------	----------------

Pre-Charge Subtotal	\$3,084.15
----------------------------	-------------------

GST	\$153.21
(5% of \$3,084.15)	

Total	\$3,217.36
--------------	-------------------

Payments & Credits	\$0.00
-------------------------------	---------------

Balance Due	\$3,217.36
--------------------	-------------------

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: _____**Printed Name:** _____ **Date:** _____



GREATWEST KENWORTH LTD



6739 67 AVENUE
RED DEER, AB T4P 1K3
(403) 342-1144

Sold To:

CMT VENTURES/LOGISTICS INC
84 BURNT LAKE PARK
RED DEER, AB T4P 0L3

Ship To:

CMT VENTURES/LOGISTICS INC
84 BURNT LAKE PARK
RED DEER, AB T4P 0L3

PARTS INVOICE NUMBER

PR2178469



Date: 04-12-24

Page: 1 of 1

Tax ID:

Authorization #:

Tax ID:		Authorization ID:							
Customer Acct Number		Phone Number	Salesman	Ship Via			Customer Purchase Order		
			DMD	Blackdog			Unit 80		
Loc	Part #	Description		Ord	Ship	B/O	List	Unit Price	Extension
UNIT # REQUIRED									
883	PA78001	CONDENSER ASSY		1	1		561.68	444.01	444.01

SERVICE

NOW OPEN: FOX CREEK PARTS ONLY 201-1A AVE 780-622-5642
BALZAC PARTS & SERVICE: 292217 PRIME AVE 587-319-

5950

RED DEER HOURS OF OPERATION:

MONDAY-FRIDAY 7:30AM-6:00PM SATURDAY 8:00AM-4:00PM

AFTERHOURS PARTS/SERVICE CALLOUT AVAILABLE

THANK YOU! WE APPRECIATE YOUR BUSINESS!

PARTS EMAIL: REDDEERPARTS@GREATWESTKENWORTH.COM

04:58PM PARTS TAX

Customer Print Name: _____

Customer Signature: _____ Date: _____

CUSTOMER
GST# R139766661

220

Sub Total	444.01
Freight	0.00
GST	22.20
Sales tax	0.00
Please Pay	466.21

ALL PARTS RETURNED AFTER 30 DAYS WILL BE SUBJECT TO A MINIMUM 15% RESTOCKING CHARGE. SPECIAL ORDER PARTS ARE ALSO SUBJECT TO A RESTOCKING CHARGE IF AND ONLY IF THEY ARE ACCEPTABLE FOR RETURN. PARTS OLDER THAN 90 DAYS ARE NOT ACCEPTABLE FOR RETURN. NO RETURNS ON ELECTRICAL PARTS.
BALZAC - CALGARY - CLAIRMONT - FOX CREEK - LETHBRIDGE - REDCLIFF - RED DEER

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3

Invoice #	24151
P.O. No.	
Date	4/9/2024

SERVICE

2009 KENWORTH T800 1497726 KMS 569 HRS K98228	VIN 1XKDD40X19J940233	ESN 79308887	Unit # 80
---	--------------------------	-----------------	--------------

Labour/Parts	QTY	Rate	Amount
ROUGH RUNNING - Remove the metering actuator for the front bank and crank the engine, found lots of compression gasses coming back through the fuel system. Bar the engine over manually and found that all 3 injectors have failed. Remove the valve cover and attempted to remove the injectors but number 2 is seized in the head. Got approval to remove the head.	6	135.00	810.00
ENGINE OVERHAUL CYL 3 ONLY - Remove cooling package, all components on the intake and exhaust sides of the engine. Remove rockers, injectors and fuel supply plumbing. remove all headbolts and the cylinder head, clean the deck, measure liner heights. Drain the engine oil, remove the pan, oil pump, suction tube, stiffener plate, remove the piston and liner. Clean all components and install new rings, piston and liner as well as gaskets, seals and o rings. Paint and install the new head and all components on the intake and charge air side of the engine. Set all valves and install the cooling package. Top up the engine oil and coolant, run engine and check for leaks.	45	135.00	6,075.00
CUT COUNTERBORES - Cut number 3 counterbore and measure the height, they are between 0.011 - 0.012"	1	135.00	135.00
WASH - Wash down all evidence of repair.	1	135.00	135.00
Labour fees subtotal			7,155.00

Workmanship warranty on all repairs is valid for 90 days from date of invoice. Parts warranty is subject to the manufacturer.
There is no workmanship warranty on high horsepower ECM files or repairs with non OEM parts.
All proper break-in procedures are the responsibility of the customer.
Please retorquer your wheels after 100 KM

Subtotal

GST/HST

Total

GST/HST No. 776903080RT0001

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:	Invoice #	24151
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3	P.O. No.	
	Date	4/9/2024

2009 KENWORTH T800 1497726 KMS 569 HRS K98228	VIN	ESN	Unit #
	1XKDD40X19J940233	79308887	80

Labour/Parts	QTY	Rate	Amount
SHOP SUPPLIES - Zip ties, rags, bolts and hardware, brake clean, solvent, butane, oxygen/acetylene etc.		249.32	249.32
INJECTOR-HD HPI	6	1,493.48	8,960.88
OIL PAN GASKET CUMMINS	1	180.24	180.24
SET, UPPER ENGINE GASKET	1	1,959.68	1,959.68
KIT, LINER	1	511.23	511.23
DOWEL, RING	2	25.23	50.46
CYLINDER HEAD	1	6,758.27	6,758.27
PISTON KIT	1	1,248.39	1,248.39
CORE FOR INJECTOR STUCK IN CYLINDER HEAD	1	242.00	242.00
PLUG THREADED	1	24.65	24.65
SCREW, HEX FLANGE HEAD CAP	2	43.195	86.39
GASKET, EXH OUT CONNECTION	1	31.71	31.71
0.020" LINER SHIM	1	107.41	107.41
ANTIFREEZE, PRESTONE, ELC 50/50, 3.78L, RED	2	16.02	32.04
ATF	2	10.03	20.06
GREY PRIMER	1	21.05	21.05

Workmanship warranty on all repairs is valid for 90 days from date of invoice. Parts warranty is subject to the manufacturer.
There is no workmanship warranty on high horsepower ECM files or repairs with non OEM parts.
All proper break-in procedures are the responsibility of the customer.
Please retorquer your wheels after 100 KM

Subtotal	\$27,638.78
GST/HST	\$1,381.94
Total	\$29,020.72

GST/HST No. 776903080RT0001

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:	Invoice #	24136
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3	P.O. No.	
	Date	3/26/2024

SERVICE

2009 KENWORTH T800 1497684 KMS 566 HRS K98228	VIN	ESN	Unit #
	1XKDD40X19J940233	79308887	80

Labour/Parts	QTY	Rate	Amount
RESEAL FRONT STRUCTURE - Drain coolant, remove all intake and charge air piping, remove the cooling package, fan hub, gear cover and all gears. Remove and reseal the structure, pin the cam and crank, set the base timing and reinstall all components. Top up coolant and oil and run the engine, no leaks were found.	24	135.00	3,240.00
REPAIR UPPER RAD HOSE BRACKET - Repair the L bracket for the upper rad hose as it was broken off.	0.5	135.00	67.50
WASH AND ROAD TEST - Wash and road test unit after repair.	1	135.00	135.00
Labour fees subtotal			3,442.50
SHOP SUPPLIES - Zip ties, rags, bolts and hardware, brake clean, solvent, butane, oxygen/acetylene etc.		8.00%	275.40
CAMSHAFT COVER GASKET	1	19.76	19.76
SEAL,O RING	1	23.36	23.36
O-RING	1	30.48	30.48
GASKET, CAMSHAFT COVER	1	28.57	28.57
GASKET,GEAR HOUSING	1	191.12	191.12
KIT,SEAL	1	196.60	196.60
PLUG,GEAR COVER	1	17.45	17.45
SEAL,RECTANGULAR STRIP	1	54.25	54.25
SEAL,RECTANGULAR STRIP	1	61.19	61.19

Workmanship warranty on all repairs is valid for 90 days from date of invoice. Parts warranty is subject to the manufacturer.

There is no workmanship warranty on high horsepower ECM files or repairs with non OEM parts.

All proper break-in procedures are the responsibility of the customer.

Please retorque your wheels after 100 KM

Subtotal

GST/HST

Total

GST/HST No. 776903080RT0001

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:	Invoice #	24136
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3	P.O. No.	
	Date	3/26/2024

2009 KENWORTH T800 1497684 KMS 566 HRS K98228	- VIN	ESN	Unit #
	1XKDD40X19J940233	79308887	80

Labour/Parts	QTY	Rate	Amount
AIR COMPRESSOR MOUNTING GASKET	1	82.96	82.96
HOUSING, GEAR	1	1,362.76	1,362.76
OIL PAN GASKET CUMMINS	1	180.24	180.24
SEAL, O-RING	1	17.99	17.99
SCREW, HEX FLANGE HEAD CAP	4	15.96	63.84
WASHER, PLAIN	1	119.91	119.91
BEARING, THRUST	1	114.88	114.88
RETAINER, GEAR	1	97.63	97.63
SHAFT, IDLER	1	198.32	198.32
SENSOR, POSITION	1	133.40	133.40
MOTOR MOUNT POLY KENWORTH	2	34.49	68.98
BOLT	1	16.19	16.19
GEAR, IDLER	1	1,441.55	1,441.55
SEAL, RECTANGULAR RING	1	33.68	33.68
SEAL, RECTANGULAR RING	1	10.36	10.36
RADIATOR MOUNT	2	23.40	46.80
CUMMINS RED SPRAY PAINT	1	53.13	53.13
ATF	2	10.03	20.06
ANTIFREEZE, PRESTONE, ELC 50/50, 3.78L, RED	2	16.02	32.04

Workmanship warranty on all repairs is valid for 90 days from date of invoice. Parts warranty is subject to the manufacturer.
There is no workmanship warranty on high horsepower ECM files or repairs with non OEM parts.
All proper break-in procedures are the responsibility of the customer.
Please retorque your wheels after 100 KM

Subtotal \$8,435.40

GST/HST \$421.77

Total \$8,857.17

GST/HST No. 776903080RT0001

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:	Invoice #	23713
CMT Logistics Inc 84 Burnt Park Red Deer, AB T4P 0L3	P.O. No.	
	Date	12/11/2023

SERVICE

2009 KENWORTH T800 1473742 KM 14213 HRS K98228	VIN	ESN	Unit #
	1XKDD40X19J940233	79308887	80

Labour/Parts	QTY	Rate	Amount
CHECK ENGINE LIGHT - Hook up to the ECM and found random codes for several engine systems. The dash would also intermittently die on the test drive. Install a test ECM and found that all issues were resolved.	2	135.00	270.00
REPLACE ECM -Remove the old ECM, program the new one and install it.	2	135.00	270.00
BROKEN WHEEL STUD AXLE 2 P/S - Jack unit up and remove the wheels and replace the broken wheel stud. Replace the brake shoes at the same time. Reinstall all components and torque wheels.	2	135.00	270.00
Labour fees subtotal			810.00
SHOP SUPPLIES - Zip ties, rags, bolts and hardware, brake clean, solvent, butane, oxygen/acetylene etc.		8.00%	64.80
M22 WHEEL NUT	2	6.58	13.16
STUD	1	11.47	11.47
EATON E2 SHOE KIT W HARDWARE	1	91.35	91.35
SCREW, HEX FLANGE HEAD CAP	1	7.76	7.76
ANTIFREEZE, PRESTONE, ELC 50/50, 3.78L, RED	2	16.02	32.04
DOT AIRBRAKE TUBE;1/4 BLK	1	1.40	1.40
1/4 SYNFLX UNION	2	13.08	26.16

Workmanship warranty on all repairs is valid for 90 days from date of invoice. Parts warranty is subject to the manufacturer.
There is no workmanship warranty on high horsepower ECM files or repairs with non OEM parts.
All proper break-in procedures are the responsibility of the customer.
Please retorquer your wheels after 100 KM

Subtotal	\$1,058.14
GST/HST	\$52.91
Total	\$1,111.05

GST/HST No. 776903080RT0001

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@idrp.ca
www.idrp.ca



Company:	Invoice #	21744
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3	P.O. No.	
	Date	11/16/2021

2009 KENWORTH T800 1206167KMS/27101HRS K98228	Vin	Unit #	ESN
	1XKDD40X19J940233	80	79308887

Labour/Parts	QTY	Rate	Amount
ENGINE OVERHAUL - Remove cooling package, all components on the intake and exhaust sides of the engine. Remove the cylinder head and clean the deck, measure liner heights. Drain the engine oil and remove the pistons and liners. Clean all components and install new main bearings, rod bearings, pistons, liners and all gaskets, seals and o rings. Set all valves and install the cooling package. Top up the engine oil and coolant, run engine and check for leaks.	40	110.00	4,400.00
CUT COUNTERBORES - Cut all 6 counterbores and measure heights, they are between 0.013 - 0.014"	5	110.00	550.00
WASH AND ROAD TEST - Wash and road test unit after repair.	1	110.00	110.00
COOLANT LEAK - Repair coolant leak inside the frame rail on the p/s.	1	110.00	110.00
Labour fees subtotal			5,170.00
SHOP SUPPLIES - Zip ties, rags, bolts and hardware, brake clean, solvent, butane, oxygen/acetylene etc.		191.65	191.65
COOLANT - 4L JUG	2	17.29	34.58
GROMMET	2	5.89	11.78
OIL FILTER	1	49.50	49.50

SERVICE

GST/HST No. 776903080RT0001

Subtotal
GST/HST
Total

INDUSTRIAL DIESEL

REPAIR & PERFORMANCE

4017 Charles St.
Red Deer County, AB
T4S 2B3
(403) 896-3572
service@ldrp.ca
www.ldrp.ca



Company:	Invoice #	21744
CMT Ventures Inc 84 Burnt Park Dr Red Deer, AB T4P 0L3	P.O. No.	
	Date	11/16/2021

2009 KENWORTH T800 1206167KMS/27101HRS K98228	Vin	Unit #	ESN
	1XKDD40X19J940233	80	79308887

Labour/Parts	QTY	Rate	Amount
ROD BEARING	6	117.39	704.34
HEAD REBUILD - 3RD PARTY	1	2,880.85	2,880.85
ORING	6	7.49	44.94
A/C ORING KIT	1	7.05	7.05
BRASS FITTING	1	9.87	9.87
FREIGHT CHARGES	1	150.00	150.00
FREON	4	14.87	59.48
CAC HOSE	2	49.18	98.36

Please retorque your wheels after 100KM

There is no workmanship warranty on high horsepower ECM files or rebuilds with non OEM parts.

GST/HST No. 776903080RT0001

Subtotal	\$9,412.40
GST/HST	\$470.62
Total	\$9,883.02