

V29-1  
NOV

HardCore Equipment Services Inc.  
RR 2 Stn Main  
Lacombe AB T4L 2N2  
(867)332-8713  
hard\_core\_equipment@outlook.com  
GST Registration No.: 743320277RT0001

# Invoice

BILL TO  
Roberts Energy Services Ltd

| INVOICE # | DATE       | TOTAL DUE  | DUE DATE   | ENCLOSED |
|-----------|------------|------------|------------|----------|
| 2022-182  | 02/05/2026 | \$4,200.00 | 01/06/2026 |          |

| DATE | ACTIVITY | DESCRIPTION                                                                                                                                                                                                                                                                                                           | TAX | QTY  | RATE   | AMOUNT   |
|------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------|--------|----------|
|      | L        | Labour for Service April 23<br>2026127- 243933 km 127<br>T/s low air buzzer, speaker in<br>dash no good, install new<br>switch and buzzer into cab,<br>replace grease nipple in tie rod<br>end<br>Check over unit, tighten loose<br>drive shaft spline nut, torque<br>ubolt straps<br>Inspect unit, advise on repairs | G   | 6    | 100.00 | 600.00 ✓ |
|      | L        | Labour for Service - April 23<br>Rig 135, t/s no power to rear<br>backup lights, open harness<br>find bad splice and bad switch<br>in Trans mission                                                                                                                                                                   | G   | 2.50 | 100.00 | 250.00 ✓ |
|      | L        | Labour for Service - April 24<br>2026,<br>127- remove drive shaft<br>between front and middle drive                                                                                                                                                                                                                   | G   | 1    | 100.00 | 100.00 ✓ |
|      | L        | Labour for Service - April 24<br>2026<br>135, install odometer interrupter<br>relay for when in rig mode,<br>finish repair for back up lights.<br>Install harness loom back and<br>zip tie up harness<br>-install and repair clamp on<br>intake on left side of engine<br>Find part number for bad<br>solenoid valve  | G   | 5    | 100.00 | 500.00 ✓ |

| DATE | ACTIVITY | DESCRIPTION                                                                                                                                                                                                                                                          | TAX | QTY  | RATE   | AMOUNT   |
|------|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------|--------|----------|
|      | L        | Labour for Service - April 29 2026<br>132 rig. Find part number for air filter dust bowl, 1/8 crank case filter issues<br>- reprogram parameters in engine to get cruise control back, brake pedal switch was not being seen by ecm<br>Tighten loose starter bolts   | G   | 4    | 100.00 | 400.00 ✓ |
|      | L        | 426 Labour for Service -April 29 2026 127 skid steer, install roda valve, wrong solenoid, change to 12v, wire up shut off into cab on rocker switch.<br>Fab support bracket for map sensor mounting                                                                  | G   | 5    | 100.00 | 500.00 ✓ |
|      | L        | Labour for Service -April 30 2026<br>132, look into broken leaf spring, replace crank case filter with winter one,<br>Make jumper wires for tail lamps                                                                                                               | G   | 4    | 100.00 | 400.00 ✓ |
|      | L        | Labour for Service -April 30 2026<br>225 pre inspection<br>Make valve bank to test trailers                                                                                                                                                                          | G   | 3    | 100.00 | 300.00 ✓ |
|      | L        | Labour for Service -April 30 2026 auto car body job<br>Fix power steering leak                                                                                                                                                                                       | G   | 1    | 100.00 | 100.00 ✓ |
|      | L        | Labour for Service -April 30 2026. 128 find part to prevent dlr from flickering, adjust low beams to the same                                                                                                                                                        | G   | 1    | 100.00 | 100.00 ✓ |
|      | L        | Labour for Service -May 1 2026<br>128 and trailer, inspect, grease<br>Replace broken grease nipples<br>Remove front ubolts on left steer axle to repair shock mount.<br>Adjust brakes out of adjustment<br>Install pin in front left slack adjuster that was missing | G   | 3.50 | 100.00 | 350.00 ✓ |
|      | L        | Labour for Service -May 1 2026<br>125, inspect and grease truck.<br>Replace broken grease nipples<br>Replace leaking power steering hose and fitting<br>Plug into ac and check for charge, no charge<br>Lubricate sticky heater control valve linkage                | G   | 4    | 100.00 | 400.00 ✓ |

We appreciate your business.  
We accept e-transfer payments to  
hard\_core\_equipment@outlook.com

|             |                   |
|-------------|-------------------|
| SUBTOTAL    | 4,000.00          |
| GST @ 5%    | 200.00            |
| TOTAL       | 4,200.00          |
| BALANCE DUE | <b>\$4,200.00</b> |

TAX SUMMARY

|  | RATE     | TAX    | NET      |
|--|----------|--------|----------|
|  | GST @ 5% | 200.00 | 4,000.00 |

Industrial Diesel Repair &  
Performance Ltd  
4017 Charles Street  
Red Deer County, AB T4S2B3, CA  
service@idrp.ca  
4038963572



Invoice: INV-25768  
Date: 12/18/2025

Bill To  
ROBERTS ENERGY SERVICES

P: (403) 348-6445

128

| Service Order | Terms | Due Date   | Authorizer   | Customer PO | Unit # |
|---------------|-------|------------|--------------|-------------|--------|
| SO-2227       | COD   | 12/18/2025 | DAVE ROBERTS |             | 1      |

| Item | Description | Quantity | Rate | Amount |
|------|-------------|----------|------|--------|
|------|-------------|----------|------|--------|

Complaint: WATER PUMP

Cause: Customer request

|       |                                                                                                                                                                                                                                                                                                                               |         |          |          |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|----------|----------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / DRAIN COOLANT, REMOVE BELTS AND REMOVE WATER PUMP CARTRIDGE. CLEAN MATING SURFACES AND INSTALL NEW CARTRIDGE USING GASKETS AND SEALS. REINSTALL ALL COMPONENTS. FILL COOLANT AND TOP UP AS REQUIRED. RUN ENGINE AND CHECK FOR LEAKS. ALL GOOD AT THIS TIME. - Completed: 12/18/2025 | 0.00000 |          | \$0.00   |
| Parts | SEAL,O RING                                                                                                                                                                                                                                                                                                                   | 1.00000 | \$23.57  | \$23.57  |
| Parts | PUMP, WATER                                                                                                                                                                                                                                                                                                                   | 1.00000 | \$796.61 | \$796.61 |
|       | <b>Subtotal</b>                                                                                                                                                                                                                                                                                                               |         |          | \$820.18 |

Complaint: CHECK ENGINE LIGHT

Cause: Customer request

|       |                                                                                                                                                                                           |         |  |        |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--|--------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / CONNECTED TO ECM AND FOUND WATER IN FUEL WIRING CODE. CHECKED FOR VOLTAGE AT CONNECTOR. REPAIRED WIRING. CLEARED FAULT. - Completed: 12/18/2025 | 0.00000 |  | \$0.00 |
|       | <b>Subtotal</b>                                                                                                                                                                           |         |  | \$0.00 |

Complaint: ROAD TEST

Cause: Customer request

|       |                                                                                                                     |         |  |        |
|-------|---------------------------------------------------------------------------------------------------------------------|---------|--|--------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / TAKE UNIT ON A TEST DRIVE. ALL GOOD AT THIS TIME. - Completed: 12/18/2025 | 0.00000 |  | \$0.00 |
|       | <b>Subtotal</b>                                                                                                     |         |  | \$0.00 |

Unit: 1 (79506310) VIN: 5KJJALBG7CPBN6888

2012 Western Star Trucks 4900  
Chassis: 580,012 Kilometers  
Engine: 13,367 Hours

|                         |          |
|-------------------------|----------|
| Parts                   | \$820.18 |
| Pre-Charge Subtotal     | \$820.18 |
| GST<br>(5% of \$820.18) | \$41.01  |
| Total                   | \$861.19 |
| Payments & Credits      | \$0.00   |
| Balance Due             | \$861.19 |

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Date: \_\_\_\_\_

**Industrial Diesel Repair & Performance Ltd**  
 4017 Charles Street  
 Red Deer County, AB T4S2B3, CA  
 service@idrp.ca  
 4038963572



**Invoice: INV-25760**  
**Date: 12/15/2025**

**Bill To**  
**ROBERTS ENERGY SERVICES**

| Service Order | Terms | Due Date   | Authorizer   | Customer PO | Unit # |
|---------------|-------|------------|--------------|-------------|--------|
| SO-2164       | COD   | 12/15/2025 | DAVE ROBERTS |             | 1      |

| Item | Description | Quantity | Rate | Amount |
|------|-------------|----------|------|--------|
|------|-------------|----------|------|--------|

**Complaint: ENGINE SWAP**

**Cause: Customer request**

|                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |          |          |                   |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|-------------------|
| Labor           | <b>Correction:</b><br>Chassis / Chassis / REMOVED INTAKE PIPING. RECOVERED REFRIDGERANT AND DETACHED AC LINES. DETACHED TRANSMISSION AND POWER STEERING COOLER LINES. REMOVED RADIATOR BRACES. DRAINED COOLANT, DETACHED ALL COOLANT LINES/HOSES AND REMOVED COOLING PACKAGE. REMOVED CABLES AND WIRING FROM STARTER AND ALTERNATOR. REMOVED CHASSIS WIRING HARNESS FROM ECM. DETACHED FUEL LINES. DETACHED AIR COMPRESSOR DISCHARGE LINE AND GOVERNOR SENSE LINE. DETACHED EXHAUST PIPE. UNBOLTED CLUTCH, TRANSMISSION BELL HOUSING AND FRONT ENGINE MOUNT. RIGGED AND REMOVED ENGINE USING A-FRAME GANTRY. AFTER COMPLETION OF OVERHAUL, REINSTALLED ENGINE IN FRAME. CONNECTED AND INSTALLED ALL PREVIOUSLY REMOVED COMPONENTS. REPLACED VARIOUS COOLANT LINES. CRIMPED NEW ENDS ON BATTERY CABLES AT ALTERNATOR. CHARGED AC SYSTEM WITH REFRIGERANT. FILLED ENGINE WITH OIL AND COOLANT. PRIMED FUEL SYSTEM. RAN ENGINE, INSPECTED FOR LEAKS AND TOPPED UP FLUIDS. - Completed: 12/15/2025 | 35.00000 | \$150.00 | \$5,250.00        |
| Parts           | SEAL # 8                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 3.00000  | \$8.10   | \$24.30           |
| Parts           | SEAL # 12                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 4.00000  | \$8.58   | \$34.32           |
| Parts           | 1" SILICONE HEATER HOSE                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 2.00000  | \$12.92  | \$25.84           |
| Parts           | 3/4" SILICONE HEATER HOSE                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 3.00000  | \$9.61   | \$28.83           |
| Parts           | 3/8" SILICONE HEATER HOSE                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 9.00000  | \$7.09   | \$63.81           |
| Parts           | GLOSS BLACK ENAMEL                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 1.00000  | \$21.05  | \$21.05           |
| Parts           | 15W40 ROTELLA BULK OIL                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 48.00000 | \$7.63   | \$366.24          |
| Parts           | HEAVY-DUTY NOAT 50/50 PREDILUTED ANTIFREEZE/COOLANT, 3.78 L, JUG                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 8.00000  | \$14.98  | \$119.84          |
| <b>Subtotal</b> |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |          |          | <b>\$5,934.23</b> |

**Complaint: FRONT STRUCTURE - REMOVED FROM CHASSIS**

**Cause: Customer request**

|       |                                                                                                                                                                                                                                                                                                                                                                    |          |                 |                   |
|-------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED GEAR COVERS AND ALL GEARS FROM HOUSING. REMOVED HIGH PRESSURE FUEL PUMP AND AIR COMPRESSOR. REMOVED GEAR HOUSING. CLEANED AND INSPECTED ALL COMPONENTS. INSTALLED NEW GEAR HOUSING WITH NEW GASKET. INSTALLED FUEL PUMP AND AIR COMPRESSOR WITH NEW GASKETS. INSTALLED GEARS AND COVERS. - Completed: 12/15/2025 | 10.00000 | \$150.00        | \$1,500.00        |
| Parts | HOUSING, GEAR                                                                                                                                                                                                                                                                                                                                                      | 1.00000  | \$1,585.46      | \$1,585.46        |
| Parts | SCREW, TWELVE POINT CAP                                                                                                                                                                                                                                                                                                                                            | 3.00000  | \$5.72          | \$17.16           |
| Parts | SHAFT, IDLER                                                                                                                                                                                                                                                                                                                                                       | 1.00000  | \$199.09        | \$199.09          |
| Parts | PLUG, GEAR COVER                                                                                                                                                                                                                                                                                                                                                   | 1.00000  | \$28.52         | \$28.52           |
| Parts | SCREW, CAPTIVE WASHER CAP                                                                                                                                                                                                                                                                                                                                          | 10.00000 | \$15.11         | \$151.10          |
|       |                                                                                                                                                                                                                                                                                                                                                                    |          | <b>Subtotal</b> | <b>\$3,481.33</b> |

**Complaint: REAR STRUCTURE - ENGINE REMOVED FROM CHASSIS****Cause:** Customer request

|       |                                                                                                                                                                                                                                                                                         |         |                 |                   |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED FLYWHEEL, REAR CRANKSHAFT SEAL AND FLYWHEEL HOUSING. CLEANED MATING SURFACES AND INSPECTED COMPONENTS. INSTALLED STRUCTURE WITH NEW GASKET. INSTALLED NEW REAR CRANKSHAFT SEAL. INSTALLED RESURFACED FLYWHEEL - Completed: 12/15/2025 | 3.00000 | \$150.00        | \$450.00          |
| Parts | KIT, LOWER ENGINE GASKET                                                                                                                                                                                                                                                                | 1.00000 | \$1,528.01      | \$1,528.01        |
|       |                                                                                                                                                                                                                                                                                         |         | <b>Subtotal</b> | <b>\$1,978.01</b> |

**Complaint: ENGINE MOUNTS****Cause:** Customer request

|       |                                                                                                                      |         |                 |                   |
|-------|----------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED AND REPLACED FRONT AND REAR ENGINE MOUNTS. - Completed: 12/15/2025 | 2.00000 | \$150.00        | \$300.00          |
| Parts | RADIATOR MOUNT POLY                                                                                                  | 4.00000 | \$16.85         | \$67.40           |
| Parts | MOTOR MOUNT BUSHING                                                                                                  | 2.00000 | \$35.19         | \$70.38           |
| Parts | SCREW-CAP, HEX, 3/4"-10X4.5                                                                                          | 2.00000 | \$15.48         | \$30.96           |
| Parts | ISOLATOR                                                                                                             | 1.00000 | \$569.08        | \$569.08          |
|       |                                                                                                                      |         | <b>Subtotal</b> | <b>\$1,037.82</b> |

**Complaint: REPLACE CLUTCH - ENGINE REMOVED FROM CHASSIS****Cause:** Customer request

|       |                                                                                                                 |         |                 |                   |
|-------|-----------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REPLACED CLUTCH WHILE THE ENGINE WAS REMOVED. - Completed: 12/15/2025 | 1.50000 | \$150.00        | \$225.00          |
| Parts | CLUTCH KIT                                                                                                      | 1.00000 | \$1,115.33      | \$1,115.33        |
| Parts | 2" CLUTCH BRAKE                                                                                                 | 1.00000 | \$71.17         | \$71.17           |
|       |                                                                                                                 |         | <b>Subtotal</b> | <b>\$1,411.50</b> |

**Complaint: INPUT SHAFT KIT****Cause:** Customer request

|       |                                                                                                                                                                                                                             |         |                 |                 |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED INPUT SHAFT, BEARING AND CROSS SHAFT BUSHINGS. INSTALLED NEW INPUT BEARING, SHAFT AND PLATE. INSTALLED NEW CROSS SHAFT BUSHINGS AND RELEASE FORK. - Completed: 12/15/2025 | 2.00000 | \$150.00        | \$300.00        |
| Parts | KIT-CLUTCH INSTALL                                                                                                                                                                                                          | 1.00000 | \$492.74        | \$492.74        |
|       |                                                                                                                                                                                                                             |         | <b>Subtotal</b> | <b>\$792.74</b> |

**Complaint: ENGINE OVERHAUL****Cause:** Customer request

|       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |          |                 |                    |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|--------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED ALL COMPONENTS FROM SIDES AND FRONT OF THE ENGINE. REMOVED ROCKERS, INJECTORS AND FUEL SUPPLY PLUMBING. REMOVED CAMSHAFT AND CYLINDER HEAD, CLEANED THE DECK AND MEASURED LINER HEIGHTS. DRAINED ENGINE OIL AND REMOVED OIL PAN, SUCTION TUBE, OIL PUMP AND STIFFENER PLATE. REMOVED PISTONS AND LINERS. FLIPPED ENGINE OVER AND REMOVED CRANKSHAFT FOR POLISHING. CLEANED AND INSPECTED ALL COMPONENTS AND ENGINE BLOCK. INSTALLED CRANKSHAFT WITH NEW MAIN BEARINGS. FLIPPED ENGINE OVER AND INSTALLED NEW LINERS, PISTONS AND ROD BEARINGS. INSTALLED NEW CYLINDER HEAD. INSTALLED CAMSHAFT. TIMED GEAR TRAIN AND INSTALLED COVER. INSTALLED ROCKER SHAFT ASSEMBLIES, INJECTORS, FUEL SUPPLY PLUMBING AND INJECTOR/JAKE HARNESS. SET VALVE AND JAKE LASH. INSTALLED ROCKER COVER. PAINTED ENGINE AND REMAINING COMPONENTS. INSTALLED STIFFENER PLATE, OIL PUMP, SUCTION TUBE AND OIL PAN. REPLACED OIL, FUEL, AND COOLANT FILTERS. REPLACED EXHAUST MANIFOLD CENTER SECTION AND INSTALLED MANIFOLD.<br>INSTALLED NEW TURBOCHARGER. INSTALLED INTAKE MANIFOLD AND CRANKCASE VENTILATION COMPONENTS. REMOVED EGR WIRING FROM HARNESS AND INSTALLED EGR BLOCKOFF PLATES. INSTALLED FAN HUB, ACCESSORY BRACKET, ALTERNATOR, AC COMPRESSOR, IDLER/TENSIONER PULLYS AND BELTS. - Completed: 12/15/2025 | 55.00000 | \$150.00        | \$8,250.00         |
| Parts | CYL HEAD X15- PERFORMANCE (S/N G1001250701259AN10                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 1.00000  | \$5,500.00      | \$5,500.00         |
| Parts | PDI BIG BOSS CUMMINS ISX SOHC IN-FRAME KIT 152MM LINER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 1.00000  | \$8,419.95      | \$8,419.95         |
| Parts | SENSOR, PRS TEMPERATURE                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 1.00000  | \$177.76        | \$177.76           |
| Parts | SCREW, HEX FLANGE HEAD CAP                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 4.00000  | \$48.94         | \$195.76           |
| Parts | SET,ROD BEARING (STD)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 6.00000  | \$181.83        | \$1,090.98         |
| Parts | OIL FILTER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 1.00000  | \$70.35         | \$70.35            |
| Parts | COOLANT FILTER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 1.00000  | \$51.72         | \$51.72            |
| Parts | CUMMINS RED PAINT                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 5.00000  | \$22.50         | \$112.50           |
| Parts | GREY SELF ETCHING PRIMER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | 5.00000  | \$36.00         | \$180.00           |
| Parts | EGR BLOCK OFF KIT                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 1.00000  | \$217.50        | \$217.50           |
| Parts | OIL FILTER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 1.00000  | \$70.35         | \$70.35            |
| Parts | COOLANT FILTER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 1.00000  | \$51.72         | \$51.72            |
| Parts | FUEL FILTER                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 1.00000  | \$81.24         | \$81.24            |
|       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |          | <b>Subtotal</b> | <b>\$24,469.83</b> |

**Complaint: COUNTERBORES - CUMMINS****Cause:** Customer request

|       |                                                                                                                                                  |         |                 |                   |
|-------|--------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / CUT COUNTERBORES AND MEASURE LINER HEIGHTS.<br>THEY ARE BETWEEN 0.011" - 0.012" - Completed: 12/2/2025 | 6.00000 | \$150.00        | \$900.00          |
| Parts | SHIM 0.032"                                                                                                                                      | 6.00000 | \$283.02        | \$1,698.12        |
|       |                                                                                                                                                  |         | <b>Subtotal</b> | <b>\$2,598.12</b> |

**Complaint: CHECK ENGINE LIGHT****Cause:** Customer request

|       |                                                                                                                                                                                                                                                                                              |         |                 |                 |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / HOOK UP TO THE ECM AND FOUND AMBIANT AIR<br>TEMPERATURE CODE. SEARCHED AND FOUND SENSOR LOCATION.<br>CHECKED FOR VOLTAGE AT SENSOR. RAN TEMPORARY OVERLAY AND<br>CLEARED FAULT. RAN PERMENANT OVERLAY. VERIFIED REPAIR. - Completed:<br>12/15/2025 | 3.00000 | \$150.00        | \$450.00        |
|       |                                                                                                                                                                                                                                                                                              |         | <b>Subtotal</b> | <b>\$450.00</b> |

**Complaint: REPLACE ENGINE FAN BLADE****Cause:** Customer request

|       |                                                                                                                          |         |                 |                 |
|-------|--------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVE AND REPLACE FAN BLADE, TORQUE MOUNTING<br>NUTS. - Completed: 12/15/2025 | 0.50000 | \$150.00        | \$75.00         |
| Parts | FAN BLADE                                                                                                                | 1.00000 | \$198.69        | \$198.69        |
|       |                                                                                                                          |         | <b>Subtotal</b> | <b>\$273.69</b> |

**Complaint: CVIP - TANDEM TRACTOR - WHEELS OFF****Cause:** Customer request

|       |                                                                                                                         |         |                 |                 |
|-------|-------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / PERFORM CVIP INSPECTION. MAKE LIST OF ALL REPAIRS. -<br>Completed: 12/15/2025 | 3.66660 | \$150.00        | \$549.99        |
|       |                                                                                                                         |         | <b>Subtotal</b> | <b>\$549.99</b> |

**Complaint: REPLACE HARMONIC BALANCER - RADIATOR REMOVED****Cause:** Customer request

|       |                                                                                                               |         |                 |                   |
|-------|---------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / PAINT AND INSTALL NEW HARMONIC BALANCER. -<br>Completed: 12/15/2025 | 1.00000 | \$150.00        | \$150.00          |
| Parts | PDI Cummins ISX   X15 Crankshaft Damper                                                                       | 1.00000 | \$1,157.63      | \$1,157.63        |
|       |                                                                                                               |         | <b>Subtotal</b> | <b>\$1,307.63</b> |

**Complaint: BRAKE JOB- ON NEEDED WHEELS- 5 DRUMS 3 SHOES****Cause:** Customer request

|       |                                                                                                                                                                                         |         |                 |                   |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / JACK UP UNIT AND PUT ON STANDS, REMOVE WHEELS, DRUMS AND SHOES. REPLACE ALL BRAKE SHOES AND DRUMS ON THE DRIVE AXLES. - Completed: 11/14/2025 | 4.00000 | \$150.00        | \$600.00          |
| Parts | BRAKE DRUM-16.50X6.00 10-HOLE 11.25 BC 8.78 PILOT                                                                                                                                       | 2.00000 | \$336.91        | \$673.82          |
| Parts | 4515 Q NEW BRAKE SHOE KIT W/HRDWRE                                                                                                                                                      | 3.00000 | \$101.43        | \$304.29          |
| Parts | BRAKE DRUM-16.50X7.00 10-HOLE 11.25 BC 8.78 PILOT                                                                                                                                       | 3.00000 | \$167.62        | \$502.86          |
|       |                                                                                                                                                                                         |         | <b>Subtotal</b> | <b>\$2,080.97</b> |

**Complaint:** WHEEL SEAL - AXLE 2 RH

**Cause:** Customer request

|       |                                                                                                                                                                                                                                                                    |         |                 |                 |
|-------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVE HUB, DISASSEMBLE HUB AND WASH ALL COMPONENTS. INSPECT COMPONENTS AND REASSEMBLE WITH NEW SEAL. REINSTALL HUB AND SET UP. REINSTALL ALL COMPONENTS CHECK OIL LEVEL AND TOP UP AS REQUIRED. - Completed: 11/12/2025 | 2.50000 | \$150.00        | \$375.00        |
| Parts | 392-9131 WHEEL SEAL 3 YEAR WARR                                                                                                                                                                                                                                    | 1.00000 | \$59.84         | \$59.84         |
| Parts | AXLE GASKET 5/8HOLE                                                                                                                                                                                                                                                | 1.00000 | \$5.67          | \$5.67          |
| Parts | SYN 75W90 GEAR OIL                                                                                                                                                                                                                                                 | 2.00000 | \$16.57         | \$33.14         |
|       |                                                                                                                                                                                                                                                                    |         | <b>Subtotal</b> | <b>\$473.65</b> |

**Complaint:** ELETRIC HORN N/W

**Cause:** .

(Inspection)

|       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |         |                 |                 |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Accessories / Horn / INSTALLED NEW HORN AND FOUND IT STILL WASN'T WORKING. CHECKED FUSE PANEL FOR A BLOWN FUSE, FOUND THEY WERE GOOD. FOUND POWER GOING TO THE FUSE, CHECKED HORN RELAY AND TESTED FOR POWER GOING TO 30 PORT AND 86 PORT. CHECKED FOR CONTINUITY FROM THE 85 PORT TO THE STEERING WHEEL WIRE, NO CONTINUITY. USED A JUMPER WIRE FROM THE 87 PORT TO THE 30 PORT, HORN TURNED ON. TESTED FOR CONTINUITY FROM THE RELAY TO THE CONNECTOR BELOW THE STEERING COLUMN, POWER WAS GOING THROUGH. TESTED FROM THE OTHER CONNECTOR UPTO THE STEERINGH WHEEL, FOUND POWER GOING THOUGH. FOUND THE WIRE HAD A BAD CONNECTION IN THE CONNECTOR. FIXED THE CONNECTION AND TESTED. GOOD AT THIS TIME. - Completed: 11/18/2025 | 2.00000 | \$150.00        | \$300.00        |
| Parts | HORN - ELECTRIC, SINGLE, BRACKET, HIGH                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 1.00000 | \$61.73         | \$61.73         |
|       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |         | <b>Subtotal</b> | <b>\$361.73</b> |

**Complaint:** BRAKE POT - AXLE 3 RH

**Cause:** Customer request

|       |                                                                                                                                                                                                                                                                                                                                              |         |          |          |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|----------|----------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / THE BACK NUTS WERE SEIZED ON, HAD TO USED HEAT TO HELP REMOVE. REMOVE THE OLD BRAKE POT AND SWAP ALL FITTINGS. CUT THE PUSH ROD TO LENGTH AND CLOCK IT SO THE FITTINGS CLEAR THE DRIVESHAFT. FOUND THE PARKING LINE WAS RUBBING THROUGH. REMOVED OLD LINE. CUT NEW ONE TO LENGTH AND INSTALLED NEW | 2.00000 | \$150.00 | \$300.00 |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|----------|----------|

FITTINGS. INSTALL ON CHASSIS AND HOOK UP AIR LINES, ADJUST AND TEST  
BRAKE OPERATION. ALL GOOD AT THIS TIME. - Completed: 11/14/2025

|       |                                     |         |                 |                 |
|-------|-------------------------------------|---------|-----------------|-----------------|
| Parts | SPRING BRAKE LS WELDED CLEVIS 2.25" | 1.00000 | \$122.82        | \$122.82        |
| Parts | 3/8"NPT-3/8 A/B FITTING             | 2.00000 | \$9.26          | \$18.52         |
| Parts | ARCTIC HOSE 3/8" AIR BRAKE          | 2.00000 | \$2.36          | \$4.72          |
|       |                                     |         | <b>Subtotal</b> | <b>\$446.06</b> |

**Complaint:** DIFF YOKE LOOSE-AXLE 2

**Cause:** .

(Inspection)

|       |                                                                                                                                                                |         |                 |                 |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / DROPPED THE DRIVELINE, REMOVED OLD YOKE NUT.<br>INSTALLED NEW NUT AND REINSTALLED DRIVELINE. - Completed: 11/17/2025 | 2.00000 | \$150.00        | \$300.00        |
| Parts | SHAFT NUT                                                                                                                                                      | 1.00000 | \$33.03         | \$33.03         |
| Parts | DRIVE LINE WASHER                                                                                                                                              | 1.00000 | \$9.03          | \$9.03          |
| Parts | U-JOINT STRAP KIT SPL 250                                                                                                                                      | 1.00000 | \$32.93         | \$32.93         |
|       |                                                                                                                                                                |         | <b>Subtotal</b> | <b>\$374.99</b> |

**Complaint:** REPLACE U JOINT- AFTER STEADY BEARING

**Cause:** Customer request

|       |                                                                                                                                                                    |         |                 |                 |
|-------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVED THE DRIVESHAFT AND INSTALL NEW U JOINT.<br>REINSTALL AL COMPONENTS AND GREASE DRIVELINE. - Completed: 11/14/2025 | 2.50000 | \$150.00        | \$375.00        |
| Parts | U-JOINT STRAP KIT SPL 250                                                                                                                                          | 1.00000 | \$32.93         | \$32.93         |
| Parts | KIT-UJOINT SPL250                                                                                                                                                  | 1.00000 | \$269.36        | \$269.36        |
|       |                                                                                                                                                                    |         | <b>Subtotal</b> | <b>\$677.29</b> |

**Complaint:** REPLACE TIE ROD ENDS

**Cause:** Customer request

|       |                                                                                                                                                                                                                                                                   |         |                 |                 |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / THE TAPERED ENDS WERE SEIZED IN. HAD TO USE HEAT<br>AND HAMMER BOTH TIE ROD ENDS OUT. REMOVE THE TIE ROD, REMOVE<br>BOTH ENDS AND INSTALL NEW. REINSTALL TIE ROD AND SET TOE TO 1/8'<br>TOE IN. - Completed: 11/13/2025 | 3.00000 | \$150.00        | \$450.00        |
| Parts | TIE ROD END L.H.                                                                                                                                                                                                                                                  | 1.00000 | \$69.46         | \$69.46         |
| Parts | TIE ROD END R.H.                                                                                                                                                                                                                                                  | 1.00000 | \$69.46         | \$69.46         |
|       |                                                                                                                                                                                                                                                                   |         | <b>Subtotal</b> | <b>\$588.92</b> |

**Complaint:** AIR LEAK- AIR TANK DRAIN

**Cause:** Customer request

|       |                                                                                      |         |                 |                |
|-------|--------------------------------------------------------------------------------------|---------|-----------------|----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REPLACE DRAIN COCK - Completed: 11/12/2025 | 0.50000 | \$150.00        | \$75.00        |
|       |                                                                                      |         | <b>Subtotal</b> | <b>\$75.00</b> |

**Complaint: REPLACE STEERING SHAFT U JOINTS****Cause:** Customer request

|       |                                                                                                                                                                                                   |         |                 |                 |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / REMOVE THE STEERING SHAFT. REPLACE BOTH STEER<br>SHAFT U JOINTS. REINSTALL SHAFT AND CHECK OPERATION. ALL GOOD AT<br>THIS TIME. - Completed: 11/17/2025 | 2.00000 | \$150.00        | \$300.00        |
| Parts | UNIVERSAL JOINT                                                                                                                                                                                   | 2.00000 | \$39.09         | \$78.18         |
|       |                                                                                                                                                                                                   |         | <b>Subtotal</b> | <b>\$378.18</b> |

**Complaint: REPLACE TURBO AND MANIFOLD CENTER SECTION- PARTS****Cause:** .

(Inspection)

|       |                                                                                                                                                                                         |         |                 |                   |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / POUND THE END SECTIONS OUT OF THE MANIFOLD,<br>REPLACE THE SEALS AND INSTALL THE ENDS INTO THE NEW CENTER<br>SECTION. - Completed: 12/15/2025 | 1.00000 | \$150.00        | \$150.00          |
| Parts | CLAMP-V BAND                                                                                                                                                                            | 1.00000 | \$118.31        | \$118.31          |
| Parts | MANIFOLD-EXHAUST                                                                                                                                                                        | 1.00000 | \$1,394.32      | \$1,394.32        |
| Parts | TURBO, NEW W/ACT                                                                                                                                                                        | 1.00000 | \$6,594.50      | \$6,594.50        |
|       |                                                                                                                                                                                         |         | <b>Subtotal</b> | <b>\$8,257.13</b> |

**Complaint: POLISH CRANKSHAFT****Cause:** Customer request

|       |                                                                                                                    |         |                 |                 |
|-------|--------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / POLISH ALL ROD AND MAIN JOURNALS AS REQUIRED. -<br>Completed: 12/15/2025 | 3.50000 | \$150.00        | \$525.00        |
|       |                                                                                                                    |         | <b>Subtotal</b> | <b>\$525.00</b> |

**Complaint: WASH AND ROAD TEST****Cause:** Customer request

|       |                                                                                                                                                                                                         |         |                 |                 |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-----------------|
| Labor | <b>Correction:</b><br>Chassis / Chassis / WASH DOWN ALL EVIDENCE OF THE REPAIR, TAKE UNIT ON<br>TEST DRIVE AND RETURN TO THE SHOP TO PERFORM A CHECKOVER, GOOD<br>AT THIS TIME. - Completed: 12/15/2025 | 1.50000 | \$150.00        | \$225.00        |
|       |                                                                                                                                                                                                         |         | <b>Subtotal</b> | <b>\$225.00</b> |

|         |       |        |         |
|---------|-------|--------|---------|
| ECO     | 2.00  | \$0.06 | \$0.12  |
| EHC     | 1.00  | \$1.25 | \$1.25  |
| EHC     | 1.00  | \$0.55 | \$0.55  |
| ECO     | 5.00  | \$0.40 | \$2.00  |
| ECO FEE | 1.00  | \$0.25 | \$0.25  |
| EHC     | 48.00 | \$0.60 | \$28.80 |
| EHC     | 1.00  | \$1.25 | \$1.25  |
| EHC     | 1.00  | \$0.55 | \$0.55  |

EHC

1.00

\$1.25

\$1.25

Unit: 1 (79506310) VIN: 5KJJALBG7CPBN6888

2012 Western Star Trucks 4900

Chassis: 579,465 Kilometers

Engine: 13,365 Hours

Labor \$22,374.99

Parts \$36,373.82

Shop Supplies \$400.00

Pre-Charge Subtotal \$59,148.81

ECO \$0.12

EHC \$1.25

EHC \$0.55

ECO \$2.00

ECO FEE \$0.25

EHC \$28.80

EHC \$1.25

EHC \$0.55

EHC \$1.25

GST  
(5% of \$59,184.83) \$2,959.24

Total \$62,144.07


Payments &amp; Credits \$0.00

Balance Due \$62,144.07

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Date: \_\_\_\_\_



INVOICE  
# 7228

2191972 AB Ltd.  
Phone: 403-887-8819  
Box 211, Leslieville, AB T0M 1H0  
GST #794837476  
stephanmonfette77@gmail.com

NAME  
Heavy Truck Repair Ltd.

ADDRESS

Robert's Heavy Services

DATE

May 20/25

TELEPHONE NO.

CHARGE TO

PURCHASE DATE

SELLING DEALER

PURCHASE ORDER NO.

MAKE

YEAR

MODEL

MOTOR NUMBER

HOUR READING

SERIAL NUMBER

ODOMETER READING

LICENSE

CASH

CHARGE

D.R.

WARRANTY

DEPOSIT \$

SERVICE SALESMAN

OPER'N

MECH.

WARRANTY

1 Replace Clydes Brake  
and Tighten loose  
brake line

1/15

\$130.00/mis

IN THE EVENT OF A DISPUTE CONCERNING THIS WORK ORDER CUSTOMER MUST NOTIFY SERVICE DEPT. WITHIN 15 DAYS OF COMPLETION OF WORK SPECIFYING THE NATURE OF DISPUTE AND AMOUNT UNDER DISPUTE. WE ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE OF OR TO YOUR VEHICLE OR CONTENTS DUE TO FIRE, THEFT, VANDALISM OR SIMILAR PERILS.

TERMS: ALL INVOICES PAYABLE ON THE 10TH OF THE MONTH FOLLOWING PURCHASE. INTEREST AT 2% PER MO. CHARGED ON ALL OVERDUE ACCOUNTS.

I (WE) HEREBY AUTHORIZE THE REPAIR WORK HEREINAFTER SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIALS.

I

N

X

OUT

HAVING AUTHORIZED REPAIRS TO MY (OUR) MOTOR VEHICLE I, WE HEREBY ACKNOWLEDGE MY (OUR) INDEBTEDNESS TO STEVE'S HEAVY TRUCK REPAIR LTD.

IN THE SUM OF: \$ 195.38

BEING ALL OR

THE BALANCE OF THE ACCOUNT FOR SAID WORK.

ESTIMATES ARE FOR LABOUR ONLY

TOTAL MATERIAL

DATE

X

SIGNATURE

130.00

56.08

9.30


195.38

THIS IS THE ONLY ITEMIZED ACCOUNT RENDERED. PLEASE PAY ON INVOICE. STATEMENT WILL NOT BE ISSUED.

PAY THIS \$

TOTAL AMOUNT

2191972 AB Ltd.  
Phone: 403-887-8819  
Box 211, Leslieville, AB T0M 1H0  
GST #794837476  
stephanemonfette77@gmail.com



Roberts Energy Services



**PURCHASE ORDER NO.**

**LICENSE**

**ENSE**

**YEAR**

MOTOR NUMBER

## HOUR READING

**WARRANTY**

CHARGE

**CASH**

DEPOSIT \$

## WARRANTY

R.R. and rebuild Fa  
Hv6

**OPER'N**

5/13/00

IN THE EVENT OF A DISPUTE CONCERNING THIS WORK ORDER CUSTOMER MUST NOTIFY SERVICE DEPT. WITHIN 15 DAYS OF COMPLETION OF WORK SPECIFYING THE NATURE OF DISPUTE AND AMOUNT UNDER DISPUTE. WE ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE OF OR TO YOUR VEHICLE OR CONTENTS DUE TO FIRE, THEFT, VANDALISM OR SIMILAR PERILS.

TERMS: ALL INVOICES PAYABLE ON THE 10TH OF THE MONTH FOLLOWING PURCHASE. INTEREST AT 2% PER MO. CHARGED ON ALL OVERDUE ACCOUNTS.

1 (WE) HEREBY AUTHORIZE THE REPAIR WORK HEREINAFTER SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIALS.

(WE) HEREBY AUTHORIZE THE REPAIR WORK HEREINAFTER SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIALS.

|                                                                                                                                              |        |              |                  |
|----------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------|------------------|
| HAVING AUTHORIZED REPAIRS TO MY (OUR) MOTOR VEHICLE, I, WE<br>HEREBY ACKNOWLEDGE MY (OUR) INDEBTEDNESS TO STEVE'S HEAVY<br>TRUCK REPAIR LTD. |        | 1683.47      | IN THE SUM OF \$ |
| TOTAL SHOP                                                                                                                                   | LABOUR | BEING ALL OR |                  |
| SUB LET LABOUR                                                                                                                               |        |              |                  |

BEING ALL OR

£15891

                x

TRUCK  
IN THE  
THE B  
DATE

TOTAL MATERIAL

**ESTIMATES ARE FOR LABOUR ONLY**

108330

|                 |  |
|-----------------|--|
| PAY THIS        |  |
| TOTAL AMOUNT \$ |  |

THIS IS THE ONLY ITEMIZED ACCOUNT RENDERED. PLEASE PAY ON INVOICE. STATEMENT WILL NOT BE ISSUED.

168347

£108

0550

5000

**WHITE: BILLING COPY**

**GOLDEN ROD: SHOP COPY**

**PINK: OFFICE COPY**

CANARY: NUMERICAL COPY

**WHITE: BILLING COPY**

