

BIG WEST MACHINE & WELDING

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

N37-1
NOV

INVOICE

Invoice No.: 36815
Date: 02/24/26
Page: 1

PT44

Sold to:
Newforce Energy Services

Ship to:

Box 7576
Drayton Valley, Alberta T7A 1S7

Ordered By:
PO Number: 026201
Unit Number: PT44
Location:
Work Order No.:
Contractor: 403-895-3997



cwb certification
C5AW471

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
0.25	Hours	Manufacture New Hitch Receiver Assembly	G	140.00	35.00
3.25	Hours	Plasma Hourly Rate	G	120.00	390.00
		Regular Hourly Rate			
0.50	Sq Ft	Material	G	37.38	18.69
3.00	Foot	1/2" HR Plate 44W	G	17.22	51.66
1.00	Feet	3" x 3" x .250" HSS	G	9.45	9.45
		2 1/2" X 2 1/2" .238 Wall Hitch Tube	G		12.62
		Shop Supplies			
		Subtotal:			517.42
		G - GST 5%			
		GST/HST			25.86
5248					
ALL TERMS ARE NET 30 on approved Charge Accounts At 2% Per Month - 24% Per Annum					
Comment:					
Total Amount					543.28

BIG WEST MACHINE & WELDING

2022 LTD.

INVOICE

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

Invoice No.: 34106
Date: 03/25/25
Page: 1

Sold to:
Newforce Energy Services

Ship to:

Box 7576
Drayton Valley, Alberta T7A 1S7

Ordered By: Derek
PO Number: 035218
Unit Number: -
Location: -
Work Order No.: -
Contractor: -



Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
18.25	Hours	Repair Cylinder - Install Correct Seal Kit - Stamped seal kit # on gland - Manufacture & install new cylinder eye - Test for leaks Regular Hourly Rate	G	120.00	2,190.00
5.00	Inches	Material 8" 1040 HR Rd	G	35.00	175.00
1.50	Inches	4 1/2" 1040 HR RD	G	13.18	19.77
		Shop Supplies	G		59.62
		Subtotal:			2,444.39
		G - GST 5% GST/HST			122.22
					5248
ALL TERMS ARE NET 30 on approved Charge Accounts At 2% Per Month - 24% Per Annum				Total Amount	2,586.61
Comment:					

BIG WEST MACHINE & WELDING

2022 LTD.

INVOICE

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

Invoice No.: 34364
Date: 03/20/25
Page: 1

PT44

Sold to:
Newforce Energy Services

Box 7576
Drayton Valley, Alberta T7A 1S7

Ship to:

Ordered By: Jason
PO Number: 035172
Unit Number: PT44
Location: -
Work Order No.: -
Contractor: -



cwbcertification
CWB 035172

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
3.75	Hours	Rebuild Picker Cylinder As Required Regular Hourly Rate	G	120.00	450.00
		Subtotal:			450.00
		G - GST 5% GST/HST			22.50
					5248
ALL TERMS ARE NET 30 on approved Charge Accounts At 2% Per Month - 24% Per Annum					
Comment:					
Total Amount					472.50



99 GOLDEN SPIKE RD. BOX 5000
 SPRUCE GROVE ALBERTA T7X 2Y3
 Phone: (780) 962-3000 • FAX: (780) 962-3068 • 1-800-222-6444
 service@zenderford.com • www.zenderford.com
 M-F 7:00AM - 6:00PM
 SATURDAY 9:00AM - 1:00PM

PT44

SO # 837066

SERVICE ORDER CUSTOMER COPY



Printed 02/27/2023 4:06:55 PM

User 4086 Page 1

Customer No
 NEWFORCE ENERGY SERVICES LTD
 BOX 7576
 DRAYTON VALLEY, AB T7A 1S7

Home **Bus** (780) 514-7882
Cell **Today**
Email

Term CASH

Advisor	Charlie English	Promised	02/27/2023 5:00 PM	Tag
Shop	S1	Opened	02/27/2023 8:42 AM	Location
Priority	80	Cashiered		PO # 1

License No	Odometer In	Odometer Out	InServ Date	Stock No
	142721	142730	06/13/2019	97789
Year	Make	Model	Model No	Colour
2019	FORD	SUPER DUTY F-550 DRW X5H		1 OXFORD
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FD0X5HT1KEE48644	01		06/13/2019	
Engine Size	6.7L 4V OHV POWER STROKE V8			Fleet #

Request	Description	Job	CSR	Status
6-0CT	CHECK AND ADVISE- TURBO HAVING PROBLEMS, AND CODES ARE COMING UP. VEHICLE HAS BEEN DELETED	1	4086	Original
Labour	Description		Type	Amount
6-0CT	CHECK AND ADVISE- TURBO HAVING PROBLEMS, AND CODES ARE COMING UP. VEHICLE HAS BEEN DELETED		CVW	244.43
Rate	162.95			
Technician	1597 -			
Correction	Insp for cust concern and found no dtc's in system, road tested truck and found turbo is functioning good with no abnormal noises, insp air intake and found air filter new and air box and tube have been cleaning, insp intake to turbo and found lots off mud and oil mixed in intake, checked blow by and found engine has lots of blowby, advisor contacted cust for more information an found code that was present was p259f for vgt performance and said they were concerned with the oil in the intake, unable to verify concern with turbo or dtc. cust also advised that they have replaced the crankcase filter ruling that out as source of blowby, oil inside the intake is due to excessive blowby caused from the engine being dusted with dirt and causing ring and cylinder damage, a manual compression test is recommend at this time.			
		Parts Total	0.00	
		Labour Total	244.43	
		Request Sub-total	244.43	

Request	Description	Job	CSR	Status
RECALL	recall 21B04	2	4086	Original
Labour	Description		Type	Amount
21B04A	Inspect Vehicle, Inspection Pass (Vehicle not equipped with Second Unit Body per Attachment V Dealer Information Sheet, Brackets not required) N59 CC 01 PART 5005		W	
Technician	1597 -			
Cause	21B04A			
Correction	Inspect Vehicle, Inspection Pass (Vehicle not equipped with Second Unit Body per Attachment V Dealer Information Sheet, Brackets not required) 21B04A 0.2 Hours			
		Parts Total	0.00	
		Labour Total	0.00	
		Request Sub-total	0.00	



Mon-Thurs 7:00AM - 7:00PM
 Fri 7:00AM - 6:00PM
 Saturday 9:00AM - 5:00PM
 NO APPOINTMENT NEEDED
 WHERE YOU WAIT SERVICE
 ALL MAKES AND MODEL-EXPRESS OIL
 CHANGES

You agree by your signature below that Zender Ford Sales Ltd. has performed the agreed upon work at the agreed upon price and that all the work has been completed to your satisfaction. You agree by your signature that Zender Ford Sales Ltd. May retain any of your personal information we presently have on file and/or any of your personal information on this form. You acknowledge and agree that we collect/use such personal information in order to provide services to you and or to communicate with you including marketing communications. We provide this personal and transactional information to Ford Motor Company of Canada, limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3678). We may also share this information with (a) our computing and marketing service providers (b) others as may be specifically allowed by law.

Customer Signature _____

DATE		☐ YES ☐ NO ☐ YES ☐ NO I HAVE NOT BEEN A MEMBER OF THE COMPANY FOR THE YEAR ENDING 31/12/2000.		ALL PARTS MUST BE PAID BY THE 15TH OF JANUARY 2001. IF YOU HAVE NOT PAID BY THE 15TH OF JANUARY 2001, YOUR ACCOUNT WILL BE FORWARDED TO THE DEBT COLLECTIONS DEPARTMENT.		CHRON CARD ☐ CASH ☐ CREDIT ☐ CHANGE ☐		PLEASE PAY THIS AMOUNT SALES TAX (VAT & PST) LESS INSURANCE TOTAL CHARGES MISC. CHARGES SUBLET AMOUNT GAS, OIL, TUBE PARTS AMOUNT LABOUR AMOUNT TOTALS	
------	--	---	--	---	--	--	--	---	--

SECTION	OPCODE	TECH	TYPE	LIST	NET	TOTAL
A	300 CHECK AND ADVISE FOR TRUCK SURGING BETWEEN 2500-3000 RPM					
	PARTS: 0.00	LABOR: 374.88	OTHER: 0.00	374.88		374.88
	169984 CK & REPORT ON TRUCK SURGING UNDER LOAD, CONFIRM, CK CODES, CK OASIS, NO CODES, NO 98MS OR TSBS, PERFORM INSPECTION, FOUND EGR VACUUM SOLENOID CONNECTED, DISCONNECT AND ROAD TEST, CONCERN STILL PRESENT, MAKE & INSTALL BLOCK OFF PLATE FOR EGR TO INTAKE PIPE, ROAD TEST, CONCERN STILL PRESENT, MONITOR PID DATA OVER SEVERAL ROAD TESTS FOUND ESR & VGT OSCILLATING UNDER HEAVY LOAD, PERFORM UNDER CARRIAGE INSPECTION FOUND, NO MUFFLER INSTALLED ON DELETE PIPE, RECOMMEND INSTALLING DELETE PIPE AND RETEST AS BACK PRESSURE CAN EFFECT TURBO OPERATION ON 450-550 TURBO, INSPECTION FOUND EXCESSIVE ENGINE OIL LEAK FROM UPPER OIL PAN AND CCV PLUGGED, RECOMMEND REPLACE CCV AND RESEAL UPPER ENGINE PAN, ... 2.5HR 8240***					
B	MULTI-POINT INSPECTION					
	PARTS: 0.00	LABOR: 0.00	OTHER: 0.00	0.00		0.00
	169984 PERFORM MULTI-POINT VEHICLE INSPECTION, NEEDS WINDSHIELD, UPPER OIL PAN, CCV, EXHAUST MUFFLER, UNEVEN PAD WEAR ON FRONT BRAKES (INNER PADS), TRACK BAR OIL SOADED AND LOOSE					
C**	REPLACE PLUGGED CCV FILTER					
	REF REPLACE PLUGGED CCV FILTER					
	1 LC32*6A785.C SEPARATOR ASY - OIL			364.03	380.39	224.93
	PARTS: 360.39	LABOR: 224.93	OTHER: 0.00	360.39		224.93
	109984 R&R CLOGGED CCV, RETEST GOOD, ... 1.5HR 8240***					
D**	RESEAL UPPER OIL PAN *LEAKING BAD /W PTO					
	REF RESEAL UPPER OIL PAN *LEAKING BAD /W PTO					
	CXO*10W30*DCSD OIL - ENGINE			2774.08		2774.08
	ENOL ENOIL					
	W715618*S437 NUT			0.10	0.10	1.30
	E4HZ*4A264*A RETAINER			1.00	1.00	4.00
	W709771*S440 NUT - ADJUSTING SCRE			2.11	2.11	8.44
	CVC*13*G ANTI-FREEZE			5.52	5.52	11.04
	W711336*S441 NUT			30.02	27.02	54.04
	F1HZ*4N272*A BOLT			2.14	2.14	12.84
	ZC*31*B CLEANER - METAL SURF			2.02	2.02	16.16
				10.44	9.40	18.80
	TOTAL LINE A:			374.88		374.88
	TOTAL LINE B:			0.00		0.00
	TOTAL LINE C:			364.03	380.39	224.93
	TOTAL LINE D:			2774.08		2774.08

09-23 12FE824		17-01 28FE824					
13JUN19 D		18:00 15FE824		CASH		29FE824	
DEC DATE:		PROD DATE:		WARRANT EXP:		PROMISED:	
WHITE		19		FORD F550		1FDOXGHT1KEE4B844	
CDJ7892		168984		PT44			
COLOUR:		YEAR:		MARK/MODEL:		VIN:	
LICENCE:		ODOMETER IN COUNT:		TAG:			
OPTIONS:		W-COMP:W DLR:B8233 ENG:6.7 Liter		READY			

SERVICE ADVISOR: 8255 BRANDON BOOKES

1011 For 1-855-841-4000
 e-mail: sales@paulsnyder.com
 Web site: www.paulsnyder.com

WALSH JOHN E
1000 1/2 N 10TH ST
DENVER CO 80202



**DRAYTON VALLEY FORD
SALES LTD.
P.O. Box 6389 • 6214 Power Centre Blvd.
DRAYTON VALLEY, ALBERTA T7A 1H8**

BOX 7576
 DRAYTON VALLEY, AB T7A 1S7
 Home: 780-514-8502 Cell: 780-514-8502 Email:

NEWFORCE ENERGY SERVICES LTD

Invoice No: 198791

CUSTOMER NUMBER:

BIG WEST MACHINE & WELDING

2022 LTD.

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

INVOICE

Invoice No.: 31501
Date: 02/15/24
Page: 1

PT44

Sold to:
Newforce Energy Services

Box 7578
Drayton Valley, Alberta T7A 1S7

Ship to:

Ordered By:
PO Number: 40340
Unit Number: PT44
Location:
Work Order No.:
Contractor:



cwbcertification
CSA W11.1

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
1	Hours	Straighten Bumper As Required Regular Hourly Rate	G	120.00	120.00
		Subtotal:			120.00
		G - GST 5% GST/HST			6.00
					5248
Term:				Total Amount	126.00
Comment:					

BIG WEST MACHINE & WELDING

2022 LTD.

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

INVOICE

Invoice No.: 31132
Date: 12/19/23
Page: 1

PT44

Sold to:
Newforce Energy Services

Ship to:

Box 7576
Drayton Valley, Alberta T7A 1S7

Ordered By:
PO Number: 40092
Unit Number: PT44
Location:
Work Order No.:
Contractor: 780-898-6486



cwbcertification
CSA W47.1

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
2.5	Hours	Remove & Replace Ball Joints Regular Hourly Rate	G	120.00	300.00
		Subtotal:			300.00
		G - GST 5% GST/HST			15.00
5248					
Term:				Total Amount	315.00
Comment:					



Big West Machine & Welding 2022 Ltd. INVOICE

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1K5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

Invoice No.: 39849
Date: 07/26/23
Page: 1

PT44

Sold to:
Newforce Energy Services

Ship to:

Ordered By:
PO Number: 32944
Unit Number: PT44
Location:
Work Order No.:
Contractor:

Box 7570
Drayton Valley, Alberta T7A 1S7



cwbcertification
CSA W17.1

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
2.0	Hours	Rebuild Extension Cylinder	G	120.00	240.00
1.5	Hour	Regular Hourly Rate	G	65.00	97.50
		Helper Hourly Rate			
		Subtotal:			337.50
		G - GST 5%			
		GST/HST			16.88
					5248
Term:				Total Amount	354.38
Comment:					



Westpoint Cutting and Design LTD. INVOICE

112-10506 Fulton Dr.
Acheson, Alberta T7X 6A1
Canada

Invoice No.: 5939
Date: 03/28/2023
Ship Date: 03/28/2023
Page: 1
Re: Order No. 32185

Sold to:

New Force Energy Services Ltd.

5710 57 Ave
Drayton Valley, AB T7A 1S7

Ship to:

New Force Energy Services Ltd.

5710 57 Ave
Drayton Valley, AB T7A 1S7

DT44

Business No.: 70068 8096

Quantity	Description	Tax	Unit Price	Amount
1	8" custom sides Design, supply, cut, form, weld and paint Hardware	G	2,944.00	2,944.00
	Subtotal:			2,944.00
	G - GST 5% GST/HST			147.20
Shipped By: Tracking Number:				Total Amount 3,091.20
Terms: Net 30, Due 04/27/2023,				Amount Paid 0.00
Comment: Thank-you!				Amount Owning 3,091.20
Sold By:				

✓ 5248



Big West Machine & Welding 2022 Ltd. INVOICE

Box 5341
5524 - 53 Avenue
Drayton Valley, Alberta T7A 1R5
Canada
Tel: (780) 514-3380
Fax: (780) 514-3381

Invoice No.: 28529
Date: 10/26/22
Page: 1

PT44

Sold to:
Newforce Energy Services

Box 7576
Drayton Valley, Alberta T7A 1S7

Ship to:

Ordered By:
PO Number: 36329
Unit Number: PT44
Location:
Work Order No.:
Contractor:



cwbcertification
CSA W47.1

Business No.: 72251 2704 RT0001

Quantity	Unit	Description	Tax	Unit Price	Amount
3.00	Hours	Manufacture Double Hinge & Install On Supplied 5th Wheel Plate Regular Hourly Rate	G	120.000	360.00
2.75	Feet	Material 3/4" 1018 CR RD	G	9.490	26.10
2.75	Feet	1" Sched 160 Pipe	G	15.435	42.45
		Subtotal:			428.55
		G - GST 5% GST/HST			21.43
Term:					
Comment:					
Total Amount					449.98

5248