

N38-1
NDV



Hudytech LTD.
 [Mailing] 22 Springwood Drive NE, Slave Lake AB
 T0G2A2
 [Shop Location] 921 8th Street NW - Slave Lake AB
 T0G2A4
 Slave Lake, AB T0G 2A2
 (780) 660-5158
 service@hudytech.com
 GST# 76317 2806 RT0001

Invoice #5616

Created: 02/23/2026 at 9:11AM
 Invoiced: 02/26/2026 at 10:25AM
 Payment Term: Net 10
 Payment Due: 03/08/2026
 Service Writer: Beverly Beaver

JNT LUMAWIG

2012 Peterbilt 367 Base (Blue, #907)
 VIN: 1XPTDW9X1CD143944
 License Plate: U-39182
 Mileage In: 1,277,951 km
 Mileage Out: 1,277,951 km

Customer Comments	Recommendations
REAR REPLACE ENGINE MOUNTS	SUBLET REPAIR DYNAMIC DIESEL INVOICE 1086

ENGINE MOUNTS R/R + PROGRESSIVE DAMAGE

-removed exhaust section behind turbo to access passenger engine mount
 -lift engine and removed arm bracket off engine then removed the mount
 -Then installed new bracket and mount (converted to 4 bolt engine mounts)
 -the proceeded to driver side, moved wires and cables with bungy strap to gain access to driver side mounts)
 -removed and installed new mount and bracket
 -lined up mounting bolts (was a bit of a struggle getting the driver side to line up) (blue lock tight and 200ft lb torque was done on mounting bolts)
 -after job was done, work area was cleaned
 D/D*
 Remove and replace fan blade, Removed multiple brackets to access and preform repair . Remove and install new crank case filter . Old filter very plugged . Cleaned all intake , charge air and exhaust piping from oil residue . Remove air filter and blow out filter with compressed air .Suggest air filter be changed . Installed all piping , rad mounts and hood cables . Check engine oil . Found engine oil very low . Topped off oil (10 L)
 Hooked up laptop to read codes , found active crank case code . Crank case and exhaust pressure readings very erratic and not in spec .Suggest changing both sensors. Tried clearing codes , crank case code still active .

Description	Price	QTY	HRS	Subtotal
Labor: ENGINE MOUNT RR FAN BLADE -removed exhaust section behind turbo to access passenger engine mount -lift engine and removed arm bracket off engine then removed the mount -Then installed new bracket and mount (converted to 4 bolt engine mounts) -the proceeded to driver side, moved wires and cables with bungy strap to gain access to driver side mounts) -removed and installed new mount and bracket -lined up mounting bolts (was a bit of a struggle getting the driver side to line up) (blue lock tight and 200ft lb torque was done on mounting bolts) -after job was done, work area was cleaned			8	\$1,223.20
Labor: Dynamic Diesel invoice 1086			4	\$611.60
Part: ELEMENT CRANKCASE FILTER	\$202.03	1		\$202.03
Part: 15-40 OIL	\$6.24	10		\$62.40
Shop Supplies (7%): \$128.44 GST (5%): \$111.38 Total: \$2,339.05				

EDGE

INDUSTRIAL SUPPLY INC

INVOICE
001-057519

Box 686 1401 Caribou Trail NW
Slave Lake, AB T0G 2A0
Tel # 780-849-4660

Bill To		Customer No.		Ship To		Customer No.	
JERVY LUMAWIG				JERVY LUMAWIG			
				AMO			
PG 1 OF 1							
Branch Edge Industrial - SLAVE LAKE						GST Number 768780348	
						Reference Number 001-057519	
Month/Day/Year		Writer		Order No.		Customer P.O.	
12/12/25		AMO		12/08/25 57519		JERVY	
Terms NET 30 DAYS						Ship Via SWT	
Quantity Ordered	Quantity Shipped	Back Ordered	Part Number and Description			Code	Price (List & Sell)
1	1		125 561.75638 COOLANT HOSE UPPER			TG	41.600 36.174 EA 36.17
			- 2.5" x 8.875" KW & PBILT				
1	1		125 575.1023 COOLANT RESERVOIR			TG	288.517 250.885 EA 250.89
1	1		125 561.59180 90 ELBOW COOLANT HOSE KW			TG	85.067 73.971 EA 73.97
1	1		125 561.75548 COOLANT HOSE w/ POLY			TG	30.700 26.696 EA 26.70
			- 45DEG ELBOW 2.5"ID				
1	1		377 K060637HD V-BELT L:63.78" 6PK ISX AC			TG	58.833 51.160 EA 51.16
1	1		377 K120858HD V-BELT L:85.78" 12PK HD			TG	183.146 146.525 EA 146.53
1	1		125 561.16400 CONECTOR HOSE COLD SIDE			TG	35.484 30.860 EA 30.86
16	16		326 16-834 PREMIX 50/50 RED COOLANT			TG	17.407 13.926 EA 222.82
1	1		308 996813252-001 FAN-ENGINE HS 32"TRIMMED			TG	634.817 476.110 EA 476.11
2	2		308 4962610 RECTANGULAR RING SEAL			TG	12.717 11.058 EA 22.12
1	1		308 4962606 OIL FILLER TUBE			TG	71.833 62.464 EA 62.46
1	1		308 4962608 OIL FILLER CAP			TG	71.950 58.680 EA 58.68
1	1		308 4962605 OIL FILLER CONNECTION			TG	96.400 72.390 EA 72.39
1	1		308 N4171003 RADIATOR FAN SHROUD ASSY			TG	2328.087 1959.660 EA 1959.66
1	1		FRT FREIGHT FREIGHT CHARGES			TG	51.250 EA 51.25
2	2		125 M17499 REAR MOTOR MOUNT PBILT			TG	325.150 EA 650.30
4	4		125 M5387 FLANGE BOLT 16mm-2 x 70mm			TG	19.250 15.400 EA 61.60
2	2		125 561.75639 COOLANT HUMP HOSE			TG	48.950 42.565 EA 85.13
			- 4" x 6.25" HOT SIDE				
8	8		125 561.230406 T-BOLT CLAMP 4.06"-4.38"			TG	10.404 9.047 EA 72.38
1	1		125 561.16400 CHARGE AIR COOLER HOSE			TG	35.484 30.860 EA 30.86
1	1		FRT FREIGHT FREIGHT CHARGES			TG	25.000 EA 25.00
2	2		405 073.58.6 5/8 X 6 UNF BOLT			TG	12.333 10.725 EA 21.45
			JEAN LUC P/U				
			DELIVERED TO HUDYTECH SHOP BY STEVE				
			GOODS & SERVICES TAX (CODE G)				\$224.43
Goods Received By: Please Print Name			Signature: X			SUBTOTAL 4488.49	
						TAX 224.43	
Terms: Positively no goods accepted for credit without our prior authorization and invoice number. Goods returned subject to restocking charges when supplied as ordered.						Time Prepared 13:22	
						TOTAL 4712.92	



Hudytech LTD.
[Mailing] 22 Springwood Drive NE, Slave Lake AB
T0G2A2
[Shop Location] 921 8th Street NW - Slave Lake AB
T0G2A4
Slave Lake, AB T0G 2A2
(780) 660-5158
service@hudytech.com
GST# 76317 2806 RT0001

Invoice #5452

Created: 12/04/2025 at 9:20AM
Invoiced: 12/18/2025 at 9:56AM
Payment Term: On Receipt
Payment Due: 12/18/2025
Service Writer: Beverly Beaver

JNT LUMAWIG

2012 Peterbilt 367 Base (Blue, #907)
VIN: 1XPTDW9X1CD143944
License Plate: U-39182
Mileage In: 1,273,125 km
Mileage Out: 1,273,125 km

Customer Comments

Check / repair for engine mount failure, progressive damage causing cooling and engine oil leaks present, electrical concerns

REAR ENGINE MOUNTS

Check / repair for damaged engine mounts

-Lift and support engine, support cab and remove LHS cab and engine mount. Remove and install exhaust pipe on RHS.
All bolts were loose on engine support bracket, both sides.
Cleaned all bolts and re-mount supports with loctite, torqued to spec
Replaced lower engine mounts and bolts.
Re secured all cab mounting locations, engine mount locations
Checked operations, ok

Description	HRS	Subtotal
Labor: Engine mount Day 1	8	\$1,223.20
Labor: Engine mount day 2	8	\$1,223.20
Shop Supplies (7%): \$171.25 GST (5%): \$130.88		Total: \$2,748.53

REPLACE RAD

Tow unit into shop - brakes were frozen. Used heat, and hammered brakes to release

Drain remaining coolant and disassemble rad
Remove all broken parts. Swap new rad into support frame.
Replaced any coolant and CAC hoses/clamps as needed, replaced engine fan.
Install rad and assemble. Fill with new coolant. Replaced Fan Belt. Install new surge tank.
Replaced damaged negative cable from starter to cab ground.
Replace engine oil fill neck

Air leak present - from steer axle - Needs to be addressed

Description	Price	QTY	HRS	Subtotal
Labor: Cooling module assembly and other accesories day 3			7	\$1,070.30
Part: DELO 50/50 RED COOLANT JUG	\$16.19	14		\$226.66
Part: BATTERY CABLE	\$10.00	3		\$30.00
Part: BRAKE AIR LINE 24"		1		\$0.00
Part: 1" COOLANT HOSE		3		\$0.00
Part: 1/2 AIR BRAKE ASSEMBLY	\$17.48	1		\$17.48



Hudytech LTD.
[Mailing] 22 Springwood Drive NE, Slave Lake AB
T0G2A2
[Shop Location] 921 8th Street NW - Slave Lake AB
T0G2A4
Slave Lake, AB T0G 2A2
(780) 660-5158
service@hudytech.com
GST# 76317 2806 RT0001

Invoice #5452

Created: 12/04/2025 at 9:20AM
Invoiced: 12/18/2025 at 9:56AM
Payment Term: On Receipt
Payment Due: 12/18/2025
Service Writer: Beverly Beaver

REPLACE RAD			
Part: FITTING,CONNECTOR,1/2-3/8	\$2.89	1	\$2.89
Part: Radiator Peterbilt	\$800.00	1	\$800.00
Shop Supplies (7%): \$74.92 GST (5%): \$111.11 Total: \$2,333.36			

Hudytech LTD. Terms & Conditions

Payment & Liens

Payments via e-transfer can be sent to admin@hudytech.com.
Payment is due upon vehicle pickup unless otherwise stated.
Mechanics' liens may be placed on vehicles until repairs are paid in full.
Deposits are non-refundable.

Returns & Refunds

No returns or refunds on specially ordered items or electrical parts.
Regularly stocked items may be subject to a 40% restocking fee.
No warranty is provided for used parts or customer-supplied parts, including labor performed by Hudytech LTD.

Liability & Delays

Hudytech LTD. is not responsible for loss or damage to vehicles, including loss of articles left inside, due to fire, theft, or any other cause beyond our control.
We are not responsible for delays caused by parts unavailability or supplier/transporter delays.

Repair Authorization & Estimates

Customers have the right to approve additional repairs and costs before they are performed.
If required repairs exceed the authorized estimate, we must obtain customer approval before proceeding.
All quotes/estimates are valid for 30 days.

Core Returns

All cores must be returned within 30 days of product shipment/purchase, or the core charge will be forfeited.

Vehicle Maintenance After Service

Wheel nuts and driveline straps must be re-torqued to factory specifications within 150 km of removal.
All removed parts will be recycled or disposed of accordingly.

Warranty & Tuning

Warranty is void after vehicle tuning.
Hudytech LTD. is not responsible for any issues resulting from aftermarket or custom tuning.
Standard workmanship warranty is 30 days unless otherwise specified.
All parts warranties are subject to manufacturer discretion.
Hudytech LTD. does not warranty the installation of customer-supplied parts.

This shop charges a 2% credit card processing fee.

Labor	\$3,516.70
Parts	\$1,077.03
Subtotal	\$4,593.73
Shop Supplies	\$246.17
EPA	\$0.00
GST	\$241.99
Grand Total	\$5,081.89
Paid to Date	(\$0.00)

REMAINING BALANCE	\$5,081.89
--------------------------	-------------------

Signature _____