THRIFTY AUTO SERVICE
(780) 451-6811
info@thriftyautoservice.com
15605 116 Ave NW, Edmonton, AB, Canada, T5M 3W1
Company Business/GST number:853874857rt0001

TRUCK FILE

Invoice # 4273

Against Estimate#: 13896
Created: Mar 26, 2026
Invoiced: Mar 27, 2026

COPY

DYNAMIC SCALE

2014 FORD F-250 SUPER DUTY
VIN: 1FT7W2B63**EEA95139**
Mileage: 382367 km
License Plate:

R04-1
DEC

Customer Notes

PO# 1178

Engine Oil Cooler R&R — **Authorized**

Item	Name	Description	Price	Qty/Hrs	Amount
1	Engine Oil Cooler R&R	Includes: The removal of component and all necessary components for access, time to add fluid. Does not include: System diagnosis and testing, or a vehicle road test.	$150.00	0.6	$90.00
2	918-431 - ENGINE OIL COOLER	918-431	$216.37	1	$216.37
			Amount: $306.37	Disc: $0.00	Subtotal: $306.37

5/20 Synthetic Oil Service — **Authorized**

Item	Name	Description	Price	Qty/Hrs	Amount
1	OIL-5/20P - 5/20 Castrol Full Synthetic		$11.09	7	$77.63
2	Oil-Oilct	OIL LUBE & FILTER - TRUCKS	$39.95	1	$39.95
3	OIL-RES - Oil Service Light Reset		$0.00	1	$0.00
4	hazmat	hazmat fee	$0.10	7	$0.70
5	B329 - Baldwin Oil Filter	Engine Oil Filter	$12.18	1	$12.18
6	Oil filter Hazmat		$0.55	1	$0.55
			Amount: $129.76	Disc: $0.00 Fees: $1.25	Subtotal: $131.01

THRIFTY AUTO SERVICE
(780) 451-6811
info@thriftyautoservice.com
15605 116 Ave NW, Edmonton, AB, Canada, T5M 3W1
Company Business/GST number:853874857rt0001

COPY

Invoice # 4117

Against Estimate#: 13679
Created: Feb 18, 2026
Invoiced: Feb 24, 2026

DYNAMIC SCALE

RECEIVED FEB 24 2026

2014 FORD F-250 SUPER DUTY
VIN: 1FT7W2B63EEA95139
Mileage: 378791 km
License Plate:

Wheel Alignment Adjust (Front Wheel Alignment)

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Wheel Alignment Adjust (Front Wheel Alignment)	Includes: Checking all tires for correct size, condition, and adjusting all tire pressures. Inspect steering and suspension components. Installing alignment equipment and making all necessary adjustments. Does not include: Steering sensor calibration, or a vehicle road test.	$150.00	1	$150.00

Amount: $150.00 | Disc: $0.00 | Subtotal: $150.00

Brake Pads R&R (Front, Without Dual Rear Wheels)

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Brake Pads R&R (Front, Without Dual Rear Wheels, Brake Disc/Disc'd Wheel ABS, Drive Type: RWD)	Includes: The removal of component and all necessary components for access, and cleaning component. Does not include: Brake Hydraulic System Bleed, System diagnosis and testing, or a vehicle road test.	$150.00	1	$150.00
2	WS1-154198 - WP Coated Brake Rotor	Disc Brake Rotor (Front)	$277.07	2	$554.14
3	17D1680MHF1 - Ac Delco Brake Pad Set	Disc Brake Pad Set (Front)	$199.77	1	$199.77

Amount: $903.91 | Disc: $0.00 | Subtotal: $903.91

Tie Rod R&R (One Side, Outer)

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Tie Rod R&R (, Outer, Drive Type: 4WD)	Includes: The removal of component and all necessary components for access. Does not include: System diagnosis, testing, wheel alignment, or a vehicle road test.	$150.00	0.8	$120.00
2	45A2182 - AC Delco Tie Rod - Passenger Outer Lower	45A2182	$401.21	1	$401.21

Amount: $521.21 | Disc: $0.00 | Subtotal: $521.21

Wheel Bearing Hub Seals R&R (Both Sides, Front, Without Dual Rear Wheels)

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Wheel Bearing removal (Both Sides, Front, With Dual Rear Wheels, Drive Type: 4WD)	Includes: The removal of component and all necessary components for access. Does not include: System diagnosis, testing, wheel alignment, or a vehicle road test.	$150.00	3.5	$525.00

THRIFTY AUTO SERVICE
(780) 451-6811
info@thriftyautoservice.com
15605 116 Ave NW, Edmonton, AB, Canada, T5M 3W1
Company Business/GST number:853874857rt0001

Invoice # 4117

Against Estimate#: 13679
Created: Feb 18, 2026
Invoiced: Feb 24, 2026

2	5c3z 3254c - Motorcraft Hub Seal Kit	$224.54	2	$449.08
3	5c3z 3249 BA - Hub universal joint	$94.26	2	$188.52
		Amount: $1,162.60	Disc: $0.00	Subtotal: $1,162.60

Diagnostic / Inspection **Authorized**

Item	Name	Description	Price	Qty/Hrs	Amount
1	Labor	Diagnose four wheel drive not working	$150.00	1	$150.00
			Amount: $150.00	Disc: $0.00	Subtotal: $150.00

Date and Time	Receipt No	Payment Method	Amount
Feb 24, 2026 1:50 pm	13168	Visa	$3,084.61

Service Amount	**$2,887.72**
Part	$1,792.72
Labor	$1,095.00
Total RO Fees	
Shop supplies	$50.00
Subtotal	**$2,937.72**
Taxes (5 %)	$146.89
Grand total	**$3,084.61**
Paid to date	**$3,084.61**
Remaining Balance	**$0.00**

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature:

Disclaimer:

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

THRIFTY AUTO SERVICE
(780) 451-6811
info@thriftyautoservice.com
15605 116 Ave NW, Edmonton, AB, Canada, T5M 3W1

Invoice # 1187

Against Estimate#: 10224
Created: Sep 5, 2024
Invoiced: Sep 10, 2024

Dynamic Scale

COPY

2014 FORD F-250 SUPER DUTY
VIN: 1FT7W2B63EEA95139
Mileage: 324088 km
License Plate:

Concern #1

Vehicle pulled into the lot and asked Jim to look at a noise underhood. Had a bad electrical burning smell. Saw the A/C compressor was smoking. Disconnected the battery.

Air Conditioning Service — **Authorized**

Item	Name	Description	Price	QTY/HRS	Amount
1	Gates Serpentine Belt Kit	Serpentine Belt Drive Component Kit	$458.37	1	$458.37
2	A/C SERVICE KIT	A/C Compressor Replacement Service Kit	$232.52	1	$232.52
3	FS A/C Compressor	A/C Compressor	$691.46	1	$691.46
4	Air Conditioning Compressor R&R		$150.00	1.5	$225.00
5	Air Conditioning Expansion Valve R&R (Without Dual Rear Wheels)		$150.00	2	$300.00
6	Recharge A/C System		$150.00	1	$150.00
7	134A Refridgerant		$33.99	2	$67.98

Service subtotal: $2,125.33

Diagnostic / Inspection — **Authorized**

Item	Name	Description	Price	QTY/HRS	Amount
1	Labor	Vehicle pulled into the lot and asked Jim to look at a noise underhood. Had a bad electrical burning smell. Saw the A/C compressor was smoking. Disconnected the battery. Inspect	$160.00	0.5	$80.00

Service subtotal: $80.00

#33

THRIFTY AUTO SERVICE
(780) 451-6811
info@thriftyautoservice.com
15605 116 Ave NW, Edmonton, AB, Canada, T5M 3W1

Invoice # 1187

Against Estimate#: 10224
Created: Sep 5, 2024
Invoiced: Sep 10, 2024

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature:

Service Amount	**$2,205.33**
Part	$1,450.33
Labor	$755.00
Total RO Fees	
Shop supplies	$44.11
Subtotal	**$2,249.44**
Taxes (Sales Tax - 5%)	$112.48
Grand total	**$2,361.92**
Paid to date	**$2,361.92**
Remaining balance	**$0.00**