ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

T20-9 DEC

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER	*REPRINT*	
Date: 09/05/25	Time: 22:03:37 (B)	Page: 01
Account No.	Phone No.	Reference No.: W52822
Ship Via	Purchase Order: NA	
	G.S.T. No.: 79759 4660 RT0001	
Credit Card No.	Salesperson: M85	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
181582	STEIGER 620 QUAD 620Q	X	JEEZ0620AJF314984		

Fold - - - -

** Need a quick update on your Parts,Service or Sales Status?
Text messaging is now available with RME!
Please text your local branch main phone number. **

SEGMENT# 1 C 06583 NA 08/12/25 08/13/25
Service Unit 12.00 HRS
CAUSE:
08/24/25
-parked machine on level surface
-drained engine oil
-blown out air filters
-blown out cabin filer
-changed hydraulic filters
-changed fuel filters
-changed transmission filters
-changed engine oil filter
-filled with fresh engine oil
-greased machine
ADDITIONAL DESCRIPTION:
Change
Engine oil and Filters
Change fuel filters
Change Hydraulic filters
Change transmission filters
blow out engine breather
blow out engine air filters
blow out all cab filters

FIL1	ENVIR FILT<8"	3	.55	1.65
FIL2	ENVIR FILT>8"	5	1.25	6.25

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	02
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
181582	STEIGER 620 QUAD 620Q	X	JEEZ0620AJF314984		
LF17547	OIL FILTER		1	198.89	198.89
OIL1	ENVIRO OIL<30LT		33	.18	5.94
UF101	FILTER		1	206.66	206.66
47833556	FILTER, HY		1	145.35	145.35
5801516883	FILTER		1	228.95	228.95
5802862326C	CORE		1-	13.88	13.88-
5949768015	FILTER		RETAIL	102.75	
			1	99.70	99.70
73344232	15/40 CJ4ENG 1G		1	32.50	32.50
73344233	15W40 2.5G		1	74.75	74.75
73344234	15W40 NO.1EN 5G		1	139.75	139.75
84196445	FILTER HYD 11.6		2	215.08	430.16
84423586	PRE-FUEL FILTER		1	341.07	341.07
84523925	HYD FILTER		1	88.32	88.32
87409377	FILTER		RETAIL	110.86	
			1	107.57	107.57
				PARTS	2093.63
				LABOR	2160.00
	17300000			SEGMENT TOTAL==>	4253.63

SEGMENT# 2 C 06583 NA 08/12/25 08/13/25

RESEAL R/H REMOTE STACK 8.00 HRS

COMPLAINT:

LEAKING

CAUSE:

08/26/25

-rear remote coupler seals pn 87635376, 87635379, 87635382

-elbow 1289481C1

-tested flow and stand by pressure are low 2800psi

CORRECTION:

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT
Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch: TABER		
Date: 09/05/25	Time: 22:03:37 (B)	Page: 03
Account No.	Phone No.	Reference No.: W52822
Ship Via	Purchase Order: NA	
	G.S.T. No.: 79759 4660 RT0001	
Credit Card No.	Salesperson: M85	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q

08/26/25
-parked machine on level surface
-disabled machine
-removed feed lines and blocked them
-removed lines to oil catch can
-removed cartridge 1 and removed seals
-cleaned area with alcohol-based cleaner
-inserted new seals
-repeat process with next set
-removed coupler block
-before cleaning took pictures (upload to multimedia)
-cleaned area
-inserted new seals
-torqued bolts 40 Nm
-marked bolts
08/27/25
-took apart cartridge insert
-removed old o-rings
-cleaned area
-installed new orings
-assembled internals
-replaced drain hoses to catch can
-elbow missing, replaced elbow
-adjusted stand by pressure at twin flow pump, no reaction
from adjustment
-talk to foreman about finding
-leave as is

ADDITIONAL DESCRIPTION:
REMOVE, RESEAL, INSTALL R/H REMOTE STACK

1289481C1	ELBOW	1	30.74	30.74

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	04
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
181582	STEIGER 620 QUAD 620Q	X	JEEZ0620AJF314984		
87635376	O-RING		6	9.15	54.87
87635379	O-RING		6	4.76	28.56
87635382	O-RING		6	9.77	58.59
				PARTS	172.76
				LABOR	1440.00
17300000			SEGMENT TOTAL==>		1612.76

Fold - - - -

SEGMENT# 3 C 06583 NA 08/12/25 08/13/25

RESEAL REMOTE VALVE 1 COUPLERS IN HOUSING 2.00 HRS

CAUSE:

08/27/25

-cartridge seals worn pn seal kit 345193A1

CORRECTION:

08/27/25

-took apart cartridge insert
-removed old o-rings
-cleaned area
-installed new orings
-assembled internals
-replaced drain hoses to catch can
-elbow missing, replaced elbow

ADDITIONAL DESCRIPTION:

RESEAL REMOTE VALVE 1 COUPLERS IN HOUSING

345193A1	KIT		RETAIL	96.95	
			2	95.26	190.52
87635387	O-RING		6	7.07	42.42
				PARTS	232.94
				LABOR	360.00
17300000			SEGMENT TOTAL==>		592.94

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT
Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	05
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q

SEGMENT# 4 C 06583 NA 08/12/25 08/13/25
GAS HOOD STRUTS FAILING 1.50 HRS
CAUSE:
08/25/20
-pressure is not as per factory
- PN 84561096
CORRECTION:
08/25/25
-removed hood struts
-installed new strut
-fastened bolts
-marked bolts
ADDITIONAL DESCRIPTION:
REMOVE AND REPLACE STRUTS FOR HOOD

84561096	GAS STRUT	RETAIL	278.35	
		2	273.56	547.12
			PARTS	547.12
			LABOR	270.00
17300000		SEGMENT TOTAL==>		817.12

SEGMENT# 5 C 06583 NA 08/12/25 08/13/25
COOLING SYSTEM CONTAMINATED 3.00 HRS
CAUSE:
08/25/25
-added chemical to dissolve unwanted material in system
-started machine and let it circulate 40 min
-drained coolant while hot
-let machine cool down before adding cold coolant 1hour
-filled with clean coolant
-bleed system

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	06
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

Fold - - - -

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q
-tested machine
ADDITIONAL DESCRIPTION:
DRAIN, FLUSH AND FILL COOLING SYSTEM

ANT1	ENVIRO ANTIFRZ	70	.01	.70
CC2638	RESTORE PLUS	1	44.94	44.94
73344304	OT ANTF PMX2.5	7	55.71	389.97
			PARTS	435.61
			LABOR	540.00
17300000			SEGMENT TOTAL==>	975.61

SEGMENT# 6 C 06583 NA 08/12/25 08/13/25
FAN BELT TORN 1.00 HRS
CAUSE:
fan belt cracked
pn 90416432
CORRECTION:
08/26/25
removed fan belt
installed new fan belt
ADDITIONAL DESCRIPTION:
REMOVE AND REPLACE ENGINE FAN BELT

90416432	ALT/AC/WP BELT	RETAIL	92.79	
		1	91.12	91.12
			PARTS	91.12
			LABOR	180.00
17300000			SEGMENT TOTAL==>	271.12

SEGMENT# 7 C 06583 NA 08/12/25 08/27/25
EXHAUST LEAK 2.00 HRS
CAUSE:

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT
Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	07
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q

08/27/25
-DEF leaking from exhaust, due to long periods of idling
CORRECTION:
08/27/25
-do not let machine stand Idel for long periods of time
ADDITIONAL DESCRIPTION:
LOCATE AND REPAIR EXHAUST LEAK REAR LEFT SIDE OF ENGINE

LABOR 360.00

17300000 SEGMENT TOTAL==> 360.00

SEGMENT# 8 C 06583 NA 08/12/25 08/28/25
LEFT FRONT WINDOW WASHER INOP 1.00 HRS
CAUSE:
08/28/25
lock nuts on wiper arms were loose
CORRECTION:
08/28/25
-loosened lock nuts
-removed wiper
-turned wipers on and off to algin them
-reattached wiper and turn on
-works proper
ADDITIONAL DESCRIPTION:
DIAG AND REPAIR WASHER INOP LEFT SIDE

LABOR 180.00

17300000 SEGMENT TOTAL==> 180.00

SEGMENT# 9 C 06583 NA 08/12/25 08/13/25
PARK BRAKE SWITCH INOP 2.00 HRS
CAUSE:

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	08
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

Fold - - - -

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q

sensor causes shaking stop
-PN 47569377
CORRECTION:
08/25/25
removed valve \block
removed sensor
08/26/25
installed sensor
cleaned area
tested machine does not have symptoms ant more
ADDITIONAL DESCRIPTION:
DIAG AND REPAIR PARK BRAKE SWITCH

47569377	SWITCH PRE	RETAIL	194.10	
		1	190.74	190.74
			PARTS	190.74
			LABOR	360.00
17300000		SEGMENT TOTAL==>		550.74

SEGMENT#10 C 06583 NA 08/12/25 08/13/25
DEF QUALITY SENSOR FAULTY 2.00 HRS
CAUSE:
08/29/25
-DEF low
-sensor faulty
-5802862326R
CORRECTION:
08/24/25
-drained DEF
-removed sensor
-cleaned area

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	09
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

Fold - - - -

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q
-installed new sensor
ADDITIONAL DESCRIPTION:
DIAG AND REPAIR DEF QUALITY SENSOR

DEF1	ENVIRO DEF LTR	40	.01	.40
5802862326C	CORE	1-	13.88	13.88-
5802862326R	quality sensor	1	617.13	617.13
5802862326C	CORE		13.88	13.88
8900RU4948	DEF 9.46L JUG	4	21.28	85.12
			PARTS	702.65
			LABOR	360.00
17300000			SEGMENT TOTAL==>	1062.65

SEGMENT#11 C 06583 NA 08/12/25 08/26/25
LEAKING CHARGE VALVE 1.00 HRS
CAUSE:
08/26/25
-did fault finding and could not pinpoint the origin of leak.
-hydraulic hose is leaking 47806567
CORRECTION:
08/27/25
-cleaned areas I founded suspicious
-took machine around the jard to get everything warm and to reach optimal operating temperature
-brought machine inside shop and spotted leak
-had a hose made in shop
ADDITIONAL DESCRIPTION:
RESEAL LEAK AT CHARGE VALVE
clean area tighten fittings and advise if parts are needed

122-06	HYD HOSE 3/8"	3	3.23	9.69

CONTINUED ON PAGE 10

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	10
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS
181582	STEIGER 620 QUAD 620Q	X	JEEZ0620AJF314984			
42083-06-06	ORFS F FITTING			1	6.86	6.86
42983-06-06	ORFS F 90' ELBO			1	14.56	14.56
					PARTS	31.11
					LABOR	180.00
	17300000			SEGMENT TOTAL==>		211.11

Fold - - - -

SEGMENT#12 C 06583 NA 08/12/25 08/25/25

LEAK AT BACK END OF ARTICULATION 1.50 HRS

CAUSE:

08/27/25

-rubber sections on hydraulic feed and return line are leaking

-PN 51518269

CORRECTION:

08/27/25

-located leak

-ordered parts

08/29/25

-drained oil 5 times 20 liters

-loosened clamps for supply hose

-removed brackets attached to supply hose

-removed supply hose (must be removed to access problem area)

-loosened clamps of return hose (used prybar to remove rubber connecting hose) note that space is very limited, only small actions can be taken

-measured hoses from tube length received prom parts, length received was 420 mm by 32mm inner measurement

-had to cut rubber hose 150mm x 2. material was enough

-cleaned out rubber hoses and made sure that edges will not

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel: (403) 223-2333
Fax: (403) 223-1515
Toll Free: 1-855-763-1427

INVOICE

Ship to: I-RME Taber

Invoice to: INTERNAL CUSTOMER

Branch		
TABER		
Date	Time	Page
09/05/25	22:03:37 (B)	11
Account No.	Phone No.	Reference No.
		W52822
Ship Via	Purchase Order	
	NA	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	M85	

Description of Work and Parts

Fold - - - -

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

181582 STEIGER 620 QUAD X JEEZ0620AJF314984
620Q

interfere with installation
-cleaned area well with alcohol-based solvent, and prepped
rubber hoses clamps, pipes for installation
-installed return hose
-fastened clamps
-installed supply hose
-fastened clamps
-attached brackets
-fastened all bolts loose
-topped up oil
-tested machine
-no leaks
-uploaded multi-media

ADDITIONAL DESCRIPTION:
DIAG AND REPAIR LEAK AT BACK END OF ARTICULATION

FREIGHT		1	15.00	15.00
141-24	HOSE PER FT	1 M	12.85	12.85
51518269	HOSE	1 N	46.19	46.19
			PARTS	74.04
			LABOR	270.00
17300000		SEGMENT TOTAL==>		344.04

****** WORK ORDER TOTALS ******

	INTERNAL	CUSTOMER
PARTS	4571.72	
LABOR	6660.00	
SHOP SUPPLIES	566.10	
INTERNAL TOTAL	11797.82	

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)