ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

T20-11 DEC

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE	*REPRINT*	
Date: 07/27/26	Time: 22:02:49 (B)	Page: 01
Account No.	Phone No.	Reference No.: W87009
Ship Via	Purchase Order	
	G.S.T. No.: 79759 4660 RT0001	
Credit Card No.	Salesperson: R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE	X	YKG241446		
	8250	1338			

Fold - - - -

** Need a quick update on your Parts,Service or Sales Status?
Text messaging is now available with RME!
Please text your local branch main phone number. **

SEGMENT# 1 C 05449 MAIN6 04/13/26 04/14/26
1200HR SERVICE 13.00 HRS
COMPLAINT:
HRS
1. 1200HR SERVICE (MAIN6) 13.00
-Change Bubble up Gearbox oil
-Change engine oil and filter
-Change feeder conveyor Gearbox oil
-Change final drive oil
-Change header gearbox oil
-Change lower unloading gearbox oil
-Change PTO gearbox oil
-Change rotor gearbox oil
-Change transmission oil
-Change unloading elbow oil
-Check tailings gearbox oil level
-Replace DEF in line filter - If equipped
-Replace DEF tank vent filter
-Replace DEF main filter
-Replace engine crankcase breather filter
-Replace fuel/water separator filter
-Replace Fuel filter
-Replace Hydraulic Oil and filter
-Replace PTO filter
-Replace fuel tank vent

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	02
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

195677 COMBINE X YKG241446
8250 1338

Fold - - - -

-Replace cab air filters
-Replace engine air filters
-Check and adjust all Chains and Belts
-Grease unit

Quantity x1

13.00

CORRECTION:
-BAtteries were dead so boost and get started
-Perform 1200 hr service as per list and manual
-Clean up and dispose old oil

FIL1	ENVIR FILT<6"	8	.55	4.40
FIL2	ENVIR FILT>6"	5	1.25	6.25
OIL1	ENVIRO OIL LTR	14	.18	2.52
OIL2	ENVIRO OIL>30	132	.06	7.92
360260A2	FILTER, ELEMENT	1	158.55	158.55
47364243	FILTER, DEF	1	196.43	196.43
47437399	FILTER, FU	2	78.56	157.12
47651824	FILTER DEF	1	311.70	311.70
51508555	FILTER HYDRAUL	2	182.48	364.96
5801415504	oil filter	1	116.98	116.98
5801516883	FILTER	1	229.93	229.93
5949768015	FILTER	1	103.31	103.31
73344230	10W40 BULK OIL	32	6.80	217.60
73344258	30W ENG OIL 1G	1	32.82	32.82
73344271	HYTRAN BULK	100	6.80	680.00
73344312	OIL 80W90 2.5g	1	91.46	91.46
73344349	M/P 251H EP GEA	2	8.27	16.54
84217229	FILTER, AI	1	96.33	96.33

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	03
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	79759 4660 RT0001
Credit Card No.	Salesperson	R62

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
195677	COMBINE		X YKG241446			Fold - - - -
	8250		1338			
84305930		AIR FILTER		1 281.48	281.48	
84305935		AIR FILTER		1 271.50	271.50	
84423586		PRE-FUEL FILTER		1 342.33	342.33	
84523925		HYD FILTER		1 88.68	88.68	
87107440		SCREEN, FI		1 229.93	229.93	
8900RU4948		DEF 9.46L JUG		1 18.98	18.98	
				PARTS	4027.72	
				LABOR	2340.00	
	17300000			SEGMENT TOTAL==>	6367.72	

SEGMENT# 2 C 05449 NA 04/13/26 05/01/26
SEAL AIR FILTER HOUSING 1.00 HRS
COMPLAINT:
REINSTALL SEAL ON AIR FILTER HOUSING AND RESEAL THE REST OF THE INTAKE WITH SILICONE
CORRECTION:
-Remove re seal and re install

		LABOR	302.40
17300000		SEGMENT TOTAL==>	302.40

SEGMENT# 3 C 05449 NA 04/13/26 04/14/26
VERTICAL UNLOAD GEARBOX/AUGER 6.00 HRS
COMPLAINT:
GEARBOX FULL OF WATER, NEED TO REPLACE. AUGER SPLINES LIKELY RUSTED OUT, QUOTE IT AS WELL
CORRECTION:
-support auger and remove gearbox
-Remove seized sprocket from shaft and install onto new
-Remove seized coupler and install onto new

120044	BOLT	1	5.00	5.00

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	04
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE		X YKG241446		
	8250	1338			
47941525C		CORE-GEARBOX		1- 144.90	144.90-
47941525R		LOW UNLOAD GBOX		1 3158.69	3158.69
47941525C		CORE-GEARBOX		144.90	144.90
				PARTS	3163.69
				LABOR	1080.00
	17300000			SEGMENT TOTAL==>	4243.69

Fold - - - -

SEGMENT# 4 C 05449 NA 04/13/26 04/14/26
CLEANING FAN SUPPORT CRACKED 7.00 HRS
COMPLAINT:
BLADE SUPPORT CRACKED ON CLEANING FAN, NEED TO REPLACE BEFORE FAN FAILS
(91761823)
CORRECTION:
-Remove guards and fan housing and remove fan from machine
-Disassemble and remove middle broken plastic disc and replace and re assemble
-Install new bearing as it was damaged removing
-Re install fan and fan housing and guards
-Clean up

47430082	BEARING, B	1 S	93.83	93.83
86512497	NUT M12FLG	1	.76	.76
87698852	BOLT M12x35CB	1	9.83	9.83
92043951	DISC	1 N	44.15	44.15
			PARTS	148.57
			LABOR	1260.00
17300000			SEGMENT TOTAL==>	1408.57

SEGMENT# 5 C 05449 ENGINE23 04/13/26 04/14/26
MAIN FUEL TANK R&I 7.50 HRS

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	05
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE		X YKG241446		
	8250	1338			

Fold - - - -

COMPLAINT:
TANK IS DRIPPING FROM MOLDED IN FITTING
****REPLACE THE RUBBER SEAL AROUND FILLER NECK AT SAME TIME, SEAL IS RIPPED****
HRS
1. MAIN FUEL TANK R&I (ENGINE23) 7.50

Quantity x1

7.50

CORRECTION:
-Drain fuel
-Remove and replace swap over fitting
-Re add fuel
-Notice slight seepage from fitting so remove and install updated screen fitting with oring

47583625	SEAL	1	62.67	62.67
48083576	STRAINER FILTE	1	130.38	130.38
92662101	FUEL TANK	1 N	2833.25	2833.25
			PARTS	3026.30
			LABOR	1350.00
17300000		SEGMENT TOTAL==>		4376.30

SEGMENT# 6 C 05449 ENGINE22 04/13/26 04/14/26
ENGINE FAN BELT TENSIONER BUSHINGS 8.00 HRS
COMPLAINT:
***REPLACE ENGINE BELT AT SAME TIME, BELT IS CRACKED**
HRS
1. ENGINE FAN BELT TENSIONER BUSHINGS (ENGINE22) 8.00

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	06
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

Fold - - - -

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE		X YKG241446		
	8250	1338			

Quantity x1
======
8.00

CORRECTION:
-Remove Engine hood assembly
-Remove tensioner and replace bushings and worn shaft
-Also notice that tensioner screw is worn through so replace
-Re isntall

382974	BUSHING	3	9.12	27.36
47411931	BELT ENGINE	1	126.78	126.78
47417330	ROD	1	68.48	68.48
47581705	SHAFT	1	93.40	93.40
			PARTS	316.02
			LABOR	1440.00
17300000			SEGMENT TOTAL==>	1756.02

SEGMENT# 7 C 05449 NA 04/13/26 04/14/26
BOTTOM STEERING COLUMN CYLINDER DOESN'T HOLD 1.00 HRS
COMPLAINT:
REPLACE TILT CYLINDER FOR LOWER STEERING COLUMN
CORRECTION:
-Remove steering coulumn covers and remove shock oin was seized and re install new one and covers

87607304	CYLINDER	1	359.08	359.08
			PARTS	359.08
			LABOR	180.00
17300000			SEGMENT TOTAL==>	539.08

SEGMENT# 8 C 05449 NA 04/13/26 04/14/26

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) _____ (date) _____

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) _____ (date) _____

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	07
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

195677 COMBINE X YKG241446
8250 1338

BOTH SIEVE SEALS RIPPED OFF/HALF MISSING .75 HRS

COMPLAINT:
*REPLACE BOTH REAR SIEVE SEALS (BLACK ONES)
CORRECTION:
-remove mounting hardware and remove linkage and install new seals and re install linkage and hardware

92173874	STRIP RUBBER	2	106.27	212.54
			PARTS	212.54
			LABOR	579.15
17300000			SEGMENT TOTAL==>	791.69

SEGMENT# 9 C 05449 NA 04/13/26 04/14/26
EXCESSIVE PLAY ON LOWER ELEVATOR SPROCKET 6.00 HRS

COMPLAINT:
LOWER SPROCKET FOR ELEVATOR CHAIN HAS A LOT OF PLAY IN IT, HAS VERY LIKELY POUNDED OUT KEYWAY IN AUGER SHAFT - QUOTE NEW SPROCKET, KEY AND CLEAN GRAIN AUGER
***REMOVE A LINK FROM THE ELEVATOR CHAIN AT SAME TIME, CHAIN ADJUSTMENT MAXXED OUT, HAVE TO SPLIT IT ANYWAY**
CORRECTION:
-Remove retaining hardware and plate and old sprocket and install new and re install all that was removed
-Tension up chain and still lots of adjustment left

87283201	KEY	1	30.74	30.74
87283436	SPROCKET	1	181.41	181.41
			PARTS	212.15
			LABOR	1080.00
17300000			SEGMENT TOTAL==>	1292.15

SEGMENT#10 C 05449 MULTIPLE 04/13/26 04/14/26

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	08
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

195677 COMBINE X YKG241446

8250 1338

WEAR STRIPS/STRIPPER PLATES/HAT BUSHINGS 6.50 HRS

COMPLAINT:

REPLACE HAT BUSHINGS AS WELL, BROKEN, CHAIN WILL BE LOOSENED OFF ANYWAY AND ZIP TIE HARNESS ON LH SIDE OF FEEDER SO IT ISN'T RUBBING + 0.5 HRS

1. CHAIN STRIPPERS (FEEDER2) 3.50
2. WEAR STRIPS (FEEDER9) 2.50

Quantity x1

6.00

CORRECTION:

-Replace wear strips and hat bushings

86558960	BUSHING, HAT FD	2	43.00	86.00
86638209	STRIP	4	50.61	202.44
			PARTS	288.44
			LABOR	1560.98
17300000			SEGMENT TOTAL==>	1849.42

SEGMENT#11 C 05449 NA 04/13/26 05/26/26

P CLAMP HOLDING HYDRO DRIVE HOSE BROKEN .50 HRS

COMPLAINT:

CLAMP ON HOSE GOING TO HYDRO BROKEN - REPLACE

CORRECTION:

Replace

			LABOR	29.25
17300000			SEGMENT TOTAL==>	29.25

SEGMENT#12 C 05449 NA 04/13/26 04/14/26

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	09
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

Fold - - - -

195677 COMBINE X YKG241446
8250 1338

UPPER TAILINGS PADDLE LOOSE ON SHAFT 3.00 HRS

COMPLAINT:
UPPER PADDLE LOOSE ON SHAFT, NEED TO TAKE OUT TO SEE WHAT IS DAMAGED - QUOTE THE 2 BEARINGS, SHAFT AND KEY + MISC$ FOR PADDLE

CORRECTION:
-it is not upper one that is loos it is middle one soRemove outer guard and check and find that set screw have backed out so remove screws clean out threads and re install and torque down set screws and check with hammer and paddle is solid on shaft now

LABOR 637.65

17300000 SEGMENT TOTAL==> 637.65

SEGMENT#13 C 05449 NA 04/13/26 04/14/26

ASPIRATOR TENSIONER LOOSE/BAD BEARING 1.00 HRS

COMPLAINT:
TENSIONER BUSHINGS WORN OUT AND BEARING MAKES NOISE IN PULLEY FOR ASPIRATOR FAN BELT TENSIONER - REPLACE BUSHINGS AND TENSIONER PULLEY. QUOTE MISC$ FOR THE BACKING PLATE IN CASE SHAFT FOR TENSIONER IS WORN OUT, SHAFT IS INTEGRAL TO PLATE
IF PLATE NEEDS TO BE REPLACED, + 2 HRS NEED TO REMOVE FAN ASSY AND TAKE IT APART

CORRECTION:
-Remove and re bushing and isnpect shaft is good re install and need new circlip and washer so
wait on parts and get new circlip and install
-Re install all hardware and belt and guards

370024	RING, SNAP	1	2.71	2.71

CONTINUED ON PAGE 10

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	10
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE		HRS
195677	COMBINE	X	YKG241446			
	8250	1338				
382974		BUSHING		3	9.12	27.36
443434		WASHER		1	3.49	3.49
84072736		PULLEY		1	132.93	132.93
					PARTS	166.49
					LABOR	180.00
	17300000			SEGMENT TOTAL==>		346.49

Fold - - - -

SEGMENT#14 C 05449 MULTIPLE 04/13/26 04/14/26
1/2 RASP BAR SET & WEAR BARS 5.80 HRS

COMPLAINT:
WEAR BARS WORN DOWN ON ELEPHANT EARS, RASP BARS ARE WORN DOWN ENOUGH THAT THE BOLT HEADS ARE ROUNDING OFF SHOULD BE REPLACED

HRS
1. RASP BARS HALF SET (ROTOR10) 4.00
2. IMPELLER WEAR PLATES ONLY (ROTOR15) 1.80
Quantity x1
5.80

CORRECTION:
-Remove and install new half set of rasp bars
-Some bolts were so rounded had to weld bar onto head and loosen
-Clean up

47586516	KIT RASP BAR	1 N	1679.61	1679.61
48118400	KIT, IMPELLER W	1	773.29	773.29
			PARTS	2452.90
			LABOR	1044.00
17300000		SEGMENT TOTAL==>		3496.90

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	11
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE	X	YKG241446		
	8250	1338			

Fold - - - -

SEGMENT#15 C 05449 NA 04/13/26 04/14/26
SHAKER BELT TENSIONER BUSHING WORN OUT 2.50 HRS
COMPLAINT:
DOES NOT LOOK LIKE TENSIONER HAS BEEN GREASED, BUSHING WORN OUT
CORRECTION:
-Remove and replace and grease

87629473	BUSHING	1	63.11	63.11
			PARTS	63.11
			LABOR	483.60
17300000		SEGMENT TOTAL==>		546.71

SEGMENT#16 C 05449 NA 04/13/26 04/14/26
ONE STATIONARY KNIFE KNOCKED DOWN
COMPLAINT:
REINSTALL KNOCKED DOWN KNIFE
CORRECTION:
-Remove and re position and torque hardware and re install

			LABOR	510.90
17300000		SEGMENT TOTAL==>		510.90

SEGMENT#17 C 05449 NA 04/13/26 04/14/26
LOWER CONE VANE BADLY DAMAGED 2.00 HRS
COMPLAINT:
REPLACE ONE DAMAGED CONE VANE
CORRECTION:
-Remove concaves and wire harness and push connecters into box and remove cone cover and remove vane and install new one and re install all that was removed

CONTINUED ON PAGE 12

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	12
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

Fold - - - -

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
195677 COMBINE X YKG241446
8250 1338
-While cover is out install new impeller wear bars from seg
14

87053359	STIFFENER	1	190.29	190.29
87106338	BOLT	9	8.25	74.25
87547587	NUT	9	3.49	31.41
			PARTS	295.95
			LABOR	360.00
17300000			SEGMENT TOTAL==>	655.95

SEGMENT#18 C 05449 NA 04/13/26 04/14/26
1 FEEDER SLAT MISSING .25 HRS
COMPLAINT:
REPLACE MISSING FEEDER SLAT
USE ONE OF THE USED ONES OUTSIDE, JUST NEED NEW HARDWARE
CORRECTION:
Replace slat

FREIGHT	FREIGHT	RETAIL	22.00	
		1	20.00	20.00
11106231	PKG-SCREW	4 M	3.04	12.16
			PARTS	32.16
			LABOR	146.25
17300000			SEGMENT TOTAL==>	178.41

SEGMENT#19 C 05449 NA 04/13/26 04/27/26
DEF FAILURE CODE 2.00 HRS
COMPLAINT:
DEF FAILURE ALARM KEEPS POPPING UP ON MONITOR - DIAGNOSE ISSUE, QUOTE REPAIR IF NOT SOMETHING SIMPLE
ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 13

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) (date)

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) (date)

ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

LETHBRIDGE
3939 - 1st Ave. S.
Lethbridge, AB T1J 4P8
Tel: (403) 327-3154
Fax: (403) 327-3545
Toll Free: 1-855-763-1427

INVOICE

Ship to:
IS-RME LETHBRIDGE
RED SEAL REPAIRS
REF W86228
013078

Invoice to:
INTERNAL CUSTOMER

Branch		
LETHBRIDGE		
Date	Time	Page
07/27/26	22:02:49 (B)	13
Account No.	Phone No.	Reference No.
		W87009
Ship Via	Purchase Order	
	G.S.T. No.	
	79759 4660 RT0001	
Credit Card No.	Salesperson	
	R62	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
195677	COMBINE		X YKG241446		
	8250	1338			

Fold - - - -

-Check tank level good but draining slow so maybe frozen
-Hook up est and run system test and see not building def pressure
-Remove inlet and run line into def jug and run test again and builds pressure so inlet line or sender unit issue
-Order sender unit and lines just incase
-Remove air tank and remove panel clean out chaff and find that inlet line has pushed off nipple so remove and inspect oring and reposition and lube and re install and make sure clips hold
-Run est and run dosing system verification and all good
-Pull combine out and run test make sure all is good no leaks

	LABOR	360.00
17300000	SEGMENT TOTAL==>	360.00

****** WORK ORDER TOTALS ******

	INTERNAL	CUSTOMER
PARTS	14765.12	
LABOR	14924.18	
DISPOSAL FEE	150.00	
SERV DISCOUNT	1000.00-	
SHOP SUPPLIES	450.00	
INTERNAL TOTAL	29289.30	

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature) _____ (date) _____

I hereby acknowledge my indebtedness in the amount of $_____ being the total amount owing or balance owing as shown hereon.

(signature) _____ (date) _____