

Work Order History Report

20-Aug-2026

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
Mobile Equipment Heavy Vehicles Graders 555		Mobile Equipment Heavy Vehicles/Equipment Graders 555 - 2007 GD555-3C Komatsu Grader						
	2076	check tyre pressure	2/12/2013		Hours	0.0	0.0	\$0.00
	2075	check tyre pressure (Michael D)	17/12/2013	3703	Hours	0.0	0.0	\$0.00
	2074	check tyre pressure	22/12/2013	3715	Hours	0.0	0.0	\$0.00
	2073	check tyre pressure-all ok(Ben)	8/02/2014		Hours	0.0	0.0	\$0.00
	2072	check tyre pressure-all ok(Michael)	25/02/2014	3940	Hours	0.0	0.0	\$0.00
	2041	checked tyre pressure(Adrian)	22/03/2014		Hours	0.0	0.0	\$0.00
	2040	replaced cutting edges used old bolts and nuts	3/04/2014	4039	Hours	0.0	0.0	\$0.00
	2032	greased machine(Adrian)	15/04/2014	4163	Hours	0.0	0.0	\$0.00
	2039	replaced A/C belt and fan belts-greased grader- checked hyd oil level and found it was low, checked grader for leaks and no leaks were found, checked diff, transmission, and drive housings for high oil level and found none, topped up hyd oil with 10 lt and will monitor oil level(Adam)	19/04/2014	4081	Hours	0.0	0.0	\$0.00
	2038	check tyre pressure(Adrian)	20/04/2014	4081	Hours	0.0	0.0	\$0.00
	2037	replaced cutting edges	22/04/2014	4088	Hours	0.0	0.0	\$0.00
	2036	greased machine(Adrian)	3/05/2014		Hours	0.0	0.0	\$0.00
	2035	replaced cutting edges(Luke)	6/05/2014	4124	Hours	0.0	0.0	\$0.00
	2034	greased machine(Mick)	7/05/2014	4130	Hours	0.0	0.0	\$0.00
	2033	replaced cutting edges	13/05/2014	4160	Hours	0.0	0.0	\$0.00
	2031	greased machine(Mick)	20/05/2014	4176	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	2029	replaced cutting edges	28/05/2014	4195	Hours	0.0	0.0	\$0.00
	2030	greased machine(Mick)	28/05/2014	4193	Hours	0.0	0.0	\$0.00
	2028	greased machine(Adrian)	31/05/2014	4197	Hours	0.0	0.0	\$0.00
	2027	checked tyre pressure-all ok(Adam)	2/06/2014		Hours	0.0	0.0	\$0.00
	2026	greased and checked tyre pressure(Evan)	10/06/2014	4226	Hours	0.0	0.0	\$0.00
	2025	greased machine(Adrian)	14/06/2014	4241	Hours	0.0	0.0	\$0.00
	2024	replaced cutting edges(Adrian)	15/06/2014	4242	Hours	0.0	0.0	\$0.00
	2023	Carried out 250 hr serviceAdjusted circle/motor clearance-replaced 3 x top blade slide bushes and shim bottom slide bushes to reduce movement-replaced u/s washer bottle-clean out cab	16/06/2014	4247	Hours	0.0	0.0	\$0.00
	2022	check tyre pressure(Evan)	24/06/2014		Hours	0.0	0.0	\$0.00
	2021	greased machine(Adrian)	26/06/2014		Hours	0.0	0.0	\$0.00
	2020	check tyre pressures (Adrian)	28/06/2014	4271	Hours	0.0	0.0	\$0.00
	2018	replaced cutting edges(Adam/Ned)	9/07/2014	4292	Hours	0.0	0.0	\$0.00
	2019	check tyre pressure-adjusted pos 2 from 35 psi to 65 psi (Adrian)	9/07/2014		Hours	0.0	0.0	\$0.00
	2017	greased machine(Adrian)	11/07/2014	4306	Hours	0.0	0.0	\$0.00
	2016	check tyre pressures(Adrian)	14/07/2014		Hours	0.0	0.0	\$0.00
	2015	replaced cutting edges	16/07/2014	4315	Hours	0.0	0.0	\$0.00
	2014	greased machine(Adrian)	26/07/2014	4354	Hours	0.0	0.0	\$0.00
	2013	tyre pressures	3/08/2014	4361	Hours	0.0	0.0	\$0.00
	2012	check tyre pressure-adjusted pos 1 and pos 2 from 45 psi to 50 psi(Evan)	5/08/2014		Hours	0.0	0.0	\$0.00
	2011	greased(Evan)	18/08/2014	4399	Hours	0.0	0.0	\$0.00
	2010	replaced cutting edges	20/08/2014	4400	Hours	0.0	0.0	\$0.00
	2009	greased(Adrian)	24/08/2014	4411	Hours	0.0	0.0	\$0.00
	2008	check tyre pressure(Adrian)	26/08/2014		Hours	0.0	0.0	\$0.00
	2007	greased(Evan)	2/09/2014	4423	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	2006	check tyre pressure(Adrian)	5/09/2014		Hours	0.0	0.0	\$0.00
	2005	greased machine (Adrian)	7/09/2014	4440	Hours	0.0	0.0	\$0.00
	2003	check tyre pressure(Adam)	9/09/2014		Hours	0.0	0.0	\$0.00
	2004	removed and repaired broken step on R/H side(Adam)	9/09/2014	4451	Hours	0.0	0.0	\$0.00
	2002	replaced cutting edges	10/09/2014	4453	Hours	0.0	0.0	\$0.00
	2001	Fit ripper set up to machine, press in all bushes, tap out all rusted threads, fit & convert over hoses, fit valve, manufacture leaver controls in cab.	15/09/2014	4462	Hours	0.0	0.0	\$0.00
	2000	Check tyre pressure(Evan)	17/09/2014		Hours	0.0	0.0	\$0.00
	1999	greased machine(Adrian)	19/09/2014	4480	Hours	0.0	0.0	\$0.00
	1998	check tyre pressures(Adrian)	22/09/2014		Hours	0.0	0.0	\$0.00
	1997	check tyre pressures(Bryce)	28/09/2014		Hours	0.0	0.0	\$0.00
	1996	Removed and replaced blown hydraulic hose from pump to filter housing(Evan)	1/10/2014	4488	Hours	0.0	0.0	\$0.00
	1995	check tyre pressures-all ok(Adrian)	3/10/2014		Hours	0.0	0.0	\$0.00
	1994	greased machine(Adrian)	5/10/2014	4493	Hours	0.0	0.0	\$0.00
	1993	carried out 500hr servicereplaced L/H rotating light	7/10/2014	4498	Hours	0.0	0.0	\$0.00
	1992	replace A/C compressor clutch	10/10/2014	4504	Hours	0.0	0.0	\$0.00
	1991	greased machine(Adrian)	14/10/2014	4510	Hours	0.0	0.0	\$0.00
	1990	check tyre pressures-all ok(Adrian)	17/10/2014		Hours	0.0	0.0	\$0.00
	1989	greased machine (Adrian)	18/10/2014	4519	Hours	0.0	0.0	\$0.00
	1987	replaced wiper blades, topped up fluid(Evan)	28/10/2014	4542	Hours	0.0	0.0	\$0.00
	1988	greased(Adrian)	28/10/2014	4542	Hours	0.0	0.0	\$0.00
	1986	checked tyre pressure-all ok(Adrian)	31/10/2014		Hours	0.0	0.0	\$0.00
	1985	greased machine(Adrian)	1/11/2014	4555	Hours	0.0	0.0	\$0.00
	1984	greased machine(Adrian)	12/11/2014	4594	Hours	0.0	0.0	\$0.00
	1983	greased machine(Adrian)	15/11/2014	4608	Hours	0.0	0.0	\$0.00
	1981	removed and replaced all drive tyres replaced cutting edges (Graham)	16/11/2014		Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1980	greased	19/11/2014	4625	Hours	0.0	0.0	\$0.00
	1979	greased	27/11/2014	4642	Hours	0.0	0.0	\$0.00
	1978	greased machine(Adrian)	28/11/2014	4645	Hours	0.0	0.0	\$0.00
	1977	greased machine (Adrian)	2/12/2014	4662	Hours	0.0	0.0	\$0.00
	1976	greased	7/12/2014	4669	Hours	0.0	0.0	\$0.00
	1974	removed and replaced bottom blade slides, shimmed up slides to correct gap	9/12/2014	4673	Hours	0.0	0.0	\$0.00
	1975	check tyre pressures(Adrian)	9/12/2014		Hours	0.0	0.0	\$0.00
	1973	greased machine(Adrian)	11/12/2014	4681	Hours	0.0	0.0	\$0.00
	1972	replaced cutting edgesreplaced grease line under articulation	14/12/2014	4691	Hours	0.0	0.0	\$0.00
	1971	greased machine(Adrian)	16/12/2014	4700	Hours	0.0	0.0	\$0.00
	1970	greased	20/12/2014	4701	Hours	0.0	0.0	\$0.00
	1969	tyre pressures	21/12/2014		Hours	0.0	0.0	\$0.00
	1968	greased machine	26/12/2014	4719	Hours	0.0	0.0	\$0.00
	1967	greased machine	30/12/2014	4724	Hours	0.0	0.0	\$0.00
	1965	replaced cutting edges	31/12/2014	4725	Hours	0.0	0.0	\$0.00
	1964	tyre pressures	2/01/2015		Hours	0.0	0.0	\$0.00
	1963	greased	3/01/2015	4725	Hours	0.0	0.0	\$0.00
	1962	Travelled to Rom and started blowing out outer air filter, found holes in filter so replaced both inner and outer air filters(Gary)	9/01/2015	4748	Hours	0.0	0.0	\$0.00
	1961	carried out 250hr service(Graham/Adrian)	12/01/2015	4766	Hours	0.0	0.0	\$0.00
	1960	greased machine	17/01/2015	4786	Hours	0.0	0.0	\$0.00
	1959	greased machine(Adrian)	22/01/2015	4798	Hours	0.0	0.0	\$0.00
	1958	greased	31/01/2015	4821	Hours	0.0	0.0	\$0.00
	1957	tyre pressures	1/02/2015		Hours	0.0	0.0	\$0.00
	1956	(Rom) replaced cutting edges	2/02/2015	4829	Hours	0.0	0.0	\$0.00
	1955	greased machine(Adrian)	5/02/2015	4845	Hours	0.0	0.0	\$0.00
	1954	Check tyre pressures(Adrian)	8/02/2015		Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1953	greased	15/02/2015	4863	Hours	0.0	0.0	\$0.00
	1951	replace grader blades9dam/Mick R)	16/02/2015	4868	Hours	0.0	0.0	\$0.00
	1950	check tyre pressures	17/02/2015		Hours	0.0	0.0	\$0.00
	1948	greased machine(Adrian)	19/02/2015	4873	Hours	0.0	0.0	\$0.00
	1949	Travelled to Rom and jump started machine as isolator was left on(Adrian)	19/02/2015		Hours	0.0	0.0	\$0.00
	1947	travelled to Sarsfield and jump start grader(new batteries ordered) topped up transmission oil with 10 lt of TFC 430 (Adrian)	23/02/2015	4878	Hours	0.0	0.0	\$0.00
	1946	Travelled to site and jump start Grader(batteries on order) (Adrian)	24/02/2015	4883	Hours	0.0	0.0	\$0.00
	1944	tyre pressures	27/02/2015		Hours	0.0	0.0	\$0.00
	1945	replaced both batteries	27/02/2015	4895	Hours	0.0	0.0	\$0.00
	1943	greased	28/02/2015	4895	Hours	0.0	0.0	\$0.00
	1942	replaced cutting edges	4/03/2015	4911	Hours	0.0	0.0	\$0.00
	1941	check tyre pressure(Adrian)	6/03/2015		Hours	0.0	0.0	\$0.00
	1940	Replaced cutting edges and lubed slides	17/03/2015	4958	Hours	0.0	0.0	\$0.00
	1939	greased machine (Adrian)	21/03/2015	4975	Hours	0.0	0.0	\$0.00
	1938	Travelled to Sarsfield added 5 lt of coolant and added 5 lt of hyd oil (Adrian)	24/03/2015	4975	Hours	0.0	0.0	\$0.00
	1935	Replaced hyd oil with new oil(been contaminated with coolant) needs to be changed again at further date(still milky slightly) removed and replaced faulty stereo, wire up rotating beacons to aux power(were on constant power) replaced faulty work light 9blade) LHS	26/03/2015	4982	Hours	0.0	0.0	\$0.00
	1926	check tyre pressure (Adrian)	4/04/2015		Hours	0.0	0.0	\$0.00
	1923	greased	11/04/2015		Hours	0.0	0.0	\$0.00
	1924	check ball joint play, slight play look at doing 6000hr service (see Steve as doing wheel/bearings/king pins)	11/04/2015	5020	Hours	0.0	0.0	\$0.00
	1922	tyre pressures	13/04/2015		Hours	0.0	0.0	\$0.00
	1921	check tyre pressure (Adrian)	19/04/2015		Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1933	travelled to Sarsfield and replaced cutting edges (Luke)	20/04/2015	5020	Hours	0.0	0.0	\$0.00
	1917	repaired cracked step RHS, welded cracks in blade side (Charlie)	24/04/2015		Hours	0.0	0.0	\$0.00
	1916	greased machine	25/04/2015	5061	Hours	0.0	0.0	\$0.00
	1915	replaced grader blades, pos 4 tyre leaking bead damage	28/04/2015	5076	Hours	0.0	0.0	\$0.00
	1914	greased machine(Adrian)	30/04/2015	5093	Hours	0.0	0.0	\$0.00
	1927	Replaced hyd oil due to coolant contaminationgreased machine, checked tyre pressures, pos 4 tyre pumped up from 30psi to 50psi, used soapy water to find any leaks but none found, reset throttle and inching pedal parameters as per OEM manual(Horse)	30/04/2015	5020	Hours	0.0	0.0	\$0.00
	1913	Removed and replaced pos 4 tyre with new tyre (Luke/Graham)	1/05/2015	5093	Hours	0.0	0.0	\$0.00
	1912	check tyre pressure (Adrian)	2/05/2015		Hours	0.0	0.0	\$0.00
	1911	travelled to Rom and jump started grader (Luke)	3/05/2015	5093	Hours	0.0	0.0	\$0.00
	1907	travelled to Rom and replaced flat battery with second hand battery (Adrian)	5/05/2015	5100	Hours	0.0	0.0	\$0.00
	1909	greased machine	5/05/2015	5100	Hours	0.0	0.0	\$0.00
	1910	travelled to Rom and jump started vehicle, one battery u/s, will need relacing (Adrian)	5/05/2015	5098	Hours	0.0	0.0	\$0.00
	1906	greased machine	9/05/2015	5105	Hours	0.0	0.0	\$0.00
	1905	checked tyre pressures	11/05/2015		Hours	0.0	0.0	\$0.00
	1902	tightened up bolts and side panels	12/05/2015	5112	Hours	0.0	0.0	\$0.00
	1901	greased machine (Adrian)	14/05/2015	5113	Hours	0.0	0.0	\$0.00
	1899	replaced cutting edges (Graham)	16/05/2015	5131	Hours	0.0	0.0	\$0.00
	1900	check tyre pressure (Adrian)	16/05/2015		Hours	0.0	0.0	\$0.00
	1896	(Rom) transmission problems, calibrate transmission, adjust cable so get full throttle	22/05/2015	5151	Hours	0.0	0.0	\$0.00
	1898	replaced seat complete assembly	22/05/2015	5147	Hours	0.0	0.0	\$0.00
	1897	greased	23/05/2015	5151	Hours	0.0	0.0	\$0.00
	1892	(Rom) Horn staying on, removed steering wheel cleaned switch and contacts. refitted test could not aet to fault	24/05/2015	5153	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	1890	tyre pressures	25/05/2015	Hours	0.0	0.0	\$0.00
	1888	check tyre pressures (Adrian)	30/05/2015	Hours	0.0	0.0	\$0.00
	1886	greased machine (Adrian)	1/06/2015	5181 Hours	0.0	0.0	\$0.00
	1884	greased	6/06/2015	5194 Hours	0.0	0.0	\$0.00
	1882	tyre pressures (Adrian)	9/06/2015	Hours	0.0	0.0	\$0.00
	1880	(tanks) replace cutting edges, tighten up clamp above alternator (coolant) tighten loose spot light (1.25 hrs) (Adrian)	10/06/2015	5206 Hours	0.0	0.0	\$0.00
	1879	greased machine (Adrian)	12/06/2015	5222 Hours	0.0	0.0	\$0.00
	1877	check tyre pressures (Adrian)	14/06/2015	Hours	0.0	0.0	\$0.00
	1876	replaced cutting edges (Graham Miller)	16/06/2015	5231 Hours	0.0	0.0	\$0.00
	1875	Fixed vibrations and rattles in cab, shimmed and tightened bolts and rods in steering column shimmed and tighten pivot points, shimmed play in leaver controls, shimmed door rod mechanisms from rattling, adjusted door catches, fitted missing bolt in plate under seat(2.5 hrs)	20/06/2015	5243 Hours	0.0	0.0	\$0.00
	1874	Carried out 250hr servicereplaced air filter, checked why indicators not working, found blown fuse, work now but do not flash, ordered flasher unit/relay	21/06/2015	5243 Hours	0.0	0.0	\$0.00
	1873	greased machine	22/06/2015	5245 Hours	0.0	0.0	\$0.00
	1871	greased (Adrian)	30/06/2015	5268 Hours	0.0	0.0	\$0.00
	1872	replaced cutting edges (Graham)	30/06/2015	5267 Hours	0.0	0.0	\$0.00
	1869	greased	6/07/2015	5269 Hours	0.0	0.0	\$0.00
	1868	Travelled to Mt Wright tanks and replaced cutting edged(1.5 hrs) (Graham Miller)	9/07/2015	5269 Hours	0.0	0.0	\$0.00
	1867	greased machine	10/07/2015	5305 Hours	0.0	0.0	\$0.00
	1865	check tyre pressure	15/07/2015	Hours	0.0	0.0	\$0.00
	1863	Adjusted blade circle to remove excess play(2.5 hrs) made and fitted shims to blade slides(3 hrs) checked wiring to interior light(light does not work) no power, run new wire to light test ok(1 hr) removed indicator flasher relay give to Jamie to get new one	17/07/2015	5323 Hours	0.0	0.0	\$0.00
	1861	greased machine	19/07/2015	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1813	Travelled to 3 ways due to hyd hose failure, found blown transmission hose at the crimp, removed R/H rear side cover, removed valve from transmission that the hose mounted to, removed R/H rear side cover, removed failed hose and travelled back to workshop. Sent hose to Charters Towers for replacement. Replaced mounting o rings and fit new hose and valve. Topped up transmission oil until level was correct refit machine side covers.(Graham Miller)	23/07/2015	5338	Hours	0.0	0.0	\$0.00
	1812	check tyre pressure(Adrian)	24/07/2015		Hours	0.0	0.0	\$0.00
	1811	replaced front tyres , RH tyre new, LH tyre S/H and repaired , filled with coolant and half filled with water(Adrian,Horse)	27/07/2015	5347	Hours	0.0	0.0	\$0.00
	1807	greased	28/07/2015	5348	Hours	0.0	0.0	\$0.00
	1808	inflate front tyres to 50 psi, remove grease line, remove broken fitting from LH artic cyl, replaced fitting and made new hose. replaced grease nipples on block for artic pins	28/07/2015	5347	Hours	0.0	0.0	\$0.00
	1803	indicators not workingm replaced flasher relay, front lights damaged mounts, removed big lights and mounted 2 x small led lights to top of front counter weight	31/07/2015		Hours	0.0	0.0	\$0.00
	1801	greased	2/08/2015	5360	Hours	0.0	0.0	\$0.00
	1799	tyre pressure	3/08/2015		Hours	0.0	0.0	\$0.00
	1796	replaced inner and outer air filter as were very dirty	4/08/2015	5370	Hours	0.0	0.0	\$0.00
	1795	(Sarsfield) replace cutting edges, replace fuel filter, replace water trap screen. Machine lacking power filters dirty(Adrian)	5/08/2015	5375	Hours	0.0	0.0	\$0.00
	1793	tyre pressure(Adrian)	10/08/2015		Hours	0.0	0.0	\$0.00
	1790	greased(Adrian)	11/08/2015	5392	Hours	0.0	0.0	\$0.00
	1788	greased	14/08/2015	5393	Hours	0.0	0.0	\$0.00
	1787	greased	17/08/2015	5396	Hours	0.0	0.0	\$0.00
	1785	check tyre pressure	18/08/2015		Hours	0.0	0.0	\$0.00
	1783	replaced cutting edges(Luke)	20/08/2015	5410	Hours	0.0	0.0	\$0.00
	1781	greased machine(Luke)	21/08/2015	5414	Hours	0.0	0.0	\$0.00
	1778	check tyre pressures(Luke)	24/08/2015		Hours	0.0	0.0	\$0.00
	1775	carried out general check over, check for excessive play in	28/08/2015	5429	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1777	blade lift ram ends greased	28/08/2015	5329	Hours	0.0	0.0	\$0.00
	1773	tyre pressures	29/08/2015		Hours	0.0	0.0	\$0.00
	1771	greased machine	3/09/2015	5438	Hours	0.0	0.0	\$0.00
	1769	Check tyre pressure(Luke)	4/09/2015		Hours	0.0	0.0	\$0.00
	1767	greased(Luke)	7/09/2015	5443	Hours	0.0	0.0	\$0.00
	1765	replace worn cutting edges and bolts	9/09/2015	5455	Hours	0.0	0.0	\$0.00
	1764	tyre pressures	10/09/2015		Hours	0.0	0.0	\$0.00
	1759	greased	11/09/2015	5465	Hours	0.0	0.0	\$0.00
	1761	carried out check over of machine, tighten loose circle adjustment bolt and LH mirror cracked	11/09/2015	5465	Hours	0.0	0.0	\$0.00
	1757	replaced smashed mirror with smaller one(ordered correct one) (Dan)	13/09/2015	5465	Hours	0.0	0.0	\$0.00
	1755	greased(Luke)	14/09/2015	5465	Hours	0.0	0.0	\$0.00
	1753	travelled to Sarsfield to replace cutting edges(Luke)	16/09/2015	5468	Hours	0.0	0.0	\$0.00
	1752	greased machine(Luke)	19/09/2015		Hours	0.0	0.0	\$0.00
	1751	check tyre pressure(Luke)	20/09/2015		Hours	0.0	0.0	\$0.00
	1749	replaced flat battery(u/s)(L/H) ac delco (Dan)	27/09/2015	5484	Hours	0.0	0.0	\$0.00
	1748	greased machine(Luke)	1/10/2015	5495	Hours	0.0	0.0	\$0.00
	1747	check tyre pressure(Luke)	2/10/2015		Hours	0.0	0.0	\$0.00
	1745	carried out 500hr service	3/10/2015	5497	Hours	0.0	0.0	\$0.00
	1741	travelled to S9 and bent bracket to adjust mirror as mirror in wrong place	6/10/2015	5503	Hours	0.0	0.0	\$0.00
	1743	greased machine	6/10/2015	5503	Hours	0.0	0.0	\$0.00
	1740	greased machine	10/10/2015	5513	Hours	0.0	0.0	\$0.00
	1739	tyre pressures	12/10/2015		Hours	0.0	0.0	\$0.00
	1738	replaced cutting edges	14/10/2015	5514	Hours	0.0	0.0	\$0.00
	1736	check tyre pressures	21/10/2015		Hours	0.0	0.0	\$0.00
	1735	greased	22/10/2015	5531	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1732	tyre flat, pump up tyre to 50 psi leaking out of patch	25/10/2015	5531	Hours	0.0	0.0	\$0.00
	1730	greased	26/10/2015	5536	Hours	0.0	0.0	\$0.00
	1727	(Sarsfield) replace worn cutting edges	28/10/2015	5544	Hours	0.0	0.0	\$0.00
	1729	inflate pos 1 tyre, 50 psi leaking out of patch	28/10/2015	5540	Hours	0.0	0.0	\$0.00
	1725	travelled to S9 and replaced circle box oil due to bad sample- checked tyre pressures-ok	29/10/2015	5544	Hours	0.0	0.0	\$0.00
	1720	Removed and replaced both front tyres with second hand tyres, refilled with coolant and water. Washed out radiator-blow out and cleaned air filter	30/10/2015	5554	Hours	0.0	0.0	\$0.00
	1719	Check tyre pressure(Luke)	31/10/2015		Hours	0.0	0.0	\$0.00
	1717	greased machine	4/11/2015	5555	Hours	0.0	0.0	\$0.00
	1715	greases machine	8/11/2015	5558	Hours	0.0	0.0	\$0.00
	1713	Checked tyre pressure(Luke)	10/11/2015		Hours	0.0	0.0	\$0.00
	1706	greased machine(Luke)	12/11/2015	5576	Hours	0.0	0.0	\$0.00
	1708	replaced cutting edges(Luke)	12/11/2015	5574	Hours	0.0	0.0	\$0.00
	1709	travelled to Rom and topped up transmission fluid as it was reading low only took 500ml(Luke)	12/11/2015	5517	Hours	0.0	0.0	\$0.00
	1703	greased machine(Luke)	16/11/2015	5576	Hours	0.0	0.0	\$0.00
	1700	greased	20/11/2015	5586	Hours	0.0	0.0	\$0.00
	1699	greased	24/11/2015	5595	Hours	0.0	0.0	\$0.00
	1698	replaced cutting edges (Graham)	25/11/2015	5606	Hours	0.0	0.0	\$0.00
	1697	check tyre pressure(Luke)	27/11/2015		Hours	0.0	0.0	\$0.00
	1696	greased machine (Luke)	28/11/2015	5615	Hours	0.0	0.0	\$0.00
	1695	travelled to Rom and added 2 litres of coolant no visible signs of leaking but will monitor (Gary)	29/11/2015	5615	Hours	0.0	0.0	\$0.00
	1693	greased machine	2/12/2015	5621	Hours	0.0	0.0	\$0.00
	1694	greased machine	2/12/2015	5621	Hours	0.0	0.0	\$0.00
	1692	tyre pressures	5/12/2015		Hours	0.0	0.0	\$0.00
	1691	greased machine (Luke)	10/12/2015	5641	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1690	Replaced inner and outer air filters replaced circle box oil	11/12/2015	5642	Hours	0.0	0.0	\$0.00
	1689	Checked tyre pressure (Luke)	12/12/2015		Hours	0.0	0.0	\$0.00
	1688	Replaced cutting edges	13/12/2015	5650	Hours	0.0	0.0	\$0.00
	1687	Greased machine (Luke)	14/12/2015	5653	Hours	0.0	0.0	\$0.00
	1686	greased	18/12/2015	5673	Hours	0.0	0.0	\$0.00
	1685	Tyre pressures	21/12/2015		Hours	0.0	0.0	\$0.00
	1665	greased (Luke)	27/12/2015	5696	Hours	0.0	0.0	\$0.00
	1667	Greased	27/12/2015	5677	Hours	0.0	0.0	\$0.00
	1661	Tyre pressures (Luke)	28/12/2015		Hours	0.0	0.0	\$0.00
	1966	greased machine	30/12/2015	4724	Hours	0.0	0.0	\$0.00
	1658	Engine overheating, removed rear cover, blew out radiator fins with compressed air	2/01/2016	5707	Hours	0.0	0.0	\$0.00
	1653	Carry out general check over, blew out A/C & engine filters, removed fan shrouds, blew out cooler, also cleaned out with condenser cleaner& washed out, front & rear windscreen washers would not work kinked pipe behind seat	5/01/2016	5720	Hours	0.0	0.0	\$0.00
	1652	Check tyre pressures (Luke)	8/01/2016		Hours	0.0	0.0	\$0.00
	1650	Greased machine	9/01/2016	5732	Hours	0.0	0.0	\$0.00
	1651	greased machine (Luke)	9/01/2016	5732	Hours	0.0	0.0	\$0.00
	1649	greased	13/01/2016	5739	Hours	0.0	0.0	\$0.00
	1648	Tyre pressures	15/01/2016		Hours	0.0	0.0	\$0.00
	1647	Carry out 250 hr service as per sheet, engine sump leaking (tensioned bolts will monitor)	16/01/2016	5740	Hours	0.0	0.0	\$0.00
	1645	greased	17/01/2016	5746	Hours	0.0	0.0	\$0.00
	1646	(OCA) removed engine door covers to see if helps with engine overheating	17/01/2016		Hours	0.0	0.0	\$0.00
	1641	(Sarsfield) refit doors back on grader, fitted 4 vents in doors	19/01/2016	5751	Hours	0.0	0.0	\$0.00
	1623	(OCA) tighten loose UHF aerial, adjust engine door hitting body	20/01/2016	5758	Hours	0.0	0.0	\$0.00
	1504	(Sarsfield) replaced worn cutting edges	21/01/2016	5770	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1513	checked tyre pressures Luke	22/01/2016		Hours	0.0	0.0	\$0.00
	1508	9Rom) coolant leak tighten clamps & topped up coolant	25/01/2016	5764	Hours	0.0	0.0	\$0.00
	1511	greased Luke	25/01/2016	5762	Hours	0.0	0.0	\$0.00
	1376	greased	29/01/2016	5784	Hours	0.0	0.0	\$0.00
	1375	blew out air filter & checked all engine bay fluids	30/01/2016	5785	Hours	0.0	0.0	\$0.00
	1374	trye pressures	31/01/2016		Hours	0.0	0.0	\$0.00
	1372	greased	2/02/2016	5788	Hours	0.0	0.0	\$0.00
	1373	greased	2/02/2016	5788	Hours	0.0	0.0	\$0.00
	1371	replaced fan belt, removed jack shaft to replace uni's (wrong ones) re ordered	3/02/2016	5795	Hours	0.0	0.0	\$0.00
	1370	replaced cutting edges re used bolts Dan	10/02/2016	5811	Hours	0.0	0.0	\$0.00
	1369	carry out general check cover, tighten L/H mirror, steering column loose removed covers play in bottom shockie end clevis removed shockie welded washers on clevis end and shimmed, shimmed up various spots on colomn to take play out, fitted new safety pin on fire extinguisher , shimmed up hyd control leavers.	13/02/2016	5828	Hours	0.0	0.0	\$0.00
	1368	greased	16/02/2016	5833	Hours	0.0	0.0	\$0.00
	1367	checked tyre pressure	17/02/2016		Hours	0.0	0.0	\$0.00
	1366	replaced cutting edges	24/02/2016	5859	Hours	0.0	0.0	\$0.00
	1364	tyre pressures	25/02/2016		Hours	0.0	0.0	\$0.00
	1365	greased	25/02/2016	5859	Hours	0.0	0.0	\$0.00
	1360	replace column tilt damper with new one, shim blade and blade sides, spun air filter so could hook up pre cleaner assembly, removed doors so boilermaker could put in vents	27/02/2016	5870	Hours	0.0	0.0	\$0.00
	1359	cut doors(engine) to fit 4 more air vents, to assist cooling Mark	28/02/2016		Hours	0.0	0.0	\$0.00
	1356	weld cracks in blade carriage, remove air filter box inside engine (not used any more will give better air flow) Mark	29/02/2016		Hours	0.0	0.0	\$0.00
	1351	tyre pressure checked	2/03/2016		Hours	0.0	0.0	\$0.00
	1353	greased	2/03/2016	5873	Hours	0.0	0.0	\$0.00
	1349	greased	6/03/2016	5875	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1345	tyre pressures	9/03/2016		Hours	0.0	0.0	\$0.00
	1346	(Rom) operator said hyd oil level low.Checked was ok slightly over full	9/03/2016	5881	Hours	0.0	0.0	\$0.00
	1343	greased	11/03/2016	5859	Hours	0.0	0.0	\$0.00
	1342	greased	13/03/2016	5897	Hours	0.0	0.0	\$0.00
	1341	tyre pressures	15/03/2016		Hours	0.0	0.0	\$0.00
	1340	replaced cutting edges, reused bolts and nuts Dave/John	20/03/2016	5908	Hours	0.0	0.0	\$0.00
	1335	greased	26/03/2016	5918	Hours	0.0	0.0	\$0.00
	1334	(Sarsfield) engine lacking power, checked fuel system, air intake, tighten all boost hoses, found turbo actuator sticky manual activated with air then worked ok, engine power back, (will need to order turbo to fix)	30/03/2016	5929	Hours	0.0	0.0	\$0.00
	1332	Replaced Turbo assemblyProblem with turbo actuator, removed & replaced turbo assembly	5/04/2016	5933	Hours	0.0	0.0	\$0.00
	1333	tyre pressures	5/04/2016		Hours	0.0	0.0	\$0.00
	1330	(Mt Wright) engine low power, found fuel filter dirty, replaced	6/04/2016	5946	Hours	0.0	0.0	\$0.00
	1329	greased	7/04/2016	5951	Hours	0.0	0.0	\$0.00
	1328	replaced cutting edges	8/04/2016	5956	Hours	0.0	0.0	\$0.00
	1327	greased John	11/04/2016	5964	Hours	0.0	0.0	\$0.00
	1326	tyre pressures John	12/04/2016		Hours	0.0	0.0	\$0.00
	1325	tyre pressures John	18/04/2016		Hours	0.0	0.0	\$0.00
	1324	greased	19/04/2016	5975	Hours	0.0	0.0	\$0.00
	1323	(Rom) replaced 2 x missing bolts on blade slide keeper plates	20/04/2016	5975	Hours	0.0	0.0	\$0.00
	1321	Replaced all blade slidesReplace worn blade slides all 5 of them, removed all covers also so boiler maker can weld cracked pipe	21/04/2016	5981	Hours	0.0	0.0	\$0.00
	1322	(S9) replace end nut on bar that holds blade covers	21/04/2016	5979	Hours	0.0	0.0	\$0.00
	1320	greased	23/04/2016	5985	Hours	0.0	0.0	\$0.00
	1318	carry out 2000hr service as per sheet, replaced both top front cab light bulbs, checked brake wear, checked brake seals for	24/04/2016	5985	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		leaks					
	1319	tyre pressures	24/04/2016	Hours	0.0	0.0	\$0.00
	1316	grease and tyre pressures John	30/04/2016	6004 Hours	0.0	0.0	\$0.00
	1315	replaced cutting edges	1/05/2016	6005 Hours	0.0	0.0	\$0.00
	1314	greased	5/05/2016	6025 Hours	0.0	0.0	\$0.00
	1313	greased	7/05/2016	6026 Hours	0.0	0.0	\$0.00
	1312	tyre pressures John	8/05/2016	Hours	0.0	0.0	\$0.00
	1311	greased John	9/05/2016	6028 Hours	0.0	0.0	\$0.00
	1310	left door A/C vent loose zip tie into place	11/05/2016	6032 Hours	0.0	0.0	\$0.00
	1309	greased and tyre pressures checked John	14/05/2016	6037 Hours	0.0	0.0	\$0.00
	1307	greased	18/05/2016	6043 Hours	0.0	0.0	\$0.00
	1308	replaced cutting edges, refused bolts	18/05/2016	6045 Hours	0.0	0.0	\$0.00
	1306	tyre pressures checked John	25/05/2016	Hours	0.0	0.0	\$0.00
	1305	greased John	26/05/2016	6057 Hours	0.0	0.0	\$0.00
	1304	(3rd & 8th) replaced all bushes & seals in front axle, king pins & shimmed up, replaced pins in wheel lean rods, re kitted tie rod ends on steering cyl & rod, replaced & greased wheel bearings & replaced wheel seals, refitted wheels & reinflated removed and replaced main draw bar support ball, shimmed to correct spec and greased. Drained coolant & replaced water pump & thermostats, refilled with new coolant. Remove tappet covers, adjusted valve clearance and replaced gaskets. Removed front fan hub replaced bearings & refitted replaced belt tensioner, adjusted belts. Removed rear fan shroud & hub, disassembled & found shaft worn(needs new one ordered) reassembled with old bearings, grease & refitted, replaced bearings in idler pulley, refit belts & tension, refit fan shroud & covers. Remove floor mat & covers, remove & replace brake treddle valve with new one, replaced all o rings on valve, refitted covers and floor mat . Removed jack shaft, removed transmission output cover & cleaned up, replaced seal & refitted cover, refitted jack shaft as parts had not arrived yet.	8/06/2016	6071 Hours	0.0	0.0	\$0.00
	1303	greased	16/06/2016	6082 Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1299	(Rom)(slow to take off) checked trans oil & checked operation found rock caught in inching pedal, removed, calibrated transmission as well	18/06/2016	6084	Hours	0.0	0.0	\$0.00
	1301	tyre pressures	18/06/2016		Hours	0.0	0.0	\$0.00
	1297	greased	20/06/2016	6087	Hours	0.0	0.0	\$0.00
	1295	(tanks)replace cutting edges and bolts	22/06/2016	6098	Hours	0.0	0.0	\$0.00
	1294	greased	29/06/2016	6117	Hours	0.0	0.0	\$0.00
	1292	tyre pressures	1/07/2016		Hours	0.0	0.0	\$0.00
	1290	greased	3/07/2016	6123	Hours	0.0	0.0	\$0.00
	1288	greased John	7/07/2016	6145	Hours	0.0	0.0	\$0.00
	1283	(leaking radiator) removed all covers so boilermaker could solder up split in tank, oil leak steering valve cleaned up could not see leak was coming from, swapped around ripper boots	9/07/2016	6164	Hours	0.0	0.0	\$0.00
	1282	tyre pressures	12/07/2016		Hours	0.0	0.0	\$0.00
	1276	Replaced pos 1 tyre fitted new Michelin tyre	13/07/2016	6161	Hours	0.0	0.0	\$0.00
	1274	greased	14/07/2016	6166	Hours	0.0	0.0	\$0.00
	1273	replaced cutting edges bolts and nuts and also turned side edges around	25/07/2016	6224	Hours	0.0	0.0	\$0.00
	1271	greased	27/07/2016	6224	Hours	0.0	0.0	\$0.00
	1269	carried out 250hr service as per sheet, list jobs to do in book	31/07/2016	6262	Hours	0.0	0.0	\$0.00
	1268	greased	1/08/2016	6266	Hours	0.0	0.0	\$0.00
	1267	tyre pressures John	2/08/2016		Hours	0.0	0.0	\$0.00
	1266	greased John	5/08/2016	6276	Hours	0.0	0.0	\$0.00
	1263	Replaced fan hub bearings & shaft(worn) replaced jack shaft uni's x 2 removed & over hauled steering orbital (replaced all seals & orings)	9/08/2016	6277	Hours	0.0	0.0	\$0.00
	1261	tyre pressures	10/08/2016		Hours	0.0	0.0	\$0.00
	1258	Replaced cutting edges, replaced blown bulbs in dash instruments, tighten leaking hose to return hose on L/H/S control valve	11/08/2016	6288	Hours	0.0	0.0	\$0.00
	1256	blow out radiator and top up coolant John	19/08/2016	6327	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1253	Replaced 4 x drive tyres(Michelin) replaced 1 tyre steer(s/h one)Replaced rear light with new led one, replaced 4 drive tyres, replaced 1 x steer tyre with s/h one	20/08/2016	6330	Hours	0.0	0.0	\$0.00
	1251	greased	23/08/2016	6335	Hours	0.0	0.0	\$0.00
	1245	greased(555 25th,26,27)	24/08/2016	6357	Hours	0.0	0.0	\$0.00
	1247	check overheating(Sarsfield) radiator temps, top 90 deg, bottom 70 deg	24/08/2016	6338	Hours	0.0	0.0	\$0.00
	1249	check tyre pressure & adjusted tyre pressures	24/08/2016	6338	Hours	0.0	0.0	\$0.00
	1241	Engine over heat & lacking power, replaced fuel filters, pressure tested intake & intercooler, found boost leaking out VHP solenoid(bunged it off) made bracket & mounted & wired up temp guage on top outside on engine couling, made up fitting to also fit new sender, replaced wiper blades	30/08/2016	6384	Hours	0.0	0.0	\$0.00
	1240	tyre pressures	6/09/2016		Hours	0.0	0.0	\$0.00
	1239	greased	8/09/2016	6403	Hours	0.0	0.0	\$0.00
	1237	greased	12/09/2016	6412	Hours	0.0	0.0	\$0.00
	1236	greased	20/09/2016	6433	Hours	0.0	0.0	\$0.00
	1235	(pump Station) replaced cutting edges and fit new bolts	21/09/2016	6443	Hours	0.0	0.0	\$0.00
	1233	Checked tyre pressures John Westbrook	1/10/2016		Hours	0.0	0.0	\$0.00
	1231	(fault code active) B4 alarm circuit short circuit found wires rubbed transmission controller, insulated and tested ok	4/10/2016	6484	Hours	0.0	0.0	\$0.00
	1228	carry out 500hr service as per sheet, refitted & wired in turbo timer, shimmed up blade slides, removed old broken window & cleaned up & fitted new one.removed & replaced cutting edges checked wiring to transmission sensor ok	6/10/2016	6498	Hours	0.0	0.0	\$0.00
	1226	tyre pressure John	11/10/2016		Hours	0.0	0.0	\$0.00
	1225	greased John	16/10/2016	6530	Hours	0.0	0.0	\$0.00
	1224	tyre pressures	18/10/2016		Hours	0.0	0.0	\$0.00
	1220	replaced worn cutting edges carry out general check over, blew out air filter	21/10/2016	6540	Hours	0.0	0.0	\$0.00
	1222	greased	21/10/2016		Hours	0.0	0.0	\$0.00
	1218	greased	22/10/2016	6551	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1216	greased John	26/10/2016	6558	Hours	0.0	0.0	\$0.00
	1214	greased and replace cutting edges John	28/10/2016	6582	Hours	0.0	0.0	\$0.00
	1212	greased John	30/10/2016	6584	Hours	0.0	0.0	\$0.00
	1210	greased	4/11/2016	6595	Hours	0.0	0.0	\$0.00
	1209	tyre pressures	5/11/2016		Hours	0.0	0.0	\$0.00
	1207	water getting into cab, found rubber grommet on roof u/s silicone up, blew out engine air filter	8/11/2016	6617	Hours	0.0	0.0	\$0.00
	1205	replaced cutting edges, refused old bolts, greased machine John/Graham	10/11/2016	6625	Hours	0.0	0.0	\$0.00
	1204	tyre pressures John Westbrook	11/11/2016		Hours	0.0	0.0	\$0.00
	1203	greased John Westbrook	12/11/2016	6634	Hours	0.0	0.0	\$0.00
	1201	greased	17/11/2016	6655	Hours	0.0	0.0	\$0.00
	1200	greased John Westbrook	21/11/2016	6661	Hours	0.0	0.0	\$0.00
	1199	tyre pressures John Westbrook	22/11/2016		Hours	0.0	0.0	\$0.00
	1197	tyre pressure John Westbrook	27/11/2016		Hours	0.0	0.0	\$0.00
	1196	replace cutting edges(Rom) Matt/Brendan	29/11/2016	6674	Hours	0.0	0.0	\$0.00
	1193	greased	3/12/2016	6685	Hours	0.0	0.0	\$0.00
	1194	(S9 waste) coolant leak, pressure tested & found leaking around header tank neck & R/H top of radiator , will both need to come out to be repaired	3/12/2016	6685	Hours	0.0	0.0	\$0.00
	1190	leaking radiator and header tank remove and refit repaired radiator fit new coolant hoses Dave/Brendan	5/12/2016	6692	Hours	0.0	0.0	\$0.00
	1192	tyre pressure	5/12/2016		Hours	0.0	0.0	\$0.00
	1187	check tyre pressure John Westbrook	10/12/2016		Hours	0.0	0.0	\$0.00
	1188	replace cutting edges and bolts John Westbrook	10/12/2016	6715	Hours	0.0	0.0	\$0.00
	1185	air con freezing updisassemble air con box and wash out evaporator and reassemble test ok Brendan	11/12/2016	6722	Hours	0.0	0.0	\$0.00
	1184	(OCA) Pos 3 wheel coolant weep, checked tyre pressure ok.Told operator to keep eye on it	15/12/2016	6741	Hours	0.0	0.0	\$0.00
	1179	Carry out 750hr service as per sheet, rear work lights and buzzer not working (plug was disconnected)19/12/16 replaced	18/12/2016	6751	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		blade slides top & bottom & shimmed, trans cooler hose leaking removed so can take to town to get madeFitted new hose and o rings, replaced bulb in L/H/S reverse light					
	1183	tyre pressures	18/12/2016		Hours	0.0	\$0.00
	1177	replaced cutting edges Brendon/Liam	21/12/2016	6771	Hours	0.0	\$0.00
	1174	check tyre pressures John Westbrook	26/12/2016		Hours	0.0	\$0.00
	1170	greased	29/12/2016	6817	Hours	0.0	\$0.00
	1172	complaint of a/c not cooling checked pressures and wiring etcremove seat and found a/c not cycling suspect relay and thermistor faulty ordered	29/12/2016	6817	Hours	0.0	\$0.00
	1165	greased machine	7/01/2017	6870	Hours	0.0	\$0.00
	1164	check tyre pressures	9/01/2017		Hours	0.0	\$0.00
	1163	greased	11/01/2017	6879	Hours	0.0	\$0.00
	1161	Replaced all circle slides top and bottom and shimmed. A/C problem- parts wrong tried to fit new thermistor but didn't work and relay was wrong(recorded parts)	16/01/2017	6885	Hours	0.0	\$0.00
	1159	greased	17/01/2017		Hours	0.0	\$0.00
	1160	greased	17/01/2017	6891	Hours	0.0	\$0.00
	1158	greased John Westbrook	19/01/2017	6915	Hours	0.0	\$0.00
	1157	tyre pressures John Westbrook	21/01/2017		Hours	0.0	\$0.00
	1156	greased John Westbrook	23/01/2017	6921	Hours	0.0	\$0.00
	1155	Wt Wright replaced cutting edges	25/01/2017	6924	Hours	0.0	\$0.00
	1152	A/C PROBLEM PLEASE READ HOW REPAIREDFitted new thermistor & relays, with thermistor plugged in compressor wont turn on, have wired in a Western Star thermostat off a Western Star, relay switches ground to thermostat wiring which turns clutch on/off through thermostat,(previously Steve had plugged in different relay and we heard noise like fuse blowing some where, did not have correct wiring diagram for A/C so was hard to fix problem this is why was done this way to get A/C to work	27/01/2017	6933	Hours	0.0	\$0.00
	1151	grease machine - Matt D	4/02/2017	6945	Hours	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1150	greased	8/02/2017	6960	Hours	0.0	0.0	\$0.00
	1148	greased	12/02/2017	6966	Hours	0.0	0.0	\$0.00
	1109	replaced cutting edges	13/02/2017	6960	Hours	0.0	0.0	\$0.00
	1107	greased machine John Westbrook	17/02/2017	6981	Hours	0.0	0.0	\$0.00
	1108	check tyre pressure John Westbrook	17/02/2017		Hours	0.0	0.0	\$0.00
	1106	greased	21/02/2017	6990	Hours	0.0	0.0	\$0.00
	1105	carry out 1000hr service as per sheet, adjust & shim up circle slides	23/02/2017	7007	Hours	0.0	0.0	\$0.00
	1104	greased	25/02/2017	7010	Hours	0.0	0.0	\$0.00
	1103	tyre pressures	26/02/2017		Hours	0.0	0.0	\$0.00
	1102	greased John Westbrook	28/02/2017	7020	Hours	0.0	0.0	\$0.00
	1100	tyre pressure	7/03/2017		Hours	0.0	0.0	\$0.00
	1101	greased	7/03/2017	7037	Hours	0.0	0.0	\$0.00
	1099	greased	10/03/2017	7040	Hours	0.0	0.0	\$0.00
	1098	oil leak on R/H side of transmission, removed hose & one beside it, (sent to Ch/Towers to get made) refitted & test run ok	13/03/2017	7050	Hours	0.0	0.0	\$0.00
	1097	grease machine John Westbrook	14/03/2017	7060	Hours	0.0	0.0	\$0.00
	1096	tyre pressure John Westbrook	18/03/2017		Hours	0.0	0.0	\$0.00
	1095	greased	22/03/2017	7064	Hours	0.0	0.0	\$0.00
	1094	replace cutting edges	31/03/2017	7077	Hours	0.0	0.0	\$0.00
	1093	greased	6/04/2017	7102	Hours	0.0	0.0	\$0.00
	1092	greased	10/04/2017	7103	Hours	0.0	0.0	\$0.00
	1091	Tyre pressure John Westbrook	11/04/2017		Hours	0.0	0.0	\$0.00
	1090	grease machine	14/04/2017	7115	Hours	0.0	0.0	\$0.00
	1089	Tyre run	18/04/2017		Hours	0.0	0.0	\$0.00
	1088	greased	21/04/2017	7135	Hours	0.0	0.0	\$0.00
	1087	low coolant - checked coolant and topped up 15l, pressure tested cooling system and tightened hose clamps on radiator hoses, replaced radiator cap	22/04/2017	7138	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1085	tyre pressures	26/04/2017		Hours	0.0	0.0	\$0.00
	1086	grease machine	26/04/2017	7170	Hours	0.0	0.0	\$0.00
	1084	greased	20/05/2017	7206	Hours	0.0	0.0	\$0.00
	1083	complete 250hr service - Graham	23/05/2017	7250	Hours	0.0	0.0	\$0.00
	1082	grease machine	25/05/2017	7250	Hours	0.0	0.0	\$0.00
	1081	tyre pressure	30/05/2017		Hours	0.0	0.0	\$0.00
	1080	greased	3/06/2017	7265	Hours	0.0	0.0	\$0.00
	1077	greased machine	7/06/2017	7288	Hours	0.0	0.0	\$0.00
	1078	tyre pressure checks	7/06/2017		Hours	0.0	0.0	\$0.00
	1079	replace cutting edges & tighten loose gear shift lever	7/06/2017	7283	Hours	0.0	0.0	\$0.00
	1076	remove hyd lines gouge 4 x cracks and weld out paint - Calvin	10/06/2017		Hours	0.0	0.0	\$0.00
	1074	greased	15/06/2017	7309	Hours	0.0	0.0	\$0.00
	1075	replaced cutting edges	15/06/2017	7309	Hours	0.0	0.0	\$0.00
	1072	tyre pressure	19/06/2017		Hours	0.0	0.0	\$0.00
	1073	carry out general check over, adjust blade slides & shim up, adjust all hyd cyl ball ends removed shims, fitted new rubber mounting D/S step, cleaned out fuel bowl(water in it)	19/06/2017	7313	Hours	0.0	0.0	\$0.00
	1070	tyre pressure	28/06/2017		Hours	0.0	0.0	\$0.00
	1071	greased	28/06/2017	7349	Hours	0.0	0.0	\$0.00
	1069	greased	1/07/2017	7357	Hours	0.0	0.0	\$0.00
	1068	greased	3/07/2017	7363	Hours	0.0	0.0	\$0.00
	1067	greased	5/07/2017	7376	Hours	0.0	0.0	\$0.00
	1066	tyre pressure	7/07/2017		Hours	0.0	0.0	\$0.00
	1064	replace cutting edges & bolts	11/07/2017	7377	Hours	0.0	0.0	\$0.00
	1063	greased	13/07/2017	7388	Hours	0.0	0.0	\$0.00
	1061	tyre pressures	14/07/2017		Hours	0.0	0.0	\$0.00
	1059	carry uot general check over (leaking radiator)	19/07/2017	7398	Hours	0.0	0.0	\$0.00
	1054	greased machine	21/07/2017	7414	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1056	replace perished fuel hose from tank to filterReset and calibrate inching pedal and clean out fuel cap.Breather blocked , repair broken wire to reverse alarm, resolder top tank in radiator	21/07/2017	7414	Hours	0.0	0.0	\$0.00
	1053	greased	26/07/2017	7420	Hours	0.0	0.0	\$0.00
	1051	greased	29/07/2017	7429	Hours	0.0	0.0	\$0.00
	1049	weld L/H broken cab step, weld crack cab pivot bar, replaced cutting edges	30/07/2017	7434	Hours	0.0	0.0	\$0.00
	1047	Rom front wipers not working found plug in dash unplugged reconnected	1/08/2017	7439	Hours	0.0	0.0	\$0.00
	1046	grease machine	2/08/2017	7453	Hours	0.0	0.0	\$0.00
	1045	tyre pressures	3/08/2017		Hours	0.0	0.0	\$0.00
	1043	Fabricate wheel chock holders	8/08/2017		Hours	0.0	0.0	\$0.00
	1042	greased	11/08/2017	7465	Hours	0.0	0.0	\$0.00
	1041	tyre pressures	12/08/2017		Hours	0.0	0.0	\$0.00
	1040	greased	14/08/2017	7468	Hours	0.0	0.0	\$0.00
	1038	replace cutting edge	17/08/2017	7482	Hours	0.0	0.0	\$0.00
	1035	reset turbo timer coolant leak at radiator looks like radiator cap , tighten lock tags and monitor inspect for under seat coolant leak parts ordered	18/08/2017	7485	Hours	0.0	0.0	\$0.00
	1037	greased machine	18/08/2017	7485	Hours	0.0	0.0	\$0.00
	1033	complete 500hr service shim blade slides	20/08/2017	7485	Hours	0.0	0.0	\$0.00
	1034	tyre pressures	20/08/2017		Hours	0.0	0.0	\$0.00
	1032	greased	22/08/2017	7490	Hours	0.0	0.0	\$0.00
	1031	greased	26/08/2017	7497	Hours	0.0	0.0	\$0.00
	1030	grease machine	30/08/2017	7507	Hours	0.0	0.0	\$0.00
	1029	check tyre pressure	31/08/2017		Hours	0.0	0.0	\$0.00
	1027	grease machine	5/09/2017	7517	Hours	0.0	0.0	\$0.00
	1028	replace cutting edges on S9 waste	6/09/2017		Hours	0.0	0.0	\$0.00
	1026	greased machine	12/09/2017	7531	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	1024	check and adjust tyre pressures	14/09/2017		Hours	0.0	0.0	\$0.00
	1025	replace 24/12 volt convertor for uhfs	14/09/2017	7535	Hours	0.0	0.0	\$0.00
	1023	Greased machine	17/09/2017	7544	Hours	0.0	0.0	\$0.00
	1020	Tyre pressures	22/09/2017		Hours	0.0	0.0	\$0.00
	1021	RESEALED CENTER JOINT & REPLACED HEATER CORERemoved & resealed centre joint & topped up with hyd oil, replaced leaking heater core	22/09/2017	7548	Hours	0.0	0.0	\$0.00
	1019	Replaced 5 Amp voltage regulator for radios with 10 Amp one	24/09/2017	7548	Hours	0.0	0.0	\$0.00
	1018	Greased	25/09/2017	7557	Hours	0.0	0.0	\$0.00
	1016	Check tyre pressures	30/09/2017		Hours	0.0	0.0	\$0.00
	1017	Grease Machine	30/09/2017	7562	Hours	0.0	0.0	\$0.00
	1015	Greased	4/10/2017	7564	Hours	0.0	0.0	\$0.00
	1013	Blew out engine air filter & A/C filter, drained water out of fuel seperator, treat fuel system with fuel treatment	6/10/2017	7583	Hours	0.0	0.0	\$0.00
	1014	Replaced cutting edges x2	6/10/2017	7583	Hours	0.0	0.0	\$0.00
	995	Blew out engine air filter and A/C filter drained water out off fuel separator, treat fuel system with fuel treatment	6/10/2017	7583	Hours	0.0	0.0	\$0.00
	993	Greased	8/10/2017	7592	Hours	0.0	0.0	\$0.00
	994	Cleaned all windows with brake clean to get grease off (rom)	8/10/2017	7591	Hours	0.0	0.0	\$0.00
	991	Greased	12/10/2017	7609	Hours	0.0	0.0	\$0.00
	989	Grease run	16/10/2017	7610	Hours	0.0	0.0	\$0.00
	990	Tyre pressures	16/10/2017		Hours	0.0	0.0	\$0.00
	988	Greased	20/10/2017	7615	Hours	0.0	0.0	\$0.00
	986	tyre pressures	21/10/2017		Hours	0.0	0.0	\$0.00
	987	(Rom) a/c not cold, hot air coming through vents ,looped heater hoses under cab(seam to be flap in cab not working correctly) topped up coolent	21/10/2017	7619	Hours	0.0	0.0	\$0.00
	985	Greased	24/10/2017	7625	Hours	0.0	0.0	\$0.00
	984	replace cutting edges and investigate heater not turning off completely,cut off flaps not sealing or fully closing,suspect	26/10/2017	7636	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	983	main housing warped ordered heater taps to isolate core grease machine	28/10/2017	7646	Hours	0.0	0.0	\$0.00
	982	Check tyre pressures	30/10/2017		Hours	0.0	0.0	\$0.00
	980	Greased	1/11/2017	7659	Hours	0.0	0.0	\$0.00
	978	Check tyre pressures	8/11/2017		Hours	0.0	0.0	\$0.00
	976	Grease machine	9/11/2017	7677	Hours	0.0	0.0	\$0.00
	975	Grease machine replace cutting edges	15/11/2017	7703	Hours	0.0	0.0	\$0.00
	974	greased	18/11/2017	7706	Hours	0.0	0.0	\$0.00
	973	Tyre pressures	19/11/2017		Hours	0.0	0.0	\$0.00
	972	Remove screw from pod 4 tyre and plug with wick,pump up tyre to 50 PSI	21/11/2017	7719	Hours	0.0	0.0	\$0.00
	970	Grease machine	26/11/2017	7729	Hours	0.0	0.0	\$0.00
	971	Check and adjust tyre pressures	26/11/2017		Hours	0.0	0.0	\$0.00
	969	Carry out 250hr service as per sheet,Drained and flushed and replaced coolant with tec infinity,Blew out air filters and A/C filters	30/11/2017	7742	Hours	0.0	0.0	\$0.00
	968	Replaced worn cutting edges	2/12/2017	7754	Hours	0.0	0.0	\$0.00
	967	Grease run	3/12/2017	7757.2	Hours	0.0	0.0	\$0.00
	965	Repair cracks on spread bar and blade	4/12/2017	7759	Hours	0.0	0.0	\$0.00
	966	Slide supports cracked along spreader bar,Removed molemoard for boily repairs,Removed moleboard slide cylinder	4/12/2017	7759	Hours	0.0	0.0	\$0.00
	963	Check and adjust tyre pressure if needed	5/12/2017		Hours	0.0	0.0	\$0.00
	964	Reassemble/Fit blade,Fit grader blade back to frame,Hook up hyd cylinder and hoses,Shimed up bottom pivot,Cut down rear guards and drill new holes,fit and test for clearance/fouling,test ok.	5/12/2017	7759	Hours	0.0	0.0	\$0.00
	962	Greased	7/12/2017	7771	Hours	0.0	0.0	\$0.00
	961	Greased	11/12/2017	7776	Hours	0.0	0.0	\$0.00
	960	Topped up Hyd oil(4 litres)	13/12/2017	7779	Hours	0.0	0.0	\$0.00
	959	Greased	19/12/2017	7816	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	954	Tyre Pressures	21/12/2017		Hours	0.0	0.0	\$0.00
	957	Greased	23/12/2017	7818	Hours	0.0	0.0	\$0.00
	958	Tyre pressures	23/12/2017		Hours	0.0	0.0	\$0.00
	49	Replaced blown hose on blade slide	26/12/2017	7827	Hours	0.0	0.0	\$0.00
	956	Hose on blade slide blown,changed with a similar hose.Original hose to be remade and hose that was fitted to go back into stock.	26/12/2017	7827	Hours	0.0	0.0	\$0.00
	84	Check Tyre Pressures	27/12/2017		Hours	0.0	0.0	\$0.00
	955	Greased	27/12/2017	7835	Hours	0.0	0.0	\$0.00
	953	Greased	31/12/2017	7843	Hours	0.0	0.0	\$0.00
	952	Plumb in heater taps.Repair L/H step that was bent.Grease all points	1/01/2018	7843	Hours	0.0	0.0	\$0.00
	160	Grease Machine	8/01/2018	7853	Hours	0.0	0.0	\$0.00
	212	REPLACED BLADE CUTTING EDGES X 2 .	12/01/2018	7866	Hours	0.0	0.0	\$0.00
	208	CARRY OUT GENERAL CHECK OVER , BLEW OUT ENGINE AIR FILTER & A/C FILTER , RELOCATED STEERING HOSE FROM RUBBING & SECURED .	12/01/2018	7866	Hours	0.0	0.0	\$0.00
	241	(ROM) REPLACED BLADE SLIDE HOSE WITH CORRECT ONE (FITTED ONE DAYS BEFORE WAS TOO LONG SO GOT CORRECT ONE MADE)	14/01/2018	7866	Hours	0.0	0.0	\$0.00
	302	Check Tyre Pressures	16/01/2018		Hours	0.0	0.0	\$0.00
	355	Grease Machine	20/01/2018	7883	Hours	0.0	0.0	\$0.00
	493	Grease Machine	24/01/2018	7885	Hours	0.0	0.0	\$0.00
	478	Check Tyre Pressures	30/01/2018		Hours	0.0	0.0	\$0.00
	459	WASH , GENERAL CHECK OVER , SHIMMED UP EXCESSIVE PLAY IN BLADE SLIDES , ENGINE TEMP GAUGE NOT WORKING REPAIRED WIRING , FIT TRANSMISSION TEMP GAUGE TO TOP ENGINE COVER BESIDE ENG TEMP GAUGE , WIRE UP & FIT TEMP SENDER TO TRANSMISSION .	30/01/2018	7901	Hours	6.0	6.0	\$0.00
	513	Found oil leaking from transmission temp sensor, replaced sensor and tested	1/02/2018	7905	Hours	2.0	2.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	541	Grease Machine	2/02/2018	7905	Hours	0.0	0.0	\$0.00
	564	Grease Machine	6/02/2018	7908	Hours	0.0	0.0	\$0.00
	694	Check Tyre Pressures	7/02/2018		Hours	0.0	0.0	\$0.00
	664	Grease Machine	10/02/2018	7919	Hours	0.0	0.0	\$0.00
	722	Grease Machine	14/02/2018	7925	Hours	0.0	0.0	\$0.00
	728	Removed and replaced cutting edges.	16/02/2018	7930	Hours	1.0	1.0	\$0.00
	737	Check Tyre Pressures	17/02/2018		Hours	0.0	0.0	\$0.00
	824	Grease Machine	22/02/2018	7937	Hours	0.0	0.0	\$0.00
	856	Check Tyre Pressures	25/02/2018		Hours	0.0	0.0	\$0.00
	929	Grease Machine	2/03/2018	7945	Hours	0.0	0.0	\$0.00
	1111	Grease Machine	7/03/2018	7964	Hours	0.0	0.0	\$0.00
	1464	Check Tyre Pressures	7/03/2018		Hours	0.0	0.0	\$0.00
	2060	Check Tyre Pressures	13/03/2018		Hours	0.0	0.0	\$0.00
	1894	2000 hour Grader Service completed. Removed pos 6 wheel end and replaced wheel seal, refitted whell end and refilled oil. Removed and replaced cutting edges.	16/03/2018	7974	Hours	83.5	23.5	\$0.00
	2130	Grease Machine	18/03/2018	7985	Hours	0.0	0.0	\$0.00
	2165	Check Tyre Pressures	20/03/2018		Hours	0.0	0.0	\$0.00
	2225	Grease Machine	22/03/2018	7993	Hours	0.0	0.0	\$0.00
	2266	Grease Machine	26/03/2018	7997	Hours	0.0	0.0	\$0.00
	2371	Topped up coolant and hydraulic oil.	28/03/2018	7997	Hours	0.5	0.5	\$0.00
	2418	Replaced flat pos 4 tyre with a run out. Greased and checked all tyre pressures	30/03/2018	8008	Hours	20.0	7.0	\$0.00
	2447	Check Tyre Pressures	30/03/2018		Hours	0.0	0.0	\$0.00
	2457	Grease Machine	30/03/2018	8008	Hours	0.0	0.0	\$0.00
	2490	Grease Machine	3/04/2018	8012	Hours	0.0	0.0	\$0.00
	3061	Grease Machine	8/04/2018		Hours	0.0	0.0	\$0.00
	3028	(ROM) LEAKING FITTING ON AFTERMARKET TRANS TEMP FITTING WENT TO TIGHTEN & BROKE FITTING	10/04/2018	8048	Hours	2.0	2.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		MADE NEW FITTING & FITTED TEST RUN OK , TRANS FAULT COMING UP CHECKED OVER WIRING & TSET COULD NOT GET TO DO IT .					
	3411	Check Tyre Pressures	12/04/2018	Hours	0.0	0.0	\$0.00
	3510	Grease Machine	16/04/2018	Hours	0.0	0.0	\$0.00
	4030	REPLACED CUTTING EDGES & BOLTS , BLEW OUT ENGINE & A/C FILTERS .	20/04/2018	8073 Hours	1.0	1.0	\$0.00
	4128	Grease Machine	24/04/2018	Hours	0.0	0.0	\$0.00
	4161	Check Tyre Pressures	24/04/2018	Hours	0.0	0.0	\$0.00
	4095	(ROM) TOP UP ENGINE OIL (3 LITRES)	24/04/2018	Hours	0.5	0.5	\$0.00
	4848	Removed stick that was jammed up in belly plate/ engine bay.	11/05/2018	8113 Hours	0.5	0.5	\$0.00
	4908	Diagnose engine low power. Removed and replaced fuel filter, cleaned out fuel/ water separator.	14/05/2018	8113 Hours	1.0	1.0	\$0.00
	5193	Replaced worn cutting edges with new ones & bolts .	22/05/2018	8129 Hours	1.0	1.0	\$0.00
	5198	General check over , re shimmed blade slides (Not sliding correctly) , spray lubed all blade slides & pivots , blew out all engine & a/c filters , topped up hyd oil (3 litres)	22/05/2018	8129 Hours	2.0	2.0	\$0.00
	5566	Replaced faulty uhf on rhs and tested	28/05/2018	8150 Hours	0.5	0.5	\$0.00
	5705	Removed and replaced cutting edges.	8/06/2018	8175 Hours	1.5	1.5	\$0.00
	5800	(Rom) L/h step bent , bent back into position with piece of pipe .	16/06/2018	8180 Hours	0.5	0.5	\$0.00
	5941	Greased and checked over machine. Topped up engine oil, blew out air filters etc.	22/06/2018	8193 Hours	1.5	1.5	\$0.00
	5954	Removed and replaced all 6 tyres with new michelins.	23/06/2018	8194 Hours	10.0	10.0	\$0.00
No of W/O for 555 : 564			Asset Total:	555	135.0	62.0	\$0.00
GD555	555 - 2007 GD555-3C Komatsu Grader						
	8164	250 hour Grader Service , Washed , installed new alarm buzzers (code was coming up) code still there inspected & found new buzzer wiring plug was wired up wrong fixed & code went out ,	24/09/2018	8225 Hours	2.0	2.0	\$0.00
	9713	Checked start fault, found rhs battery down to 8.5 volts and fuel shutoff solenoid over cammed rod into off position, will	8/01/2019	8294 Hours	0.5	0.5	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		need adjusting and tightening lock nut.						
	9784	Adjusted governor rod and nut from fuel shut off solenoid and tested function. (had come undone)	11/01/2019	8300	Hours	1.0	1.0	\$0.00
	10231	(Rom) would not start , replaced r/h u/s battery .	21/02/2019	8325	Hours	1.0	1.0	\$0.00
	10294	(Rom) Replaced cutting edges X 2	25/02/2019	8327	Hours	1.0	1.0	\$0.00
	10849	Tightened work light mounts, adjusted and lubed lh door latch. Removed circle drive and replaced pinion seal, refitted and refilled with oil. Adjusted circle wear pads, welded crack in lhs access step, cab fan u/s and needs replacement.	7/04/2019	8346	Hours	29.0	14.0	\$0.00
	11052	Topped up hydraulic oil 5L	27/04/2019	8362	Hours	0.5	0.5	\$0.00
	11210	Washed and checked over, removed u/s cab fan, cleaned cab and lubed up door latches and hinges.	8/05/2019	8366	Hours	6.0	6.0	\$0.00
	11310	(Kakadu) Flip over all ripper tines on back .	15/05/2019	8373	Hours	1.0	1.0	\$0.00
	11657	Replaced fan belt , Replaced faulty hour meter (Hr meter was 8386 hrs now 0 hrs)	27/05/2019		Hours	3.5	3.5	\$0.00
	11484	Removed and replaced broken bolt in lhs accumulator, shimmed blade slides. 8806km	28/05/2019	1202	Hours	5.0	5.0	\$0.00
	11638	Replaced cutting edges & replaced l/h worn blade slide bush .	30/05/2019	10	Hours	2.0	2.0	\$0.00
	12805	Topped up coolant	15/08/2019		Hours	0.5	0.5	\$0.00
	12922	Replaced cutting edges	24/08/2019	70	Hours	1.5	1.5	\$0.00
	13597	Check over machine going to town , made sure all door locks work & lubed , topped up hyd oil (5 litres) Shimmed up 3 x blade slides	21/10/2019	101	Hours	3.0	3.0	\$0.00
	14362	Accumulator mode on blade circuit not working properly , checked pressures both 70 / 80 psi (supposed to be 290 psi) adjusted pressures , tested solenoid & wiring (ok) tested seemed to be working now .	24/12/2019	147	Hours	0.0	2.0	\$0.00
	14426	Removed and replaced cutting edges with new.	31/12/2019	156	Hours	1.0	1.0	\$0.00
	15160	250 hour Grader Service completed.	13/03/2020	236	Hours	2.0	2.0	\$0.00
	15357	Replaced blown blade slide hose (rocks jammed in ram & slide)	7/04/2020	245	Hours	0.0	1.0	\$0.00
	16057	R&R blown blade slide hyd hose RHS removed all rocks stuck in blade cylinders	4/07/2020	299	Hours	19.5	3.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	16296	Repaired reverse alarm wiring, checked alarm coming on at start up, topped up trans oil, carried out re learn on transmission and accelerator and inching pedals.	16/08/2020	326	Hours	5.0	5.0	\$0.00
	16352	Replaced bottom window	25/08/2020		Hours	0.0	2.0	\$0.00
	16752	Would not start , replaced faulty l/h battery with new a/c delco one (test run ok)	12/11/2020	345	Hours	0.0	2.0	\$0.00
	17319	(Pratches house yard)Machine engine running ruff , put 210 litres fuel , removed filters & filled with fuel , blew back fuel line to tank , bleed system & test run ok .	7/03/2021	428	Hours	0.0	1.0	\$0.00
	17582	Removed l/h step assembly , fabricate new step , straighten rest of assembly , bolt back together & refit to machine .	3/05/2021	461	Hours	0.0	4.0	\$0.00
	17619	No reverse gear,Found bolt had wound out of gear lever. Refitted bolt and tested	12/05/2021	465	Hours	0.0	1.0	\$0.00
	17667	Oil leak Blade , replaced blade slide hose , washed & test run ok .	22/05/2021	480	Hours	0.0	2.0	\$0.00
	17736	Replaced cutting edges	2/06/2021	496	Hours	0.0	1.5	\$0.00
	17725	500 hour Grader Service completed, drained and sucked debis from fuel tank, refilled and added fuel dose. Repaired wiring to sensor in diff, adjusted circle, replaced all oils as some had 900hrs due to hour meter being changed out.	7/06/2021	496	Hours	111.0	25.0	\$0.00
	18130	travel to site , Would not go into reverse , tighten loose screw in gear shift lever .	2/09/2021	551	Hours	0.0	1.0	\$0.00
	18163	Replaced cutting edges , general check over , blew out all filters , topped up washer fluid	4/09/2021	561	Hours	0.0	2.0	\$0.00
	18440	Replaced cracked windscreen , adjusted all tyre pressures , general check over , blew out all filters , greased , jacked up & checked front end ,	11/11/2021	641	Hours	0.0	8.5	\$0.00
	18595	Brake pressure light coming on, pressure check cut in and cut out pressures on brake accumulators, removed pos 4 and bled all brakes. Dropped bottom plate with brake accumulators attached, checked accumulator gas pressures and found 35psi and 350psi, discharged and checked for oil, recharged accumulators and reassemble machine and test.	18/12/2021	687	Hours	6.5	6.5	\$0.00
	18680	check over,wash, clean windows, blow filters, A/C filters, check lights, check fluidscheck tyre pressures, cutting edges in good condition	7/01/2022	687	Hours	0.0	4.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	19544	Check Tyre Pressures	16/07/2022		Hours	0.0	4.0	\$0.00
	19700	Grease Machine as per sheet	16/08/2022		Hours	0.0	4.0	\$0.00
	19712	Inspect machine, blown hose to tranny filter, move grader out of the wayReplace hose, fill tranny oil, test runBring back to site, wash and degreasePark brake not holding, inspect park brake. Out of adjustmentPark brake needs to be inspected for wear and adjusted if possible	17/08/2022	687	Hours	6.0	6.0	\$0.00
	19686	Adjust park brake, inspect components. Test	18/08/2022	741	Hours	2.5	2.5	\$0.00
	19732	250 hour Grader Service , washed , adjusted all tyre pressures , replaced reverse alarm to squawker type , repaired turbo timer fault , made & replaced artic hose bracket , topped up trans oil , drained over full drive case oil , replaced engine oil & filter , fuel filters , air filter & a/c filter .	24/08/2022	751	Hours	16.0	8.5	\$0.00
	19809	Take back to depot and wash, Tranny temp gauge on zero, C/O HS belt. Check over wiring under shift lever and testedRemove alarm for testing	6/09/2022	756	Hours	4.0	4.0	\$0.00
	19817	Found fitting on side shift cylinder snapped off, due to reject rocks stuck under RAM conesTook back to depot, washed and removed cylinder. Chris cut old fitting off and weld new one on.Re-fit cylinder, test run, wash and park on go line	13/09/2022	775	Hours	7.5	7.5	\$0.00
	19830	Grease Machine as per sheet	15/09/2022		Hours	0.0	4.0	\$0.00
	19868	Replace cutting edges	22/09/2022	779	Hours	1.5	1.5	\$0.00
	20183	Removed P1/P2/P3/P4/P5 and p6 tyres. Cleaned rim assemblies. Kept P1/2/3/4/6 for R/O tyres. Scrapped P5 tyre due to puncture. Installed all new tyres and O-rings. Installed new lock ring to P4.Filled P1/2 tyres 50 percent with water.	28/11/2022	824	Hours	11.0	10.5	\$0.00
	20199	C/O cutting edges and bolts.	2/12/2022	8468	Hours	1.0	1.0	\$0.00
	20198	Removed cover, replaced O-ring and tighten hose and refit cover. Wash oil off blade.	2/12/2022	851	Hours	0.5	0.5	\$0.00
	20269	Leaking hyd oil RH side shift area found rocks jammed under blade side shift covers removed covers too remove all rocks ,Found rocks had damaged hose & o-ring & broken cover on RHS replaced o-ring welded up cover refit & tested topped up hyd oil washed unit sent too work.	17/12/2022	886	Hours	2.0	2.0	\$0.00
	20279	C/O cutting edges	19/12/2022	889	Hours	0.5	0.5	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	20298	Side shift cylinder missing retainer bolt & washer fab up new washer fit & tested	20/12/2022	912	Hours	1.0	1.0	\$0.00
	20341	Check over and wash machine	27/12/2022	945	Hours	4.0	4.0	\$0.00
	20367	Brought machine back to depot. On arrival found coolant leak, heater hose had hole in it. Turned off heater taps, hose will need replacing at some point. Thorough check over A/C system, didn't see visible leaks, had no dye. Cleaned cabin filter. Gassed A/C system, compressor noisy. Condenser has had a few Knicks in it, but cant see leaks. Removed rear grill and flushed coolers and condenser. A/C cold for now.Recommend doing a A/C system overhaul.	31/12/2022	978	Hours	3.0	3.0	\$0.00
	20371	Re-gas A/C. Lube seat and glue rubber onto adjuster. Fit new bolt and retainer	5/01/2023	1023	Hours	2.5	2.5	\$0.00
	20390	heat up and straighten bent steps. Reweld where cracked from being bent	10/01/2023	1028	Hours	2.0	2.0	\$0.00
	20405	1000 hour Grader Service completed, removed and rebuilt rhs lift cylinder, adjusted play in drawbar ball joint, replaced and shimmed blade slides, fixed windscreen washers, temporary repaired a/c leak and topped up gas.	15/01/2023	1030	Hours	97.0	31.5	\$0.00
	20425	Inspected oil level in tranny, found low. Topped up. Topped up hydraulic oil , no transmission light illuminated. Inspected A/C system fault, found low on refrigerant and compressor noisy. Topped up with 750grams of R134a and ensured compressor ordered for A/C overhaul	20/01/2023	1087	Hours	2.0	2.0	\$0.00
	20493	Welded crack in bottom of fuel tank. Removed battery boxes ect..	26/01/2023		Hours	6.0	6.0	\$0.00
	20631	Strip components and hoses. Replaced condenser, Evap, Rx/dryer, HP and LP compressor hoses, compressor. Strip and wash out Evap box, clean out cab, buff and paint rust in cab floor. Close system once parts are fitted, vac system for 3 hours, gas and tested (dye added). Re-assemble cab and panels. Fit new beacon light. Fixed sticking engine door cover latches. Need to order new fan speed resister and or new fan. Can be replaced without removing whole Evap box	24/02/2023	1185	Hours	88.0	28.5	\$0.00
	20912	Trammed back to depot and washed. Removed and replaced fan speed resisters and tested. Replaced circle wear pads and adjusted circle. Shimmed to spec. Tested operation and	27/04/2023	1252	Hours	31.5	19.5	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		ensured turning freely. Replaced worn tilt clamp on mull board and adjusted. Welded up crack in tilt bar. Repaired hydraulic leak on side shift cylinder. Shimmed up ball					
	20944	250 hour Grader Service completed, shimmed and replaced blade slides.	10/05/2023	Hours	6.5	6.5	\$0.00
	20814	Grease Machine	10/05/2023	Hours	0.0	0.0	\$0.00
	20815	Grease Machine	10/05/2023	Hours	0.0	0.0	\$0.00
	21010	Grease Machine as per sheet	28/05/2023	Hours	0.0	4.0	\$0.00
	21235	Wash. Remove side shaft cylinder. Weld new fitting onto cylinder. Refit cylinder. Test and wash	8/07/2023	1280 Hours	4.0	4.0	\$0.00
	21231	Fill tank, bled up and test	9/07/2023	1281 Hours	1.0	1.0	\$0.00
	21655	Pumped up Pos4 tyre and checked for leaks around bead and locking ring. Checked and adjusted tyre pressure on other tyres	4/10/2023	1324 Hours	1.5	1.5	\$0.00
	21672	Re-kit blade lift cylinders. LH one tight coming out, unscrewing head. Damage to head and cylinder. Cleaned up threads and body of head where O-ring/back up ring sit and gouge marks on inside of cylinder, then reassembled. Wash down and tested	5/10/2023	1332 Hours	8.0	6.0	\$0.00
	21796	C/O cutting edges	4/11/2023	1352 Hours	2.0	2.0	\$0.00
	21909	Change hour metre and install 24v to 12v converter	26/11/2023	1415 Hours	3.0	3.0	\$0.00
	21970	Block up RH tandem and limp back to depot from top of TFS. C/O pos6 tyre. Set old tyre aside for puncture repair. Parked on Go-line	6/12/2023	37 Hours	2.0	2.0	\$0.00
	21958	1000 hour Grader Service	8/12/2023	1585 Hours	0.0	0.0	\$0.00
	22092	Change Pos4 tyre	27/12/2023	48 Hours	2.0	2.0	\$0.00
	22121	Pick up from site and washed. C/O cutting edges. Checked over washers, found bottles to be blocked with green algae. Removed bottles, washed out. Blew lines through, fit and refill, tested	12/01/2024	77 Hours	3.0	3.0	\$0.00
	22477	C/O Pos3 tyre and put on new lock ring, old one stretched	22/03/2024	136 Hours	1.5	1.5	\$0.00
	22782	C/O pos O-Ring as it was leaking top up with coolant wash & tested.	18/06/2024	178 Hours	2.0	2.0	\$0.00
	22968	Replace cutting edges. Fab bracket to hold roof triangle.	6/08/2024	225 Hours	18.5	6.5	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		Replace work lights on top of cab. Full check over. Top up hydraulic oil 10L						
	23038	C/O Pos3 flat with R/O	22/08/2024	230	Hours	1.0	1.0	\$0.00
	23086	Tighten gear shift lever	3/09/2024		Hours	0.5	0.5	\$0.00
	23152	Carry out 250 hour Grader Service	20/09/2024	236	Hours	4.5	4.5	\$0.00
	23653	Flat Pos4 on go-line, jack up and C/O O-ring. Pumped up tyre and took down to workshop. Let sit overnight and check in the morning, still at 50psi. Spray with soapy water, found a leak. O-ring at fault	31/12/2024	258	Hours	15.0	3.0	\$0.00
	23889	Check over. Blow out air filter. Top up coolant. Check tyre pressure. Hose off radiators. * Left hand tilt RAM is leaking	27/02/2025	271	Hours	2.5	2.5	\$0.00
	24211	Flat tyre pos 6 , removed & replaced tyre with run out tyre ,	6/05/2025	310	Hours	3.0	3.0	\$0.00
	24417	Resealed lh steer cylinder, checked over machine, removed blade slide cylinder guards and removed jammed rocks, reinstalled guards.	20/06/2025	318	Hours	6.0	6.0	\$0.00
	24529	Replace worn cutting edges.	15/07/2025	3310	Hours	1.0	1.0	\$0.00
	24555	Prepare machine for hireCheck over machine top up fluidsClean machine and cab. Unblock washersReplaced batteries	18/07/2025	335	Hours	9.0	9.0	\$0.00
	25291	C/O pos 1&2 with 2 new fit pos 2 to pos 6 patch/welded roof.	9/12/2025	433	Hours	4.0	4.0	\$0.00
	25294	Leaking RH steering cylinder reseal & tested.	11/12/2025	438	Hours	3.0	3.0	\$0.00
	25611	Flat Pos 4 tyreRemove & Refit pos 3 and pos 4 tyresChecked for leaks	3/02/2026	452	Hours	3.0	0.0	\$0.00
	25717	Replaced pos 5 and 6 tyres.	3/03/2026	457	Hours	2.5	2.5	\$0.00
No of W/O for GD555		:	88	Asset Total:	GD555	602.0	358.5	\$0.00
No of W/O for [REDACTED]		:	652	Parent Total:	[REDACTED]	737.0	420.5	\$0.00
Grand Total			652			737.0	420.5	\$0.00