

Asset History Report

Thursday, 20 August 2

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
WS10	WS10 - 2014 4900 Series Western Star Primemover							
199	REPLACED L/H/R DOWY DRIVE TYRE ,	11/01/2018	.00	.00	1.00		Request	\$0.00
361	Refitted lhs headlight with new retaining bracket	20/01/2018	.50	.50	.50		Correct	\$0.00
467	Truck Weekly Check Over. front rhs spring sagged	1/02/2018	1.00	1.00	1.00	9	PM	\$0.00
568	Swapped front springs from left to right as right was sagged.	5/02/2018	5.50	5.50	5.50		Correct	\$0.00
670	Adjusted turntable and replaced wheel brace bar in cab.	14/02/2018	1.00	1.00	1.00		Correct	\$0.00
867	REPLACED R/H BROKEN BONNET HINGE , CHECK ENGINE LIGHT ON , FOUND DPF CODE , CHECKED WIRING TO SENSORS , ECM DOSENT CONVERT VOLTAGE TO DEGREES CELSIUS, ON INLET TEMP SENSOR , DONE FAULT TROUBLE SHOOTING & SAID ECM FAULTY , REMOVED ECM & SENT TO TOWN TO GET FLASHED TO NEW ECM , FITTED NEW ECM & CODE WAS FIXED TEST RUN OK . PYRO DOSE NOT WORK REPLACED SENSOR WORKS OK .	24/02/2018	80.00	17.0	16.50		Break	\$0.00
4478	REPLACED POS 3 FLAT DRIVE TYRE	7/05/2017	.00	.00	.00		PM	\$0.00
4479	177940 KMREPLACE TURNTABLE SKID PADS	11/05/2017	.00	.00	.00		PM	\$0.00
4481	REPLACE BOTH WINDSCREENSCOOLECTRIX REPAIRED A/C BLOWN HOSE	16/05/2017	.00	.00	.00		Correct	\$0.00
4482	REMOVED DAMAGED MAIN DRIVE SHAFT TO SEND TO TOWN	29/05/2017	.00	.00	.00		Correct	\$0.00
4483	FIT UP REBUILT DRIVE LINE, FITTED NEW UNI'S & CENTER BEARING(GRAHAM MILLER)	1/06/2017	.00	.00	.00		PM	\$0.00
4495	179187 KMCARRY OUT 250 HR SERVICE AS PER SHEETREPLACED MOUNT BUSHES ON TURNTABLE &	1/06/2017	.00	.00	.00		PM	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
	FITTED DOG BONE WEAR PLATESREPLACE BULBS IN FRONT BLINKERSREPLACED BROKEN BRAKE BACKING PLATE(GRAHAM MILLER)							
4496	REPLACED BROKEN BONNET PIVOT ROSE JOINT LHGREASED CLUTCH THROW OUT BEARING	7/06/2017	.00	.00	.00		PM	\$0.00
4497	(SARSFIELD) NOISE IN SEAT LUBED UP	15/06/2017	.00	.00	.00		PM	\$0.00
4499	183340 KMCARRY OUT WEEKLY SERVICE AS PER SHEETELECTRICAL FAULT REPLACED TRAILER PLUG REAR OF CABDPF EXHAUST GASKET LEAKING, REPLACED GASKET(PIPE U/S)(GRAHAM MILLER)	18/06/2017	.00	.00	.00		PM	\$0.00
4503	184032 KMENGINE BRAKE NOT WORKING ON 3RD STAGEHOOKED UP COMPUTER AND CHECKED SWITCHES ON DASHREMOVED PLUG FROM ENGINE AND CLEANED OIL OUT AND RETRIED TEST OK	24/06/2017	.00	.00	.00		PM	\$0.00
4505	186603 KMCARRY OUT WEEKLY SERVICE AS PER SHEET	3/07/2017	.00	.00	.00		PM	\$0.00
4506	REPAIRED BROKEN EARTH STRAP ON ALTERNATOR	8/07/2017	.00	.00	.00		PM	\$0.00
4507	187440 KMCARRIED OUT 2000 HR SERVICEREPAIRED CRACK IN REAR OF FRONT DIFF HOUSINGREPAIRED SMALL CRACK AROUND HYD TANK SUCTION LINE	8/07/2017	.00	.00	.00		PM	\$0.00
4519	187921 KMREMOVED AND REPAIRED WORN D/S SEAT ASSEMBLY WITH NEW NATIONAL ONE	12/07/2017	.00	.00	.00		Correct	\$0.00
4520	188782 KMEXHAUST BROKEN AT FLEX BEHIND CABREPLACED FLEX AND CLAMPS, REPLACED LOOSE CLAMP ON L/H SIDE EXHAUST STACKREMOVED REAR PIPE TO DPF & REPLACED WORN FLANGE ON PIPE(CUT OFF & WELDED ON NEW ONE, RE SILICONED ALL PLUGS INTO BOOSTERS(GRAHAM MILLER)	15/07/2017	.00	.00	.00		Correct	\$0.00
4521	190789 KMCOMPLETE WEEKLY SERVICE AND CHECK OVER REPLACE CLUTCH MASTER WITH REMAN UNIT LOAD TEST BATTERIESREPAIR AIR LEAKS, CHECK OVER FRONT SPRING SAGGING 50MM DROP ON R/H SIDE	22/07/2017	.00	.00	.00		PM	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
4522	REMOVE HYD TANK AND BOILERMAKERS WELDED BOSS TO REPAIR CRACKFAULT FIND SLUGGISH STARTING FOUND CASING BOLTS LOOSE TIGHTEN AND TEST OK	24/07/2017	.00	.00	.00		Correct	\$0.00
4523	FAN BELT WEARING FUNNYREMOVED CHECKED ALL PULLEYS AND BEARINGS COULDN'T SEE ANYTHING WRONGREASSEMBLED AND TEST RUN OK	26/07/2017	.00	.00	.00		PM	\$0.00
4524	REPAIRED CRACK IN ALLOY STEP	9/08/2017	.00	.00	.00		PM	\$0.00
4525	195209 KMCARRY OUT 250 HR SERVICE AS PER SHEETREMOVED AND REPLACED FAULTY JAKE BRAKE WIRING HARNESSREMOVED R/H CAB STEP TO GET REPAIRED AND REFITTIGHTEN L/H BOTTOM STEP, REMOVED JACK SHAFT AND TORQUED THROUGH SHAFT NUTREPLACED ALL 8 DRIVE TYRES AND REPLACED STEER TYRESREPLACED R/H ROOF LIGHT ASSEMBLY, TOPPED UP HYD OIL 15 LITRES	10/08/2017	.00	.00	.00		PM	\$0.00
4526	CHECK AND ADJUST HYD RELIEF VALVES	21/08/2017	.00	.00	.00		PM	\$0.00
4527	197964 KMCARRY OUT WEEKLY SERVICE AS PER SHEETRESEALED LEAKING HYD FITTING BACK OF CAB	29/08/2017	.00	.00	.00		PM	\$0.00
4528	198513 KMLOCATE SHORT IN LIGHT CIRCUIT IN TRAILER ELECT PLUGREWIRE PLUG AND TEST OK	4/09/2017	.00	.00	.00		Correct	\$0.00
4529	200000 KMWEEKLY SERVICEREPLACE SUNVISORS	12/09/2017	.00	.00	.00		PM	\$0.00
4530	200923 KMREMOVE AND REPLACE D/S BOTTOM STEP WITH NEW ONE	20/09/2017	.00	.00	.00		Correct	\$0.00
4531	REPAIR CRACKED ALLOY SIDE STEP	21/09/2017	.00	.00	.00		PM	\$0.00
4532	202091 KMCARRY OUT WEEKLY SERVICE AS PER SHEETOIL WEEP OUT OF PTO TIGHTEN ALL BOLTS	24/09/2017	.00	.00	.00		PM	\$0.00
4533	202700 KMCARRY OUT WEEKLY SERVICE AS PER SHEET	8/10/2017	.00	.00	.00		PM	\$0.00
4534	(ROM) CHECK ENGINE LIGHT ON, CODES ROAD SPEED, CRANKCASE PRESSURE, ECU POWER, TURBO, ENGINE STARTERENGINE EXHAUST, CLEANED SPEED SENSOR	9/10/2017	.00	.00	.00		PM	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
	ON GEARBOX AND CHECKED WIRINGS SENT TO WORK WILL MONITOR							
4535	REPLACED 8 X DRIVE TYRES (HDO PATTERN) REPLACED BOTTOMS OF REAR ENGINE/TRANS MOUNTS AS HAD WORN OUT X 4	11/10/2017	.00	.00	.00		Correct	\$0.00
4536	CARRIED OUT 500 HR SERVICE REPLACED COOLANT TO TEC INFINITY AFTER COOLANT WAS CHANGED LEAK BEGAN AT HEATER CONTROL VALVE TAP ORDERED PARTS	12/10/2017	.00	.00	.00		PM	\$0.00
4537	CHANGED LEAKING HEATER CONTROL TAPPED AND TOPPED UP COOLANT	17/10/2017	.00	.00	.00		Correct	\$0.00
4538	(MOP) TRUCK LOST POWER ON RAMP CHECKED FAULT CODES FOUND 2791 EGR/EXHAUST GAS CODE CHECK WIRING TO EGR VALVE SEAMS OK, BUT SAYS FAULT CODE EGR VALVE STUCK OPEN DISCONNECTED & BROUGHT BACK TO WORKSHOP REMOVED EGR VALVE FROM TRUCK AND CHECKED FOUND VALVE STUCK REPLACED UNIT WITH S/HAND ONE OFF OLD ENGINE FITTED AND TEST RUN OK CLEARED CODES AND DID FORCED DPF BURN	22/10/2017	.00	.00	.00		Correct	\$0.00
4539	POS 5 AXLE BOLTS LOOSE TIGHTEN ALL AXLES	24/10/2017	.00	.00	.00		PM	\$0.00
4540	204050 KM CARRY OUT WEEKLY SERVICE AS PER SHEET	2/11/2017	.00	.00	.00		PM	\$0.00
4541	204692 KM (SARSFIELD) REPLACED BLOWN CAB AIR BAG	20/11/2017	.00	.00	.00		Correct	\$0.00
4542	REPLACE MISSING BOLT IN POWER STEER RESERVOIR, CLEANED ELECT CONNECTIONS ON ENGINE BRAKE HARNESS	23/11/2017	.00	.00	.00		PM	\$0.00
4543	205330 KM COMPLETE WEEKLY SERVICE TIGHTEN MUDGUARD L/H SIDE REPLACE U/S REVERSE LIGHT SEALED BEAM	24/11/2017	.00	.00	.00		PM	\$0.00
4544	205354 KM R/H FRONT MUD FLAP PERISHED, C/O WITH NEW ONE	31/12/2017	.00	.00	.00		PM	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
5634	250 hour Truck Service , washed , wrapped hoses that are rubbing , adjusted all brakes .	31/05/2018	3.00	3.00	3.00	14	PM	\$0.00
8388	A/c not getting cold, checked pressures and high side only 90psi. Evaporator also badly blocked, washed out with evap cleaner and blew out a/c filters. Repaired air leak at air fittings in treadle valve.	12/10/2018	3.50	3.50	3.50		Correct	\$0.00
8484	Truck Weekly Check Over completed. (208536km)	16/10/2018	2.50	1.50	1.50	9	PM	\$0.00
8485	Replaced leaking access valves, vac and gassed vehicle.	16/10/2018	3.00	3.00	4.00		Correct	\$0.00
9395	a/c not cold. Checked over and found low on gas, leaking from schrader valve. (209113km)	12/12/2018	1.00	1.00	1.00		Correct	\$0.00
9793	Removed and replaced discharge hose from compressor, tx valve dryer and o'rings, vac and gassed (Coolectrix Jason)	7/01/2019	2.00	2.00	2.00		Correct	\$0.00
10371	R&R broken trailer plug	7/03/2019	1.50	1.50	169.5		Request	\$0.00
10507	A/c not working , replaced a/c hoses x 2 to tx valve , found leaking evaporator replaced with new one . vac & gased , test run ok . (Jason)	11/03/2019	.00	.00	.00		Request	\$0.00
10593	Replaced flat tyre pos 6	21/03/2019	.50	.50	.50		Request	\$0.00
10655	Truck Weekly Check Over completed, bled clutch hydraulic system. (211191km)	28/03/2019	3.00	3.00	3.00	9	PM	\$0.00
10784	Starting problem , load tested batteries ok , found through shaft bolts on starter motor loose tighten & test run ok , will monitor .	7/04/2019	.50	.50	.50		Request	\$0.00
11122	1000 hour Truck Service , Remove & reseal front diff counter shaft cap plate , Clutch pedal stuck to floor replaced faulty clutch master cylinder & bleed system , Replaced all diff & gearbox breathers to new filter style , removed all battery cables & cleaned load tested batteries sprayed all terminals with protectant spray . (212867 Km)	1/05/2019	13.50	13.5	13.50	17	PM	\$0.00
11271	Removed and replaced air filters as there was no stock when service was completed. Drained and replaced transmission oil due to bad sample (dust) checked breather lines and found	10/05/2019	5.00	5.00	5.00		Correct	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
12097	had no ivile in fitting near filter, repaired. Clutch pedal wont return, removed inspection cover from bell housing and checked clutch adjustment, ok. Removed slave cylinder and cleaned out dirt from bell housing, stripped pedal and cleaed out master cylinder, back bled clutch and test. (215247km)	22/06/2019	3.00	3.00	3.00		Correct	\$0.00
12123	Removed and replaced all 8 drive tyres. (215310km)	24/06/2019	1.50	1.50	3.00		Correct	\$0.00
12256	Truck Weekly Check Over completed, topped up engine oil 3L, topped up power steering oil, tightened loose centre bearing nut with loc tite, removed and replaced pos 6 booster. fitting leaking at firewall (parts ordered) Removed and replaced turntable jaw and horseshoe. (215557km)	4/07/2019	3.00	3.00	6.00	9	PM	\$0.00
12373	Replaced both leaking cab shockies , replaced leaking air fitting in brake treadle valve , fitted new bonnet pivot rose joint & bolt to l/h/s of bonnet , tighten & replaced bonnet lower mount rubbers .	13/07/2019	4.50	4.50	4.50		Request	\$0.00
12442	Tightened DPF front and rear exhaust clamps. (215916km)	18/07/2019	.50	.50	.50		Correct	\$0.00
12445	Repaired start isolator, diagnosed tipping fault, checked pressures and found spiking and erratic, removed and replaced pto box with new. (old pto had severely worn clutch plates)	21/07/2019	5.50	5.50	5.50		Break	\$0.00
12500	Truck Weekly Check Over, repaired holes in plastic mudguards, Boost hose leak replaced clamp & hose, fitted new inter cooler mounting rubbers, cleaned boost sensor (check engine light on) fitted new boost sensor test run ok.	25/07/2019	12.00	12.0	12.00	9	PM	\$0.00
12590	Replaced wiper blades , replaced fire extinguisher strap , replaced blown trailer light fuse .	30/07/2019	.50	.50	.50		Request	\$0.00
12659	Checked into why trailer light fuse keeps blowing, found wires in trailer plug where squashed and touching, repaired wiring.	2/08/2019	2.00	2.00	2.00		Correct	\$0.00
12695	Replaced blown pto hose , replaced hose & modified bracket to stop rubbing .	6/08/2019	2.50	2.50	2.50			\$0.00
12806	Fitted new cab chocks and hooked to float. (217044km)	15/08/2019	1.00	1.00	1.00		Correct	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
12910	250 hour Truck Service , Rerouted wiring harness away from dpf muffler as was melting , replaced grease nipple from pos 4 slack adjuster , tighten bolts around trans output seal (weeping) tighten leaking fuel line under tank .	24/08/2019	10.00	10.0	10.00	14	PM	\$0.00
13436	Removed and replaced front spring packs with new, replaced top shackle bushes and pins, greased. Fitted spacer blocks to front springs and tensioned up u-bolts, checked over front end and inflated tyres.	8/10/2019	5.00	5.00	5.00		Correct	\$0.00
13560	No clutch , replaced weeping clutch hose & replaced master cylinder with new one . bleed system & test run ok .	19/10/2019	.00	2.50	2.50		Request	\$0.00
13566	No clutch pedal on floor , bleed system (pressure bleed) checked adjustment , could not get to work (orderd some parts)	16/10/2019	2.00	2.00	4.00			\$0.00
13599	Replaced gear stick isolator bush	21/10/2019	2.00	2.00	2.00		PM	\$0.00
13926	POS 3 drive tyre flat had no run outs so had to change all 8 drive tyres	21/11/2019	2.00	2.00	3.50		Break	\$0.00
13967	Bonnet jammed down, lifted up with forklift and found rubber had folded over on itself and jammed, cut off flap and tested, ok.	23/11/2019	1.50	1.50	1.50		Correct	\$0.00
14011	Truck Weekly Check Over , Replaced jaw & kitted turntable , replaced 2 x steer tyres .	27/11/2019	3.00	3.00	2.00	9	PM	\$0.00
14126	Truck Weekly Check Over completed, removed and replaced pos 3 drive brake booster, wired up new reverse buzzer and replaced reverse switch in gearbox, replaced rubber mount on cab ride height valve rod. (220527km)	9/12/2019	30.50	16.0	18.00	9	PM	\$0.00
14678	Coolant leak pressure tested could not find leak (will monitor) replaced worn l/h bonnet top mount block .	27/01/2020	1.00	.00	1.00		Request	\$0.00
14986	Replaced broken rubber bonnet strap l/h	21/02/2020	.00	.50	.50		Request	\$0.00
15043	Tighten loose l/h bonnet pivot mount .	24/02/2020	.00	1.00	1.00		Request	\$0.00
15133	Starting problems , checked batteries (ok) cleaned up all terminals & leads , tested & fitted new latch end on isolator (	8/03/2020	.00	6.00	12.00		Request	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
	broken) , found to have faulty starter motor fitted good s/hand one & fitted new throw out & start solenoids , repaired air leaks on fire wall .							
15139	(Rom) leaking hyd fitting under trailer , tighten .	8/03/2020	.00	.50	.50		Request	\$0.00
15191	removed broken bolt from l/h gearbox / cab mounts , drilled & tapped new thread , refitted fuel tank & refilled with fuel .	13/03/2020	.00	4.00	4.00		Request	\$0.00
15308	Hooked up scan tool to check eng light, found dpf fault (dpf blocked). Removed dpf and cleaned, cleaned differential pressure sensor and refitted, reset dpf in computer and carried out manual burn.	25/03/2020	12.50	12.5	12.50		Correct	\$0.00
15382	replaced wiper blade.secured grill with 2x new 3/8 bolts	7/04/2020	.50	.00	.50		Correct	\$0.00
15395	Removed and replaced pos 6 outer tyre with reuse, had to re tap thread on 1 stud.	10/04/2020	1.00	1.00	1.00		Correct	\$0.00
15480	1 of 4 batteries U/S...fitted new style into bank. check running voltage 14 volts "ok"	22/04/2020	2.50	.00	2.00		Request	\$0.00
15486	carried out forced re-gen cycle due to DPF Burn light illuminated	21/04/2020	1.00	.00	1.00		Correct	\$0.00
15551	500 hour Truck Service , replaced l/h/f u/s slack adjuster , replaced u/s drivers side seat belt , replaced l/h/f mud flap , replaced l/h/f broken cab to chassis mounting bolt (removed fuel tank & removed gearbox mount to replace bolt)	11/03/2020	.00	17.0	37.00	16	PM	\$0.00
15556	Truck Weekly Check Over , removed top l/h step straighten & remounted , side marker lights not working replaced blown fuse could not get to fault , cracked hyd tank cleaned up & putty it up , replaced pos 3 tyres ,	27/04/2020	.00	20.0	20.00	9	PM	\$0.00
15780	Carried out inspection, replaced alt and a/c belts, replaced both rear mudguards. Removed and replaced transmission out put seal, replaced lhs mudflap stay bracket, resealed fittings on pto, cleaned up crack in hyd tank and sealed with metal putty. Secured all wiring hanging down. Fabricated new mount bracket and remounted hydraulic hose from tank. Removed and replaced drivers side windscreen.	23/05/2020	45.50	14.0	17.00		Correct	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
15933	Roadworthy inspection , washed , wired in & fitted new number plate light , removed all wheels & inspected brakes relined rear axles x 4 new brakes , seals , hardware , 4 x s/cams & bush kits , cleaned & adjusted all abs speed sensors , drained fuel tank & removed & made new fuel hose (leaking) ,	13/06/2020	.00	32.0	44.00		Request	\$0.00
15988	Fit new reverse light & repaired wiring , indicator light would not work repaired wiring & replaced faulty flasher relay	18/06/2020	.00	4.00	4.00		Request	\$0.00
16407	(Roadworthy repairs) replaced r/h/f clearance light, replaced r/h seat belt. replaced 2 x broken a/c vents, replaced leaking fuel line to tank, removed leaking fittings on p/steer pump & resealed, resealed leaking bottom bung on hyd tank, repaired wiring to spot lights, glued down lifting leather on steer wheel, replaced leaking trailer brake release push valve in dash, replaced 1 x mud flap pressure cleaned engine.	31/07/2020	.00	22.5	18.00		PM	\$0.00
17595	Replaced snapped coolant sensor in header tank.	7/05/2021	.50	.50	.50		Correct	\$0.00
17675	Get ready for roadworthy , Replaced headlights with new led ones , replaced front bumper bar had to modify to make fit (cut out & meshed slots to get air flow to coolers) , replaced turn table & dog bones , replaced gearbox out put shaft seal , replaced front diff input shaft seal , removed all stickers , drain oil from hyd oil tank & remove weld up cracks refit & fill with oil .	27/05/2021	.00	16.5	16.50		Request	\$0.00
18771	Bin tarp fault adjusted tarp cable & tested ok	25/01/2022	.00	.00	2.00			\$0.00
20084	Carry out check over, weekly service. Found centre bearing failed C/O. Broken bracket on diff housing, repaired and refit. Adjusted tub cover cables	4/11/2022	21.00	9.00	9.00		PM	\$0.00
20459	Drained oil out of tub. Replace wiper blades. Topped up engine oil. Resealed PTO fittings. Replaced RH bonnet stop rubber (square ones, need to order more) Thorough check over. Test rear gate, cover, locks and tub works	31/01/2023	1.50	1.50	1.50		PM	\$0.00
21020	Checked over, topped up coolant 1L, topped up clutch fluid, adjusted clutch. replaced bearings in cover rollers. cut booster	30/05/2023	13.50	13.5	13.50		Correct	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
21154	rods on gate latch, greased and topped up hyd oil. 06L 250 hour Truck Service as per sheet	19/06/2023	12.00	5.50	5.50	14	PM	\$0.00
21258	R&R air filters. Checked intake for dust and damage. Made new bonnet strap. Check over. * Leaking P/S box	12/07/2023	2.00	2.00	2.00		PM	\$0.00
23132	Check over and grease. Fit wheel chocks. Stickers for isolators and fire extinguisher's	12/09/2024	1.50	1.50	3.00		Correct	\$0.00
23213	Replaced lhs mudflap yellow/ red marker sign	17/10/2024	1.50	1.50	1.50			\$0.00
105		Total	336.5	329.5				\$0.00