Vehicle History Summary



Fleet #	24134
Registration	XN45DB
Make	Kenworth
Model	T404 6*4
VIN / Chassis #	6F50000003A425274
Build Date	2003

Date	Reading / Units	Type / Repairer Notes	Repairer
29/09/2026		**CTP** O-2269 CTN368358129	GIO
29/09/2026		**Registration** O-2270 Rego	SERVICES NSW
05/09/2026	2,312,500 kms	**A** S-2592 A Service. Grease all points. Adjust brakes. Replace Cab light globes. Degrease & Hot wash engine & chassis. Note: Engine cooling system pressurizing.	KSY Workshop
28/08/2026	2,308,856 kms	**Puncture Repair** T-2086 Puncture Repair - Truck Tyre 1 MECHANICS DROPPED WHEEL OFF LOOSE	Bridgestone Kempsey
28/08/2026	2,308,856 kms	**DEFECT CLEARANCE** R-7036 Vehicle intercepted at Pine Creek, NSW. 2 x Defects for loose Pitman Arm & Engine oil leaks. Convey truck to MTC Coffs Hbr for repair and Clearance of Pitman arm defect.. Tighten bolt on pitman arm, Check for wear- Ok. Ksy Workshop:- Degrease and hoist wash underneath driveline. Wash engine, degrease & wash cab and body. Axle 3, Lh side Hub seal leaking, Remove Wheels & Hub, clean all parts. Replace Hub seal & brakes shoes. Fit Hub & wheels and torque wheel nuts. Convey to MTC Kempsey for defect clearance of Oil leak defect. Connor, Bill.	Mavin Truck Centre Pty Ltd
15/08/2026	2,303,141 kms	**B** S-2561 B Service. Change oil & filters. Grease all points. Adjust brakes.	KSY Workshop
30/07/2026		**Puncture Repair** T-2058 DUBBO 33000096 PUNCTURE REPAIR	Bridgestone Kempsey
25/07/2026	2,292,436 kms	**A** S-2505 A Service. Grease all points. Adjust brakes. Degreased & hot wash engine and chassis.	KSY Workshop
10/07/2026	2,282,254 kms	**DEFECT WINDSCREEN** R-6905 Arrange replacement of windscreen at Macleay Automotive.	Macleay valley automotive
10/07/2026		**Registration** O-2121 rego	SERVICES NSW
10/07/2026	2,284,494 kms	**replace window** R-6912 replace broken window	Macleay valley automotive
03/07/2026		**CTP** O-2111 CTN368358129	GIO
30/06/2026		**Engine Oil Leak** R-6894 removed diff filter housing removed piping fit blank in bottom of diff clean housing and washed engine down	Torque N Diesel
26/06/2026	2,280,934 kms	**B** S-2497	KSY Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		B Service. Change Oil & Filters. Grease all points. Adjust brakes. Tighten Pitman arm bolt. Air dryer leaking at top & bottom joint- Tighten bolts. Replace leaking heater tap. Center bearing yoke loose- Drop drive shaft and tighten yoke nut. Connor. Bill.	
12/06/2026	2,272,752 kms	**Puncture Repair** T-1997	Bridgestone Kempsey
		POS 9 PUNT Puncture Repair - Truck Tyre	
12/06/2026	2,271,934 kms	**Fuel return valve leaking** R-6861	KSY Workshop
		Remove & Replace return check valve. Pressurize fuel system and check starting-	
05/06/2026	2,270,154 kms	**A** S-2467	KSY Workshop
		A Service. Grease all points. Adjust brakes. Replace Fan belts. Replace wiper blades Replace faulty Radiator cap. Repair damaged wiring to reverse lights	
05/06/2026	2,270,156 kms	**TRUCK TYRE** T-2008	Bridgestone Kempsey
		POS 2 8006271 295/80R22.5 18PR ECO76 ECOSAVER ZBALB BALANCE BEADS #12 FITTR Fitting - Truck Tyre	
25/05/2026		**defect cleared** T-1996	
		Defected for Engine oil leaks, Degrease and pressure wash. Locate oil leak at Turbo drain. Remove drain & reseal, Fit bolts & tighten.	
15/05/2026	2,258,594 kms	**B** S-2456	KSY Workshop
		B Service. Change oil & Filters. Grease all points. Adjust brakes. Change Air filter. Replace blown globes on cab roof. Tighten center bearing yoke nut. Tighten Fan belts. Tighten Rh front shock mount bolt. Water getting past air horn seals- loosen & Sikaflex around seals. Bill.	
22/04/2026	2,243,545 kms	**Suspension Airleak** R-6724	KSY Workshop
		Truck loosing air on suspension system. Call out to Taree. Load tools and parts into Ute, Travel to Taree, NSW to diagnose & repair. Rh Height control valve faulty- leaking internally. Remove & replace valve, set height to spec. Check operation- Ok Load tools & head back to ksy workshop.	
11/04/2026	2,238,133 kms	**B - 20k** S-2418	KSY Workshop
		B Service. Change Oil & Filters. Grease all points Adjust brakes. Replace light bar brackets. Axle 1, Tie Rod tube thread stripped out- Left tie rod end movement. Replace Tie rod assembly.(B&H)	
09/04/2026		**After Hour Call Out** R-6676	HNL Fleet Newcastle.
		XN45DB (NW24134) -After hours call out to BP Beresfield. Flat batteries, had to jump start truck on starter motor Labour x4	
01/04/2026		**Truck Annual Inspection** I-21	Pendergast Northwest freight services
		speed limiter compliance - working park brake alarm - working Turn table - working	
31/03/2026		**Registration** O-1956	SERVICES NSW
		rego	
31/03/2026		**CTP** O-1924	GIO
		GIO CPT	
30/03/2026	2,231,555 kms	**BATTERIES** R-6569	KSY Workshop
		Check charge rate from Alternator- Ok. Check for heavy draw from truck, No excessive draw. Remove & Fully charge all batteries, load test all.- 2 below spec, 2 just on spec.- Replace all 4 batteries. Check starting- Good. Replace Oil pressure light switch & gauge sender	
26/03/2026	2,228,755 kms	**REPLACE FAN BELTS** R-6567	All Fleet Services
		Convey truck to All Fleet Services, Richlands, QLD for supply & Fit new belts.	
13/03/2026	225,825 kms	**TRUCK TYRE** T-1952	Bridgestone Kempsey
		POS 3,4 2282012 11R22.5 18PR ECO24 ECOSAVER 2 FITTR Fitting - Truck Tyre 2 ZBALB BALANCE BEADS #12	
10/03/2026	2,222,559 kms	**Breakdown Call out, Jumpstart** R-6526	Weller Automotive
		Low batteries, Contact Weller Automotive to attend & jump start truck.	
06/03/2026	2,222,103 kms	**Horton Air line** R-6557	KSY Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Horton hose perished and leaking.- replace hose from Horton Fan hub back to Air/Elec solenoid.	
05/03/2026	2,221,650 kms	**Coolant Leak** R-6535	Torque N Diesel
		5/03/2026 DRAIN COOLANT REMOVE HEATER HOSES REMOVE ALTERNATOR & A/C COMPRESSOR REMOVE BRACKET FOR A/C & ALT MOUNTING REMOVE TOP & BOTTOM RADIATOR HOSES REMOVE COOLER PIPE REMOVE THERMOSTAT HOUSING	
28/02/2026	219,672 kms	**B - 20k** S-2372	KSY Workshop
		B Service. Change oil & filters. Adjust brakes. Grease all points. Replace cab roof marker light globes.	
27/02/2026	219,214 kms	**INDICATOR ISSUE** R-6523	Torque N Diesel
		DIAGNOSE INDICATOR ISSUE FOUND ISSUE WITH FLASHER CAN ORGANISE & PICK UP PARTS FIT NEW FLASHER CAN TEST ALL OK	
07/02/2026	209,879 kms	**A - 10k** S-2363	KSY Workshop
		A Service. Grease all points. Adjust brakes. Replace wiper washer motor. Tighten yoke on axle 2, input shaft.	
09/01/2026	198,255 kms	**General Repairs** R-6366	KSY Workshop
		Replace Sr1 valve beneath Cab. Turbo drain leaking from swivel O-Ring- Remove, Clean & replace O-ring. Replace Alternator Belts. Repair loose & Damaged fuel tank side skirts. Degrease Engine & Chassis and Hot wash.	
02/01/2026		**Registration** O-1752	SERVICES NSW
		REGO	
02/01/2026		**CTP** O-1751	GIO
		CTP GIO	
19/12/2025	198,038 kms	**TRUCK TYRE** T-1824	Bridgestone Kempsey
		POS 2 2280009 295/80R22.5 18PR ECO76 ECOSAVER 1 2 FITTR Fitting - Truck Tyre 1 ZBALB BALANCE BEADS #12 1	
15/12/2025		**Registration** O-1692	SERVICES NSW
		TRANSFER REGO	
06/12/2025	2,189,499 kms	**B - 20k** S-2300	KSY Workshop
		B Service. Change Oil & Filters. Grease all points. Adjust brakes. Replace Left Muffler box & clamps. Degrease and Hot wash engine & chassis.	
15/11/2025	2,177,643 kms	**A - 10k** S-2274	KSY Workshop
		A Service. Grease all points. Adjust brakes. Top up Pwr Steer fluid. Axle 2 & 3 Rh side hub seals leaking- Remove axles, strip hubs, Check bearings-Ok Fit new hub seals to both hubs. Remove & Replace brake shoes on Axle 3, Rh side. Center Bearing Yoke loose- Removed 2nd drive shaft & tighten Yoke nut. Fit drive shaft.	

Signed: _____

Name: _____

Date: _____