Vehicle History Summary



Fleet #	FT2249
Registration	L86010
Make	BARKER
Model	Triaxle Flat Top
VIN / Chassis #	6B9012800TWAA6946
Build Date	1996

Date	Reading / Units	Type / Repairer Notes	Repairer
18/05/2023	542,884 kms	**B - 20k** S-1169	KSY Workshop
		B service. Grease all points. Adjust brakes. Secure loose tool boxes. Replace front tool box top lock. Replace rusted strap winch. Replace rear marker plates. Make repairs to Timber box.	
12/05/2023	541,193 kms	**LHS Bearing** R-3824	Torque N Diesel
		Jack up 3rd axle. Remove LHS bearing- only outside. Bearing dirty Wash bearing Adjust wheel bearing Get hub cap from Maxi parts and fit to trailer. Clean work area.	
01/03/2023	524,548 kms	**B - 20k** S-1068	KSY Workshop
		B service. Grease all points. Adjust Brakes. Replace Air bag Spring on Axle 1 & 2 Left side. Replace side clearance lights Rh side x 2. replace water tank Tap.	
02/02/2023	518,159 kms	**HUB CAP** R-3552	KSY Workshop
		Remove wheel hub, Axle 3 Lh side. Remove, Clean & inspect bearings- Ok. Repack bearing with fresh grease, Fit hub to axle, torque bearing nuts. Fit new Cap.	
31/01/2023		**Trailer Tyre** T-705	North West Freight Services
		2x 11R22.5 Haulstar HA601 POS - 19/20	
20/01/2023		**Trailer Tyre** T-688	North West Freight Services
		2x 11R22.5 Haulstar HA601 POS - 21/22	
17/11/2022	506,047 kms	**B - 20k** S-957	KSY Workshop
		B Service. Grease all points. Inspect & adjust brakes. Replace damaged wiring on Rh front Clearance lights. Repair & weld cracks in Rear tool box sides.	
24/06/2022	481,687 kms	**B - 20k** S-776	KSY Workshop
		B Service. Grease all points, Inspect & adjust brakes.	
20/06/2022	481,687 kms	**Clearance Lights** R-2990	KSY Workshop
		Remove and replace faulty clearance Led on Lh side, 3rd from rear.	
28/04/2022		**Runout** T-398	Bridgestone Kempsey
		Fit Runout Trailer tyres to Pos. 11& 12	
22/03/2022	462,654 kms	**B - 20k** S-654	KSY Workshop
		B Service. Grease all points. Check all Hub bearings. Check and Adjust all brakes.	
18/01/2022	443,165 kms	**indicator** R-2487	KSY Workshop
		Remove and replace LED	
04/01/2022	442,963 kms	**B - 20k** S-582	KSY Workshop
		B service. Grease all points. Adjust all brakes. Replace faulty number plate light.	
30/12/2021	442,962 kms	**New Tyres** T-280	Bridgestone Kempsey
		4 x 11R22.5-16 HH104 146/143M Hifly Trailer POS 1/ 2/ 3/ 4	

Date	Reading / Units	Type / Repairer Notes	Repairer
18/05/2021		**B** S-362	HNL WORKSHOP
		Carry Out B Service Replace all MVT Mud flaps to NFS Replace & secure brake hose. Replace faulty rotating beacon. Replace 2 winch straps	

Signed: _____

Name: _____

Date: _____