Vehicle History Summary



Fleet #	34147
Registration	XN23HH
Make	Freightliner
Model	ARG000A
VIN / Chassis #	1FVJAWBG6CLBR3215
Build Date	2012

Date	Reading / Units	Type / Repairer Notes	Repairer
19/10/2026		**CTP** O-2298 CTN370278639	GIO
19/10/2026		**Registration** O-2299 registration	SERVICES NSW
30/09/2026		**connected to scan tool** R-7121 brought truck in workshop connected scan tool performed cylinder cut out test diagnose injector issue with number 4 & 6 remove rocker cover found injector 4 & 6 supplied by customer was also supplied the rocker gear and fitted also carry out valve set started truck misfire number 4 and coolant running out of exhaust remove front of EGR, no coolant bypassing drop turbo at mouth of manifold put camera to valves on number 4 found coolant sitting in seats and steaming out put engine back together as customer request drop back to yard	Torque N Diesel
10/09/2026		**check brake, horton hose** R-7078 XN23HH. Checked all the breaks on the truck and the trailer. Repaired the drivers side step. washed the bugs off the truck. Checked the horton and found a hole in the horton hose and repaired the hose. Removed the heater tap out of the wreck and fitted to the truck. DOC	Doc's Mobile Mechanical
01/09/2026		**Broken Mud guard Mount** R-7052 XN23HH. Fitted a new mud gard to the RHS fear drive wheel. Had to remove the mounting brackets off an old gard and fit to the new gard.	Doc's Mobile Mechanical
31/08/2026	2,563,077 kms	**C** S-2513 air leak ride Hight value oil leak Jake harness plug oil leak rear diff LH washer jet gearbox plug had chucks of metal on it heater core or hose rear number plate bent slight exhaust leak after closing pipe axle z wire pulled out exposed wires on engine harness Jay	Pendergast Northwest freight services
27/08/2026	2,553,709 kms	**Air Leak** R-7035 fixed air leak in dash by pulling middle dash panel off and re connecting air line fixed gear stick trim by pulling the mounting bolt out and reinstalled it with the trim Cooper	Pendergast Northwest freight services
31/07/2026		**Registration** O-2150	SERVICES NSW
31/07/2026		**CTP** O-2151 CTN370278639	GIO
25/07/2026	2,551,481 kms	**TRUCK TYRE** T-2054 POS 5,6 T11225LD268 11R22.5 18PLY LANVIGATOR D268 149/146M (B202) FITTR Fitting - Truck Tyre ZBALB BALANCE BEADS #12	Bridgestone Kempsey
24/07/2026	2,551,483 kms	**Coolant Leak, Gearbox, splitter,, General Repairs** R-6930	KSY Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Gearbox Splitter not working- Replaced corroded & seized Pressure protection valve on Gbox supply hose. Remove splitter cylinder, Found heavily pitted Cylinder & piston, O-ring on piston perished & broken. Fit replacement cylinder and fit new O-rings & Gaskets. Checl operation-OK Coolant leak- Bottom radiator hose perished, Hose clamps seized, Drain coolant, Replace top & bottom hoses and fit new clamps. Fill with fresh coolant and pressure test-Ok. Gearbox holding in gears on downshift- Check cables, Gear stick and linkages-Ok. Check clutch adjustment, way out- Adjust clutch as required & test drive-Good. Brake relay hose kinked at Valve- Remove hose, Cut back kinked piece- Extend hose with joiner and new piece of hose to stop from kinking. Power divider input shaft bearing loose- Remove driveshaft, Remove Yoke and replace seal. Remove shim from input bearing carrier & Assemble. Replace diff Oil & filter. Drivers side window not working- Strip door trim and check regulator, Works. Trace wiring to break in wires- Repairs wiring and test operation- Ok. Passenger side window inoperative, Trace fault to switch on drivers door- Replace switch & check operation- Ok. Horton fan stuck on- found airline from solenoid to fan split and leaking. Cut out damaged hose and fit inline joiner. Geoff, Bill, Connor.	
19/07/2026		**gasket range, range slave, splitter vav** R-6919	Pendergast Northwest freight services
25/06/2026		**Air Leak** R-6893	Pendergast Northwest freight services
		ride Hight control valve leaking air out at air lifting people with new air fitting no longer leaking out at ride height control valve checked brake booster for air leaks count find any leak on splitter valve from truckline use soapy water to see if still leaking no longer leaking air valve under turntable missing cap and screw took parts off wreck no longer leaking when brakes are off air leak behind dash opened clash up found suspension dump valve leaking replaced parts from wreak now longer leaking put dash back together	
28/04/2026		**General Repair** R-6740	Doc's Mobile Mechanical
		XN23HH. Checked the brake lights where working through the suzzi coil.	
28/04/2026	2,536,706 kms	**AIR LINE LEAK** R-6746	Pendergast Northwest freight services
		THE RELIEF VALVE ON THE RH AIR TANK WAS LOOSE REMOVED FITTING RESEALED TIGHTENED STARTED TRUCK TESTED FOR AIR LEAKS WAS GOOD FOUND THAT THE AIR DRYER WAS LEAKING REMOVED HOSE TANK MOUNTING PLATE OFF TOOK AIR DRYER OFF THE WRECKED ARGUSY TO PUT ON MOINTED PUT HOSE IN TIGHTENED UP STARTED TO BUILD UP AIR THEN MAIN HOSE FITTING WAS CREAKED TOOK FITTING OFF THE WRECK PUT ON SINSTALLED HOSE BACK TIGHTENED STARTED TRUCK TO TEST WAS FINE FIXED SPLIT IN HOSE GOING TO BOTTOM OF LH AIR TANK CUT PUT HOSE JOINER WAS ALL FINE TESTED LIGHTS ADJUSTED BRAKE AIDEN	
24/04/2026		**CTP** O-1985	GIO
		GIO insurance	
24/04/2026		**Registration** O-1986	SERVICES NSW
		rego	
24/04/2026		**Registration** O-1987	SERVICES NSW
		rego	
14/04/2026	531,123 kms	**Breakdown After Hours.** R-6678	Torque N Diesel
		LAB BREAK DOWN A/H LABOUR BREAKDOWN AFTER HOURS - JOB 262 531123kms Attend after hrs breakdown at Metcash Yard Diagnosed and found loose oil filter Tighten plus check oil and found ok	
28/03/2026		**Drive Tyre** T-1930	Pendergast Northwest freight services
		2 X 11R22.5 HAULSTAR HD608 POS 9/10	
26/03/2026		**Clutch Brake** R-6670	Torque N Diesel
		Diagnose clutch brake issue Found no clutch brake Fit New clutch brake 2 piece **note** Clutch brake is better but will need box removal due to cross shaft bushes no longer there, shafts wearing into bell housing.	
26/03/2026		**Truck Annual Inspection** I-29	Pendergast Northwest freight services
		speed limiter - working park brake alarm - working turn table - working	
21/02/2026	2,514,040 kms	**B** S-2364	KSY Workshop
		B Service. Change Oil & Filters. Grease all points. Adjust brakes.	
16/02/2026	2,511,301 kms	**BREAKDOWN** R-6479	Torque N Diesel
		ORGANISE & PICKUP PARTS ATTEND CALLOUT JACK CAP & R & R STARTER MOTOR REMOVE DAMAGED EARTH CABLE MAKE NEW EARTH CABLE FIT TEST OPERATION & FOUND OK	
13/02/2026	2,510,445 kms	**Coolant Leak** R-6476	Torque N Diesel

Date	Reading / Units	Type / Repairer Notes	Repairer
		DIAGNOSE COOLANT LEAK FOUND HEATER HOSE ON R/H OF MOTOR LEAKING REPLACE HOSE REFILL SYSTEM RECHECK ALL OK	
02/02/2026		**General Repairs** R-6437	Doc's Mobile Mechanical
		XN23HH. Removed the water filter housing and fitted a new second hand filter housing. Helped refit the sump. Picked the truck up and and prusere cleaned under the truck. Replaced the RHS frount air bag. Welded up the top of the muffler and cleaned up the soot on the back of the cab. filled with collant and oil and washed out the radiator. Removed the turbo collant hose and got a new one made refitted the new hose	
02/02/2026		**CTP** O-1809	GIO
		CTP	
02/02/2026		**Registration** O-1810	SERVICES NSW
		REGO	
31/01/2026	2,504,829 kms	**LEAKING SUMP** R-6487	Pendergast Northwest freight services
		Removed the bolts from the broken sump was cracked near the drain plug and up the side. Removed sump cleaned the silicon of the bottom of the engine. Found the oil pick up was broken un bolted and replaced with new one. Cleaned new sump up put new gasket in installed the sump. Put stabilizer back in torqued sump bolt to spec. Replaced coolant heater tap / reseemed the fitting, tighten exhaust clamps put new clamp out of flat bar drilled and tapped with a thread fixed oil leak coming front rear diff drain plug was loose I so was the fill plug. Fixed air leaks to rear air bags . loose fittings/ the heat shield. Oil change / oil filter found air bag was leaking . Removed / Doc Replaced. Aiden	
12/01/2026		**General** R-6621	Pendergast Northwest freight services
09/01/2026		**Drive Tyre** T-1837	Pendergast Northwest freight services
		2 X 11R22.5 HAULSTAR HD668 POS 7/8 1 X 295/80R22.5 HAULSTAR HS605 POS 2	
05/01/2026	2,493,016 kms	**B** S-2331	
		B Service Completed NHVR label starting to fade Replaced wiper blades Parts - oil filter fuel filter Aiden	
11/12/2025		**Hose** R-6302	Express Truck Maintenance
		travel out to vehicle and only place to turn around was at the end of the freeway. once onsite. plugged air into trailer and found new hose that was fitted was routed wrong and too tight for suspension movement. adjusted and refitted and all ok.	
03/12/2025	8,900 kms	**Blown Diff** R-6329	Pendergast Northwest freight services
		We bought truck in than I started undoing all bolts, shocks, airlines. Luke and I than took the diff out than put another one in out of the smashed century class in the yard. Put diff in and tighten all bolts up and shocks and airlines Put tyres back on and adjusted brake than tested to make sure it moved. Ryan and Luke	
02/12/2025		**Towing** O-1947	DUNNS RECOVERY SERVICE
		1 of argosy from willow tree to pendergast yard	
01/12/2025	8,143 kms	**Exhaust** R-6307	Pendergast Northwest freight services
		Packed up where Aiden previously had welded Cleaned up surface off exhaust and welded back together Painted over welds Ryan	
29/11/2025		**Heater Hose** R-6267	Doc's Mobile Mechanical
		XN23HH. Replaced the egr valve. traveled down to willow tree and cut a pice of heater hose out that was blowen and added a new pice in to get him going. Replaced the heater hose that was blowen	
26/11/2025		**Boost Issue** R-6252	HNL Fleet Newcastle.
		XN23HH - Attend site to check boost noise. Found boost intake hose at EGR the issue. Repaired fault, ran and test, OK	
23/11/2025		**Coolant** R-6244	Doc's Mobile Mechanical
		XN23HH. checked the truck over for using coolant found there was coolant in the egr pipes. removed the turbo and the egr cooler found another egr cooler in the spair patrs trailer. Got the cooler tested for leaks it was no good. Removed the egr cooler off the other K200 And fitted it to the truck. Fitted a new turbo back onto the engine. and filled with coolant started the truck and took for a test drive checked for leaks.	
16/11/2025	2,534,040 kms	**B** S-2277	Doc's Mobile Mechanical
		B Service on the truck and replace a heater hose. Removed the boost sensor out of the 200 series and fitted it to the truck.	

Date	Reading / Units	Type / Repairer Notes	Repairer
12/11/2025		**Wheel Nuts** R-6721	Pendergast Northwest freight services
11/11/2025		**General Repairs** R-6683	Pendergast Northwest freight services
03/11/2025	2,452,852 kms	**DOOR HANDLE** R-6201 Replaced broken door handle with new handle Aiden	Pendergast Northwest
03/11/2025		**Registration** O-1566 REGO	SERVICES NSW

Signed: _____

Name: _____

Date: _____