Vehicle History Summary



Fleet #	34146
Registration	XO93FZ
Make	Kenworth
Model	T403 6*4
VIN / Chassis #	6F5000000CA446918
Build Date	2012

Date	Reading / Units	Type / Repairer Notes	Repairer
13/10/2026		**Air Leak , BROKEN WINDOW, Checked lights , Driver seat** R-7182	Pendergast Northwest freight services
		7:30 checked fuses and removed door card checked switch and control box checked power at motor found plug pins were flogged out crimp pins down and tested reassembled door found seat position adjuster fallen off clipped back on washed motor down found leak from rocker cover removed air intake assembly remove centre kick panel air con vent and ac dash panel removed cover cleaned seal and sealing surfaced resealed cover refitted cover and air intake assembly refitted all interior pieces JAY	
03/10/2026		**Engine Light , Mudguard** R-7133	Pendergast Northwest freight services
		Remove & replace 2 mudguards tighten up mudguard bar scan engine light found exhaust pressure data irreverent erratic or incorrect check wiring found no issue replaced sensor and checked pressure tube not clogged cleared codes no faults	
17/09/2026	474,195 kms	**Oil Leak** R-7097	Pendergast Northwest freight services
		Noticed oil running down from the turbo had a look and was leaking from turbo & drain & spotted the oil line from gearbox to filter was leaking i took the line off as there was a hole sent it to pertek to get fixed the pick up a new turbo drain gasket clean turbo drain area and fitted a new gasket then starter filtering the oil line back up once fitted i ran the truck until it was to see if there was any more oil leaking nothing was leaking	
12/09/2026		**CTP** O-2233	GIO
		CTN366517234	
12/09/2026		**Registration** O-2234	SERVICES NSW
		Rego	
11/09/2026		**Brake shoes** R-7069	Doc's Mobile Mechanical
19/08/2026		**chrome nut cover** R-7014	Pendergast Northwest freight services
		Found compressor intake hose blown Replaced hose using one off LVP108	
06/08/2026	1,465,188 kms	**C** S-2533	Pendergast Northwest freight services
		LH axel 2 wheel seal leaking pulled off replaced seal & seated completely number plate light very dull replaced with new one checked it working all good window driver side front 2 start crakes and crack from centre down Luke asked me to pull oil cooler off & swap it with truck up side of shed i pull off turbo and all coolant and oil lines , drain coolant out of the radiator pull off oil cooler and swapped put new gasket on oil cooler fitted oil cooler put turbo back on with a new exhaust & turbo gasket then put turbo coolant and oil lines on as well as turbo drain pipe then filled engine with oil and coolant LH window wouldn't go up or down i checked fuses they were good i checked wiring i checked window relay i then checked wiring i checked window relay i then pulled out window reg and pulled motor apart 1 spring out of the 2 were missing i put another spring in it and put everything back together window goes up and down RYAN	
30/07/2026		**coolant leak , Water leak** R-6959	Doc's Mobile Mechanical
		repaired the water leak at the top radiator hose	
24/07/2026	1,461,991 kms	**TRUCK TYRE** T-2064	TEMPE TYRE
		11225HD620 2 X HAULSTAR 11R22.5 HD620 POS: 5/6 PUNCTURE REPAIR X 1 POS: 3	
18/07/2026	1,409,628 kms	**Broken Mirror** R-6929	Pendergast Northwest freight services
		Ryan	
11/07/2026		**oil seal** R-6918	Pendergast Northwest freight services

Date	Reading / Units	Type / Repairer Notes	Repairer
14/06/2026		**General Check Over** R-6805	Doc's Mobile Mechanical
		XO93FZ. Went out to the truck to jump start it but found it was left in gear. Pulled the stick into nutral and started the truck drove back to the yard. Disconeted the trailer and went down to truck line and got 2 new red gards. doc	
12/06/2026		**CTP** O-2067	GIO
		CTP CTN366517234	
12/06/2026		**Registration** O-2066	SERVICES NSW
		rego	
12/06/2026		**Drive Tyre** T-1994	Pendergast Northwest freight services
		2 X 11R22.5 HAILSTAR HD608 POS 3/4	
14/05/2026		**Anderson Plug** R-6783	Doc's Mobile Mechanical
		XO93FZ. Removed the charge lead and fitted a new andersen plug end to one end of the charge lead. Refitted the charge lead to the truck	
01/04/2026	1,418,876 kms	**AIR BAG** R-6600	KSY Workshop
		Axle 2, Rh front Airbag leaking- Remove & replace Airbag, Check for leaks- Ok. Turntable Teflon wear plate damaged- Remove & replace as required.	
30/03/2026		**Truck Annual Inspection** I-24	Pendergast Northwest freight services
		Turn table - working Speed limiter - working Park brake alarm - working	
22/03/2026		**AC SYSTEM** R-6593	Doc's Mobile Mechanical
		Repaired the wiring to the heater fan relay and fitted a new heater fan relay put the dash back together, checked the AC system for leaks and re gassed the AC system	
13/03/2026		**CTP** O-1910	GIO
		CTP	
13/03/2026		**Registration** O-1909	SERVICES NSW
		REGO	
28/02/2026	1,409,628 kms	**B - 20k** S-2377	KSY Workshop
		B Service. Change Oil & Filters. Adjust brakes. Grease all points. Replace Air Filter. Axle 2 V-stay bush's worn- Remove both stays and press out bush's, Fit new bush's & install V-stays to axle.	
27/02/2026	1,403,500 kms	**Engine Overheating** R-6492	KSY Workshop
		Bring into workshop and check over for leaks.-None found. Remove and Replace Oil thermostat. Replace Coolant Thermostat. Removed water pump- Found cavitation pitting & holes in Impeller. Replaced water pump and fit new belt tensioner. Remove radiator & Intercooler and pressure wash through. Replace Oil temp sender and Gauge. Replaced leaking heater taps. Charge A/C with 1kg of R134a. Test drive with loaded trailer on local hills, Scan tool connected- Coolant Temp normal, Horton cutting in as required. Oil temp normal on Scan tool but high on gauge, Suspect corrosion in wiring causing high resistance. Test drive - Ok	
03/02/2026		**General Repair** R-6619	Pendergast Northwest freight services
29/01/2026	401,375 kms	**Puncture Repair** T-1852	Bridgestone Kempsey
		POS 3 PUNT Puncture Repair - Truck Tyre	
09/01/2026	389,818 kms	**TRUCK TYRE** T-1851	Bridgestone Kempsey
		BOHLE - POS 1,2 11003589 295/80R22.5 152/148M FIRESTONE FS401 2 33000084 FIT TBR TYRE 2h 33000051 BALANCE TBR 2 33000241 DISPOSAL TRUCK	
13/12/2025		**Registration** O-1679	SERVICES NSW
		REGO	
13/12/2025		**CTP** O-1678	GIO
		CTP	
08/12/2025		**Registration** O-1660	SERVICES NSW

Date	Reading / Units	Type / Repairer Notes	Repairer
		TRANSFER REGO	
05/12/2025	276,273 kms	**TRUCK TYRE** T-1809	Bridgestone Kempsey
		FLIP ON RIM POS 1 - NEW POS 7,8,9,10 FITTR Fitting - Truck Tyre 1 2282012 11R22.5 18PR ECO24 ECOSAVER FITTR Fitting - Truck Tyre ZBALB BALANCE BEADS #12	
04/12/2025	1,376,286 kms	**B - 20k** S-2293	KSY Workshop
		B Service. Change Oil & Filters. Grease all points. Adjust brakes.	
03/12/2025	1,376,249 kms	**General Repairs , REPLACE CLUTCH** R-6259	KSY Workshop
		Remove Gear box, Clutch springs broken and falling out, Friction material worn. Replace Faulty Clutch assembly. Fit new rear main seal to engine. Remove flywheel & convey for machining. (Whitbread's) Rear engine mounts flogged out - Remove and Replace mounts.. Power Divider shift piston cracked and bypassing air into diff, Forcing oil out of breather.- Remove piston and re-kit as required. Bonnet mount broken at upper stay- Fabricate alloy plate and Sikaflex & bolt to bonnet. Fit A/c condenser and evacuate system.	
08/11/2025	1,366,351 kms	**A - 10k** S-2270	
		A Service. Grease all points. Adjust brakes. Axle 1, Rh side hub seal leaking- Strip hub, Clean & inspect bearings. Remove & replace hub seal. Fit wheel to axle, Torque bearing nuts and fill fresh gear oil. Replace gear linkage rose joints x 2. Replace Suzi hose female fitting.	
05/11/2025	1,364,210 kms	**Clutch Brake, Turntable Jaws** R-6186	KSY Workshop
		Unable to select gears when Stationary- Inspect clutch & found Clutch Break worn- Cut out damaged breaker and fit 2 piece Clutch Break, Adjust clutch & free travel. Turntable not locking on pin- Inspected and found Jaw bent down- Remove Turntable, Clean & replace Jaws. Fit to truck and test operation- Ok. Hook truck to trailer and adjust jaws as per spec.	

Signed: _____

Name: _____

Date: _____