Vehicle History Summary



Fleet #	24151
Registration	XO42YJ
Make	Mack
Model	TRID98A
VIN / Chassis #	6FMF08C567D713467
Build Date	2007

Date	Reading / Units	Type / Repairer Notes	Repairer
30/10/2026		**Registration** O-2319	SERVICES NSW
		REFUND cancellation of registration 30.10.2026	
26/10/2026		**Adjust Value, cable bonnet** R-7221	Pendergast Northwest freight services
06/10/2026		**alternator bracket loose** R-7149	Pendergast Northwest freight services
		Bottom alternator bracket bolt loose tighten bolt up then checked it to see if there was still movement RH & LH hand partly loose pushed them back to where they were meant to be then tightened up LH step loose on the strap i tightened up its bolt until there was no more movement Ryan	
23/09/2026		**over heating issue** R-7108	Pendergast Northwest freight services
		check engine system temp confirmed engine hoy but radiator and water pump cold removed water pump to inspect impeller found no issues inspected thermostat housing for blockage found thermostat removed inspected bleed hose found blocked not allowing full amount of coolant test drove and was unable to get hot need thermostat Jay XO42YJ. Cleaned the grime off the truck and checked it over for getting hot.	
25/05/2026		**Defect Clearance** O-2077	Pendergast Northwest freight services
		1. A truck fitted with an advanced braking system does not have a compliant ABS/EBS connector to attach an ABS/EBS equipped trailer 2. Engine oil leaks 3. Transmission oil leaks NCR79	
08/05/2026		**CTP** O-2007	GIO
		GIO	
02/04/2026		**General Repairs** R-6667	JT Fossey Trucks
09/03/2026		**Towing** O-1902	Redback Towing
		New England Hwy RIXS CREEK NSW 2330 TO 36 Waterloo Ave THORNTON NSW 2322	
06/03/2026	1,834,604 kms	**Engine repair** R-6581	Penske Aust
		TRAVELLED TO BREAKDOWN AND LOCATED VAHICLE, VEHICLE WAS ON THE MERGE LANE FOUND REDIATOR HAD 2 BOG HOLES AND MULTIPLE CORES TAKEN OUT OF THE RADIATOR. BENT FINS AND CORES OVER BEST AS POSSIBLE, TO GET VEHICLE OFF THE ROAD TO A SAFE SPOT TO BE TOWED	
10/02/2026		**Registration** O-1828	SERVICES NSW
		REGO	
10/02/2026		**CTP** O-1829	GIO
		CTP	
30/01/2026	300,681 kms	**breakdown afterhours** R-6447	Torque N Diesel
		ATTEND BREAKDOWN AT NORTHWEST YARD DIAGNOSE COOLANT LEAK FAN ISSUE FOUND W/PUMP BEARINGS FAILED & W/ PUMP LEAKING ORGANISE PARTS REMOVE BELTS & FOUND BELTS NEED REPLACING REMOVE FAN & ACCESSORIES & WATER PUMP R & R WATER PUMP & REFIT PULLYS FROM ALD TO NEW REFIT ACCESSORIES & TOP COOLANT & RUN UP & FOUND OK ORGANISE SUBLET HOSE RE MANUFACTURED FOR VENT LINE OFF WATER PUMP	
26/01/2026		**General Repairs** R-6413	Doc's Mobile Mechanical
		XO42YJ. Made a braket to be welded to the bottom of the radiator for the mounts.	

Date	Reading / Units	Type / Repairer Notes	Repairer
24/01/2026	299,240 kms	**Radiator Bracket** R-6480	Pendergast Northwest freight services
		Undone both left & Right side Radiator support brackets and cut off right side as it was the cracked one. While i was doing that Doc made a new radiator bracket . once received bracket i welded back in place were the old one was bolted both sides back down tighten back up both. boost hoses the double checked all bolts were tighten. also put a bolt in right side of condenser. put another bolt in and tighten it and also put spaces in as they were also missing. tighten up fan bolts. Ryan Rudd	
20/01/2026	296,692 kms	**BREAKDOWN** R-6418	Torque N Diesel
		LABOUR BREAKDOWN STANDARD HOUR ATTEND BREAKDOWN AT SYDNEY MARKETS FIX BROKEN WIRE ON ALTERNATOR CHECK CHARGE RATE ALL OK	
17/01/2026		**AC Not working , CHECK OVER** R-6404	Pendergast Northwest freight services
		Found A/C compressor fault Removed bolts loosen belts Took belt off Removed A/C compressor Replaced with new compressor Fitted new bolts Fitted belt Gas up compressor Removed tail shaft and fitted new centre bearing Fitted new uni to centre Check rest of the truck Needs new tailgate Parts - A/C compressor - JT Fossey Centre Bearing Uni Luke	
16/01/2026		**Registration** O-1787	SERVICES NSW
		TRANSFER REGO	
14/01/2026	296,239 kms	**CHECK OVER** R-6379	Pendergast Northwest freight services
		Inspected the lights, reflectors, airbags, air fittings. Found that the top airline was loose RHR to the top of the airbag, tightened fitting - stopped leak Greased the turn table Checked guards, tyres, mudflaps, stacks, windows, tank rubbers and beacons. Aiden	
03/01/2026		**Brake Pads** R-6363	Doc's Mobile Mechanical
		XO42YJ. Replaced the steer brake pads	
22/12/2025		**Steer Tyre** T-1808	Doc's Mobile Mechanical
		XO42YJ. Removed the steer tyres and tryed to get brake pads. Could not get any so i ordered a set and fitted 2 new steer tyres	
29/11/2025		**Water Pump** R-6271	Doc's Mobile Mechanical
		Removed the water pump and fitted 2 new mounting gaskets to repair the water leak. Removed the steel pipe off the frount of the diff and resealed it to repair the diff oil leak	
07/11/2025		**Registration** O-1573	SERVICES NSW
		REGO	
07/11/2025		**CTP** O-1574	GIO
		CTP	

Signed: _____

Name: _____

Date: _____