



REES N.D.T. INSPECTION SERVICES 2008 LTD.

CERTIFIED
Aspirational Business

15612-89 Street
Grande Prairie, AB T8V 2N8

Grande Prairie
(780) 539-3594
(780) 532-8047 (Fax)

Dispatch
1-888-540-3594
www.reesndt.com

Vegreville
(780) 603-4887
Email: gcoers@reesndt.com

203-2

INSPECTION DATE: 03-Mar-26

CLIENT: Solution Services Inc.
ADDRESS: Box 934
Sexsmith AB T0H 3C0

REES NDT PO NUMBER: R90440
CLIENT PO NUMBER: GP-08328
REES NDT WO NUMBER: 226528

INSPECTION CERTIFICATE

CERTIFICATION OF: Corner Mount Picker

MAKE: Hiab

MODEL: 033 T

SERIAL NUMBER: BL033T000966

UNIT NUMBER: MT-11

CAPACITY: 2310 kg

OWNER: Solution Services Inc.

Rees NDT Inspection Services 2008 Ltd. performed a VISUAL AND NON-DESTRUCTIVE TESTING inspection on the above mentioned CORNER MOUNT PICKER. All observations have been recorded and are disclosed in the complete documentation for Rees NDT Work Order #226528. The scope of this certificate is limited to the inspection of the item's structural condition at the time of inspection and does not imply a review of the equipment's design or its associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxiliary equipment that has a lower capacity rating.


The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all required repairs (if any) were completed. In the undersigned Engineer's opinion, the CORNER MOUNT PICKER may be returned to service and is safe to use within the original manufacturer's specifications. The equipment owner is obliged to supply the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM information cannot be obtained, certified replacements must be obtained from a Professional Engineer.

This certification covers the above mentioned unit for a period of 1 YEAR from the date of inspection, or until the unit is damaged by handling, transportation or operation.

Reviewed
By:



06-Mar-2026



Inspected By: C. Bussiere CGSB #16091 (MPI II) SNT #063 (MPI II)

Non-destructive Testing · Wall Thickness Testing · Hardness Testing · Crane & Picker Certification · Drilling Rig Certification