Plant Service Record

Date: 17/11/2025

Plant Id: MX10 **Description:** MX10 745 Moxy

Rego Number: **Make:** Caterpillar

Model: 745 **Serial Number:** 3F600530

Service Date	SMU	Description of Service	Service Step	Service Completed By	Company	Labour Hours	Type
14/10/2025	10900	Ad-hoc Checklist - Equipment Related TIS-2029	-	-	-	1.00	-
13/08/2025	10799	Ad-hoc Checklist - Equipment Related TBI-1853	-	-	-	0.17	-
23/06/2025	10549	Ad-hoc Checklist - Equipment Related TIS-1688	-	-	-	5.00	-
12/06/2025	10485	Ad-hoc Checklist - Equipment Related TIS-1641	-	-	-	5.00	-
10/06/2025	10615	Moxy Maintenance Schedule	Step 1 - 500 Hr Service	Natalie Dawson	Kilcullen Contracting Pty Ltd	0.00	Service
28/05/2025	10410	Ad-hoc Checklist - Equipment Related TIS-1598	-	-	-	1.00	-
27/03/2025	10136	Moxy Maintenance Schedule	Step 2 - 1000 Hr Service	Natalie Dawson	Kilcullen Contracting Pty Ltd	0.00	Repair
04/02/2025	10130	Moxy Maintenance Schedule	Step 1 - 500 Hr Service	Natalie Dawson	William Adams (CAT)	0.00	Repair

Plant Service Record

Date: 17/11/2025

Plant Id: MX10 **Description:** MX10 745 Moxy

Rego Number: **Make:** Caterpillar

Model: 745 **Serial Number:** 3F600530

Service Date	SMU	WO Number	Description of Service	Service Step	Service Completed By	Type
14/10/2025	10900	-	Oil leak on right side of engine	-	Timothy Isaac|Natalie Dawson|Tyler Bird	-
14/10/2025	10900	WO-1879 - for MX10 - Oil Leak RHS engine	Ad-hoc Checklist - Equipment Related TIS-2029	-	-	-
13/08/2025	10799	-	Lights and indicators bright and visible	-	Tyler Bird|Natalie Dawson	-
13/08/2025	10799	WO-2054 - for MX10, HEADLIGHT GLOBE OUT	Ad-hoc Checklist - Equipment Related TBI-1853	-	-	-
25/06/2025	10557	-	Leaking oil from transmission filter	-	Timothy Isaac|Kilcullen Contracting|Natalie Dawson|Tyler Bird	-
25/06/2025	10557	-	Check condition and fully inflated	-	Timothy Isaac|Kilcullen Contracting|Natalie Dawson|Tyler Bird	-
25/06/2025	10557	-	At an appropriate level and free of leaks	-	Timothy Isaac|Kilcullen Contracting|Natalie Dawson|Tyler Bird	-
23/06/2025	10549	WO-1840 - for MX10 - Fault list	Ad-hoc Checklist - Equipment Related TIS-1688	-	-	-
13/06/2025	10493	-	Wipers and sprays working correctly	-	Timothy Isaac|Natalie Dawson|Tyler Bird	-
13/06/2025	10493	-	Low engine oil	-	Timothy Isaac|Natalie Dawson|Tyler Bird	-
12/06/2025	10485	WO-1793 - for MX10 - Water pump, Sprayers & Coolant top up	Ad-hoc Checklist - Equipment Related TIS-1641	-	-	-
10/06/2025	10615	-	Moxy Maintenance Schedule	Step 1 - 500 Hr Service	Natalie Dawson	Service
28/05/2025	10410	WO-1746 for MX10- Auto greaser adjustment	Ad-hoc Checklist - Equipment Related TIS-1598	-	-	-
15/05/2025	10339	WO-1685 for MX10 - Water pump	Ad-hoc Checklist - Equipment Related TIS-1525	-	-	-

08/05/2025	10297	-	Any other notes for workshop not covered in inspection	-	Tyler Bird|Natalie Dawson	-
08/05/2025	10297	WO-1618 - for MX10 Tailgate bolts & check engine oil levels	Ad-hoc Checklist - Equipment Related TBI-1502	-	-	-
28/04/2025	10232	-	Any other notes for workshop not covered in inspection	-	Daniel Stephens|Natalie Dawson	-
23/04/2025	10225	WO-1577 - for MX10 - reverse camera test	Ad-hoc Checklist - Equipment Related DST-1456	-	-	-
16/04/2025	10221	WO-1586 for MX10 CAT 745 Moxy TORQUE CONVERTER TEST PORT HOSE AND CHECK REVERSE CAMERA	Ad-hoc Checklist - Equipment Related TIS-1442	-	-	-
14/04/2025	10213	WO-1576 for MX10 CAT 745 Moxy LOSS OF CAB POWER ON RAMP	Ad-hoc Checklist - Equipment Related TIS-1437	-	-	-
31/03/2025	10138	WO-1358 for MX10 CAT 745 Moxy REPLACE ISOLATOR	Ad-hoc Checklist - Equipment Related TIS-1380	-	-	-
31/03/2025	10139	WO-1387 for MX10 CAT 745 Moxy REMOVE TRANSMISSION TO DIAGNOSE TORQUE CONVERTER FAULT	Ad-hoc Checklist - Equipment Related TIS-1391	-	-	-
27/03/2025	10136	-	Moxy Maintenance Schedule	Step 2 - 1000 Hr Service	Natalie Dawson	Repair
05/02/2025	10130	WO-1345 for MX10 CAT 745 - Post delivery inspection	Ad-hoc Checklist - Equipment Related TIS-1248	-	-	-
04/02/2025	10130	-	Moxy Maintenance Schedule	Step 1 - 500 Hr Service	Natalie Dawson	Repair

AVARD CIVIL
132 Strickland Road
East Bendigo VIC 3550
ABN: 28 164 276 439

PURCHASE ORDER

Purchase Order	07784
Date	21 Feb 2025
Project	Workshop - 132 Strickland Road
Equipment	MX10 745 Moxy #MX10
PO Number	07784
Reference Number	SI103400
Type	XeroPO
Status	BILLED
Line Amount Types	Exclusive

GP Smith Equipment VIC Pty Ltd
405 Hammond Road Dandenong Vic Australia 3175

torque converter 2nd hand Smiths

DESCRIPTION	QUANTITY	PRICE	TOTAL
TORQUE CONVERTOR GROUP TORQUE CONVERTOR GROUP	1 each	20,000.00	20,000.00
FREIGHT - WADAMS HORSHAM FREIGHT - WADAMS HORSHAM	1 each	135.00	135.00

Subtotal	20,135.00
GST 10%	2,013.50
Total AUD	**22,148.50**

BANK DETAILS: AVARD CIVIL PTY LTD
BSB: 633000
ACC: 149712382

THIS IS A PAYMENT CLAIM UNDER THE BUILDING & CONSTRUCTION INDUSTRY SECURITY OF PAYMENT ACT 2002 (VIC).

SALES PERSON
Tyler Bird
tylerbird24@gmail.com
0427 645 104