

MID COUNTRY MACHINERY, LLC.

3478 5th Avenue South
 Fort Dodge, IA 50501
 515-574-2302 • 800-206-5936
 www.midcountry.com

A01-291

Ship To:

SAME AS BELOW

Invoice To:

Vieth Construction Corp
 6419 Nordic Dr
 Cedar Falls IA 50613

Branch FORT DODGE		
Date 07/17/25	Time 10:54:37 (O)	Page 01
Account No. VIETH001	Phone No. 3192771006	Invoice No. W29511
Ship Via		Purchase Order
		Salesperson 080

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
 BRM27 BLUE DIAMOND 84" A X 145989
 ANGLE BROOM

SEGMENT# 1 C 199 N/A 07/01/25 07/01/25

BROOM NOT WORKING

Unloaded broom off of truck. Hooked up to one of our skid loaders and trying to figure out why broom isn't working. Found a few of the pins in the quick attach connector will push out when trying to connect. Fixed two pins and got functions to start working. Tore old broom core out and took off wafers to replace.

Replaced wafers and put broom back together and greased.

IFRT	INBND FREIGHT	1	224.03	224.03
216417	BROOM WAFER	43	29.24	1257.32
	PARTS			1481.35
	LABOR			1354.90
12011000	SEGMENT TOTAL==>			2836.25

***** WORK ORDER TOTALS *****

PARTS	1481.35
LABOR	1354.90
ENVIROMENTALFEE	7.00
SHOP SUPPLIES	94.84
SUB TOTAL==>	2938.09
IOWA STATE 6%	176.28
WEBSTER CO 1%	29.38
CHARGE SALE	3143.75