



AMA Energy Rentals Ltd.
Box 6475, Fort St John, BC V1J 4H9
Office: (250) 261-6500

Equipment: 474

Work Order #: 1964

Date: 12/19/2023

Year: 2020

Make: Kenworth

Model: T880

Odometer: 425421

Hours: 1

Serial Number: 1NKZX4TXXLJ963584

Labor

Mechanic	Quantity/Hours	Price/Rate	Amount
Allistair Dwyer	6.00	75.00	450.00
Jake Robinson	20.00	75.00	1,500.00
Nick Alten	10.00	75.00	750.00
Cody Morton	16.00	75.00	1,200.00
Ryan	2		

Parts

Description	Quantity/Hours	Price/Rate	Amount
308925-25, CLUTCH 2050LBFT EASY PEDAL	1.00	.00	.00
K4245, TRANSMISSION HEAT EXCHANGER (T880/PB)	1.00	.00	.00
PGLPS386PL, TRANSMISSION FLUID 75W90/SAE40 PAIL	1.00	.00	.00
RTLO18918B-PCAN, TRANSMISSION, EATON 18SPD	1.00	.00	.00
K240-883, Shaft clutch release	1.00	.00	.00
CS106C1498, CLUTCH CROSS-SHAFT	1.00	.00	.00
4305294, GASKET, SHIFT TOWER	1.00	.00	.00
4308226, GASKET, CLUTCH HOUSING	1.00	.00	.00
Q27-6081-1203X, SWITCH/MODULE ASSEMBLY, DOOR CONTROLS T880	1.00	.00	.00
SB200, CLUTCH BRAKE 2" BABCOCK	1.00	.00	.00
577-75507, SENSOR, TEMPERATURE (TRANS/DIFF)	1.00	.00	.00
E80-1027, WEAR PAD, TRANSMISSION SUPPORT T880	2.00	.00	.00
FWHD, FLYWHEEL GRINDING CHARGE	1.00	.00	.00

Nick Rabbed New bumper mount

TRUCK BROKE, CURRENTLY HAS 18 NEUTRALS, REPLACE TRANSMISSION WITH CLUTCH AND COOLER FOR 3RD YEAR WARRANTY COVERAGE.

ALSO REPLACING DRIVERS DOOR SWITCH/MODULE ASSEMBLY, ORDERED IN NOVEMBER.

2x Spl 250, Strap kit ✓
18L Fuller trans oil ✓

Total Labor	3,900.00
Total Parts	.00
Total Returns	.00
Total Sublet	.00
Shop Supplies	585.00
Invoice Total	4,485.00