

002-109

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3456452
		Invoice Date:	9/3/2025
		Location:	07
		Work Order Number:	505535
		Payment Type:	
		Page:	1 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JGL4WD JD ALL**COMPLAINT:**

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER
 INSPECTION BILLED ON WO 504691

CORRECTION:**VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST**

HOURS: 1216

TRACTOR DYNOED AT:

DOES THIS UNIT GET A VALUEMAX STICKER _S.F._ YES _NO
 HAS STICKER BEEN INSTALLED _YES_ _S.F._ NO
 CAB HAS BEEN COMPLETELY CLEANED _YES_ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _S.F._ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _S.F._ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

ONE MID ROLLER NOT REPLACED.
 NO GREENLIGHT STICKERS TO FIT.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

JFCC JD ALL**COMPLAINT:**

02 FREE CLEANUP OF CAB

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DISI	LAB DISC INTERN	-1.00	172.50	172.50	(\$172.50)	N
Labor: \$172.50	Parts: \$0.00	OL&M: \$0.00	Misc: (\$172.50)	Sub-Total: \$0.00		

JSOFTWARE JD 9RX 540**COMPLAINT:**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Baiecarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3456452**
 Invoice Date: **9/3/2025**
 Location: **07**
 Work Order Number: **505535**
 Payment Type:
 Page: **2 of 7**

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JSOFTWARE JD 9RX 540
03 UPDATE ALL CONTROLLER SOFTWARE

UPDATED SOFTWARE ON _____ CONTROLLERS.
 HAD TO PERFORM THE FOLLOWING CALIBRATIONS.

CORRECTION:
 UPDATED SOFTWARE ON _____ CONTROLLERS.

ENGINE
 CAB
 COREOS
 DEFHEADER
 ROOF
 DISPLAY

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
-----------------	---------------	--------------	--------------	---------------------

JGEN01-
COMPLAINT:
04 TOP UP COOLANT

CORRECTION:
 ADD COOLANT TO CORRECT LEVEL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	1.00	63.12	63.12	\$63.12	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
Labor: \$25.00	Parts: \$63.12	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$89.62		

JELECDIAG1 JD ALL
COMPLAINT:
05 LIGHTS/ TURN SIGNALS- PASSENGER SIDE FOLDING LIGHT ARM IS BURNT OUT ON BACK SIDE

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3456452
		Invoice Date:	9/3/2025
		Location:	07
		Work Order Number:	505535
		Payment Type:	
		Page:	3 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JELECDIAG1 JD ALL

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

REMOVE LIGHT ARM BRACKET.

REMOVE REAR LIGHT ON BRACKET AND REPLACE WITH NEW LIGHT.

FIT LIGHT ARM BRACKET AND TIGHTEN BOLTS.

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
-----------------	---------------	--------------	--------------	---------------------

J01001701 JD 9520RX

COMPLAINT:

06 REPLACE OIL IN ALL TRACK MID ROLLERS AND IDLERS. (32 TOTAL)

CORRECTION:

REPLACED OIL IN ALL TRACK IDLERS AND ROLLERS. (32 TOTAL)

REMOVED COVERS TO DRAIN OILS.

CLEANED UP SEALING SURFACES OF COVER AND HUB.

REPLACED O-RINGS IF REQUIRED.

REINSTALLED COVERS AND TORQUES HARDWARE.

REFILLED WITH OIL.

DROVE TRACTORS AND RECHECKED OIL LEVELS.

CHECKED FOR LEAKS.

DISPOSED OF USED OIL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	174.32	174.32	\$174.32	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
Labor: \$950.00	Parts: \$174.32	OL&M: \$0.00	Misc: \$3.00	Sub-Total: \$1,127.32		

JENGAIRFI JD 9RX 540

COMPLAINT:

07 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3456452
		Invoice Date:	9/3/2025
		Location:	07
		Work Order Number:	505535
		Payment Type:	
		Page:	4 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JENGAIRFI JD 9RX 540

CORRECTION:

UNFASTEN AIR FILTER HOUSING CLIPS.

CHECK COVER SEAL AND HOUSING FOR DAMAGE.

REMOVE AND REPLACE BOTH ENGINE AIR FILTERS.

ASSEMBLE IN THE REVERSE ORDER.
 MARK HOURS ON FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE230985	Secondary EngAir Filter	1.00	174.06	174.06	\$174.06	N
TA17973	Primary EngAir Filter 13.6	1.00	357.53	357.53	\$357.53	N
Labor: \$50.00		Parts: \$531.59	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$581.69	

JENGOILCH JD 9RX 640

COMPLAINT:

08 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.
 CLEAN AREA.
 INSTALL NEW OIL AND FILTER.
 RUN UNIT AND LEAK CHECK.
 MARK ENGINE HOURS ON NEW FILTER.
 ADJUST OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	151.30	151.30	\$151.30	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	196.77	196.77	\$590.31	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3456452 Invoice Date: 9/3/2025 Location: 07 Work Order Number: 505535 Payment Type: Page: 5 of 7
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JENGOILCH JD 9RX 640

EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	3.00	3.00	3.00	\$9.00	N

Labor: \$125.00 Parts: \$741.61 OL&M: \$0.00 Misc: \$10.25 Sub-Total: \$876.86

J100300 JD 9RX 640

COMPLAINT:

09 REPLACE ENGINE FUEL FILTERS

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
 REMOVED AND CLEANED FUEL STRAINER/WATER SEPARATOR.
 BLED FUEL SYSTEM.
 FUNCTION AND LEAK CHECKED.
 MARK HOURS ON FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	171.28	171.28	\$171.28	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	164.54	164.54	\$164.54	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$80.00 Parts: \$335.82 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$418.32

JCABFILTER JD 9RX540

COMPLAINT:

10 REPLACE CAB AIR FILTERS

CORRECTION:

PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3456452
		Invoice Date:	9/3/2025
		Location:	07
		Work Order Number:	505535
		Payment Type:	
		Page:	6 of 7

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JCABFILTER JD 9RX540

FOR THE RECIRCULATION FILTER, REMOVE UPHOLSTERY COVER.

REMOVE AND DISCARD OLD RECIRCULATION FILTER AND INSTALL NEW FILTER.

FOR THE FRESH AIR FILTER, TURN KNOB FULLY COUNTERCLOCKWISE TO UNLATCH COVER.

SWING DOWN COVER.

REMOVE AND DISCARD OLD FRESH AIR FILTER AND INSTALL NEW FILTER.

MARK HOURS ON FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE593819	CAB RECIRC AIR FILTER	1.00	71.44	71.44	\$71.44	N



PATTISON AGRICULTURE LIMITED
 10041 Durum Avenue, Box 580
 North Battleford, SK S9A 2Y7
 Phone: (306) 445-4468
 Fax: (306) 446-0146
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 453-2583	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3456452 Invoice Date: 9/3/2025 Location: 07 Work Order Number: 505535 Payment Type: Page: 7 of 7
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	1216	1RW9540DKNJ820816	070816U	

JCABFILTER JD 9RX540

TA32591	Cab FreshAir Filter	1.00	121.63	121.63	\$121.63	N
---------	---------------------	------	--------	--------	----------	---

Labor: \$50.00	Parts: \$193.07	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$243.07
-----------------------	------------------------	-------------------------	---------------------	----------------------------

Miscellaneous Charges:
 SERVICE ACCESSORIES

\$150.00

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$1,952.50
Parts:	\$2,039.53
OL&M:	\$0.00
Misc:	(\$5.25)
Grand Total:	\$3,986.78

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN 35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: _____ Date: _____