V01-244

PATTISON AGRICULTURE LIMITED
Box 1330
Russell, MB R0J 1W0
Phone: (204) 773-2149
Fax: (204) 773-3921
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No

Deliver To:

Invoice Number:	**3552952**
Invoice Date:	3/30/2026
Location:	17
Work Order Number:	524048
Payment Type:	
Page:	1 of 5

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	935	1RW9540DPRJ825227	241687	

JGL4WD JD ALL
COMPLAINT:
01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:
VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST
****
HOURS: ___935_____
TRACTOR DYNOED AT: __N/A_____
****
DOES THIS UNIT GET A VALUEMAX STICKER _^_ YES __NO
HAS STICKER BEEN INSTALLED _^_ YES __ NO
CAB HAS BEEN COMPLETELY CLEANED _____ZA_____(INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____fs___(INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB ____CK____(INITIAL)
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	85.83	85.83	$85.83	N
TY6341	SD POLYUREA GREASE	1.00	10.76	10.76	$10.76	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	1.00	0.00	-744.59	($744.59)	N

Labor: $2,625.00 **Parts: $96.59** **OL&M: $0.00** **Misc: ($744.59)** **Sub-Total: $1,977.00**

JFCC JD ALL
COMPLAINT:
02 FREE CLEANUP OF CAB

CORRECTION:

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Box 1330
Russell, MB R0J 1W0
Phone: (204) 773-2149
Fax: (204) 773-3921
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3552952**
Invoice Date:	3/30/2026
Location:	17
Work Order Number:	524048
Payment Type:	
Page:	2 of 5

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	935	1RW9540DPRJ825227	241687	

J06001001 JD S790
COMPLAINT:
04 TOP UP ALL FLUIDS.

CORRECTION:
Coolant - DONE
Engine Oil - DONE
DEF - DONE
TRANSMISSION /HYDRAULIC - DONE
WASHER FLUID - DONE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	148.09	148.09	$148.09	N
SWDEF025	DIESEL EXHAUST FLUID	1.00	21.99	21.99	$21.99	N
TY22062	HY-GARD J20C 9.46L	1.00	75.01	75.01	$75.01	N
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	1.00	63.12	63.12	$63.12	N
TY26673	15W40 3.78L Plus-50II CK4/SN	1.00	37.78	37.78	$37.78	N
15-204	WINDSHIELD WASH -40C 3.78L	1.00	6.27	6.27	$6.27	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	$1.25	N
EF150	ENVIRO FEE	2.00	1.50	1.50	$3.00	N
EF300	ENVIRO FEE	1.00	3.00	3.00	$3.00	N
EF60	ENVIRO FEE	1.00	0.60	0.60	$0.60	N

Labor: $50.00 **Parts: $352.26** **OL&M: $0.00** **Misc: $7.85** **Sub-Total: $410.11**

EXPERT-1000000027814
COMPLAINT:
05 RECOMMEND - REPLACE ETHER CAN- PUT IN CAB

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Box 1330
Russell, MB R0J 1W0
Phone: (204) 773-2149
Fax: (204) 773-3921
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number:	**3552952**
Invoice Date:	3/30/2026
Location:	17
Work Order Number:	524048
Payment Type:	
Page:	3 of 5

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	935	1RW9540DPRJ825227	241687	

EXPERT-1000000027814
REPLACED ETHER CAN
PLACED IN CAB
DONE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE556468	PREMIUM ETHER STARTING FLUID	1.00	14.65	14.65	$14.65	N

Labor: $16.80 **Parts: $14.65** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $31.45**

J01030070 JD 9410R
COMPLAINT:
07 REPLACE ENGINE VARIABLE SPEED FAN BELT.

CORRECTION:
take off shields
loosen tension
take belt off
put new belt on
set tension
done test ran



Labor: $409.50 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $409.50**

EXPERT-1000000148804
COMPLAINT:
10 DPF Service Regeneration, Perform

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Box 1330
Russell, MB R0J 1W0
Phone: (204) 773-2149
Fax: (204) 773-3921
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3552952**
Invoice Date:	3/30/2026
Location:	17
Work Order Number:	524048
Payment Type:	
Page:	4 of 5

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	935	1RW9540DPRJ825227	241687	

EXPERT-1000000148804
Ignition ON, engine running.
Ensure the application exhaust filter cleaning mode is enabled. For more information on enabling exhaust filter cleaning, see the application Operator's Manual.
In Service ADVISOR : Select Tests tab from Diagnostics toolbar.> Select ECU- (Engine Serial Number).> Select Service Regeneration.
Follow the directions on the screen. Select the type of Service Regeneration to be performed:
If you select a Service Regeneration and it automatically prompts you that a DPF Service Recovery is necessary, this is because the soot level in the exhaust filter is very high or at the Service Only level.
NOTE: If you select a Service Regeneration and it automatically prompts you that a DPF Service Recovery is necessary, this is because the soot level in the exhaust filter is very high or at the Service Only level.
NOTE: DO NOT begin a DPF Service Recovery unless you are absolutely certain that one needs to be performed. Once selected, the DPF Service Recovery runs until it is completed.
Service Regeneration — An active regeneration with fuel dosing. During this test the ECU also performs additional diagnostics on the DPF.
DPF Service Recovery — An approximately 3 hour long process which begins with a passive regeneration without fuel dosing. After the passive regeneration is complete, the ECU determines if an active regeneration with fuel dosing is required to further clean the DPF. If needed, the ECU will automatically start the active regeneration upon completion of the passive regeneration.
At the end of the Service Regeneration, return to the DTC or troubleshooting procedure that you came from and continue to follow those instructions. If there are no more instructions or if you did not come from a procedure, troubleshoot any new DTCs, beginning with any active ones.

-Performed service regeneration via service advisor
-top-up 9 liters of Def
-Regeneration completed.
-No issues

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SWDEF025	DIESEL EXHAUST FLUID	1.00	23.09	23.09	$23.09	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->>

PATTISON AGRICULTURE LIMITED
Box 1330
Russell, MB R0J 1W0
Phone: (204) 773-2149
Fax: (204) 773-3921
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3552952**
Invoice Date:	3/30/2026
Location:	17
Work Order Number:	524048
Payment Type:	
Page:	5 of 5

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 540 36" PTO	935	1RW9540DPRJ825227	241687	

EXPERT-1000000148804

EF100	ENVIRO FEE	1.00	1.25	1.25	$1.25	N

Labor: $210.00 **Parts: $23.09** **OL&M: $0.00** **Misc: $1.25** **Sub-Total: $234.34**

Miscellaneous Charges:

SERVICE ACCESSORIES	$150.00

Customer PO No:
Tax Exempt No:
Advisor:

Labor:	$3,311.30
Parts:	$486.59
OL&M:	$0.00
Misc:	($585.49)
Grand Total:	$3,212.40

*** * * DOCUMENT COPY * * ***



ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN $35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....