

Invoice

DIESEL TRUCK REPAIR
 NORTH FRONTAGE ROAD
 LLINGS, MT 59101

Date	Invoice #
5/10/2024	2739

Bill To
PECK TRANSPORT & EXCAVATING 6131 SHEPHERD ROAD SHEPHERD, MT 59079

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	HARNESSES AND FUEL LINES. INSTALL ENGINE ACCESSORIES. REINSTALL COOLING PACKAGE AND HOOK UP ALL LINES. SUCK DOWN AC SYSTEM AND RECHARGE AC SYSTEM. REPLACED OIL FILTER. FILLED ENGINE WITH OIL AND NEW COOLANT. REINSTALL INTAKE PIPING. CHARGE BATTERIES. REPLACED FUEL FILTER. GET TRUCK STARTED. RUN TRUCK AN RECHECK LEVELS. TOPED OFF LEVELS. HAS CODE FOR DPF OUTLET PRESSURE. WENT THRU TROUBLE SHOOTING, CLEANED SENSOR TUBES AN INSPECTED FOR LEAKS, OK., CLEARED CODE AND CODE CAME BACK. REMOVED DIFFERENTIAL PRESSURE SENSOR AND IT WAS FULL OF WATER. INSTALL NEW SENSOR, CODE WENT INACTIVE. CLEARED CODE. RUN TRUCK AND RECHECK FOR LEAKS, RECHECK LEVELS AGAIN. OK.		
11	DELVAC 15W40	19.95	219.45
13	EXTENDED LIFE COOLANT	13.10	170.30
1	ATF	9.75	9.75
1	BRAKE CLEAN	110.00	110.00
1	CYLINDER HEAD	7,350.00	7,350.00
1	EPA OVERHAUL KIT X15	8,200.00	8,200.00
6	SHIM LINER	72.25	433.50
8	HEAD BOLT	31.10	248.80
3	RED PAINT CUMMINS	29.50	88.50
1	ASSEMBLY GREASE	13.20	13.20
1	DPF PRESSURE SENSOR	181.80	181.80
1	CUT BLOCK COUNTER BORES	1,050.00	1,050.00
	SHOP SUPPLIES	325.00	325.00
Thank you for your business.		Total	\$28,115.30

HIGGINS DIESEL TRUCK REPAIR

3011 NORTH FRONTAGE ROAD
BILLINGS, MT 59101

Invoice

Date	Invoice #
5/10/2024	2739

Bill To
PECK TRANSPORT & EXCAVATING 6131 SHEPHERD ROAD SHEPHERD, MT 59079

paid check # 11339
\$ 25,000

Balance
\$ 3115.30

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	<p>2020 KENWORTH; VIN-LF387132; MIL-515650</p> <p>ENGINE IS BUILDING PRESSURE IN COOLING SYSTEM. DIAGNOSE AND REPAIR AS NEEDED.</p> <p>CHECK ENGINE, IT IS BUILDING PRESSURE IN COOLANT SYSTEM, REMOVED BACK OF EGR COOLER AN CHECK FOR LEAKS, OK. REINSTALLED PIPE, RUN TRUCK AND CHECK FOR COMBUSTION GAS IN COOLANT, IT IS POSITIVE. DRAIN COOLANT, REMOVED ALL ACCESSORIES TO GET HEAD OFF. REMOVED RADIATOR ASSEMBLY, FRONT TIN. REMOVED VALVE COVER AND REMOVED ROCKER ARMS AND CAMSHAFT. REMOVED HEAD BOLTS AND REMOVED HEAD FORM BLOCK. FOUND HEAD GASKET BLOWN AT #1 CYLINDER, AND STARTING TO BLOW ON REAR CYLINDERS. CLEANED BOTTOM OF HEAD , HEAD HAS GROOVE FROM HEAD GASKET BLOWN. DRAIN OIL. REMOVE OIL PAN, STIFFENER PLATE, OIL TUBES AND OIL PUMP. REMOVED SPRAY NOZZLES. REMOVED CYLINDERS AND LINERS. INSPECTED BLOCK. NEEDS CUT. CLEAN UP BLOCK. HAD BLOCK CUT. INSTALL NEW LINERS. REPLACED BEARINGS. CHECK ALL LINERS PROTRUSIONS, ALL AT .012. DISASSEMBLE RODS FROM OLD PISTONS, INSTALL NEW PISTONS ON RODS WITH NEW RINGS, ETC. INSTALL PISTON ASSEMBLIES IN ;LINERS WITH NEW BEARINGS. INSTALL NEW OIL NOZZLES. . SWAP OVER ALL PARTS TO NEW HEAD. INSTALL HEAD WITH NEW HEAD GASKET. TORQUED HEAD TO SPEC'S. REINSTALL CAMSHAFT, IDLER GEAR, ROCKER ARMS, ETC. INSTALL FRONT TIN WITH NEW GASKET. ADJUSTED VALVES, INJECTORS, JAKES ETC. REINSTALL VALVE COVER, EXHAUST MANIFOLD, THERMOSTAT HOUSING WITH NEW STAT. REINSTALLED EGR VALVE AND PIPING. DISASSEMBLED OIL PUMP AND INSPECTED. LOOKS OK. REINSTALLED OIL PUMP ON ENGINE. INSTALL STIFFENER PLATE, OIL TUBES AND REINSTALL PAN. REINSTALL INTAKE MANIFOLD,</p>	9,715.00	9,715.00

Thank you for your business.

Total

HIGGINS DIESEL TRUCK REPAIR

3011 NORTH FRONTAGE ROAD
 BILLINGS, MT 59101

Invoice

Date	Invoice #
5/31/2024	2766

Bill To
PECK TRANSPORT & EXCAVATING 6131 SHEPHERD ROAD SHEPHERD, MT 59079

34

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	2020 KENWORTH; VIN-LF387132; MIL-518498		
	OIL LEAK AT REAR OF ENGINE, DIAGNOSE AND REPAIR AS NEEDED.	527.00	527.00
	CHECKED FOR OIL LEAK, FOUND VALVE COVER HAS A CRACK IN IT. REMOVED EGR PIPING AND VALVE COVER. FOUND ISOLATOR BOLT RUSTED AND SWELLED UP IN HOLE. INSTALL NEW VALVE COVER, SWAPPED OVER ENGINE DATA TAG TO NEW VALVE COVER. REINSTALLED EGR PIPE. CLEANED OIL OFF BACK OF ENGINE. RAN TRUCK TO OPERATING TEMP AND RECHECK FOR LEAKS, OK.		
1	VALVE COVER	395.00	395.00
1	GASKET	71.90	71.90
6	ISOLATOR	16.25	97.50
	SHOP SUPPLIES	32.70	32.70

Thank you for your business.	Total	\$1,124.10
------------------------------	--------------	------------

HIGGINS DIESEL TRUCK REPAIR

Invoice

3011 NORTH FRONTAGE ROAD
BILLINGS, MT 59101

Date	Invoice #
10/28/2024	2926

Bill To
PECK TRANSPORT & EXCAVATING 6131 SHEPHERD ROAD SHEPHERD, MT 59079

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	2020 KENWORTH; VIN-LF387132; MIL-532327; UNIT-34		
	CHECK ENGINE LIGHT IS ON, DIAGNOSE AND REPAIR AS NEEDED.	464.00	464.00
	CHECK CODES, HAD ACTIVE CODE FOR TURBO ACTUATOR NOT RESPONDING. DRAINED COOLANT, REMOVED ACTUATOR, CHECKED TURBO IT MOVES FREELY. PERFORMED ACTUATOR INSTALL PROCEDURE, IT WOULD NOT MOVE. GET NEW ACTUATOR, PLUG IN AND INSTALL, IT PASSED. INSTALL NEW ACTUATOR AND CALIBRATE. REFILLED WITH COOLANT. RAN TRUCK AN TOPPED OFF COOLANT. CLEARED CODES FROM ECM.		
1	TURBO ACTUATOR ASSEMBLY	1,672.25	1,672.25
	SHOP SUPPLIES	64.10	64.10
Thank you for your business.		Total	\$2,200.35