

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	200.3	Will mann	9/16/21	

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
	/	/						

Repair Comments:

oil filter - 51568 wix  
engine oil 0w-40

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	408.1	Will Mann	10/15/21	

	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
Service	✓	✓		✓				

Repair Comments: Oil Filter - Wix 51568

Fuel Filters - ~~WF 10176~~

Wix

WF 10176



## PARTS INVOICE

Invoice To Account No.: [REDACTED] Deliver To Account No.: [REDACTED]

Invoice No: 1915320  
 Date: 10/20/2022  
 Page: 1 of 1  
 Payment Type: Finance

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
Machine ID: 202576	Make: JOHN DEERE	Model: 317G	PIN: 1T0317GJVNJ414949	Hours: 510				
2.00	0.00	3665	317D/G(13 IN)MULTI BAR	RACK37	1,549.80	1,549.80	\$3,099.60	Y

**Invoice Notes:**

JASON [REDACTED]

Please remit payments to PowerPlan at the address shown on your statement.

**Finance Information**

Customer PO No: 6016  
 Tax Exempt No:  
 Salesperson: VICKIE PITTMAN

Type: Power Plan      Auth. No: 892382  
 Merchant No: 88001631  
 Card No: xxxxxxxxxxxx8381  
 Bill Code: - N/A  
 Credit Plan: 249 - PURCHASE

Parts: \$3,099.60  
 Misc: \$0.00  
 Sales Tax: \$293.68  
 Deposit: \$0.00  
**Total: \$3,393.28**

*6016  
 Repair New tracks  
 #1-40  
 10-20-22  
 SS*

**TERMS AND CONDITIONS**

**Repayment Terms:**

This purchase is subject to the terms of the issuer's credit agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described. Please remit payments to PowerPlan at the address shown on your PowerPlan statement.

No merchandise may be returned without permission. Claims or returns must be made within 10 days and accompanied by this invoice. Returns are subject to a 15% handling charge. Returns must be in the original package and in resalable condition. No refunds on electronic or fuel injection parts.

Received by:

Date: \_\_\_\_\_

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
0016	1450.4	Matthew	5-13-24	Adam

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
	✓	✓	OK	✓	OK	NA	NA	

1546 7404

600176  
600396

Repair Comments:

Napa Filters + Oil

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
12016	1540.8	Matt	8/27/24	Adam

	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
Service			X					

Repair Comments: Changed air filters

---

---

---

---

---

---

---

---

---

---

# Send to Scott

## SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	1655.5	Matt	2-6-25	Adam

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
				6031A				

Repair Comments:

Replaced water/~~sep~~<sup>fuel</sup> separator Element.  
Replaced quick tach plate Bushings



**PARTS INVOICE**

Invoice To Account No.: [REDACTED]  Deliver To Account No.: [REDACTED]

Invoice No: [REDACTED]  
 Date: 4/10/2025  
 Page: 1 of 1  
 Payment Type: Finance

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
Eq ID: 232544		Make: JOHN DEERE	Model: 317G	PIN: 1P0317GJCPJ438245		Hours: 308		
2.00	0.00	JD7759	LUBRICATIO	01F3B	1.10	1.10	\$2.20	N
2.00	0.00	14M7647	NUT	01I3C	3.98	3.98	\$7.96	N
4.00	0.00	24M7617	WASHER	03K5B	1.79	1.79	\$7.16	N
2.00	0.00	T259403	SPACER	02C5D	69.32	69.32	\$138.64	N
2.00	0.00	T388038	PLUG	12F3C	13.01	13.01	\$26.02	N
2.00	0.00	T392448	BOLT	11H4A	26.56	26.56	\$53.12	N
1.00	0.00	AT505041	QUICK COUP		1,366.31	1,366.31	\$1,366.31	N

Invoice Notes:  
 ADAM [REDACTED]

Please remit payments to PowerPlan at the address shown on your statement.

**Finance Information**

Customer PO No: 6016  
 Tax Exempt No: 1/17/2023  
 Salesperson: RICKY MILLER

Type: Power Plan Auth. No: 35284  
 Merchant No: 88001631  
 Card No: xxxxxxxxxxxx8381  
 Bill Code: - N/A  
 Credit Plan: 249 - PURCHASE

Parts: \$1,601.41  
 Misc: \$0.00  
 Sales Tax: \$0.00  
 Deposit: \$0.00  
**Total: \$1,601.41**

4-14-25

Bucket  
 Quick Plate  
 & pins.

6016

Repair #1-40

55

**TERMS AND CONDITIONS**

Repayment Terms:

This purchase is subject to the terms of the issuer's credit agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described. Please remit payments to PowerPlan at the address shown on your PowerPlan statement.

No merchandise may be returned without permission. Claims or returns must be made within 10 days and accompanied by this invoice. Returns are subject to a 25% handling charge. Returns must be in the original package and in resalable condition. No refunds on freight, electronics, fuel injection parts and paint products.

Received by: ..... Date: .....

# Send to Scott

## SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	1747.4	Matthew	4-24-25	Adam

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments

Repair Comments:

Remove & replace quick tach  
plate & bushings

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	1853.3	Matthew	8.13.25	Adam

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments

Repair Comments:

500162  
500385

R+R Air Filters

SS0175

R+R Cabin Filter

Blow out Fresh Air Intake filter (cab)

R+R Female Aux connector (Hydraulic)

AT406475



# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	1958	Will Mann	10/5/25	

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments
	/	/	/	/	/		/	

Repair Comments: Cabin filter inner/outer AT 441536 AT 359416  
oil filter MIU 800650  
Hydraulic filter AT 314164  
inner air AT 336803  
outer air AT 338105  
fuel MIU 802421  
water seperator MIU 805005  
fuel vent filter H216169  
Hydraulic tank cap AT 443309  
engine oil 5.5 qts 15-40 Botella  
final drive oil 12 oz 80-90 gear oil per side

# SERVICE SHEET

Unit #	Miles/ Hours	Done By	Date	Foreman
6016	1969	Will Mann	12/2/25	

Service	Oil	Oil Filter	Air Filter	Fuel Filter	Hyd	Trans.	Rear end	Comments

Repair Comments:

Replace Blower motor

Replace wiper blade

Install new wiper switch