



# Penn View Equipment Co., Inc.

TRUCKS PARTS • SERVICE • TOWING

592 PENN VIEW RD • BLAIRSVILLE, PA 15717

PARTS (724) 459-6057 • SERVICE (724) 459-9560

TOLL FREE 1-800-882-1701



INVOICE DATE	
01/30/2020 03:02PM C	
INVOICE NO.	PAGE
30669	1
CUSTOMER NO.	BRANCH
21385	

SOLD  
TO

WM. DICKSON INDS. INC.

SHIP  
TO

WM. DICKSON INDS. INC.

113 LEE VALLEY ROAD  
DERRY PA 15627

113 LEE VALLEY ROAD  
DERRY PA 15627

TERMS: NET 30. Finance charge of 1-1/2% per month will be added to all accounts after 30 days. This is an annual rate of 18%.

CUSTOMER P.O.	R/S ORDER NO.		
	136978	(724) 539-6605	PE 000/000
		PRICE/PER	EXTENSION

COMPLETION DATE: 01/23/2020

UNIT: KW53 YEAR: 2005 MAKE/MODEL: KENWORTH W900

SERIAL: 1XKWD80X25J102512 MILEAGE: 394719

LICENSE NO.:

ENGINE MAKE: CAT

ENG MODEL/H.P.: C-15

ENGINE S/N: MXS14147

CPL/ARR: 260-2820

JOB#01 00 000 16 ENGINE

STEAM CLEAN ENGINE. REMOVE AIR PIPING, VALVE COVERS, VALVE COVER BASE, TOP TURBO, ACTUATORS, ROCKER SHAFT ASSEMBLIES, INJECTORS, PEANUT GEAR COVER, CAM GEAR, AND CYLINDER HEAD. FOUND HEAD GASKET LEAKING AT #2 AND #6 CYLINDERS. REMOVE OIL PAN. REMOVE ALL SIX CYLINDER PACKS. CLEAN BLOCK. CUT COUNTERBORE IN ALL SIX HOLES AND INSTALL LINER SHIMS. CLEAN CYLINDER PACKS AND CHECK THEM FOR REUSE. REPLACE #1, #2, AND #5 CYLINDER PACKS BECAUSE LINER SEALING SURFACE WAS PITTED SEVERELY. REINSTALL THE OTHER THREE CYLINDER PACKS. INSTALL NEW TOP BLOCK SPACER PLATE. INSTALL ALL NEW CONNECTING ROD BEARINGS. REINSTALL OIL PUMP, OIL PICK UP TUBES, AND OIL PAN. REMOVE ALL COMPONENTS FROM CYLINDER HEAD AND GET IT PRESSURE TESTED AND RESURFACED. REASSEMBLE CYLINDER HEAD. INSTALL ALL NEW EXHAUST MANIFOLD GASKETS (HEAT SLEEVES). REINSTALL INJECTORS WITH NEW O-RINGS ON THEM. REPLACE #2 AND #5 EXHAUST ROCKER ARMS. REINSTALL ROCKER SHAFT ASSEMBLIES. REINSTALL CAM GEAR AND PEANUT COVER WITH NEW O-RING SEAL. REINSTALL VALVE COVER BASE WITH NEW GASKET. ADJUST VALVES AND INJECTORS. REINSTALL ACTUATORS AND ADJUST. REINSTALL THERMOSTAT HOUSING WITH TWO NEW THERMOSTATS, SEALS, AND GASKETS. REINSTALL VALVE COVERS WITH NEW GASKETS. INSTALL NEW ENGINE OIL AND OIL FILTER. REPLACE TOP L COOLANT HOSE ON AIR COMPRESSOR. REPLACE COOLANT HOSE BETWEEN THERMOSTAT AND WATER PUMP. REFILL COOLANT AND TOP IT OFF. TROUBLE-SHOOT FAULT CODE 31 - SPEED SENSOR LOSS OF SIGNAL. RUN TWO NEW WIRES FROM OEM ECM PLUG TO SPEED SENSOR AND INSTALL NEW PIGTAIL AND NEW SPEED SENSOR. CLEAR FAULT CODES.

6 CA 2303728	SEAL	\$8.18	6.62EA	39.72
6 CA 2303775	SEAL	\$10.60	8.65EA	51.00
FREIGHT		TAXABLE SUB TOTAL	SALES TAX	
			PLEASE PAY	

\*CONTINUED\*

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Customer Signature X



# Penn View Equipment Co., Inc.

TRUCKS PARTS • SERVICE • TOWING

592 PENN VIEW RD • BLAIRSVILLE, PA 15717

PARTS (724) 459-6057 • SERVICE (724) 459-9560

TOLL FREE 1-800-882-1701



INVOICE DATE		01/30/2020 03:02PM
INVOICE NO.	PAGE	30669 2
CUSTOMER NO.	BRANCH	21385

SOLD  
TO

WM. DICKSON INDS. INC.

113 LEE VALLEY ROAD  
DERRY PA 15627

SHIP  
TO

WM. DICKSON INDS. INC.

113 LEE VALLEY ROAD  
DERRY PA 15627

TERMS: NET 30. Finance charge of 1-1/2% per month will be added to all accounts after 30 days. This is an annual rate of 18%.

CUSTOMER P.O.		P/S ORDER NO.					
136978		(724) 539-6605		PE		000/000	
				PRICE/PER		EXTENSION	
6 CA	9X7317	ORING	\$4.22	3.42EA		20.52	
6 CA	8S9191	BOLT	\$1.57	1.27EA		7.62	
1 CA	5076208	GASKET KIT	\$1024.33	829.79EA		829.79	
6 CA	2613450	BEARING-ROD	\$38.71	31.36EA		188.16	
1 CA	1090072	ORING	\$7.32	5.93EA		5.93	
1 CA	1090078	ORING	\$6.54	5.30EA		5.30	
1 CA	1R1808	FILTER AS-LU	\$36.77	29.79EA		29.79	
6 CA	6I4361	.030 LINER SHIM	\$79.68	64.55EA		387.30	
3 CA	10R6215	CYL PACK	\$705.47 EXC	571.49EA		1714.47	
3 CA	10R6215-C1	CYL PACK	\$190.07 CHG	190.07EA		570.21	
3-CA	10R6215-C1	CYL PACK	RET	190.07EA		570.21	
1 CA	6I4421	PLATE SPACER	\$517.90	419.54EA		419.54	
3 CA	1609874	GASKET KIT	\$46.32	37.52EA		112.56	
1 CA	1241854	BOLT 12PT	\$20.62	16.70EA		16.70	
1 CA	1241855	12PT. HEAD BOLT	\$18.72	15.17EA		15.17	
1 GW	JL-28003-1	MOLY PASTE 1/3 CAN	\$24.66	18.50EA		18.50	
2 CA	2477133	REGULATOR-TE	\$52.64	42.64EA		85.28	
12 CA	2N2766	LOCK NUT	\$6.29	5.09EA		61.08	
1 CA	2239257	HOSE	\$11.35	9.20EA		9.20	
1 CA	1029089	COVER	\$19.62	15.89EA		15.89	
1 CA	2355678	SEAL-O-RING	\$0.90	0.73EA		0.73	
1 CA	8T5917	SEAL-O-RING	\$1.90	1.54EA		1.54	
1 AUT	561.27416	HOSE CLAMP SS 13/16-1-	\$2.32	1.74EA		1.74	
1 M3	7447	SCOTCH BRITE PAD	\$1.72	1.29EAT		1.29	
2 CA	2971813	BUTTON SCREW	\$3.23	2.62EA		5.24	
1 CA	9L8925	BOLT	\$0.24	0.20EA		0.20	
2 CA	20R3317	ARM ROCKER INT/E	\$135.93 EXC	110.12EA		220.24	
2 CA	20R3317-C1	CORE	\$36.98 CHG	36.98EA		73.96	
2-CA	20R3317-C1	CORE	RET	36.98EA		73.96	
1 CA	2415682	CLIP	\$2.19	1.77EA		1.77	
10 GW	6226	MEDIUM WIRE TIE	\$0.14	0.11EAT		1.10	
10 GW	6227	LONG WIRE TIE	\$0.24	0.18EAT		1.80	
10 GW	6240	HEAVY DUTY WIRE TIE	\$0.42	0.32EAT		3.20	
2 CA	4F0411	CAPSCREW	\$2.47	2.00EA		4.00	
1 MEI	0011	ORING	\$0.24	0.18EA		0.18	
1 MEI	0013	ORING	\$0.40	0.30EA		0.30	
1 MEI	0015	ORING	\$0.58	0.46EA		0.46	
6 GW	6MMFLAT	6MM FLAT WASHER	\$0.28	0.21EA		1.26	
2 GW	1/4X1NC	1/4 X 1 USS BOLT	\$1.22	0.92EA		1.84	
2 GW	1/4NC	1/4 USS NUT	\$0.22	0.17EA		0.34	
4 GW	1/4X1/4	1/4 SAE FLAT WASHER	\$0.22	0.26EA		0.24	

FREIGHT

TAXABLES

SUB TOTAL

TAX STATUS/STATE

SALES TAX

PLEASE PAY

\*CONTINUED\*

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Customer Signature X



# Penn View Equipment Co., Inc.

TRUCKS PARTS • SERVICE • TOWING

592 PENN VIEW RD • BLAIRSVILLE, PA 15717

PARTS (724) 459-6057 • SERVICE (724) 459-9560

TOLL FREE 1-800-882-1701



INVOICE DATE

01/30/2020 03:02PM C

INVOICE NO.

30669

PAGE

3

CUSTOMER NO.

21385

BRANCH

SOLD  
TO

WM. DICKSON INDS. INC.

SHIP  
TO

WM. DICKSON INDS. INC.

113 LEE VALLEY ROAD  
DERRY PA 15627

113 LEE VALLEY ROAD  
DERRY PA 15627

TERMS: NET 30. Finance charge of 1-1/2% per month will be added to all accounts after 30 days. This is an annual rate of 18%.

CUSTOMER P.O. R/S ORDER NO.

136978

(724) 539-6605

PE 000/000

			PRICE/PER	EXTENSION
1 CA	2769507	HOSE	\$22.61	18.32EA 18.32
1 CA	6V5048	SEAL-O-RING	\$3.73	3.02EA 3.02
1 CA	9S8002	PLUG	\$4.51	3.65EA 3.65
1 CU	3823256	ASSY, T	\$13.64	10.20EA 10.20
1 KW	Q21-6005	SENSOR - SPEED/TACH	\$176.56	132.42EA 132.42
4 GW	6226	MEDIUM WIRE TIE	\$0.14	0.11EAT 0.44
2 CR	1261768	12/14 GA PIN	\$2.09	1.69EA 3.38
1 CA	1440367	CLAMP	\$15.64	12.67EA 12.67
1 M1	L0034-094	105 LUBRIPLATE WHITE	\$14.22	13.88EA 13.88
1 M3	7447	SCOTCH BRITE PAD	\$1.72	1.29EAT 1.29
2 M3	02433	COARSE EMERY CLOTH	\$2.80	2.10EAT 4.20
4 M3	7450	SCOTCH BRITE DISC	\$5.68	4.26EAT 17.04
2 CC	5089T	BRAKE CLEAN	\$6.18	4.64EAT 9.28
1 PSI	B6	BLUE SILICONE	\$3.30	2.47EA 2.47
1 LO	27100	271 LOCTITE	\$6.32	4.74EA 4.74
		CYL HEAD P/T		736.00
		& RESURFACE		
10 CG	701	GAL 15W40 MOTOR OIL	\$20.74	12.96EA 129.60
		STEAM CLEAN DISPOSAL		20.00
		SHOP SUPPLIES		5.00
		MISC SUBTOTAL		761.00
		PARTS SUBTOTAL		4648.49
		LABOR SUBTOTAL		4725.00
		** JOB SUBTOTAL		10134.49

\*TOTAL PARTS: 4648.49  
\*TOTAL LABOR: 4725.00  
\*TOTAL OTHER: 761.00

FREIGHT

TAXABLE SUB TOTAL

TAX STATUS/STATE

SALES TAX

PLEASE PAY

10134.49

EXEMPT PA\*

2.38

10136.87

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Customer Signature X